

Ref: 12

COMFORTDELGRO ENGINEERING

Our Ref : T 0519 / SH 7819S /WT(st)

Your Ref :

Date : 10-Jun-19

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6353 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registered No: 196022400

CHINA TAIPING INSURANCE CO LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING OUR TAXI SH 7819S YOUR INSURED SLP8465M
AND OTHER ON 28.05.19

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : **SH 7819S** which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SLP8465M** we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 1,284.00
6	3 days Loss of Rental @ \$ 165.46 per day	\$ 496.38
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transporation Fees	\$ -
Sub Total :		\$ 1,787.87

HIRER'S CLAIM

7	3 days Loss of Income @ \$ 80.00 per days	\$ 240.00
Total Claims :		\$ 2,027.87

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 4 pcs.
- b) LTA search slip/s of : SLP8465M
- c) GIA / Police report/s of : SH 7819S
- d) Letter of authority from owner / hirer / operator
 - () Traffic Compound () Towing/Medical bill/receipts () Certificate of Insurance
 - (X) Photograph/s of Accident Scen (x) Downtime/Mileage record (x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

William Tan

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email : williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sei Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408648

Senoko
24 Senoko Loop
Singapore 758158

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
Jishun Industrial Park A
Singapore 768732

A member of

COMFORTDELGRO





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/CTI19009497/K1eb3

26 SEPT 2019

PHUA SOON NGEE
70 JALAN EUNOS
SINGAPORE 419515

Dear Sir/Madam,

ACCIDENT INVOLVING SLP 8465M AND SH 7819S ON 28/05/2019

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING
ALONG****MERCEDES E220 SH7819S , SLP8465M
SERVICE RD OFF JALAN EUNOS****ON 28-May-19 09:20**

I / We

NEO TIONG HUAT(Hirer) NRIC No.: **S1156564F**

and/or

(Relief) NRIC No.:

Taxi Number

SH7819S

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date

28-May-2019


Name of Hirer

NEO TIONG HUAT

Hirer NRIC

S1156564F

Signature :



Address

**521 HOUGANG AVENUE 6 #10-59
530521**

Contact No.

96724635

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMPCSN1743111801

Claim No :

Claimant : COMFORT TRANSPORTATION PTE LTD

Amount : S\$1,830.00

DOLLARS ONE THOUSAND EIGHT HUNDRED AND THIRTY ONLY.

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving
TAN ENG KHOON

Claimant Vehicle No. : SH 78195

Insured Vehicle No. : SLP 8465M

Date of Loss : 28/05/2019

Place of Accident : SERVICE RD OFF JALAN EUNOS

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name : PHUA SOON NGEE

Driver Name : PHUA SOON NGEE

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

(1) Global Sum	S\$ 1,830.00
TOTAL	S\$ 1,830.00

Claimant Name : COMFORT TRANSPORTATION PTE LTD

NRIC No :

Signature :

Date :

14/10/19

CLAIMS DEPARTMENT
COMFORTDELGRD ENGINEERING PTE LTD
25 LOYANG DRIVE
SINGAPORE 639051

"The contents of this document apply to vehicle damages only
All personal injuries and damages arising therefrom are excluded
from the ambit and application of this document"

Please forward your cheque made payable to:
COMFORTDELGRD ENGINEERING PTE LTD

TAX INVOICE

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD
SPRINGLEAF TOWER

3 ANSON ROAD #16-00
SINGAPORE 079909

CONTACT NO: 62222366

VEHICLE NO
SH 7819S

NO/DATE
91446959 31.05.2019

MAKE
MERCEDES BENZ

JOB NO.
305299026

MODEL
E220CDI (E5)

ODOMETER READING

DATE OF REG
25.10.2013

CHASSIS CODE
WDD2120022A757481

JOB TYPE

Description : 3P 28.05.2019

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt	1,200.00
Add GST @ 7.000 %	84.00
Total Invoice amount	1,284.00

Issued by : CHEWHEELING 31.05.2019 15:36:36
Repair Type : CLSO/57/57
Payment Type/Term : /Credit 30 days

WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST THE THEFT OF ANY MATERIAL DELIVERED TO THE COMPANY, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR LOSS OR DAMAGE TO ANY MATERIAL DELIVERED TO THE COMPANY AND VEHICLES ARE DAMAGED AND THEREBY AS OWNERS RISK. CUSTOMERS SHALL BE RESPONSIBLE FOR ANY DAMAGE TO ANY MATERIAL DELIVERED TO THE COMPANY AND VEHICLES ARE DAMAGED AND THEREBY AS OWNERS RISK. NOTICE RELATING TO THE COMPANY IS NOT CONSIDERED VALID UNLESS THE VEHICLE IS DELIVERED TO THE COMPANY WITHIN THE PERIOD OF 14 DAYS. INTEREST ON LUMP SUM AMOUNT WILL BE CHARGED ON A DAILY BASIS IN RESPECT OF ANY LUMP SUM AMOUNT PAID TO THE COMPANY BY THE CUSTOMER. THE CUSTOMER SHALL BE RESPONSIBLE FOR ANY DAMAGE TO ANY MATERIAL DELIVERED TO THE COMPANY AND VEHICLES ARE DAMAGED AND THEREBY AS OWNERS RISK. PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY DISCREPANCIES WITHIN 14 DAYS OF RECEIPT OF THE INVOICE. IF NO DISCREPANCIES ARE NOTICED, THE CUSTOMER SHALL BE RESPONSIBLE FOR ANY DAMAGE TO ANY MATERIAL DELIVERED TO THE COMPANY AND VEHICLES ARE DAMAGED AND THEREBY AS OWNERS RISK.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Our Ref: CT19050769

Date: 31 May 2019



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	28/05/2019 @ 09:20 hrs
ALONG	SERVICE RD OFF JALAN EUNOS
INVOLVING	SLP8465M

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH7819S** (the "Taxi"). The Taxi was hired to **NEO TIONG HUAT IC NO S1156564F** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$165.46** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

[illegible]

Enquire Vehicle Insurer

SLP8465M	28 May 2019 / 09:20:00	Successful	C01	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
----------	------------------------	------------	-----	---

Previous OK

SH 78195