COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

: SH 7819S

DATE: 28. May. 2019

EL	: E220 (E5)	DOA:	28. May. 2019 Unit Price	Amount
Qty	Parts Description/ Labour	Туре	Unit Price	\$1,890.50
	1 Front Bumper × rear			\$1,830.30
	1 Radiator Grille			\$1,220.00
	1 Radiator Grille Star Logo			\$170.00
	SUB TOTAL			\$3,280.50
	LESS 20%	1		\$656.10
	DISCOUNTED TOTAL			\$2,624.40
	DISCOUNTED TOTAL			1-/-
				\$-
	Labour Charge			200
	1 Panel Beating			\$500.00
	1 Spray Painting Charge			\$500.00
	1 Wiring Charge			\$50.00
	Kahi ICICAS TOTAL LABOUR 28/5/19 15/06-5 ESTIMATE TOTA 2/5 AML Rost place			
	Kaluh 1010	1		64.050.00
	TOTAL LABOUR	R Sherice notif		\$1,050.00
	1/ 28/5/19 15 10ms	3 15 herry pain	1.05U' has	40.074.11
	ESTIMATE TOTA	F Con string and	resurvey resurv	\$3,674.40
Larry	NO 11- (KILLINGER	10 8 3 2 3 LII 3 10 CO.	Standard Weder Subbans	
Paul)	24 2 . 1	05 16 230 12 OU 3	ST TO INSUITANCE	
	Ath Report part	319 SUPPLICATIONS	prathon,	
	101/d	E DI VIAN IN BID	. /	
	This is an initial estimate based on a visual inspection of	the above ve	chicle. The final repair	quantum will