

ASS. REC. BY:

REF: 093/17117009503/Ged3el Special Instruction:

Assigner:

ASSIGNMENT (Office)

Munmen

From (Person): Chong Euan Sen

of CTI

Date/Time: 24/5/19 @ 3.45pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 300SR

Insured:

PA 9172H

at Workshop n/s

Lee Jew Sing Motor

Tel:

64837412

of 10 AMK Ind. Park 2A #03-10

Policy No: DMB1ENB0313319000.

Claim No:

SNM19D202387

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27/05/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9.45am @ 24/5/19

Person Contacted:

Ms. Kim

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction	Estimate (X)
	SKW 300SR - CR/INC/17004471/Hgh 3m2	DOA: 24/02/2017
	PA 9172H - CR/AXA/15004784/Klum 3q2	DOA: 17/03/2015
	Dismantle: 30/5/2019	
	After repair: 6/6/2019	

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Lee Kew Sing Motor

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$75K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKW3005R

Yr Regn:

26 Oct 2015

Type: ☒ M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 116D

c.c

1496

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

90556

T/Radio: Insured / Std / NI / NA

Eng/No:

WBA1V72070V 249830

C/No:

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/40ZR18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

28-05-19

Survey held at

w/s

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

Spun

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$7000 - \$8000

30/5/2019

Date/Time, File Pass to?



: Preli. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I. (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 May 2019		29 May 2019 09:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:

Main Claimant: **LEONG YIN PHENG**, ID: S7626911D

Vehicle Reg. No.:

SKW3005R

Claim Type:

TP / SNM19D202387C02

Vehicle Reg. No. (Insured):

PA9172H

Date of Loss:

27/05/2019 07:00 - :59

Policy/Cover Note No.:

DMB1SN30313319000

Policy No. (Claimant):

10697597

Excess:

S\$0.00

Repairer:

Lee Leuw Sing Motor (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-10 AMK AUTOPOINT, 568047
Ang Mo Kio - Tel:

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by **Chong Boon Sen**]

Claimant's Insurer:

Aviva Ltd (HQ) - Tel: (65) 6827 9966

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/06/2019]

View All

Compose Case Mail

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

View All

Search Tasks

Create New Task

Complete

No results.

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 28 May 2019 3:45 PM
To: Sow-ye Wong
Cc: leeluewsingmotor@live.com; ethtan88@singnet.com.sg; assignments
Subject: RE: OUR REF: SNM19D202387

WITHOUT PREJUDICE SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Sow-ye Wong [mailto:wongsylaw@gmail.com]
Sent: Tuesday, 28 May, 2019 3:44 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: leeluewsingmotor@live.com; ethtan88@singnet.com.sg
Subject: Re: OUR REF: SNM19D202387

Dear Boon Sen

We thank you for your proposed PRS Surveyor list *below*

We regret to inform you that our Client is unable to agree to your list of nominated Surveyors

Our Client proposes

	Name of Firm	Surveyor	Mobile

1.	M/s Pro Plus Automobile Engineers	Errol Tan	9673 0595
2.	CA Appraisal Services	Ang Guea Kiang	9639 9762
3.	Lee Automobile Appraisers Services	Lee Kok Weng	8188 2833
4.	Prominent Appraiser Services	Andrew How	9295 2204
5.	Prestige Appraiser Services	Francis Ng	9689 7474
6.	Sincere Appraisal Services	Dave Chang	8186 9497
7.	Prestige Appraiser Services	Louis Ng	9682 4663
8.	KTO Automobile Assessors	Kent Ong	9850 5311
9.	Aeon Auto Consultants LLP	Amas Ong	9768 7958
10.	Precision Appraisal Services	Philip Foo	9685 2057

Please contact our **Mr Kim @ 9668 6354 / 6483 7412**

Appreciate your kind understanding & help

Yours Sincerely

Sow yee

cc: Client

PS: Dear Boon Sen - Kindly - Please revert to my numerous reminders by email & telephone on our outstanding matters

Most grateful if you can at least revert

On Tue, May 28, 2019 at 3:34 PM Chong Boon Sen <boonsen.chong@sg.entaiping.com> wrote:

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI

HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Tuesday, 28 May, 2019 2:33 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; wongsylaw@gmail.com

Cc: leeluewsingmotor@live.com; ethan88@singnet.com.sg; Angie Foo <angie.foo@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: OUR REF: SNM19D202387

Dear Boon Sen,

Please conduct PRS on behalf of Elaine – TP: SKW3005R (SNM19D202387) soonest possible.

File with Boon Sen – 63896171

OIC – Elaine - 63896530

From: Sow-ye Wong [<mailto:wongsylaw@gmail.com>]

Sent: Tuesday, 28 May 2019 1:52 PM

To: Irene Tay <irene.tay@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; KIM - SENG SON <leeluewsingmotor@live.com>; Errol Tan <ethtan88@singnet.com.sg>

Subject: Fwd:

Our Ref : FCY / 625 / 19

Your Ref : PA 9172H - FORTEC AUTOMOTIVE P L

M/s China Taiping Insurance (S) P L

Email: claimsdept@sg.cntaiping.com

Attn: Ms Irene Tay, The Executive - Motor Claims

Dear Sirs

NOTICE OF ACCIDENT

CLAIMANT: LEONG YIN PHENG (LIANG YANPING) - S7626911D

ACCIDENT INVOLVING SKW 3005R & PA 9172H ON 27.05.19 ALONG PIE/TUAS @ ABOUT 07:50 AM

We act for **LEONG YIN PHENG (LIANG YANPING)** Owner & Driver

Our Client's Car : SKW 3005R

Your / Your Insured's Taxi : PA 9172H

Date & Time of Accident : 27 MAY 2019 / 07:50 AM

Place of Accident : PIE/TUAS

Before our Client proceed to repair the damaged car, we are requesting a Pre-Repair Survey
Kindly let us know within **2 working days** of this Notice whether you or your Insurers would like to conduct a PRS
of the car

If we do not receive any reply from you/your Insurers within the stipulated timeline, our Client shall proceed to repair
the car without further reference to you & our Client will be compensated for the loss of use of the car for this period
of time

Our Client's Appointed Workshop - **M/s Lee Leuw Sing Motor** (Please contact: **Kim - 9668 6354**)

10 Ang Mo Kio Industrial Park 2A # 03 - 10 AMK Autopoint S 568047

Tel : 6483 7412 / 6483 0827

Copies of Claimant's GIA Report, NRIC & Driving License, COI, LTA Search, Warrant-To-Act & Letter Of Authority
& **Front & Rear Video Footage** are enclosed for your kind attention

Appreciate your prompt action

Faithfully

Sow yee

enc cc: Client

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	6911D
Vehicle No.:	SKW3005R
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2019
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR HATCHBACK DSC LED
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	37219362B37D15A
Chassis No.:	WBA1V72070V249830
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,356.00
Original Registration Date:	26 Oct 2015
First Registration Date:	26 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$11,099.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Oct 2025
PARF Rebate Amount:	\$8,324.00
COE Expiry Date:	25 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,301.00
COE Rebate Amount:	\$36,691.00
Total Rebate Amount:	\$45,015.00

The information contained herein is correct as at 29 May 2019

OK

▶ **bmw 116d Used Vehicle List (4 vehicles)**

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
BMW 1 Series 116d (Diesel - Euro 5 Engine and Above)	\$74,900	\$11,120 /yr	25-Aug-2015	1,496 cc	27,000 km		Availal
Low Mileage, As Good As New, In Excellent Condition, 5 Years Warranty, Always Serviced By PML, Single Owner, Well Maintained And Accide Free							
Office No. - -							
Kavita Shivkumar - 98249431							
BMW 1 Series 116d (Diesel - Euro 5 Engine and Above)	\$75,800	\$11,270 /yr	14-Sep-2015	1,496 cc	54,000 km	MK Autohaus Pte Ltd	Availal
Lady Owner. PML Maintained And Accident Free. Mileage 54,000 And Recent Change Runflat Tyres. Paint Protection By CSII Ceramic Coating And Car Wash Mantain By CSII Only.Beautiful White Exterior With ...							
Office No. - -							
Mr Ng - 92705621							
BMW 1 Series 116d (Diesel - Euro 5 Engine and Above)	\$75,800	\$10,890 /yr	28-Oct-2015	1,496 cc	81,000 km	Supreme Cars Pte Ltd	Availal
5 Yrs/200,000Km Warranty And 5 Yrs/100,000Km Free Servicing From Agent PML! Attractive Financing Available. Gorgeous Mineral Grey Paintwork With Black Leather Interior! Trade In Available. Come And Vi...							
Office No. - 64796280							
Ice Chan - 82986355 Johnathan Kong - 94599554 Eugene Seoh - 86861770 Eric Chua - 87772233							
BMW 1 Series 116d (Diesel - Euro 5 Engine and Above)	\$75,800	\$10,930 /yr	27-Nov-2015	1,496 cc	70,688 km	Benefit Auto Enterprise Pte Ltd	Availal
Offer Best Price For Trade In! Offer Best Interest Rate With High Loan! Hurry Please Call For Availability, High Loan Discussion Or Viewing Appointment! Please Call Sales Person!							
Office No. - 68444161							
Andy Ng - 90222757 Razali - 90405005 Thom Lai - 97493638							

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authori car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, ca reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/05/2019 11:43
Date Of Accident	27/05/2019 07:50
Exact Location Of Accident	PIE (TUAS) AFTER SINGAPORE DISCOVERY CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW3005R
Insured/Policyholder	
Name Of Registered Owner	LEONG YIN PHENG
NRIC No	S7626911D
Email Address	W3NDYLYP@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-92348355
Alternative Phone No	OFFICE-92348355

Vehicle Particulars

Manufacturer	BMW
Model	116D 5DR HATCHBACK DSC LED
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10697597
Cover Note Number	

Driver

Name of Driver	LEONG YIN PHENG
NRIC No	S7626911D
Date Of Birth	27/08/1976
Occupation	INDOOR
Date Of Driving Pass	03/10/2006
Driving Experience	12 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92348355
Fax Number	
Contact Number	OFFICE-92348355
Email Address	W3NDYLYP@YAHOO.COM.SG

* Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED ROAD AND WHEN A VEHICLE MADE A STOP, I FOLLOWED SUIT BEHIND IT AT A DISTANCE. WHEN MY VEHICLE WAS STATIONARY, IT WAS HIT FROM THE REAR BY VEHICLE B. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT. THIS INCIDENT WAS CAPTURED IN MY IN CAR VIDEO.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING VIDEO FROM INSURED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA9172H
Vehicle Make/Model/Colour	ISUZU LT134P / ORANGE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	FOO SIK CHIEW
NRIC/Passport Number	
Contact Number	82376838
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured my vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARKS
REPORTING OFFICER
Hashim Kamari

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel 270516.

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED ROAD AND WHEN A VEHICLE MADE A STOP, I FOLLOWED SUIT BEHIND IT AT A DISTANCE. WHEN MY VEHICLE WAS STATIONARY, IT WAS HIT FROM THE REAR BY VEHICLE B. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT. THIS INCIDENT WAS CAPTURED IN MY IN CAR VIDEO. .


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

27 May 2019 at 10:26 AM

Date/Time:

27 May 2019 at 10:26 AM

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 May 2019		29 May 2019 09:56 Edit Adj Rpt	\$S\$0.00 Edit Estimates	\$S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
<div>CLAIM SUBFOLDER DETAILS [Created by insurer]</div> <div> <div>Insured: -, Co. Reg. No.: -</div> <div> <div>Main Claimant: LEONG YIN PHENG, ID: S7626911D</div> <div> <div>Vehicle Reg. No.: SKW3005R</div> <div>Date of Loss: 27/05/2019 07:00 - :59 [43 Months and 1 Days From LTA Reg Date (Man Yr)]</div> </div> <div> <div>Claim Type: TP / SNM19D202387C02</div> <div>Policy/Cover Note No.: DMB1SN30313319000</div> </div> <div> <div>Vehicle Reg. No. (Insured): PA9172H</div> <div>Policy No. (Claimant): 10697597</div> </div> <div> <div>Excess: \$S\$0.00</div> </div> </div> <div> <div>Repairer: Lee Leuw Sing Motor (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-10 AMK AUTOPOINT, 568047 Ang Mo Kio - Tel:</div> <div>Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]</div> <div>Claimant's Insurer: Aviva Ltd (HQ) - Tel: (65) 6827 9966</div> <div>Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/06/2019]</div> </div> </div>				

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?















































No results.









































Claim Documents













































***SKW3005R (SNM19D202387C02)**
[PA9172H]

TP
LEONG YIN PHENG
May 27 2019 7:00AM
[-]
Lee Leuw Sing Motor

Upload Documents Upload Photos Compose New Letter			View View in Browser	
			1 per page	<input checked="" type="checkbox"/>
Assessment Reports			Thumbnail	Print
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		
1	27/05/19 11:53	Accident Statement	Load HTM	
2	27/05/19 17:52	Addendum Sheet	Load TIFF	
3	27/05/19 17:54	Accident Statement Addm. #1	Load HTM	
			3 per page	<input checked="" type="checkbox"/>
Photos/Images			Thumbnail	Print
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)		
1	27/05/19 11:49	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	27/05/19 11:49	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
14	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
15	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
16	27/05/19 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
17	27/05/19 11:50	Identification Card [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
18	27/05/19 11:50	Identification Card [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/19 12:41	General View	Load JPG	<input checked="" type="checkbox"/>
2	13/06/19 12:41	General View	Load JPG	<input checked="" type="checkbox"/>
3	13/06/19 12:41	General View	Load JPG	<input checked="" type="checkbox"/>
4	13/06/19 12:41	General View	Load JPG	<input checked="" type="checkbox"/>
5	13/06/19 12:41	General View	Load JPG	<input checked="" type="checkbox"/>
6	13/06/19 12:41	General View	Load JPG	<input checked="" type="checkbox"/>
7	13/06/19 12:41	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
Ajax Mars Pte Ltd (Bukit Merah)				
8	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
9	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
10	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
11	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
12	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
13	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
14	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
15	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
16	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
17	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
18	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
19	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
20	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
21	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
22	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
23	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
24	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
25	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
26	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
27	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
28	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
29	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
30	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
31	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
32	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
33	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
34	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
35	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
36	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
37	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
38	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
39	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
40	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
41	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
42	13/06/19 12:41	General View	 Load JPG	<input checked="" type="checkbox"/>
43	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	13/06/19 12:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
55	13/06/19 12:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
56	13/06/19 12:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
57	13/06/19 12:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
58	13/06/19 12:48	Ajax Mars Pte Ltd (Bukit Merah) Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	13/06/19 12:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	13/06/19 12:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
105	13/06/19 12:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
106	13/06/19 12:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
107	13/06/19 12:48	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
108	13/06/19 12:48	Ajax Mars Pte Ltd (Bukit Merah) Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
123	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
124	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
125	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
126	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
127	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
128	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
129	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
130	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
131	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
132	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
133	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
134	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
135	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
136	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
137	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
138	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
139	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
140	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
141	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
142	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
143	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
144	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
145	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
146	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
147	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
148	13/06/19 12:49	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	29/05/19 09:58	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) PRI CONTACT	 Load PDF	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	27/05/19 11:49	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	27/05/19 11:49	Common Statement [Linked Accident Report Documents]	 Load TIFF	

Linked Accident Report Documents

Assessment Reports			View <input type="button" value="View in Browser"/>	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	1 per page	<input checked="" type="checkbox"/>
1	27/05/19 11:53	Accident Statement	<input type="button" value="Thumbnail"/>	<input type="button" value="Print"/>
2	27/05/19 17:52	Addendum Sheet	<input type="button" value="Load HTM"/>	
3	27/05/19 17:54	Accident Statement Addm. #1	<input type="button" value="Load TIFF"/>	
			<input type="button" value="Load HTM"/>	

Photos/Images			3 per page <input type="button" value="View in Browser"/>	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	27/05/19 11:49	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
2	27/05/19 11:49	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
3	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
4	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
5	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
6	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
7	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
8	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
9	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
10	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
11	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
12	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
13	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
14	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
15	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
16	27/05/19 11:50	Accident Photo	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
17	27/05/19 11:50	Identification Card	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
18	27/05/19 11:50	Identification Card	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>

Documentation			1 per page <input type="button" value="View in Browser"/>	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	27/05/19 11:49	Sketch Plan	<input type="button" value="Load JPG"/>	<input checked="" type="checkbox"/>
2	27/05/19 11:49	Common Statement	<input type="button" value="Load TIFF"/>	

Documents Checklist

DOCUMENTS CHECKLIST	
There are no document checklists configured.	
<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19009503/GCD3E2
Date: 20/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SN30313319000

Claimant Vehicle No: SKW3005R

Insured Vehicle No: PA9172H

Date of Loss: 27/05/2019

Nature of Claim: TP

Claim No: SNM19D202387C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW3005R**
Make & Model: BMW 116I, 1.6 F20 (A)
Reg. Date: 26/10/2015 (Man. Year: 2015)
Colour: White
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 37219362B37D15A
Chassis No: WBA1V72070V249830
Odometer: 90556 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No
Footbrake (Serviceable): Yes
Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18
Front Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm
Rear Tyre Size: 225/40Z R18
Rear Left Side: Michelin 6 mm
Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/05/2019
Date Inspected: 29/05/2019 Inspected At:

Lee Leuw Sing Motor (HQ)
10 ANG MO KIO INDUSTRIAL PARK 2A,
#03-10 AMK AUTOPOINT
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 -\$8,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2019)
Parts:	144	BMW 116I 1.6 F20 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW3005R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.