

22/02/2002

ASS. REC. BY:

Surveyor:

REF:

CS/CTI/19009517/7190302

Special Instruction:

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTI

Date/Time: 29/5/1909 9.46am

Estimated Cost:

Bill to:

OD / TP / W/S / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 8376M

Insured:

yp1045J

at Workshop m/s

Weeames Automotive

Tel:

9129 4556

of

249 Alexandra Road

Policy No:

PMCVSN16056819033

Claim No:

SNM19D26216602

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13/05/2019

CA / REV / REP. / REV 24 HRS

1 up

H.O.D. Endorsement:

Date/Time:

11:02am @ 29/5/19

Person Contacted:

Michelle

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction	Estimate	✓
	SLK 8376M - NA / CTI / 19008572 / 24		
	YP1045J - NA / CTI / 19008572 / 24		
21/8/19 @ 2.10pm	Michelle informed that the TP owner convert to claim OD.		
21/8/19	Submit Prel. report.		

Tanaka

REF

CTI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD: ☒ WP / ☐ TP / ☐ RL / ☐ OD / ☐ RL / ☐ VV / ☐ MV / ☐ MV
 To inspect Vehicle No: _____
 at Workshop No: _____
 of _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Date Insured: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: **976k**
 WAC/Accident Report: Consistent? Yes or No
 GVA / PC / Govt: Consistent? Yes or No
 Est. Repairs: **8** days: Yes or No
 Lump Sum: % 3 Val: Yes or No

CA / REV / REP / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: **W / OUT**
Marek

Veh No: **SLK 8376M** or Prop: **20/7 Jan.**
 Type: ☒ Car / ☐ Bus / ☐ Van / ☐ Truck / ☐ Trailer or
 Make: **Renault Megane** or **1461**
 Color: **Blue** Insured / ☐ SGI / ☐ RI / ☐ NA
 Sig Reading: **33991** or Insured / ☐ SGI / ☐ RI / ☐ NA
 Engine: **VFIRFB00856325693**
 C/N: **VFIRFB00856325693**
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ Harder / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Brake: ☒ Harder / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Mod: ☒ Std / ☐ STD A/Rim or
 Tyre Size: **205/50R17**

RS / DUN / EXHIOVA / GY / TS / LZA / ☒ MIP / ☐ OHSU / ☐ PIR / ☐ SUMI /
 TOYO / YOKO or

Front: _____ Rear: _____
 R/Rid: **6** mm R/Rid: **6** mm
 L/Rid: **6** mm L/Rid: **6** mm
 D.O.A: **29/5/90 220pm**
 Survey held at: **Weaver 249 Alexander**

Des. of Damages: ☐ Fit / ☐ Rear / ☐ O/S / ☐ HP / ☐ U/C / ☐ Roodtop or
Fit w/s, u/c
 The U/C / Chassis frame / Body Structure affected due to collision

Vehicle: **942764**

RECEIVED 21 AUG 2019

Date/Time, File Pass 607 ☒ Profit Report

21/8 14:58 ☐ Final Report

Date/Time, File 607

Report Format:

Lump Sum / L.B.L: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Insp (\$) ☐ Weekend (\$)

Survey For:	220
Transportation	
Photo	
Others	
TOTAL	220

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 29 May 2019 9:46 AM
To: Michelle Ong Siew Bee
Cc: assignments
Subject: RE: OUR REF: SNM19D202166-YP1045J - Direct Settlement - YR REF: SLK8376M
DOA 13/05/2019

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Michelle Ong Siew Bee [mailto:michelle.ong@wearnes.com]
Sent: Wednesday, 29 May, 2019 9:40 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D202166-YP1045J - Direct Settlement - YR REF: SLK8376M DOA 13/05/2019

Dear Boon Sen,

Please Arrange for survey immediately.

Best regards,

Michelle Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte. Ltd.
249 Alexandra Road Singapore 159103

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Michelle Ong Siew Bee
Sent: Monday, May 27, 2019 6:58 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D202166-YP1045J - Direct Settlement - YR REF: SLK8376M DOA 13/05/2019
Importance: High

Dear Boon Sen,

Please advise on liability clearance and arrange for survey on urgent basis,

Vehicle is already in our workshop since the accident.

Thanks.

Best regards,

Michelle Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte. Ltd.
249 Alexandra Road Singapore 159103
M (65) 9129 4556 F (65) 6264 7137
www.wearnes.com michelle.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Michelle Ong Siew Bee
Sent: Friday, May 24, 2019 7:47 PM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D202166-YP1045J - Direct Settlement - YR REF: SLK8376M DOA 13/05/2019
Importance: High

Dear All,

We refer to our email dated 16th May 2019.

We have yet to receive any reply from your side. Kindly note that the car is already in the workshop and assign a surveyor to conduct the survey asap.

Please revert on liability clearance on urgent basis.

Thanks.

Best regards,

Michelle Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte. Ltd.
249 Alexandra Road Singapore 159103
M (65) 9129 4556 F (65) 6264 7137
www.wearnes.com michelle.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Michelle Ong Siew Bee
Sent: Friday, May 24, 2019 9:59 AM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D202166-YP1045J - Direct Settlement - YR REF: SLK8376M DOA 13/05/2019

Dear Elaine,

Please revert asap.

Thanks

Get [Outlook for Android](#)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Thursday, May 16, 2019 5:34:11 PM
To: Elaine Cheong; Chee So Chow; Michelle Ong Siew Bee; Alfred Toh
Subject: OUR REF: SNM19D202166-YP1045J - Direct Settlement - YR REF: SLK8376M DOA 13/05/2019

Dear Elaine,

Please conduct PRS-SLK8376M soonest possible.

File with officer in charge- Elaine Cheong – 6389 6530.

Regards
Angie Foo

From: Michelle Ong Siew Bee [<mailto:michelle.ong@wearnes.com>]
Sent: Thursday, 16 May, 2019 8:58 AM
To: Claims Dept of CTI
Subject: Direct Settlement - Our Ref: SLK8376M ; Your Insured YP1045J DOA 13/05/2019
Importance: High

Dear Sirs,

We refer to the above matter.
Attached for Direct Settlement.
Kindly revert asap.

Best regards,

Michelle Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte. Ltd.
249 Alexandra Road Singapore 159103
M (65) 9129 4556 F (65) 6264 7137
www.wearnes.com michelle.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAuto)

From: Michelle Ong Siew Bee <michelle.ong@wearnes.com>
Sent: Wednesday, 21 August 2019 2:10 PM
To: Shiau Chan (LKKAuto)
Subject: RE: TP VEHICLE SLK 8376M (DOA: 13/05/2019)

Importance: High

Dear Shiau Chan,

Customer reverted to OD claim already.

Thanks.

Best regards,

Michelle Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte. Ltd.
249 Alexandra Road Singapore 159103
M (65) 9129 4556 F (65) 6264 7137
www.wearnes.com michelle.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, August 21, 2019 2:08 PM
To: Michelle Ong Siew Bee <michelle.ong@wearnes.com>
Subject: RE: TP VEHICLE SLK 8376M (DOA: 13/05/2019)

Dear Michelle,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Michelle Ong Siew Bee <michelle.ong@wearnes.com>
Sent: Tuesday, 18 June 2019 9:19 AM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: RE: TP VEHICLE SLK 8376M (DOA: 13/05/2019)
Importance: High

4770

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Complete and submit this Form to Allied World's Authorised Reporting Centre ("ARC") for filing.
2. Please report correctly the details of the accident to speed up the claims process.
3. This Form must be completed by the Policyholder and/or the Authorised Driver.
4. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
5. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
6. Any false reporting may be referred to the Traffic Police Department for investigation.

ACCIDENT STATEMENT

Date and Time of Accident

Date: 13/05/2019 Time: 16:33

Exact Location of Accident

BEDOK NORTH AVI 1

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLK 837617

INSURED / POLICYHOLDER (OWN VEHICLE)

Name of Registered Owner (See Insurance Cert.)

CHONG WEI YUAN

Personal Identification - NRIC (Singaporean/PR)

S8929491F

- FIN/Passport Number

- Not Applicable

VEHICLE PARTICULARS (OWN VEHICLE)

Vehicle Make / Model

Manufacturer RENAULT Model MELANE-CI

Type of Vehicle*

☐ Saloon ☐ MPV ☐ CRV ☐ Van ☐ Lorry
☐ Bus ☐ M/cycle ☒ Others, HATCH BACK

Exact Purpose for which vehicle was being used at time of accident

SOCIAL

Are you claiming under your own insurance policy for repair to your vehicle?

☐ Yes ☐ No (If No, Pls select: ☐ Third Party ☐ Reporting)

Vehicle Category*

☒ Private ☐ Commercial ☐ Motorcycle

INSURANCE COMPANY (OWN VEHICLE)

Name of Insurance Company *

LIBERTY INSURANCE

Type of Policy

☐ Comprehensive ☐ Third Party Fire & Theft ☐ TP Only

Fleet Policy

☐ Yes ☐ No

Policy Number

SD19V00552

Motor CI

DRIVER

☒ Same as Insured above

Name of Driver

CHONG WEI YUAN

Personal Identification - NRIC (Singaporean/PR)

S8929491F

- FIN/Passport Number

Date of Birth

01 dd/ 09 mm/ 1989 yy

Driving Date Pass

12 dd/ 01 mm/ 2009 yy

Year of Driving Experience

Year(s)

Month(s)

Occupation

☒ Indoor ☐ Outdoor

Gender

☒ Male ☐ Female

Contact Number / Mobile Phone / Fax No.

97397308

Address of Driver		BIC 317 TAMPINES ST 33	
Email Address		#0956	Postcode (52037)
Was driver an employee of the Insured's Company?		NO EMAIL	
If No, Relationship of the Driver with the Insured		<input type="radio"/> Yes <input checked="" type="radio"/> No	
Vehicle Registration Number of Driver's Own		OWNER	
Vehicle Registration Number of Driver's Own Vehicle (if applicable)		<input type="radio"/> Yes <input type="radio"/> No	
Insurance Company of Driver's Own Vehicle (if applicable)			
GENERAL INFORMATION OF THE ACCIDENT			
Type of Collision (Eg. Chain collision, Head-On collision, Side Swipe, Front to Rear)		Side SWIPE	
Weather Conditions		<input checked="" type="radio"/> Clear <input type="radio"/> Raining <input type="radio"/> Others, _____	
Road Surface		<input checked="" type="radio"/> Dry <input type="radio"/> Wet <input type="radio"/> Others, _____	
OTHER INFORMATION			
Was any foreign vehicle involved in this accident?		<input type="radio"/> Yes <input checked="" type="radio"/> No	
Was any body injured in the accident?		<input type="radio"/> Yes <input checked="" type="radio"/> No	
Was any other vehicle or property damaged?		<input type="radio"/> Yes <input checked="" type="radio"/> No	
Was there any video captured by Car Camera?		<input type="radio"/> Yes <input checked="" type="radio"/> No	
Number of Passengers (Including Driver)		ONE	
DETAILS OF POLICE ACTION			
Was the Accident reported to the Police?		<input type="radio"/> Yes <input checked="" type="radio"/> No (If Yes, please state which Police Station.)	
Police Station Name			
Police Station Address			
Police Station Contact		Tel No. Fax No.	
Was notice of intended Prosecution given?		<input type="radio"/> Yes <input type="radio"/> No (If Yes, against whom?)	
DETAILS OF OTHER VEHICLE / PROPERTY 1			
Vehicle Registration Number		YP 10453	
Vehicle Make/ Model/ Colour		FUSO / WHITE	
Details of Properties			
Name of Driver		KALIVAPERUMAL VANIDHASAN	
Personal Identification - NRIC (Singaporean/PR)		G 8161917X	
- FIN/Passport Number			
Contact Number		9143 0150	
Address			
Name of Insurance Company			
Nature of Damage			
No. of Passenger (Including Driver)		ONE	
(Note - Please use page 6 if you need to add more vehicles)			

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstance of the Accident

- Stationary behind a queue of car due to traffic light condition.
- Front car moved and while I was about to move off, vehicle B (YP10453) suddenly changed lane and collided into my car.

IMPORTANT NOTE

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8929491F



Name

CHONG WEI YUAN

張 瑋 元

Race

CHINESE

Date of birth

01-09-1989

Sex

M

Country of birth

SINGAPORE

S8929491F

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: S8929491F


Name:

CHONG WEI YUAN



Birth Date: 01 Sep 1989

Issue Date: 12 Jan 2009



0016972700

3610562



NRIC No: S8929491F



Date of issue

08-09-2004

APT BLK 317 TAMPINES STREET 33 #09-56
SINGAPORE 520317


NRIC No: S8929491F

Date: 19/03/2019

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg 12 Jan 2009



Licence No: S8929491F

NP 429A

14770

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/05/2019 14:35
Date Of Accident	13/05/2019 16:30
Exact Location Of Accident	BEDOK NORTH AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK8376M
Insured/Policyholder	
Name Of Registered Owner	CHONG WEI YUAN
NRIC No	S8929491F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97397308
Alternative Phone No	OTHERS-97397308

Vehicle Particulars

Manufacturer	RENAULT
Model	MEGANE GT-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD19V00552
Cover Note Number	

Driver

Name of Driver	CHONG WEI YUAN
NRIC No	S8929491F
Date Of Birth	01/09/1989
Occupation	INDOOR
Date Of Driving Pass	12/01/2009
Driving Experience	10 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97397308
Fax Number	
Contact Number	OTHERS-97397308
Email Address	NOEMAIL

Address	BLK 317 TAMPINES STREET 33
	#09-56
Postcode	520317
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP1045J
Vehicle Make/Model/Colour	FUSO WHITE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KARIYAPERUMAL VANIDHASAN
NRIC/Passport Number	G8161917X
Contact Number	91430150
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

VEHICLE CONDITION REPORT FORM / JOB RECORD

Allianz

Worldwide Partners

Date: 13/5/19 Time: 17:45
 Technician Name: NATHAN
 Reg. No: SLK8376M Job No: _____
 Odometer Reading (Customer Vehicle): 33990
 KM Travelled by Assistance Vehicle: _____ (1 way)
 Fault Reported: Accident
 Fault Found: _____
 How was vehicle repaired? Towing

Customer Name: CHONG JEN FUNN
 Customer Telephone: 97377308
 Make/Model: Renault Megan
 Location: Chen Chee St
 Time on Scene: 18:15
 Time Job Completed: _____
 Repaired at Breakdown Scene: Y/N
 VIN No: _____

Hubcaps Y/N

Spare Wheel Y/N

Tools Y/N

Audio System Y/N

Keys + Remote Y/N

Aerial Y/N

Cashcard Y/N

Fuel

E		F
---	--	---

Interior Condition :

Front Seats

Rear Seats

Floor Covering

Headlining




Day/Night

Wet/Dry

Clean/Soiled

Please circle the above as appropriate

Place X on damaged area for scratch and Y for dent



Delivery to Dealership / Date and Time: _____




Vehicle received in the above condition YES/NO

If not stated as above specify difference: _____

Long kee road

CUSTOMER DECLARATION

1. I am entitled to the service requested. In the event of this subsequently not being the case I shall be responsible for the cost of any assistance provided.
2. I accept that any roadside repairs will be of a temporary nature and that advice of a franchised dealer should be sought by me as soon as possible.
3. In the case of forced entry, I confirm that I specifically requested that the operator forcefully enter the vehicle and that all damages occasioned thereby is and shall be my sole responsibility.
4. I accept that any removable items left in the vehicle will not be the responsibility of the emergency service or their agents.

Customer Name & Signature (green copy)		Dealer/Workshop Signature, Name & Stamp (yellow copy)		Operators Signature (white & pink copy)	
--	---	---	--	---	---

SERVICE ESTIMATE

88456 - C00001 SL: SERVICE SALES - PC

Mr CHONG WEI YUAN

Blk 317 Tampines St 33

#09-56

Singapore 520317

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 15/05/2019

WIP No. : 14770

Veh.In/Out:

*Tel.No. : Mobile: 97397308CHONG

Reg.No. : SLK8376M

Reg.date : 31/01/2017

Mileage : 0

Chassis No: VF1RFB00856325693

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr CHONG WEI YUAN

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER,FRT BRACKET,FRT HEADLAMP,FRT LH FENDER,FRT LH DOOR,FRT LH DOOR TRIM,FRT LH WING MIRROR	450 0	4050.00	0		4,050.00	S
800	TO PUTTY SPRAY PAINT ON FRT BONNET,FRT BUMPER,FRT LH FENDER,FRT LH DOOR,REAR LH DOOR,LH ROCKER PANEL,ETC	400 0	2800.00	0		2,800.00	S
802	TO TRANSFER FRONT LH DOOR PART	0	250.00	0		250.00	S
0031	TO REPLACE FRT LH RIM	0	50.00	0		50.00	S
0030	01PC TYRE REPLACE	0	650.00	0		650.00	S
419	COMPUTERISED WHEEL ALIGNMENT	0	280.00	0		280.00	S
280	TO FOCUS HEADLAMP	0	110.00	0		110.00	S
280	TO CHECK WIRING INCLUDE	0	330.00	0		330.00	S
	RESETTING OF ALL ELECTRICAL MODULES						

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 9749549
WP
Resurvey before paint
Tanpin @ Khawtawun
8-9 days
29/5/19 @ 230pm
30/5/19

SERVICE ESTIMATE

88456 - C00001 SL: SERVICE SALES - PC

Mr CHONG WEI YUAN

Blk 317 Tampines St 33

#09-56

Singapore 520317

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 15/05/2019

WIP No. : 14770

Veh.In/Out:

*Tel.No. : Mobile: 97397308CHONG

Reg.No. : SLK8376M

Reg.date. : 31/01/2017

Mileage : 0

Chassis No: VF1RFB00856325693

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr CHONG WEI YUAN

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
R16	TOWING CHARGES		0	250.00	0		250.00	S ✓
	BUMPER FRT M4H GT LI	1.0	EA	699.10			699.10	S de ✓
	FOG LAMP MOULDING M4	1.0	EA	221.90			221.90	S cut ✓
	COLLECTION	1.0	EA	139.90			139.90	S ?
	BUMPER FRT TOP SUPPO	1.0	EA	80.70			80.70	S ?
	BUMPER FRT CENTER SU	1.0	EA	166.30			166.30	S ?
	BUMPER FRT SPOILER H	1.0	EA	193.70			193.70	S x An
	REINFORCEMENT FRT M4	1.0	EA	653.80			653.80	S x An
	HEADLAMP LHF W/XENON	1.0	EA	1285.30			1,285.30	S con ✓
	BULB HEADLAMP R26 DI	1.0	EA	219.00			219.00	S ?
	FOG LAMP LH/RH S3/ M	1.0	EA	185.50			185.50	S ?
	BUMPER SIGN LAMP FRT	1.0	EA	296.80			296.80	S ?
	FENDER FRT LH M4S	1.0	EA	386.40			386.40	S dis ✓
	GRILLA PANEL INNER L	1.0	EA	59.80			59.80	S at ✓
	FENDER BRACKET FRT L	1.0	EA	87.70			87.70	S ?
	FENDER BRACKET FRT L	1.0	EA	169.30			169.30	S ?
	SUPPORT FIX	1.0	EA	139.20			139.20	S ?

SERVICE ESTIMATE

88456 - C00001 SL: SERVICE SALES - PC

Mr CHONG WEI YUAN

Blk 317 Tampines St 33

#09-56

Singapore 520317

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date : 15/05/2019

WIP No. : 14770

Veh.In/Out:

*Tel.No. : Mobile: 97397308CHONG

Reg.No. : SLK8376H

Reg.date : 31/01/2017

Mileage : 0

Chassis No: VF1RFB00856325693

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr CHONG WEI YUAN

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

	FENDER FINISHER LH	1.0 EA	533.00			533.00	S?
	ALLOY RIM 17 " M4 R9	1.0 EA	558.00			558.00	Sat
	TYRE PRESSURE SENSOR	1.0 EA	119.10			119.10	S?
	WHEELARCH LHF	1.0 EA	243.40			243.40	S?
	WING MIRROR COVER TO	1.0 EA	99.20			99.20	Sat
	DOOR FRT LHS M4 RS	1.0 EA	1437.50			1,437.50	Sbt
	MIRROR MLDG LH	1.0 EA	140.10			140.10	S?
	DOOR SEAL LHF	1.0 EA	86.80			86.80	Sr
	DOOR SEAL LOWER LH	1.0 EA	120.90			120.90	Sr
	REAR FENDER LH M4H G	1.0 EA	1674.80			1,674.80	Sx nn
	WINDSCREEN REAR M4H	1.0 EA	578.00			578.00	Sx nn
	WINDSCREEN SEALANT	2.0 EA	112.10			224.20	Sx nn
	PRIMER	1.0 EA	176.60			176.60	Sx nn
	BODY PANEL SEALANT X	1.0 EA	883.20			883.20	Sx nn
	ADHESIVE SEALER FL2	1.0 EA	549.10			549.10	Sx nn

Gross Total. 21,178.30

Net..... 21,178.30

GST @ 7.0% 1,482.48

Total..... 22,660.80

Paid..... 0.00

Please Pay.. 22,660.80

Labour Total	8,770.00
Parts Total	12,408.30
Package Total	0.00

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2019		30 May 2019 16:30 Edit Adj Rpt	S\$11,044.90 Edit Estimates	S\$11,044.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: UMS LOGISTICS , Co. Reg. No.: 53173436									
Main Claimant: CHONG WEI YUAN , ID: S8929491F									
Vehicle Reg. No.: SLK8376M		Date of Loss: 13/05/2019 16:00 - :59 [27 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D202166C02		Policy/Cover Note No.: DMCVSN16056819033							
Vehicle Reg. No. (Insured): YP1045J		Policy No. (Claimant): SD19V00552							
		Excess: S\$0.00							
Repairer: Wearnes Automotive Pte Ltd (Leng Kee) 28 Leng Kee Road, 159105 Leng Kee - Tel: 63782680									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]									
Claimant's Insurer: Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 11/06/2019]									
Driver/Custodian (Insured): KALIYAPERUMAL VANIDHASAN (36 / Male) , NRIC: G8161917X Email:									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK8376M (SNM19D202166C02)
[YP1045J]

TP
CHONG WEI YUAN
May 13 2019 4:00PM
[UMS LOGISTICS]
Wearnes Automotive Pte Ltd

View View in Browser

Upload Documents
Upload Photos
Compose New Letter

1 per page
1

Assessment Reports			Thumbnail	Print
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	1	Load HTM
1	14/05/19 15:18	Accident Statement		

3 per page
3

Photos/Images			Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1	Load JPG
1	21/08/19 14:48	Odometer Reading	1	Load JPG
2	21/08/19 14:48	General View	1	Load JPG
3	21/08/19 14:48	General View	1	Load JPG
4	21/08/19 14:48	General View	1	Load JPG
5	21/08/19 14:48	General View	1	Load JPG
6	21/08/19 14:48	General View	1	Load JPG
7	21/08/19 14:48	General View	1	Load JPG
8	21/08/19 14:48	General View	1	Load JPG
9	21/08/19 14:48	General View	1	Load JPG
10	21/08/19 14:48	General View	1	Load JPG
11	21/08/19 14:48	General View	1	Load JPG
12	21/08/19 14:48	General View	1	Load JPG
13	21/08/19 14:48	General View	1	Load JPG
14	21/08/19 14:48	General View	1	Load JPG
15	21/08/19 14:48	General View	1	Load JPG
16	21/08/19 14:48	General View	1	Load JPG
17	21/08/19 14:48	General View	1	Load JPG
18	21/08/19 14:48	General View	1	Load JPG
19	21/08/19 14:48	General View	1	Load JPG
20	21/08/19 14:48	General View	1	Load JPG
21	21/08/19 14:48	General View	1	Load JPG
22	21/08/19 14:48	General View	1	Load JPG
23	21/08/19 14:48	General View	1	Load JPG
24	21/08/19 14:48	General View	1	Load JPG
25	21/08/19 14:48	General View	1	Load JPG
26	21/08/19 14:48	General View	1	Load JPG
27	21/08/19 14:48	General View	1	Load JPG
28	21/08/19 14:48	General View	1	Load JPG
29	21/08/19 14:48	General View	1	Load JPG
30	21/08/19 14:48	General View	1	Load JPG
31	21/08/19 14:48	General View	1	Load JPG
32	21/08/19 14:48	General View	1	Load JPG
33	21/08/19 14:48	General View	1	Load JPG
34	21/08/19 14:48	General View	1	Load JPG








Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
36	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
37	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
38	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
39	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
40	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
41	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
42	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
43	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
44	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
45	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
46	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
47	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
48	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>
49	21/08/19 14:48	General View	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	03/06/19 09:19	Video - Accident	Load MP4	<input checked="" type="checkbox"/>
2	03/06/19 09:19	Video - Accident	Load MP4	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	14/05/19 15:18	Accident Statement	Load HTM	<input checked="" type="checkbox"/>
2	30/05/19 19:51	Addendum Sheet	Load TIF	<input checked="" type="checkbox"/>
3	30/05/19 19:51	Accident Statement Addm. #1	Load HTM	<input checked="" type="checkbox"/>
4	03/06/19 09:27	Addendum Sheet	Load TIF	<input checked="" type="checkbox"/>
5	03/06/19 09:27	Accident Statement Addm. #2	Load HTM	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	14/05/19 15:16	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	14/05/19 15:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
16	14/05/19 15:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
17	14/05/19 15:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
18	14/05/19 15:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
19	14/05/19 15:17	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Wearnes Automotive Pte Ltd (Alexandra Road)	Thumbnail	Print
1	14/05/19 14:39	Accident Sketch Plan	 Load TIF	
2	14/05/19 14:39	Accident Sketch Plan	 Load TIF	
3	14/05/19 14:39	Accident Sketch Plan	 Load TIF	
4	14/05/19 14:39	Accident Sketch Plan	 Load TIF	
5	14/05/19 14:39	Accident Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19009517/T1QD3E2
Date: 29/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN16056819033

Claimant Vehicle No: SLK8376M

Insured Vehicle No: YP1045J

Date of Loss: 13/05/2019

Nature of Claim: TP

Claim No: SNM19D202166C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK8376M

Make & Model: RENAULT MEGANE GT, 1.5 (A)

Reg. Date: 31/01/2017 (Man. Year: 2016)

Colour: Blue

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: K9KG657D041264

Chassis No: VF1RFB00856325693

Odometer: 33991 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No

Footbrake (Serviceable): Yes

Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/50 R17

Front Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Tyre Size: 205/50 R17

Rear Left Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,058.30	5,474.90	7,583.40	58.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,120.00	5,570.00	2,550.00	31.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,178.30	11,044.90	10,133.40	47.85
+ GST 7.00/7.00% (S\$)	1,482.48	773.14	709.34	47.85
Nett Amount (S\$)	22,660.78	11,818.04	10,842.74	47.85

INSPECTION

Date of Assignment: 30/05/2019

Date Inspected: 29/05/2019

Inspected At:

Wearnes Automotive Pte Ltd
249 ALEXANDRA ROAD
SINGAPORE 159935

Estimated Period of Repair: 8.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 29/8/2019

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$2,520.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Aug 2019)
Parts:	144	RENAULT MEGANE GT 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK8376M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TYRE (80%)	Cut	650.00 FS	*520.00 FS
2	1		*BUMPER FRT M4H GT LI	Deformed	699.10 FS	*699.10 FS
3	1		*FOG LAMP MOULDING M4	Cut	221.90 FS	*221.90 FS
4	1		*COLLECTION	* Check	139.90 FS	*- FS
5	1		*BUMPER FRT TOP SUPPO	* Check	80.70 FS	*- FS
6	1		*BUMPER FRT CENTER SU	* Check	166.30 FS	*- FS
7	1		*BUMPER FRT SPOILER M	Not Necessary	193.70 FS	*- FS
8	1		*REINFORCEMENT FRT M4	Not Necessary	653.80 FS	*- FS
9	1		*HEADLAMP LHF W/XENON	Cracked	1,285.30 FS	*1,285.30 FS
10	1		*BULB HEADLAMP R26 DI	* Check	219.00 FS	*- FS
11	1		*FOG LAMP LH/RH S3/M	* Check	185.50 FS	*- FS
12	1		*BUMPER SIGN LAMP FRT	* Check	296.80 FS	*- FS
13	1		*FENDER FRT LH M4S	Distorted	386.40 FS	*386.40 FS
14	1		*GRILLA PANEL INNER L	Cut	59.80 FS	*59.80 FS
15	1		*FENDER BRACKET FRT L	* Check	87.70 FS	*- FS
16	1		*FENDER BRACKET FRT L	* Check	169.30 FS	*- FS
17	1		*SUPPORT FIX	* Check	139.20 FS	*- FS
18	1		*FENDER FINISHER LH	* Check	533.00 FS	*- FS
19	1		*ALLOY RIM 17 M4 R9	Cut	558.00 FS	*558.00 FS
20	1		*TYRE PRESSURE SENSOR	* Check	119.10 FS	*- FS
21	1		*WHEELARCH LHF	* Check	243.40 FS	*- FS
22	1		*WING MIRROR COVER TO	Cut	99.20 FS	*99.20 FS
23	1		*DOOR FRT LHS M4 RS	Bent	1,437.50 FS	*1,437.50 FS
24	1		*MIRROR MLDG LH	* Check	140.10 FS	*- FS
25	1		*DOOR SEAL LHF	Necessary	86.80 FS	*86.80 FS
26	1		*DOOR SEAL LOWER LH	Necessary	120.90 FS	*120.90 FS
27	1		*REAR FENDER LH M4H G	Not Necessary	1,674.80 FS	*- FS
28	1		*WINDSCREEN REAR M4H	Not Necessary	578.00 FS	*- FS
29	2		*WINDSCREEN SEALANT	Not Necessary	224.20 FS	*- FS
30	1		*PRIMER	Not Necessary	176.60 FS	*- FS
31	1		*BODY PANEL SEALANT X	Not Necessary	883.20 FS	*- FS
32	1		*ADHESIVE SEALER FL2	Not Necessary	549.10 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	13,058.30	5,474.90
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER, FRT BRACKET, FRT HEADLAMP, FRT LH FENDER, FRT LH DOOR, FRT LH DOOR TRIM, FRT LH WING MIRROR, REAR LH DOOR, FRT BONNET, ETC	New	4,050.00	2,700.00
2	TO PUTTY SPRAY PAINT ON FRT BONNET, FRT BUMPER, FRT LH FENDER, FRT LH DOOR, REAR LH DOOR, LH ROCKER PANEL, ETC	New	2,800.00	1,600.00
3	TO TRANSFER FRONT LH DOOR PART	New	250.00	250.00
4	TO REPLACE FRT LH RIM	New	50.00	50.00
5	TO FOCUS HEADLAMP	New	110.00	110.00
6	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	330.00	330.00
7	TOWING CHARGE	New	250.00	250.00
8	COMPUTERISED WHEEL ALIGNMENT	New	280.00	280.00
Gross Labour Cost (S\$)			8,120.00	5,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >