

ASS. REC. BY:

REF: CS/INC19009525/G/dsr

Special Instruction:

Surveyor: Amo Giron

ASSIGNMENT (Office)

From (Person): Cynthia Ang of INC Date/Time: 28/5/19 @ 10:01am

Estimated Cost: _____ Bill to: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CSTo Inspect Vehicle No: FBF 9597E Insured: SKW 1915Cat Workshop m/s F.T. Fasttruck Tel: 63852138of 25 Keki Bukit Rd 4 #01-77 SynergyPolicy No: _____ Claim No: MT/1041518-002

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23/4/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 9:21am 29/5/19 Person Contacted: Freddie Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction	Estimate	✓
	FBF 9597E - X		
	SKW 1915C - X		
	Submit preli advise		
	Vehicle not sent in for repair.		

ASS. REQ. BY:

REF: INC

91544

Pls call before going

ASSIGNMENT

From:

Date:

29/5/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBF 9597E

at Workshop m/s

F.T. Fasttruck

of

25 Kaki Bulcit RD 4 # 01-77

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Freddie G 63852138

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBF 9597E

Yr Regn:

10 Feb 2012

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suzuki GSX1300 c.c. 1340

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading:

97813

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JSLCK111100108559

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ M / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70ZR17

R:

190/55ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

METZELER

Front

Rear

R/Bal.

5 mm

R/Bal.

5 mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

29-05-19

Survey held at

w/s

3pm

Des. of Damages: Fnt / Rear / O/S / ☒ M/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 05 SEP 2019

Date/Time, File Pass to?



: Preli. Report



: Final Report

1) 419 Typst

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

Transportation:

3 + PS 31

Flake

Other:

TOTAL

Report Format:

Lump Sum / LBJ: (\$)

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 28 May 2019 10:01 AM
To: 'assignments@lkkauto.com'
Cc: Thio Tse Kiat; Clarence Richard Anthony; Cynthia Ang
Subject: TP CASES FARMED OUT TO LKK ON 28/05/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Clarence's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Muhammad Airwan	MT/1046202-001	SLL8811T	96 MOTORSPORTS PTE LTD	62/64 KAKI BUKIT AVENUE 6	Royce Phua / 6702 6996		FR8369T	25/05/2019	
2	Charlotte Chew	MT/1046273-001	GY3077U	96 MOTORSPORTS PTE LTD	62/64 KAKI BUKIT AVENUE 6	Jade Lim / 6702 6996		SLJ1413R	26/05/2019	
3	Charlotte Chew	MT/1041518-002	FBE9597E	F T FASTTRACK	25 KAKI BUKIT ROAD 4 #01-77 SYNERGY @ KB	FREDDIE TAN / 67491002		SKW1915C	23/04/2019	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang

Admin Assistant

Motor Insurance

T +65 6430 7900

www.income.com.sg



in with
you

At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/04/2019 12:18
Date Of Accident	23/04/2019 07:50
Exact Location Of Accident	CHIN BEE DR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBF9597E
Insured/Policyholder	
Name Of Registered Owner	WAHEED HUSSAIN BIN UMORTHA
NRIC No	S9029154H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96201417
Alternative Phone No	OFFICE-96201417

Vehicle Particulars

Manufacturer	SUZUKI
Model	GSX1300RL1-1.3

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5071189828-03
Cover Note Number	5071189828-03

Driver

Name of Driver	PUVENDREN S/O RAJARETNAM
NRIC No	S8913412I
Date Of Birth	19/04/1989
Occupation	INDOOR
Date Of Driving Pass	05/05/2008
Driving Experience	10 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90091389
Fax Number	
Contact Number	
Email Address	PUVENKAMU@HOTMAIL.COM

Address YUNG AN RD BLK 357 #03-51

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured FRIEND

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

ON 23/04/19 AT ABOUT 0750AM I WAS RIDING ALONG THE RD OF CHIN BEE DR. I WAS ON MY LANE GOING STRAIGHT TO WORK, OUT OF SUDDEN A CAR NUMBER SKW1915C CUT IN TO MY LANE WYHOUT SIGNALLING AND BANG ME ON MY LEFT HAND SIDE OF MY BIKE. I WAS SHOCKED AND TRIED TO STOP MY BIKE LUCKILY I MANAGED TO STOP WITHOUT FALLING. AFTER THE ACCIDENT I CHECKED MY BIKE IS DAMAGED ON LEFT SIDE COVER AND SOME OTHER.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: UPOUN REQUEST

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKW1915C

Vehicle Make/Model/Colour PEUGEOT DARK GREY

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver DANG ANOM BINTE MHD DALI

NRIC/Passport Number S7721754A

Contact Number 98246574

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: : BOY

GENDER: : MALE

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	9154H
Vehicle No.:	FBF9597E
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2019
Vehicle Make:	SUZUKI
Vehicle Model:	GSX1300RL1
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	X704133511
Chassis No.:	J51CK111100108559
Maximum Power Output:	-
Open Market Value:	\$17,849.00
Original Registration Date:	10 Feb 2012
First Registration Date:	10 Feb 2012
Transfer Count:	2
Actual ARF Paid:	\$2,678.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	09 Feb 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,802.00
COE Rebate Amount:	\$486.00
Total Rebate Amount:	\$486.00

The information contained herein is correct as at 29 May 2019

OK

F.T.FASTTRACK

25 KAKI BUKIT ROAD 4 #01-77 SYNERGY @ KB 417800

TEL: 6749 1002 FAX NO : 6385 2138

RCB REG NO: 50233100C

Email : freddietan2010@gmail.com

NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSE

SINGAPORE 189556

TEL : 6430 7900 FAX : 6338 1504

ATTN : CLAIM DEPT

DATE : 23/5/2019

REF NO : MFTF19052979

VEH NO.: FBF9597E

HAYABUSA

RE : ESTIMATION FOR ACCIDENT INVOLVING VEH NO. FBF9597E /SKW1915C ON 23/04/2019.

ITEM	QTY	DESCRIPTION	PRICE(S\$)
1	1	HANDLE BAR (LH) <i>X cut</i>	110.00 <i>X</i>
2	1	BALANCER (LH) <i>cut</i>	30.00 <i>/</i>
3	1	MIRROR (LH) <i>cut</i>	170.00 <i>105</i>
4	1	CLUTCH LEVER <i>cut</i>	98.00 <i>85</i>
5	1	FRONT COWLING <i>cut</i>	930.00 <i>580</i>
6	1	SIGNAL HOLDER COVER <i>cut</i>	323.00 <i>254</i>
7	1	LOWER COWLING (LH) <i>cut</i>	1,245.00 <i>380</i>
8	1	FRONT FENDER <i>X repair</i>	448.00 <i>X</i>
9	1	TAIL COVER (LH) <i>cut</i>	890.00 <i>460</i>
10	1	VISOR <i>cut</i>	320.00 <i>285</i>

TOTAL PARTS 4,564.00 *2179*

LESS 10% 456.40

TOTAL : 4,107.60 *1961.1*

LABOUR & MISC

LABOUR CHARGE 300.00 *120*

GRAND TOTAL : 4,407.60



AUTHORISED SIGNATURE

2 + Day
30/5/19

Unp Sm repair.

After repair photos.

Emo Qian - 82880282

29/5/19

2081.1

20% 1650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS/INC19009525/Gtd3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date : 05-09-2019

189556

ATTN: CHARLOTTE CHEW

Code : INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	SKW 1915C	Veh. Inspected	FBF 9597E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1041518-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	28/05/2019

2. Vehicle Particulars & Condition

Make & Model	SUZUKI GSX1300	c.c	1340
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JS1CK111100108559	Colour	BLACK
Odometer	97813	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70 ZR17	METZELER	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	190/55 ZR17	METZELER	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/04/2019	Inspection Date	29/05/2019
Survey held at	F T FASTTRACK 25 KAKI BUKIT ROAD 4 #01-77 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIR. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 9597E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR (LH)	NOT NECESSARY	110.00	-
1	BALANCER (LH)	CUT	30.00	30.00
1	MIRROR (LH)	CUT	170.00	105.00
1	CLUTCH LEVER	CUT	98.00	85.00
1	FRONT COWLING	CUT	930.00	580.00
1	SIGNAL HOLDER COVER	CUT	323.00	254.00
1	LOWER COWLING (LH)	CUT	1,245.00	380.00
1	FRONT FENDER	TO REPAIR SEE LABOUR	448.00	-
1	TAIL COVER (LH)	CUT	890.00	460.00
1	VISOR	CUT	320.00	285.00
	LESS 10% DISCOUNT		-456.40	-217.90
			4,107.60	1,961.10
	<u>LABOUR</u>			
	LABOUR CHARGE.INCLUSIVE OF THE REPAIR OF FRONT FENDER.		300.00	120.00
			300.00	120.00
	GRAND TOTAL		4,407.60	2,081.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE)			1,650.00

Report Ref No. CS/INC19009525/Gtd3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.