ASS. REQ. BY: Gd. REF: INC 91544

Pls call Before going.

ASSIGNMENT

From: Date: 29/5/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBF 9597E

at Workshop m/s F. T. Fastruck

of 25 Kaki Bukit Rd 4 # 01-77

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Freddie 63852138

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBF 9597E Yr Regn: 10 Feb 2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Suzuki GSX1300 c.c 1340

Colour Black A/C: Insured / Std / NI / NA

Sp.Reading 97813 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JS1CK11100108559

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70ZR17

R: 190/55ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or METZELER

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	mm	L/Bal.	mm

D.O.A. D.O.I. 29-05-19

Survey held at w/s 3pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

RECEIVED 05 SEP 2019

Date/Time, File Pass to?

1) 4/9 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

Survey Fee:

Transportation: S + PS. SI

Photos

Others

TOTAL