

22/03/2019

ASS. REC. BY:

REF:

CS3/AIG/9009529/Gcd30

Special Instruction:

Surveyor:

Mummen

ASSIGNMENT (Office)

From (Person):

chin tee ying

of

AIG

Date/Time:

24/5/2019 @ 3:23pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBK 86SP

Insured:

SML821E

at Workshop m/s

H.L. Cycle

Tel:

9748 9940

of

1 kaki Bukit Ave 6 # 02-58

Policy No:

1900093138

Claim No:

608398445386

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/05/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Mr. Shawn

Vehicle IN / OUT

Date/Time

Action/Instruction Estimate (X)

FBK 86SP - NBA / AIG / 9008963 / Y

DUA: 21/5/2019

SML821E - NBA / AIG / 9008963 / Y

DUA: 21/5/2019

Dismantle: 31/5/2019

ASS. REQ. BY:

REF: A19

PRS

## ASSIGNMENT

From:

Date:

29/5/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SME 9447A

at Workshop m/s

H.T. Cycle

of

11 kaki Bukit Ave 6 # 02-58

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Shawn @ 9748 9940

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$12K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBK 865P

Yr Regn:

05 Mar 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CB400X

c.c

399

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

40930

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JH2NC 4791 EK 000 200

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70-17

R:

160/60-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ZENEO S

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

D.O.I.

29-05-19

Survey held at

w/s

Des. of Damages: Frt / Rear / N/S / U/C / Rooftop or

O/S  
aml.

22:30pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

COB: 2708

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Week end (\$)

Survey Fee:

180

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

191

Report Format:

DAR

Lump Sum / U/C (\$)

# ...CLAIM SUBFOLDER...(Pending for Survey Report)


PRI

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 May 2019 <a href="#">Edit Reg</a>		29 May 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	HO WHYE HENG, ID: S0106862H								
Main Claimant:	WEE KUM YEW, ID: S1711435B								
Vehicle Reg. No.:	FBK865P	Date of Loss:	21/05/2019 14:00 - :59						
Claim Type:	TP / 6083984453SG	Policy/Cover Note No.:	1900093138 (Comprehensive)						
Vehicle Reg. No. (Insured):	SML821E	Policy No. (Claimant):							
		Excess:							
Repairer:	HI Cycle Pte Ltd (HQ) AUTOBAY @ KAKI BUKIT, 1 KAKI BUKIT AVE 6 #02-58, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Hai-Chuan] Hai-Chuan.Ng@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/06/2019]								
Claimant's Solicitor:	JusEquity Law Corporation - Tel: 65369339								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (30/05/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...**

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 5/24/2019 3:23:57 PM  
Attachments:  tmpB0AC.TIF

---

Hi LKK,

Kindly assist to survey, bike in workshop.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Alfred Ng [mailto:[alfred\\_ng@juseq.com.sg](mailto:alfred_ng@juseq.com.sg)]  
**Sent:** Friday, May 24, 2019 3:11 PM  
**To:** Hor, Yinrul  
**Subject:** [EXTERNAL] ACCIDENT INVOLVING FBK865P AND SML821E ON 21 MAY 2019.

**This message is from an external sender; be cautious with links and attachments.**

Your ref: SML821E  
Our ref: JEQ/190451/0519/HC

Dear Yin Rul,

We refer to your email today.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

1. Absolute Appraisal Services Pte Ltd;
2. Sincere Appraisal Services;
3. Mc Coy Appraiser Pte Ltd;
4. Delta V Consultant
5. Prominent Appraisal Services Pte Ltd;
6. Advance Automotive Consultancy Pte Ltd;
7. Pal's Appraiser Pte Ltd;

8. S K Auto Consultants;
9. Oh Appraisal Services;
10. Kelvin Automotive Appraising Services.

Please be informed that if the above mentioned surveyors is not agreeable by you, our clients' motor vehicle is available for pre-repair inspection at the under-stated workshop:-

**H L CyclePte Ltd**

1 Kaki Bukit Ave 6  
#02-58/60 , Auto Bay @Kaki Bukit  
Singapore 417883  
Contact Person : Mr Shawn Tan  
Mobile: 9748-9940.  
Fax: 6484-44342

\* Further, please remind your appointed surveyor to request for post repair inspection if you wish to do so under NIMA Protocol Appendix C paragraph 2.11

With Regards

Alfred Ng  
Executive  
On behalf of Mr Michael Yap  
M/s JusEquity Law Corporation  
No. 171 Chin Swee Road  
#02-01/02/06 Singapore 169877  
Tel : 6536 9339  
Fax: 6536 5368

**IMPORTANT NOTICE:**

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



# JusEquity Law Corporation

**ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS**

171 Chin Swee Road #02-06, CES Centre, Singapore 169877

Telephone (65) 6536 9339,

Fax : (65) 6536 5368 (Litigation & Conveyancing)

Email : [claims@juseq.com.sg](mailto:claims@juseq.com.sg)

website : [www.juseq.com.sg](http://www.juseq.com.sg)

Our Ref: JEQ/FBK865P/HC/PI (zl)

Your Ref: SML821E

24 May 2019

**HO WHYE HENG**

530 Jurong West Street 52 #09 -- 391

Singapore 640530

By Post Only

**AIG ASIA PACIFIC INSURANCE PTE LTD**

Singapore

By Fax: 6835 7416 Only

Dear Sir

**ACCIDENT INVOLVING FBK865P & SML821E ON 21.05.2019**

We act for the owner of vehicle no. FBK865P.

We hereby notify you of a road traffic accident on **21 May 2019** at about 1430 hrs, at Upper Paya Lebar Road involving our client's vehicle and vehicle registration no. **SML821E** driven by you / your insured at the material time. A copy of our client's accident report is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know **within 2 working days of your receipt of this notice** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Encl.

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	1435B
<b>Vehicle Details</b>	
Vehicle No.:	FBK865P
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	CB400X ABS
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	NC47E5000204
Chassis No.:	JH2NC4791EK000200
Maximum Power Output:	-
Open Market Value:	\$6,794.00
Original Registration Date:	05 Mar 2015
First Registration Date:	05 Mar 2015
Transfer Count:	2
Actual ARF Paid:	\$1,020.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	04 Mar 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$5,800.00
COE Rebate Amount:	\$3,308.00
<b>Total Rebate Amount:</b>	<b>\$3,308.00</b>

The information contained herein is correct as at 19 Jun 2019

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	23/05/2019 18:12
Date Of Accident	21/05/2019 14:30
Exact Location Of Accident	UPPER PAYA LEBAR ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBK865P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WEE KUM YEW
NRIC No	S1711435B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82006339
Alternative Phone No	OFFICE-82006339
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	CB400X
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own Insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
<b>Insurance Company</b>	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	PNNC2019-00001363
Cover Note Number	
<b>Driver</b>	
Name of Driver	VICTOR WEE CHEE SENG
NRIC No	S9325997A
Date Of Birth	23/07/1993
Occupation	INDOOR
Date Of Driving Pass	03/11/2014
Driving Experience	4 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82006339
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address	APT BLK 124 PAYA LEBAR WAY #02-2917
Postcode	381124
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	GEYLANG N.P.C
Police Station Address	ROAD: 132 PAYA LEBAR ROAD , POSTCODE: 409014 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SML821E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	VICTOR WEE CHEE SENG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBK865P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	APT BLK 124 PAYA LEBAR WAY #02-2917
Postcode	381124

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



(A) FBK 865 P

(B) SML 821 E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

20

29/8/19

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/PIH No.:

## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190522/2165

Police Station Of Origin:

1 of 3

Gaylang N.P.C.

Report No. T/20190522/2165

132 Paya Lebar Road SINGAPORE 409014

Tel No: 1800-8486999

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/05/2019 22:07		Vide Report No.: E/20190521/0097		Station Diary No.: 131	
<b>Informant's Particulars</b>					
Name of Informant: VICTOR WEE CHEE SENG			Address: APT BLK 124 PAYA LEBAR WAY #02-2917 SINGAPORE 381124		
ID Type / ID No.: NRIC NO / S9325997A			Contact No.: Home/Office: Mobile: 82006339		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 25	Date of Birth: 23/07/1993	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SELF EMPLOYED			Driving Licence Information: Class: 2B,2A,3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 21/05/2019 14:30	Type of Location: Straight Road
Location: Along Road 1 UPPER PAYA LEBAR ROAD towards Ang Mo Kio				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBK865P	Motorcycle				Seriously Damaged	0
SML821E	Car				Slightly Damaged	1

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190522/2165

Police Station Of Origin:

2 of 3

Geylang-N.P.O.

Report No: T/20190522/2165

132 Paya Lebar Road SINGAPORE 409014

Tel No: 1800-8486999

## CONTINUATION OF REPORT

Rider			
Name	VICTOR WEE CHEE SENG	ID No.	S9325997A
Related Vehicle	FBK865P (Motorcycle)	Contact No.	82006339
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	21/05/2019	Date Discharge	22/05/2019
No. of Days granted Medical Leave	07	Degree of Injury	Serious
Driver			
Name	HO WHYE HENG	ID No.	S0106862H
Related Vehicle	SML821E (Car)	Contact No.	84230808
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 21/05/2019 at about 1430hrs, I was riding along Upper Paya Lebar Road heading towards Ang Mo Kio on the first lane. As I was riding, I noticed that there was a vehicle bearing registration plate SML821E in front of me. I then signaled to the left and had check the second lane was clear and changed on to the second lane. As I have changed in to the second lane, the said vehicle in front of me had just swerve in to my lane and as a result collided in to the right front side of my motorcycle.

Due to the collision, I immediately got thrown off my motorcycle and landed on the ground. The said vehicle also stopped on lane 1 and alighted from his vehicle. As I was in a shock, I did not realized if the said driver had signaled before changing in to my lane. Shortly after both Ambulance and Traffic Police arrived at my scene and attended to me and I was conveyed to Tan Tock Seng Hospital. I was hospitalized for a day and discharged on the 22/05/2019. I suffered abrasions on both my left hand and leg and contusion on the back due to the accident. I am also given 7 days of hospitalization leave starting from 21/05/2019. I am lodging this report as requested by Traffic Police

**SINGAPORE  
POLICE FORCE**

T/20190522/2165

Police Station Of Origin:  
Geylang N.P.C.

3 of 3

Report No. T/20190522/2165

132 Paya Lebar Road SINGAPORE 409014

Tel No: 1800-8486999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
G /  
Sgt 2 AWYONG ZHAO LUN ALOYSIUSSignature Of Interpreter:  
Not applicableOfficer In Charge Of Case:  
TP / GIT /  
SI YEO CHUN JIAN  
Contact No.: 65476213Authentication Stamp  
NP168

SIGNATURE

Signature Of Informant:

Date/Time:  
22/05/2019 22:07

Classification Of Case:

## FOR MOTORCYCLE

## Motorcycle

Vehicle No: **FBK 865P**

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate	Mis	✓	
3001	995065	Front Tyre	Scr	✓	
3002	995095	Front Rim <b>AXLE</b>	Cut	✓	
3003	994872	Front <del>Rim Spoke</del>	Cut	✓	
3004	991771	Front Fender Wheel Guard	CRA	✓	
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy	BT	✓	
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork <del>Bracket</del> <b>oil</b>	NEC	✓	
3011	991182	Front Fork Oil Seal	NEC	✓	
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp	CRA	✓	
3015	992337	Front Headlamp Bracket	BT	✓	
3016	992345	Front Headlamp Fairing <b>Cut</b>	CRA	✓	
3017	992130	Front Windshield	Mis	✓	
3018	992134	Front Wing Mirror	Dis	✓	
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp	PR	✓	
3021	992556	Meter Casing			
3022	992553	Meter Assy			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem	BT	✓	
3027	994427	Steering Cone <b>and bearing</b>	NEC	✓	
3028	992299	Handle Bar	BT	✓	
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip			
3031	995184	Handle Bar Balancer LH			
3032	992300	Handle Bar Balancer RH	Cut	✓	
1252	992179	Fuel Tank			
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever			
3035	992293	Hand Brake Lever	Cut	✓	
3036	991119	Side Fairing	CRA	✓	
3037	994220	Side Fairing Top Garnish			
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield <b>Re</b>	Cut	✓	
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing	Cut	✓	
3043	993378	Rear Fairing			
3044	991121	Fairing Stopper <b>Rear</b>	Cut	✓	
3045	991117	Fairing Lower	Cut	✓	

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator			
1053	992738	Radiator Cowling			
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar	Cut	✓	
3048	990928	Engine Guard			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
3049	991144	Foot Brake	Cut	✓	
3050	991154	Front Foot Rest	Cut	✓	
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest	Cut	✓	
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield	Cut	✓	2
3061	991058	Exhaust Muffler Assy	Cut	✓	
1405	993719	Rear LH Shock Absorber			
1445	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard	Cut	✓	
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
1420	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp			
3074	995246	Rear RH Signal Lamp			
3075	995251	Rear Taillamp			
1137	993626	Rear Number Plate			
3076	994192	Side Box			
3077	992927	Rear Box	Cut	✓	
3078	992928	Rear Box Bracket			
3079	991328	Emblem			
1136	990247	Sticker	NEC	✓	
		<b>Body Frame</b>		<b>Repair</b>	
		<b>5 Days</b>			

No of Items: \_\_\_\_\_

Assessor: \_\_\_\_\_



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

#### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 May 2019 <a href="#">Edit Reg</a>		24 May 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$S\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	HO WHYE HENG, ID: S0106862H								
Main Claimant:	WEE KUM YEW, ID: S1711435B								
Vehicle Reg. No.:	FBK865P	Date of Loss:	21/05/2019 14:00 - :59 [50 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6083984453SG	Policy/Cover Note No.:	1900093138 (Comprehensive)						
Vehicle Reg. No. (Insured):	SML821E	Policy No. (Claimant):							
		Excess:							
Repairer:	HI Cycle Pte Ltd (HQ) AUTOBAY @ KAKI BUKIT, 1 KAKI BUKIT AVE 6 #02-58, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Hai-Chuan] Hai-Chuan.Ng@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/06/2019]								
Claimant's Solicitor:	JusEquity Law Corporation - Tel: 65369339								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
<ul style="list-style-type: none"> <li>AIG_SG (30/05/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBK865P (6083984453SG)

[SML821E]

TP
























































WEE KUM YEW

May 21 2019 2:00PM

[HO WHYE HENG]

HI Cycle Pte Ltd

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<a href="#">Upload Video</a>	<a href="#">Upload Audio</a>	<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>	
<b>Video</b>						1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		
1	04/06/19 09:46	<b>Video - Accident</b> 01 VIDEO FOOTAGE (REAR)		Load MP4	<input type="checkbox"/>		
2	04/06/19 09:48	<b>Video - Accident</b> 01 VIDEO FOOTAGE (FRONT)		Load MP4	<input type="checkbox"/>		
<b>Photos/Images</b>						3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
2	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
3	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
4	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
5	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
6	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
7	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
8	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
9	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
10	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
11	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
12	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
13	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
14	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
15	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
16	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
17	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
18	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
19	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
20	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
21	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
22	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
23	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
24	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
25	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
26	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
27	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
28	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
29	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
30	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
31	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
32	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
33	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
34	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
35	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
36	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
37	19/06/19 12:51	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>		
38	19/06/19 12:51	<b>General View</b>		Load JPG	<input type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
				<input checked="" type="checkbox"/>
39	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
40	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
41	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
42	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
43	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
44	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
45	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
46	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
47	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
48	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
49	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
50	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
51	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
52	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
53	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
54	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
55	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
56	19/06/19 12:51	General View	 Load JPG	<input checked="" type="checkbox"/>
57	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
94	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	19/06/19 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/05/19 10:24	OI GIA report	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19009529/GCD3E2

Date: 19/09/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900093138

Claimant Vehicle No : FBK865P Insured Vehicle No : SML821E

Date of Loss: 21/05/2019 Nature of Claim: TP Claim No: 6083984453SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FBK865P

Make &amp; Model: HONDA CB400X, 399cc

Engine No: NC47E5000204

Reg. Date: 05/03/2015 (Man. Year: 2015)

Chassis No: JH2NC4791EK000200

Colour: Black

Odometer: 40930 km

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 120/70-17

Rear Tyre Size: 160/60-17

Front Left Side: Zeneos 4 mm

Rear Left Side: Zeneos 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 24/05/2019

Date Inspected: 29/05/2019 Inspected At:

HI Cycle Pte Ltd (HQ)  
 AUTOBAY @ KAKI BUKIT, 1 KAKI  
 BUKIT AVE 6 #02-58  
 Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Missing	0.00 F	*- F
2	1		*FRONT TYRE	Scratched	0.00 F	*- F
3	1		*FRONT RIM AXLE	Cut	0.00 F	*- F
4	1		*FRONT RIM	Cut	0.00 F	*- F
5	1		*FRONT FENDER WHEEL GUARD	Cracked	0.00 F	*- F
6	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
7	1		*FRONT FORK OIL	Necessary	0.00 F	*- F
8	1		*FRONT FORK OIL SEAL	Necessary	0.00 F	*- F
9	1		*FRONT HEADLAMP	Cracked	0.00 F	*- F
10	1		*FRONT HEADLAMP BRACKET	Bent	0.00 F	*- F
11	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
12	1		*FRONT WINDSHIELD	Missing	0.00 F	*- F
13	1		*FRONT WING MIRROR	Distorted	0.00 F	*- F
14	1		*FRONT RH SIGNAL LAMP	Broken	0.00 F	*- F
15	1		*STEERING STEM	Bent	0.00 F	*- F
16	1		*STEERING CONE AND BEARING	Necessary	0.00 F	*- F
17	1		*HANDLE BAR	Bent	0.00 F	*- F
18	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
19	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
20	1		*SIDE FAIRING	Cracked	0.00 F	*- F
21	1		*FAIRING SHIELD	Deformed	0.00 F	*- F
22	1		*CENTER FAIRING	Cut	0.00 F	*- F
23	1		*STOPPER REAR	Cut	0.00 F	*- F
24	1		*FAIRING LOWER	Cut	0.00 F	*- F
25	1		*ENGINE CRASH BAR	Cut	0.00 F	*- F
26	1		*FOOT BRAKE	Cut	0.00 F	*- F
27	1		*REAR FOOT REST	Cut	0.00 F	*- F
28	2		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
29	1		*EXHAUST MUFFLER ASSY	Cut	0.00 F	*- F
30	1		*REAR FENDER WHEEL GUARD	Cut	0.00 F	*- F
31	1		*REAR BOX	Cut	0.00 F	*- F
32	1		*STICKER	Necessary	0.00 F	*- F
33	1		*BODY FRAME	Repair	0.00 F	*- F
34	1		*FRONT FOOT REST	Cut	0.00 F	*- F

F=Franchise part.

<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >