

ASS. REC. BY:

REF: S/AWA19009532/RVD3

Special Instruction:

Surveyor: Randy

ASSIGNMENT (Office)

From (Person): Tong Ben

of

AWACDate/Time: 28/5/19 @ 4:32pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 4584T

Insured:

GBJ 7788M

at Workshop m/s

Pegasus

Tel:

6513 7745

of

74 Kien Teck Road

Policy No:

AVCSPSBO096521900

Claim No:

NSV1900255/BT

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24/5/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:54am @ 24/5/19

Person Contacted:

Mee KeyVehicle IN / OUT

Date/Time

Action/Instruction

Estimate

☒SLR 4584T - XGBJ 7788M - X25/6/19Final fig \$4038 confirmed by email (Ref 7620.80, 65%)

Signature: *P. Asim*

REF:

72009

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP DWS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **SLR 4584T**
 at Workshop m/s **PELAGUS**
 of **74, Kinn Park Rd**
 Insured: **NTUC**
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLR 4584T** Yr Regn: **2017 / Aug**
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **MAZDA 3 SEDAN 1.5 AT** c.c. **1496**
 Colour: **WHITE** A/C: Insured / Std / NI / NA
 Sp. Reading: **147700** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **JM6BN22A8H0154411**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **205/60R16**
 R: **16**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **WESTLAK**
 Front: _____ Rear: _____
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. **24/05/19** D.O.I. **29/05/19**
 Survey held at **PELAGUS**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
o/s Frt
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 25 JUN 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) **25/6 - typist**

Report Format : **TP**
 Lump Sum / I.B.I. (\$) **40281/2**

Days Of Repair: **6**

Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

250

Nivitha (LKK Auto)

From: Tang, Ben <Ben.Tang@awac.com> on behalf of Motorsurvey
<Motorsurvey@awac.com>
Sent: Tuesday, 28 May 2019 4:32 PM
To: 'assignments@lkkauto.com'
Cc: 'meekey.pegasusengrg@gmail.com'
Subject: TP Survey assignment for SLR 4584 T DOA: 24/05/2019 Our ref: NSV1900255/BT

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of Mr Marcus Chua as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SLR 4584 T
Insured Vehicle	:	GBJ 7788 M
Policy Number	:	AVCSPSB0096521900
Name of Workshop	:	Pegasus Engineering & Trading Pte Ltd
Contact Number	:	6513 7745
Person to Contact	:	Mee Key
Estimated Cost of repairs	:	\$ NA

Regards,
Claims Division

Copy to Pegasus Engineering & Trading Pte Ltd (Your Ref: SLR 4584 T) via Email / Fax No.

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards
Motor Claims
Claims Group

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 25 June 2019 12:00 PM
To: Vivian Tan; SUR
Subject: RE: Finalise For SLR4584T (DOA 24/05/2019)

Dear Vivian,

Noted with thanks.

Amount confirmed.

Kindly send Final invoice and all supporting documents directly to ALLIED WORLD ASSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vivian Tan <vivian.pegasusengrg@gmail.com>
Sent: Tuesday, 25 June 2019 10:05 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: Finalise For SLR4584T (DOA 24/05/2019)

Good morning Veron,

WITHOUT PREJUDICE

Finalise amount will be \$4,028.00 @ 6 working days, because the RHS Front Door no under SN price should be list price.

Thank you.

Best Regards,

Vivian Ta

On Mon, 24 Jun 2019 at 16:20, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Vivian,

WITHOUT PREJUDICE

Finalise amount \$4240.40 @ 6 working days.

Parts-\$1998 (less 20%)=\$1598.40

SN-\$1062

Labour-\$1580

Total-\$4240.40

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vivian Tan <vivian.pegasusengrg@gmail.com>

Sent: Monday, 24 June 2019 3:37 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: ar_claims@pegasusengrg.com.sg; lionelchua@pegasusengrg.com.sg; lawrencesim@pegasusengrg.com.sg; belindasim@pegasusengrg.com.sg; ngsoontat@vendaengrg.com.sg; josephyeh@vendaengrg.com.sg

Subject: RE: Finalise For SLR4584T (DOA 24/05/2019)

Dear Veron,

Please find the calculation for your confirmation.

Part By Part repair @ \$4,386.40 (before GST) and 6 days repair.

The attached copies of the documents & before paint photos for your attention.

Thank You

-

Best Regards,

Vivian Tan

Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road S628800

Office: 65137748

Fax: 62513161

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/05/2019 12:36
Date Of Accident	24/05/2019 17:45
Exact Location Of Accident	EUNOS LINK TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR4584T
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98550112
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	

Driver

Name of Driver	KAHARUDIN BIN ISHAK
NRIC No	S1251143D
Date Of Birth	26/08/1957
Occupation	OUTDOOR
Date Of Driving Pass	09/02/2010
Driving Experience	9 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98550112
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 765 BEDOK RESERVOIR VIEW #05-257
Postcode	470765
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 24 MAY 2019 AT 1745HRS, I WAS FILTERING OUT FROM AIRPORT RD TOWARDS EUNOS LINK. I WAS TRAVELLING ON THE 3RD LANE. SUDDENLY, OUT OF NOWHERE, A LORRY (VEH B) CUT INTO MY LANE AND COLLIDED INTO MY CAR. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ7788M
Vehicle Make/Model/Colour	TOYOTA / BLUE LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHINESE MALE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	LEFT DOOR DAMAGE
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Scanned with
CamScanner


24/5/19
@ 2145h


Name:
NRIC/FIN No.:

Sketch Plan #2

15/11/19

SKETCH PLAN



Veh A: SCR 4584T
Veh B: GBJ 7788M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/5/19 @ 1745hrs. I was filtering out of from Pupar Rd towards Eunos Link. I was travelling on the 3rd lane. Suddenly out of nowhere a lorry (Veh B) cut into my lane and collided into my car. No one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Scanned with
CamScanner

24/5/19
@ 2145hrs

My car.

Accident Photo





PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE 628800

Officer in Charge : YAP MEE KEY
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax No. :

Quotation No. : QO19/05-1364	Quotation Date : 28/05/2019	Terms : 30 DAYS
Vehicle No. : SLR4584T	Chassis No. : JM6BN22A8H0154411	Third Party Insurer : ALLIED
Model : MAZDA 3	Date of Accident : 24/05/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT BUMPER <i>de</i>	1	1,130.0000	<i>826</i> 1,130.00
2	FRONT BUMPER SIDE RETAINER RHS <i>9. X 800</i>	1	70.0000	70.00
3	FRONT BUMPER CLIP <i>ne</i>	10	4.0000	40.00
4	FRONT BUMPER RIVET <i>ne</i>	4	5.0000	20.00
5	FRONT FENDER RHS <i>bt</i>	1	395.0000	<i>334</i> 395.00
6	FRONT FENDER SPLASH SHIELD <i>X nn</i>	1	148.0000	148.00
7	FRONT FENDER SPLASH SHIELD CLIP <i>ne</i>	10	4.0000	40.00
8	FRONT FENDER LOWER ARM DEFLECTOR RHS <i>X 800</i>	1	75.0000	75.00
9	FRONT FENDER SIDE BRACKET <i>ne</i>	1	85.0000	85.00
10	FRONT FENDER STAND INSULATOR <i>X 800</i>	1	95.0000	95.00
11	FRONT DOOR HINGE <i>X } nn</i>	2	65.0000	130.00
12	FRONT DOOR CHECKER <i>X }</i>	1	78.0000	78.00
13	FRONT DOOR WEATHERSTRIP <i>ne</i>	1	155.0000	155.00
14	FRONT DOOR OUTER CHROME MOUDLING RHS <i>7. X 112</i>	1	135.0000	135.00
15	FRONT SIDE MIRROR RHS <i>Mrs</i>	1	498.0000	498.00 ✓
16	FRONT SIDE MIRROR COVER <i>repair</i>	1	155.0000	155.00
17	FRONT SIDE MIRROR LIGHT <i>X</i>	1	105.0000	105.00
18	FRONT SIDE MIRROR GLASS <i>X</i>	1	103.0000	103.00
19	^S FRONT HOCK ABSORBER RHS <i>X</i>	1	298.0000	298.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : YAP MEE KEY Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO19/05-1364	Quotation Date : 28/05/2019	Terms : 30 DAYS
Vehicle No. : SLR4584T	Chassis No. : JM6BN22A8H0154411	Third Party Insurer : ALLIED
Model : MAZDA 3	Date of Accident : 24/05/2019	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
20	FRONT LOWER ARM RHS X	1	485.0000	485.00
21	FRONT KNUCKLE ARM RHS X	1	398.0000	398.00
22	FRONT STABILIZER LINK RHS X	1	135.0000	135.00
23	FRONT DOOR REGULATOR X	1	158.0000	158.00
24	FRONT DOOR REGULATOR MOTOR X	1	195.0000	195.00
25	FRONT HEADLAMP RHS ? X	1	1,020.0000	1,020.00
26	FRONT FENDER WHEEL HOUSE RHS X	1	550.0000	550.00
27	FRONT A PILLAR PANEL RHS X	1	1,215.0000	1,215.00
28	LESS 20%	1	-1,582.2000	-1,582.20
29	FRONT TYRE RHS X n	1	400.0000	400.00
30	FRONT DOOR RHS Bf	1	1,145.0000	1,145.00
31	FRONT WHEEL HUB CAP RHS X n	1	125.0000	125.00
32	TOWING FEE ? receipt	1	100.0000	100.00
33	TO CONDUCT WHEEL ALIGNMENT	1	100.0000	100.00
34	TO REMOVE & REPLACED TYRE & RIM X n	1	100.0000	100.00
35	TO CONDUCT WHEEL BALANCING X n	1	100.0000	100.00
36	TO REMOVE & REFOCUS FRONT HEADLAMP	1	100.0000	100.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : YAP MEE KEY Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO19/05-1364	Quotation Date : 28/05/2019	Terms : 30 DAYS
Vehicle No. : SLR4584T	Chassis No. : JM6BN22A8H0154411	Third Party Insurer : ALLIED
Model : MAZDA 3		Date of Accident : 24/05/2019
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
37	TO REMOVE & TRANSFER DOOR MECHANISM TO THE NEW DOOR	1	200.0000	60 200.00
38	TO APPLY RUSTPROOFING & TUFFCOATING TREATMEN	1	150.0000	60 150.00
39	TO KNOCKING & PANEL BEATING	1	1,600.0000	600 1,600.00
40	TO PUTTY & SPRAY PAINTING ON THE AFFECTED AREAS	1	1,200.0000	700 1,200.00

[Signature]
30/5/19
Rasul
Hp 90010068

6 days

P/P

29/05/19 @ 1420

Resny before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub Total	11,648.80
GST(7.00%)	815.42
Total (SGD)	12,464.22

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

29/5 Marcus
Lkr
(Grounded)

From :
PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE 628800
Officer in Charge : YAP MEE KEY
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960
Attn :
Tel :
Fax No. :

Quotation No. : QO19/05-1364	Quotation Date : 28/05/2019	Terms : 30 DAYS
Vehicle No. : SLR4584T	Chassis No. : JM6BN22A8H0154411	Third Party Insurer : ALLIED
Model : MAZDA 3		Date of Accident : 24/05/2019
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	FRONT BUMPER <i>de/</i>	1	1,130.0000	1,130.00
2	FRONT BUMPER SIDE RETAINER RHS <i>9. X</i>	1	70.0000	70.00
3	FRONT BUMPER CLIP <i>ne/</i>	10	4.0000	40.00
4	FRONT BUMPER RIVET <i>ne/</i>	4	5.0000	20.00
5	FRONT FENDER RHS <i>bt/</i>	1	395.0000	395.00
6	FRONT FENDER SPLASH SHIELD <i>X</i>	1	148.0000	148.00
7	FRONT FENDER SPLASH SHIELD CLIP <i>ne/</i>	10	4.0000	40.00
8	FRONT FENDER LOWER ARM DEFLECTOR RHS <i>X</i>	1	75.0000	75.00
9	FRONT FENDER SIDE BRACKET <i>ne/</i>	1	85.0000	85.00
10	FRONT FENDER STAND INSULATOR <i>X</i>	1	95.0000	95.00
11	FRONT DOOR HINGE <i>X</i>	2	65.0000	130.00
12	FRONT DOOR CHECKER <i>X</i>	1	78.0000	78.00
13	FRONT DOOR WEATHERSTRIP <i>ne/</i>	1	155.0000	155.00
14	FRONT DOOR OUTER CHROME MOUDLING RHS <i>7. X</i>	1	135.0000	135.00
15	FRONT SIDE MIRROR RHS <i>Mis/</i>	1	498.0000	498.00
16	FRONT SIDE MIRROR COVER <i>repair</i>	1	155.0000	155.00
17	FRONT SIDE MIRROR LIGHT <i>X</i>	1	105.0000	105.00
18	FRONT SIDE MIRROR GLASS <i>X</i>	1	103.0000	103.00
19	FRONT HOCK ABSORBER RHS <i>X</i>	1	298.0000	298.00

2363.00
+ 1145.00
3508.00
701.60
2806.40

C/F 0.00
Page 1 of 3



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800
Officer In Charge : YAP MEE KEY
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn :
Tel :
Fax No. :

Quotation No. : QO19/05-1364	Quotation Date : 28/05/2019	Terms : 30 DAYS
Vehicle No. : SLR4584T	Chassis No. : JM6BN22A8H0154411	Third Party Insurer : ALLIED
Model : MAZDA 3		Date of Accident : 24/05/2019
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
20	FRONT LOWER ARM RHS X	1	485.0000	485.00
21	FRONT KNUCKLE ARM RHS X	1	398.0000	398.00
22	FRONT STABILIZER LINK RHS X	1	135.0000	135.00
23	FRONT DOOR REGULATOR X	1	158.0000	158.00
24	FRONT DOOR REGULATOR MOTOR X	1	195.0000	195.00
25	FRONT HEADLAMP RHS ? X	1	1,020.0000	1,020.00
26	FRONT FENDER WHEEL HOUSE RHS X	1	550.0000	550.00
27	FRONT A PILLAR PANEL RHS X	1	1,215.0000	1,215.00
28	LESS 20%	1	-1,582.2000	-1,582.20
29	FRONT TYRE RHS X	1	400.0000	400.00
30	FRONT DOOR RHS /	1	1,145.0000	1,145.00
31	FRONT WHEEL HUB CAP RHS X	1	125.0000	125.00
32	TOWING FEE ? receipt	1 50	100.0000	100.00
33	TO CONDUCT WHEEL ALIGNMENT	1	100.0000	60 100.00
34	TO REMOVE & REPLACED TYRE & RIM X	1	100.0000	100.00
35	TO CONDUCT WHEEL BALANCING X	1	100.0000	100.00
36	TO REMOVE & REFOCUS FRONT HEADLAMP	1	100.0000	30 100.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE 628800

Officer in Charge : YAP MEE KEY
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax No. :

Quotation No. : QO19/05-1364	Quotation Date : 28/05/2019	Terms : 30 DAYS
Vehicle No. : SLR4584T	Chassis No. : JM6BN22A8H0154411	Third Party Insurer : ALLIED
Del : MAZDA 3		Date of Accident : 24/05/2019
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
37	TO REMOVE & TRANSFER DOOR MECHANISM TO THE NEW DOOR	1	200.0000	60 200.00
38	TO APPLY RUSTPROOFING & TUFFCOATING TREATMEN	1	150.0000	60 150.00
39	TO KNOCKING & PANEL BEATING .	1	1,600.0000	600 1,600.00
40	TO PUTTY & SPRAY PAINTING ON THE AFFECTED AREAS	1	1,200.0000	700 1,200.00

P - \$ 2806.40
E - \$ 1580.00
7 - \$ 4,386.40 P/P

Resul
Hp 90010068
6 days
P/P
29/05/19 @ 1420
Resny before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub Total 11,648.80
GST(7.00%) 815.42
Total (SGD) 12,464.22

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800



ISLAND RECOVERY SERVICES

Blk 3026, Ubi Road 1 #04-146 Singapore 408719

Telephone: 6747 7400

Email: islandrecovery@gmail.com

Facsimile: 6844 7233

Web: www.islandrecovery.com.sg

GST Reg.No: M90370499P

Co. Reg. 53120055L

Cash Sales/ Work Order

NO. 1215784

Date: 24/11/19

HOTLINE: 9182 8211

M/S: Pegasus Pte Ltd

Vehicle No: SIA 4584J

Model: Mazda3

From: Eunus Link

Time Start: 1835 pm

To: 74 Kian Tech Pte Ltd

Time End: 751 pm

Remarks: 9855 0112

Change Tyres / Jump Start

Assessment / Multi Carpark

Using King Dolly

☒ Accident

☐ Crane Up / Winch Out

☐ Dismantle Shaft / Brake

☐ Use Car Carrier

☐ Open Door

☐ Loaded

AMOUNT S\$ 50.00

GST S\$

TOTAL S\$

bizSAFE₃

Important Note:

Issued By

Transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported.

Yuan

Island Recovery Services



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA19009532/R1vd3n2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLE TREE ANSON
SINGAPORE 079914

Date : 28-06-2019



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBJ 7788M	Veh. Inspected	SLR 4584T
Policy No.	AVCSPSB0096521900	Coverage (\$)	0.00
Claim No.	NSV1900255/BT	Excess (\$)	0.00
Assign From	TANG BEN	Assign Date	28/05/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 SEDAN 1.5 AT	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0154411	Colour	WHITE
Odometer	147700	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/05/2019	Inspection Date	29/05/2019
Survey held at	74 KIAN TECK ROAD		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 4584T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	1,130.00	826.00
1	FRONT BUMPER SIDE RETAINER RHS	SERVICEABLE	70.00	-
10	FRONT BUMPER CLIP @\$4.00	NECESSARY	40.00	40.00
4	FRONT BUMPER RIVET @\$5.00	NECESSARY	20.00	20.00
1	FRONT FENDER RHS	BENT	395.00	334.00
1	FRONT FENDER SPLASH SHIELD	NOT NECESSARY	148.00	-
10	FRONT FENDER SPLASH SHIELD CLIP @\$4.00	NECESSARY	40.00	40.00
1	FRONT FENDER LOWER ARM DEFLECTOR RHS	SERVICEABLE	75.00	-
1	FRONT FENDER SIDE BRACKET	NECESSARY	85.00	85.00
1	FRONT FENDER STAND INSULATOR	SERVICEABLE	95.00	-
2	FRONT DOOR HINGE @\$65.00	NOT NECESSARY	130.00	-
1	FRONT DOOR CHECKER	NOT NECESSARY	78.00	-
1	FRONT DOOR WEATHERSTRIP	NECESSARY	155.00	155.00
1	FRONT DOOR OUTER CHROME MOULDING RHS	NOT NECESSARY	135.00	-
1	FRONT SIDE MIRROR RHS	MISSING	498.00	498.00
1	FRONT SIDE MIRROR COVER	TO REPAIR SEE LABOUR	155.00	-
1	FRONT SIDE MIRROR LIGHT	NOT NECESSARY	105.00	-
1	FRONT SIDE MIRROR GLASS	NOT NECESSARY	103.00	-
1	FRONT HOCK ABSORBER RHS	NOT NECESSARY	298.00	-
1	FRONT LOWER ARM RHS	NOT NECESSARY	485.00	-
1	FRONT KNUCKLE ARM RHS	NOT NECESSARY	398.00	-
1	FRONT STABILIZER LINK RHS	NOT NECESSARY	135.00	-
1	FRONT DOOR REGULATOR	NOT NECESSARY	158.00	-
1	FRONT DOOR REGULATOR MOTOR	NOT NECESSARY	195.00	-
1	FRONT HEADLAMP RHS	NOT NECESSARY	1,020.00	-
1	FRONT FENDER WHEEL HOUSE RHS	NOT NECESSARY	550.00	-
1	FRONT A PILLAR PANEL RHS	NOT NECESSARY	1,215.00	-
	LESS 20% DISCOUNT		-1,582.20	-399.60
			6,328.80	1,598.40
1	FRONT DOOR RHS	BENT	1,145.00	1,062.00

Report Ref No. CS/AWA19009532/R1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-	-212.40
			1,145.00	849.60
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE RHS (SN)	NOT NECESSARY	400.00	-
1	FRONT WHEEL HUB CAP RHS (SN)	NOT NECESSARY	125.00	-
			525.00	-
	<u>LABOUR</u>			
	TOWING FEE.		100.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.		100.00	80.00
	TO REMOVE & REPLACED TYRE & RIM.	NOT NECESSARY	100.00	-
	TO CONDUCT WHEEL BALANCING.	NOT NECESSARY	100.00	-
	TO REMOVE & REFOCUS FRONT HEADLAMP.		100.00	30.00
	TO REMOVE & TRANSFER DOOR MECHANISM TO NEW DOOR.		200.00	60.00
	TO APPLY RUSTPROOFING & TUFFCOATING TREATMENT.		150.00	60.00
	TO KNOCKING & PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT SIDE MIRROR COVER.		1,600.00	600.00
	TO PUTTY & SPRAY PAINTING ON THE AFFECTED AREAS.		1,200.00	700.00
			3,650.00	1,580.00
	GRAND TOTAL		11,648.80	4,028.00
	RECOMMENDED COST OF REPAIRS			4,028.00

Report Ref No. CS/AWA19009532/R1vd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.