

22/03/2002

ASS. REC. BY:

REF: (S3/A19 19009543/UC1327)

Special Instruction:

Surveyor: MarcusASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

A19

Date/Time:

28.5.19 12.10 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JSC 5853

Insured:

GY 2247C

at Workshop m/s

Erofa motoTeam Auto

Tel:

96612955

of

KakiBukit Awi6#02-62

Policy No:

1800098848

Claim No:

002688740956

Sum Insured:

Excess:

Make of Veh:

D.O.A

28.5.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

my

H.O.D. Endorsement:

Date/Time:

1.7.191.35 p.m

Person Contacted:

QuikVehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

JSC 5853 - XGY 2247C - XDismantle: 13/6/2019

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD (TP/WS/TP RES/OD RES/EVA/INV/MV)
 To Inspect Vehicle No: JSC5853
 at Workshop m/s Team Auto Team Auto
 of Pro (AMK)
 Insured: 385 Simmy Drive
 Policy No. 01-02 VICONA Inspection Centre
 Claims No. 62581955
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: JSC5853 Yr Regn: Apr 17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha 135LC c.c. 134
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 34885 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: PMYUG0420H0077201
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 70-90-17
 R: 70-90-17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or maxxis
 Front 6 mm Rear 6 mm
 R/Bal. mm R/Bal. mm
 L/Bal. mm L/Bal. mm
 D.O.A. 23/5/18 D.O.I. 12/6/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 L, o/s 3rd.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

N/S Self Ins. PRS
 No resurvey after repair
 Vehicle repair at Team Auto Pro.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: 180

Transportation:

Photos

Others

TOTAL

Report Format: DAR.

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS, SI
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

11

191

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2019 Edit Reg		29 May 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	NA			
Main Claimant:	NA			
Vehicle Reg. No.:	JSC5853	Date of Loss:	23/05/2019 00:00 - :59	
Claim Type:	TP / 0026887409SG	Policy/Cover Note No.:	1800098848	
Vehicle Reg. No. (Insured):	GY2247C	Policy No. (Claimant):		
		Excess:		
Repairer:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62, 417883 Kaki Bukit - Tel:			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/06/2019]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (30/05/2019): Request To Upload TP GIA Report
- AIG_SG (30/05/2019): No OI GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 5/28/2019 12:10:12 PM
Attachments:  tmpD7AD.TIF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

prism@motorworksg.com.sg

2.46pm @ 29/5/2019
person @ Caleb
VNI

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Ref: GY 2247 C

Our Ref: AL.INS.2019.JSC5853

27 May 2019

AIG ASIA PACIFIC INSURANCE PTE. LTD.

BY FAX: 6835 7416 ONLY

78 Shenton Way
Tower 2 #07-16
Singapore 079120

Dear Sirs,

**ACCIDENT INVOLVING JSC 5853 & GY 2247 C ALONG ALEXANDRA ROAD
SLIP ROAD TOWARDS TELOK BLANGAH ROAD ON 23 MAY 2019 AT ABOUT
1515 HOURS**

We act for the owner of vehicle no. JSC 5853.

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop:-


EROFIA MOTOR WORKSHOP

1 Kaki Bukit Avenue 6
#02-62 Autobay @ Kaki Bukit
Singapore 417883
Person In-Charge: Caleb Nee
Mobile Number: 9661 2955

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jerdine / Jiamin at 6422 2187 or email us at jiamin.mak@alt.sg / jerdine.wang@alt.sg for future correspondences.

Yours faithfully


+ ALLISTER LIM

ALLISTER LIM & THRUMURGAN

111 North Bridge Road, #11-04 Peninsula Plaza, Singapore 179098 UEN & GST Reg. No.: 53130941W
Tel: 6438 3303 Fax: 6438 1211 (Not for service of court documents) Email: mail@alt.sg

SAJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

0376301F

No Pendaftaran : JSC5853
 No. ID : 871024527071
 Nama Pemunya Berdaftar : FAIZULLAH BIN ABU HASSAN
 Alamat : NO 8-D JALAN KELEDEK KAMPUNG BENGKAWA
 81100 JOHOR BAHRU JOHOR
 No Chasis/Enjin : PMYUG0420H0077201 / G399E-576321
 Buatan/Nama Model : YAMAHA / YAMAHA 135LC
 Keupayaan Enjin : 134
 Bahan Bakar : PETROL
 Status Asal : PEMASANGAN TEMPATAN
 Kelas Kegunaan : MOTOSIKAL
 Jenis Badan/Tahun Dibuat : MOTOSIKAL / 2017
 Tarikh Pendaftaran : 30/04/2017
 B D H/B G K/BIM : MOTOSIKAL No. Sijil AG 039294
 Syarat Pendaftaran 1 : 29 APR 2018
 Syarat Pendaftaran 2 : JSC5853

Syarat Pendaftaran 3 :
 00Y43130042017 JSC5853 RM100
 0101011 RAHMATIN 23042018 134 SPAA
 ALLAPJ
 WET 002823-17003518
 1951

050



Zurich General Insurance Malaysia Berhad (1999/1945)
Level 23A, Menara 3, No. 3, Jalan Bangsar, KL City, 55200 Kuala Lumpur, Malaysia
Tel: 03-2109 4000 Fax: 03-2109 6888 Call Centre: 1-800-886 422

Code / Kod 18 MY3

CERTIFICATE OF INSURANCE

NOTE: THIS POLICY IS NOT VALID UNLESS THE POLICYHOLDER IS A MEMBER OF THE MOTOR VEHICLES INSURANCE (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 180) REPUBLIC OF SINGAPORE.
THE MOTOR VEHICLES INSURANCE (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 180) REPUBLIC OF SINGAPORE.
THE MOTOR VEHICLES INSURANCE (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 180) REPUBLIC OF SINGAPORE.

SIJIL INSURANS

NOTE: THIS POLICY IS NOT VALID UNLESS THE POLICYHOLDER IS A MEMBER OF THE MOTOR VEHICLES INSURANCE (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 180) REPUBLIC OF SINGAPORE.
THE MOTOR VEHICLES INSURANCE (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 180) REPUBLIC OF SINGAPORE.
THE MOTOR VEHICLES INSURANCE (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 180) REPUBLIC OF SINGAPORE.

Certificate No. (No. Sijil) : 501700062148-02

D14884-000

1. Index Mark and Registration Number of Vehicle : JSC5853
(Tanda Indeks dan Nombor Pendaftaran Kenderaan) : YAMAHA 150 LC
2. Name of Policyholder (Nama Pemegang Polisi) : FAIZULLAH BIN ABU HASSAN
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance of Parliament
4. Date of Expiry of the Insurance (Tarikh Tamat Tempoh) : 29 APR 2019
5. Persons or Classes of Persons entitled to drive* (Orang-orang Kelas Orang yang berhak memandu)* :

30 APR 2019

a) Policyholder b) Any other person who is riding on the Policyholder's order or with his permission. Provided that the person riding is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from riding the Motorcycle.

Limitation on Usage

Use for social, domestic and pleasure purposes and by the Policyholder in person in connection with his business or other lawful purpose. This policy does not cover use for hire or reward, racing, pace-making, reliability trials, speed testing or trial driving or police control (road spectacles) in connection with any issue or otherwise or use for any purpose in connection with the Motor Trade.

* Limitation imposed pursuant to Section 35 of the Road Transport Act 1967 (Malaysia) or Section 2 of the Motor Vehicle Insurance (Third Party Risks and Compensation) Act (Cap 180) Republic of Singapore or Section 3 of the Motor Vehicle Insurance (Third Party Risks) Act (Cap 180) Negara Brunei Darussalam are not to be included in the policy.

* This is not a valid policy for use in connection with the Road Transport Act 1967 (Malaysia) or Section 2 of the Motor Vehicle Insurance (Third Party Risks and Compensation) Act (Cap 180) Republic of Singapore or Section 3 of the Motor Vehicle Insurance (Third Party Risks) Act (Cap 180) Negara Brunei Darussalam.

Insured in pursuance to cover Note No : D14884-19000476
Dibekalkan mengikut Nota Insurans No :

1 / We hereby certify that the Policy to which the Certificate is issued in accordance with the provisions of Part IV of the Road Transport Act 1967 (Malaysia), Motor Vehicles (Third Party Risks & Compensation) Act (Cap 180) Republic of Singapore and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 180) Negara Brunei Darussalam.

For and on behalf of / Untuk dan bagi pihak
ZURICH GENERAL INSURANCE MALAYSIA BERHAD

Saya / Kami dengan ini mengesahkan bahawa Polisi yang dikeluarkan dengan Sijil ini adalah sah mengikut peruntukan - peruntukan Bahagian IV Akta Pengangkutan Jalan 1967 (Malaysia), Akta Insurans Kenderaan (Risiko Pihak Ketiga & Kompensasi) (Cap 180) Republik Singapura dan Akta Insurans Kenderaan (Risiko Pihak Ketiga) (Cap 180) Negara Brunei Darussalam.

David Png



SINGAPORE POLICE FORCE

Police Station Of Origin:
Telok Blangah NPP
51 Telok Blangah Drive #01-116
SINGAPORE 100055
Tel No: 1800-2729999



T/20190523/2131

1 of 3

Report No. T/20190523/2131

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/05/2019 18:01		Vide Report No.: D/20190523/0064		Station Diary No.: 44
Informant's Particulars				
Name of Informant: AWANG RIZALWANDI BIN AWANG SARBINI		Address: JOHOR BAHRU		
ID Type / ID No.: FIN NO / G7499061X		Contact No.: Home/Office: Mobile: 0177099249		
Nationality: MALAYSIAN		Email:		
Sex: Male	Age: 37	Date of Birth: 08/02/1982	Type of Informant: Rider	
Race: Malay		Language: English		Institution / School Name:
Occupation: ROAD CLEANER		Driving Licence Information: Class: 2B,3		Date of Expiry: 08/02/2020

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 23/05/2019 15:15	Type of Location: Bend
Location: Along Road 1 Traveling Toward Road 2 ALEXANDRA ROAD TELOK BLANGAH ROAD Alexandra Road slip road towards Telok Blangah Road Lamp Post Number: 157				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 60 Km/h
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicles Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GY2247C	Van	TOYOTA		Blue	Slightly Damaged	0
JSC5853	Motorcycle	YAMAHA	LC	Blue	Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190523/2131

2 of 3

Police Station Of Origin:
Telok Blangah NPP
51 Telok Blangah Drive #01-116
SINGAPORE 100055
Tel No: 1800-2729999

Report No. T/20190523/2131

CONTINUATION OF REPORT

Driver				
Name	AHMAD KAMAL BIN GHAZALI		ID No.	NIL
Related Vehicle	GY2247C (Van)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: 20/11/2019
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Rider				
Name	AWANG RIZALWANDI BIN AWANG SARBINI		ID No.	G7499061X
Related Vehicle	JSC5853 (Motorcycle)		Contact No.	0177099249
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: 08/02/2020
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	Serious

Brief Details.

On 23/05/2019 at about 1510hrs, I was at the junction along Alexandra Road beside Labrador MRT going towards Telok Blangah Road. When the traffic light turned green for me to turn right, I then ride my motorcycle towards Telok Blangah Road. Upon turning right, one blue colour Van, GY2247C, which was at the slip road along Alexandra Road towards Telok Blangah Road suddenly drove out and hit onto the side of my motorcycle which caused me to fall off my motorcycle.

One motorcyclist then stopped along the road and came to render assistance to me. The motorcyclist then called for police and paramedics which came shortly after to treat my injuries.

I wish to state that I suffered abrasions on both my hands and legs due to the accident and there are scratches on my bike. I also wish to state that I turned right from Alexandra Road into the center lane of the three lane road along Telok Blangah Road and the van turn out to the center lane as well when he came out of the slip road.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Telok Blangah NPP
51 Telok Blangah Drive #01-116
SINGAPORE 100055
Tel No: 1800-2729999



T720190523/2131

3 of 3

Report No. T720190523/2131

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report.

D/

Sgt 3 JEREMY TAN KAY JIN

Signature Of Informant

Signature Of Interpreter

Not applicable

Date/Time:

23/05/2019 18:01

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MOHAMED HUSNUL TAUFIQ BIN MD
YUSOF

Classification Of Case:

Contact No. 65476258

Authentication Stamp

SP-166

Sgt 045

Singapore Police Force

JSC 5853

Yamaha Lc


WORK PERMIT
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore


Employer
YS YONG SERVICES PTE LTD

 Name
AWANG RIZALWANDI BIN AWANG SARBINI

Work Permit No.
4 01512608

Sector
SERVICE

Y260  **K0858170**

 **LESEN MEMANDU**
DRIVING LICENCE  **MALAYSIA**

AWANG RIZALWANDI BIN AWANG SARBINI

Warganegara / Nationality: **MALAYSIA** No. Pemanduan / Identity No.: **820208136059**

Jenis / Class: **B2 D**

Tarikh / Validity: **19/02/2018 - 08/02/2020**

Alamat / Address:
**NO 03-05 PANGLIMA C
PANGSAPURI BUKIT SAUJANA
JALAN YAHYA AWAL
81100 JOHOR BAHRU
JOHOR**

VISIT PASS Immigration Regulations

DD-10-2018

No. 12
AWANG RIZALWANDI BIN AWANG SARGINI

FIN
G7R99081X

Date of Birth
09-02-1982


Sex
M

Nationality
MALAYSIAN

Download SG Work Pass
App to check status



YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED
OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



JPJL6

28069917

- A. Automotive Gasing Capak (Motosikal) BMK tidak melebihi 400 kg
Small Carriage (Motor Cycle) without weight not exceeding 400 kg
- A1. Motosikal Gasing Capak (Motosikal) BMK tidak melebihi 350 kg
Small Carriage (Motor Cycle) without weight not exceeding 350 kg
- B. Motosikal tidak melebihi 500 cc
Motor Cycle not exceeding 500 cc
- B1. Motosikal tidak melebihi 500 cc
Motor Cycle not exceeding 500 cc
- B2. Motosikal tidak melebihi 500 cc
Motor Cycle not exceeding 500 cc
- C. Motosikal Tiga Roda
Three Wheel Motor Cycle
- D. Motosikal BMK tidak melebihi 350 kg
Motor Cycle without weight not exceeding 350 kg
- D1. Motosikal BMK tidak melebihi 350 kg
Motor Cycle without weight not exceeding 350 kg
- E. Motosikal BMK tidak melebihi 7500 kg
Heavy Motor Car without weight exceeding 7500 kg
- E1. Motosikal BMK tidak melebihi 7500 kg
Heavy Motor Car without weight exceeding 7500 kg
- E2. Motosikal BMK tidak melebihi 5000 kg
Heavy Motor Car without weight not exceeding 5000 kg

- F. Traktor/Jenaka Berpasak Ringan (Berantai) BMK tidak melebihi 5000 kg
Tracked/Track Machine Light (Tracked) without weight not exceeding 5000 kg
- G. Traktor/Jenaka Berpasak Ringan (Berantai) BMK tidak melebihi 5000 kg
Tracked/Track Machine Light (Tracked) without weight not exceeding 5000 kg
- H. Traktor/Jenaka Berpasak Berat (Berantai) BMK tidak melebihi 5000 kg
Tracked/Track Machine Heavy (Tracked) without weight not exceeding 5000 kg
- I. Traktor/Jenaka Berpasak Berat (Berantai) BMK tidak melebihi 5000 kg
Tracked/Track Machine Heavy (Tracked) without weight not exceeding 5000 kg
- M. Motosikal Motosikal
Cart Carriage

208027 NV13BF2D



Ketua Pagarah Pengangkutan Jalan

JSC SFR-3

Date

No.

front fender	cut —
front sport rim	RX
front cowling	cut —
front mirror	cut —
front brake lever	scr —
Blanca	scr —
handle bar	Bent —
front black visor	scr —
licence plate sticker	rec —
headlamp	scr —
front fork assy	guy/tw. —
side fairing o/s	cut —
foot brake	cut —
foot rest o/s	to n ✓
foot rest bracket	Bent —
Yamaha sticker	rec ✓
exhaust chrome	scr —
exhaust black cover	scr —
exhaust	Repair X
side board o/s	cut —
1 set side board sticker o/s	rec —

...CLAIM SUBFOLDER...(Pending for Survey Report)






































PRI



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 May 2019 Edit Reg		28 May 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	NA, Co. Reg. No.: -								
Main Claimant:	NA								
Vehicle Reg. No.:	JSC5853	Date of Loss:	23/05/2019 00:00 - :59 [24 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0026887409SG	Policy/Cover Note No.:	1800098848						
Vehicle Reg. No. (Insured):	GY2247C	Policy No. (Claimant):							
		Excess:							
Repairer:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (30/05/2019): Request To Upload TP GIA Report AIG_SG (30/05/2019): No OI GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***JSC5853 (0026887409SG)**
[GY2247C]
TP
NA
May 23 2019 12:00AM
[NA]
Erofia Motor Trading Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
2	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
3	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
4	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
5	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
6	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
7	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
8	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
9	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
10	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
11	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
12	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
13	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
14	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
15	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
16	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
17	29/07/19 08:32	General View														Load JPG	<input checked="" type="checkbox"/>			
18	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
19	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
20	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
21	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
22	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
23	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
24	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
25	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
26	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
27	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
28	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
29	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
30	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
31	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
32	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
33	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
34	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
35	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
36	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			
37	29/07/19 08:33	General View														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
39	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
40	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
41	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
42	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
43	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
44	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
45	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
46	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
47	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
48	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
49	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
50	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
51	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
52	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
53	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
54	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
55	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
56	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
57	29/07/19 08:33	General View	 Load JPG	<input checked="" type="checkbox"/>
58	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	29/07/19 08:33	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/05/19 19:27	EMAIL FROM AIG DD 28052019	 Load PDF	
2	29/05/19 19:27	NOTICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19009543/UCD3E2

Date: 31/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800098848
Claimant Vehicle No : JSC5853 **Insured Vehicle No :** GY2247C
 Date of Loss: 23/05/2019 Nature of Claim: TP Claim No: 0026887409SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **JSC5853**
 Make & Model: YAMAHA LC135, 134cc Engine No: G399E576321
 Reg. Date: 30/04/2017 (Man. Year: 2017) Chassis No: PMYUG0420H0077201
 Colour: Blue Odometer: 34885 km
 Engine Capacity: 134 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 70/90-17 Rear Tyre Size: 80/90-17
 Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/05/2019
 Date Inspected: 12/06/2019 Inspected At: 1 KAKI BUKIT AVE 6 #02-62 S'PORE 417883
 Repairer : TEAM AUTOPRO PTE LTD
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	0.00 F	*- F
2	1		*FRONT SPORT RIM	Repair	0.00 F	*- F
3	1		*FRONT COWLING	Cut	0.00 F	*- F
4	1		*FRONT MIRROR	Cut	0.00 F	*- F
5	1		*FRONT BRAKE LEVER	Scratched	0.00 F	*- F
6	1		*BALANCER	Scratched	0.00 F	*- F
7	1		*HANDLE BAR	Bent	0.00 F	*- F
8	1		*FRONT BLACK VISOR	Scratched	0.00 F	*- F
9	1		*LICENCE PLATE STICKER	Necessary	0.00 F	*- F
10	1		*HEADLAMP	Scratched	0.00 F	*- F
11	1		*FRONT FOLK ASSY	Bent / Twisted	0.00 F	*- F
12	1		*SIDE FAIRING O/S	Cut	0.00 F	*- F
13	1		*FOOT BRAKE	Cut	0.00 F	*- F
14	1		*FOOT REST O/S	Torn	0.00 F	*- F
15	1		*FOOT REST BRACKET	Bent	0.00 F	*- F
16	1		*YAMAHA STICKER	Necessary	0.00 F	*- F
17	1		*EXHAUST CHROME	Scratched	0.00 F	*- F
18	1		*EXHAUST BLACK COVER	Scratched	0.00 F	*- F
19	1		*EXHAUST	Repair	0.00 F	*- F
20	1		*SIDE BOARD O/S	Cut	0.00 F	*- F
21	1		*SET SIDE BOARD STICKER O/S	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >