

(08/11/13)

REF: CC3/TM119009562/KISD302

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD 7213R Yr Regn: 18 Nov 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 357215 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: J70KB3F49035J7723

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 195 / 65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Baronti

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 28/5/19 D.O.I. 29/5/19Survey held at CPGE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHD 7213R - X
	SJR 48852 - X
31/5/19	Cash P/P \$1454 / 26% (\$380.00 Red - 21%)

RECEIVED 31 MAY 2019

Date/Time, File Pass to?

31/05/19

1) Typ: 4

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS (\$ _____)☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____) TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ 1,454/- P/P)Survey Fee: 260

Transportation: _____

Others

TOTAL

11

261

COMFORTDELGRO

Date/Time: 29.05.2019 14:45

Page 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:


JC NO.: 305299343

STOMER	COMFORT TRANSPORTATION PTE LTD	REGN NO.: SHD7213R	MILEAGE
MS	7010045	MAKE: TOYOTA	FUEL
STOMER NO.	383 SIN MING DRIVE	MODEL	E.....1/2.....F
DRESS	Singapore SINGAPORE 575717	DATE/TIME IN	29.05.2019 11:55
(R)	65508755	YR OF MANU	TARGET DATE
(P)		CHASSIS CODE	COMPLETION DATE/TIME:
COUNT CARD NO.		JTDKB3FU903537723	

JOB DESCRIPTION

Accident Date: 28.05.2019
NATURE: 3P 28.05.2019

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHD7213R CHIANG

Vehicle No.: SHD7213R

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/05/2019 14:18
Date Of Accident	28/05/2019 16:25
Exact Location Of Accident	GRANGE ROAD >> NAPIER RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD7213R
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	MUHAMMAD AJMAL
NRIC No	S7263106D
Date Of Birth	11/06/1972
Occupation	OUTDOOR
Date Of Driving Pass	01/09/2003
Driving Experience	15 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98522466
Fax Number	
Contact Number	
EMail Address	NOEMAIL

• Address	126A #22-507 KIM TIAN ROAD
• Postcode	161126
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : FEMALE
Passenger 2	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR4885Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode


Insurance Company Name

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/5/19 at about 1625hrs when I veh A gradually behind other vehicles in front. Veh B collided onto the rear of my stationary vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO REG NO. 19932721R

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:





- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





ComfortDelGro Engineering Pte Ltd (Co Reg No: 199506046W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	28/05/2019
Vehicle Reg. No.:	SHD7213R	Driveable?	YES
Party At Fault:	UNKNOWN		

Make/Model:	TOYOTA PRIUS, 1.5 HYBRID CVT (A)	Vehicle Reg. Date:	18/11/2016
Vehicle Colour:	BLUE	Gen Condition:	EXCELLENT
Engine No:	2ZRR963948	Chassis No:	JTDKB3FU903537723
Odometer:	357215 KM		

Paint Type:

List Item Discount:	25.00 %
Total Loss?	NO
Est. Duration of Repair (day)	3

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	774.90
Miscellaneous Items	10.00
Labour	810.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,594.90
+ GST 7.00% (S\$)	111.64
Nett Amount (S\$)	1,706.54

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 May 2019)**Parts:** 144 TOYOTA PRIUS 1.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD7213R/29/05/2019 15:21**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	*458.60 FL
2	1		*REAR BUMPER UNDER COVER	25.00	0.00	*552.60 FL
3	10		*REAR BUMPER CLIPS	25.00	0.00	*22.00 FL
Sub Total (S\$)						1,033.20
- List Item Discount on L Items (S\$)						258.30
Total Parts (S\$)						774.90

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHD7213R/29/05/2019 15:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (\$\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			<u>200</u>
1	PANEL BEATING	New	400.00
2	SPRAY PAINTING	New	300.00
3	WIRING	New	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00
Gross Labour Cost (\$\$)			810.00

ComfortDelGro Engineering Pte Ltd/SHD7213R/29/05/2019 15:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Kahir Ullah
29/5/11 1508h
2 By 1
P/P
Better Part photo

1. A Repair Order must be received and verified by the Insurance Company prior to starting work.
 2. The Insurance Company must be kept apprised of the progress of the repair.
 3. The Insurance Company must be kept apprised of the cost of the repair.
 4. The Insurance Company must be kept apprised of the time of the repair.
 5. The Insurance Company must be kept apprised of the location of the repair.
 6. The Insurance Company must be kept apprised of the status of the repair.
 7. The Insurance Company must be kept apprised of the completion of the repair.
 8. The Insurance Company must be kept apprised of the satisfaction of the customer.
 9. The Insurance Company must be kept apprised of the payment of the bill.
 10. The Insurance Company must be kept apprised of the return of the vehicle.

Acknowledged by Repairer:
 Signature: _____
 Date: _____

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

(SUPPLEMENTARY)

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
 GIRESH
 Singapore

PARTICULARS OF CLAIM			
Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	MI001708	Date of Loss:	28/05/2019
Vehicle Reg. No.:	SHD7213R	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.5 HYBRID CVT (A)	Vehicle Reg. Date:	18/11/2016
Vehicle Colour:	BLUE	Gen Condition:	EXCELLENT
Engine No:	L15A5208138	Chassis No:	GJ11306656
Odometer:	357215 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Description of Accident/Loss	ACCIDENT INVOLVING SJR4885Z & SHD7213R GRANGE RD TWDS NAPIER RD @ 16.25		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	239.10
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	239.10
+ GST 7.00% (\$\$)	16.74
Nett Amount (\$\$)	255.84
+ Previous Estimates (\$\$)	1,706.54
Claim Total (\$\$)	1,962.38

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS	
Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 31 May 2019)
Parts: 144	TOYOTA PRIUS 1.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHD7213R/31/05/2019 09:02
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER REINFORCEMENT <i>Bent</i>	25.00	0.00	*318.80 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)						318.80
- List Item Discount on L Items (S\$)						79.70
Total Parts (S\$)						239.10

ComfortDelGro Engineering Pte Ltd/SHD7213R/31/05/2019 09:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Our Job Ref No : 305299343
Date : 31/05/19

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156



FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No. : SHD7213R

Fax :

28/05/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- Z The repair job shall bill to: TOKIO SJR4885Z
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | <u>\$1,014.00</u> |
| (b) Labour Charges | <u>\$440.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$1,454.00</u> |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.
- Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156
- We confirm the estimates and finalized amount
- Signature : 
Name : Kahr
Date : 31/5/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 31.05.2019
Time: 09:04:47
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305299343
REGN NO : SHD7213R
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 18.11.2016
DATE/TIME IN : 29.05.2019 11:55
ACCIDENT DATE : 28.05.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95
0002 04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45
0003 04-01-0302-2267-G	PRIVC BUMPER PIECE	10	22.00	25.00	16.50
0004 04-01-0302-2288-G	PRIG4 REINFORCEMENT SUB-A	1	318.80	25.00	239.10

SUB-TOTAL : 1,014.00

JOB NATURE

0000 PB	PANEL BEATING	200.00
0001 SP	SPRAYPAINT CHARGE	200.00
0002 20-22	REMOVE/REFIX REVERSE SENSOR	30.00
0003 L	MERIMEN FEE	10.00

SUB-TOTAL : 440.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 31.05.2019

Time: 09:04:47

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305299343
REGN NO : SHD7213R
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 18.11.2016
DATE/TIME IN : 29.05.2019 11:55
ACCIDENT DATE : 28.05.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,454.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 May 2019 Sendback Est	29 May 2019 15:21 S\$1,594.90	30 May 2019 13:27 Edit Adj Rpt	S\$1,455.00 Edit Estimates	S\$1,455.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	31 May 2019 09:01	31 May 2019 09:02 S\$239.10	31 May 2019 09:02			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	GIRESH , Co. Reg. No.: 53325325W		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHD7213R	Date of Loss:	28/05/2019 16:00 - :59 [30 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1903952	Policy/Cover Note No.:	MI001708 (Comprehensive) Coverage: 25/12/2018 - 24/06/2019
Vehicle Reg. No. (Insured):	SJR4885Z	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 11/06/2019]		
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

































ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHD7213R (M1903952)
[SJR4885Z]
TP
CTPL
May 28 2019 4:00PM
[GIRESH]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)							Thumbnail	Print	
1	29/05/19 15:21	Repairer Estimates							Load HTM		
2	31/05/19 09:02	Repairer Estimates Suppl. #1							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
2	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
3	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
4	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
5	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
6	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
7	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
8	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
9	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
10	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
11	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
12	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
13	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
14	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
15	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
16	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
17	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
18	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
19	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
20	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
21	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
22	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
23	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
24	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
25	31/05/19 09:04	General View							Load JPG	<input checked="" type="checkbox"/>	
26	31/05/19 09:12	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
27	31/05/19 09:12	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
28	31/05/19 09:12	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
29	31/05/19 09:12	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
30	31/05/19 09:12	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)							Thumbnail	Print	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	10/06/19 10:24	ComfortDelGro Engineering Pte Ltd (Loyang)			
		LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee		Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	29/05/19 15:24	E-filed GIA report			
				Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/06/19 16:30	Supplementary			
				Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19009568/K1SD3E2

Date: 11/06/2019

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MI001708

Claimant Vehicle No : SHD7213R

Insured Vehicle No : SJR4885Z

Date of Loss: 28/05/2019

Nature of Claim: TP

Claim No: M1903952

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD7213R

Make & Model: TOYOTA PRIUS, 1.5 HYBRID CVT (A)

Engine No: 2ZRR963948

Reg. Date: 18/11/2016 (Man. Year: 2016)

Chassis No: JTDKB3FU903537723

Colour: Blue

Odometer: 357215 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Excellent	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 7 mm	Rear Left Side:	Davanti 7 mm
Front Right Side:	Davanti 7 mm	Rear Right Side:	Davanti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,014.00	1,014.00	0.00	0.00
Miscellaneous Items	10.00	11.00	-1.00	-10.00
Labour	810.00	430.00	380.00	46.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,834.00	1,455.00	379.00	20.67
+ GST 7.00/7.00% (S\$)	128.38	101.85	26.53	20.67
Nett Amount (S\$)	1,962.38	1,556.85	405.53	20.67

INSPECTION

Date of Assignment: 30/05/2019 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 29/05/2019 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Jun 2019)
Parts: 144	TOYOTA PRIUS 1.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD7213R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	1		*REAR BUMPER UNDER COVER	Cut	552.60 FL	*552.60 FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
Supplementary #1						
4	1		*REAR BUMPER REINFORCEMENT	Bent	318.80 FL	*318.80 FL
					Sub Total (S\$)	1,352.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	338.00
					Total Parts (S\$)	1,014.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	11.00
Sub Total (S\$)			10.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING	New	300.00	200.00
3	WIRING	New	30.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (S\$)			810.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >