

ASS. REC. BY:

REF: CS/FCI 19009573/

Jgd3

Special Instruction:

Survivor: Awlee Jie

ASSIGNMENT (Office)

From (Person): Karent

of

FCIDate/Time: 29.5.2019 5.18 p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect, Vehicle No:

SFF 8866M

Insured:

S4 C1826 S

at Workshop m/s

CYS Automobile

Tel:

6219 2098of 38 Woodland Industrial Park E1 #07-17

Policy No:

Claim No:

D19003489 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25.5.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time:

29.5.19 10.45 a.m

Person Contacted:

Wee Sin

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SFF 8866M - X07/6/19 @ 2:08pm revised to Karen Tan by email.

(08/11/13)

REF

FCI

SS. REC. BY: Hwee Jie

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFF8866M Yr Regn: 25 May 2018Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mitsubishi Eclipse Cross c.c. 1499Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 38559 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMAXTGK1WJZ001785Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/R / STD A/Rim or _____Tyre Size: F: 225/55 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 25/5/19 D.O.I. 4/6/19Survey held at CYS AutoDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orrear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Confirmed P/P \$1899.70 / 3 days of repair. (Red \$391.90, 12%)

RECEIVED 4 JUL 2019

Date/Time, File Pass to?

1) 04/7/19 hwee jie

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____) S + RS, \$ _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

TOTAL

Report Format : TPLump Sum / I.B.I. (\$) 1899.70

Survey Fee:

Transportation:

S + RS, \$ _____

Photos

Others

110

50

50

27

237



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003489MFSH
Our Ref: CS/FCI19009573/Jqd3

Date: 07 June 2019

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SFF 8866M .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/06/2019 at the premises of M/s CYS AUTOMOBILE, and have the following to report:-

Workshop Estimate Amount	: S\$ 2,291.60 .
Revised Estimate Amount	: S\$ 1,899.70 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Yours faithfully

Hwee Jie
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	28-05-2019	Our Ref No. D19003489MFSH
Accident Date	25-05-2019	Claim Type. Third Party
Insured Vehicle	SHC1826S	Third Party Vehicle. SFF8866M
Survey Location	38 WOODLANDS INDUSTRIAL PARK E1 #07-17	
Contact Person.	MS TEE WEE SIN	
Contact No.	62192098/ 0	Fax No. 62192096
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYS AUTOMOBILE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 7 June 2019 2:08 PM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Karen Tan'
Subject: RE: SURVEY ASSESSMENT - D19003489MFSH/1
Attachments: CSFCI19009573Jqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SFF 8866M.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 30 May 2019 10:47 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19003489MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Thursday, 30 May, 2019 10:46 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>; 'SUR' <sur@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19003489MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6003Z
Vehicle Details	
Vehicle No.:	SFF8866M
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	ECLIPSE CROSS 1.5 CVT
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	4B40DL7396
Chassis No.:	JMAXTGK1WJZ001785
Maximum Power Output:	120.0 kW (160 bhp)
Open Market Value:	\$24,418.00
Original Registration Date:	25 May 2018
First Registration Date:	25 May 2018
Transfer Count:	0
Actual ARF Paid:	\$26,186.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 May 2028
PARF Rebate Amount:	\$19,639.00
Intended COE Rebate Details	
COE Expiry Date:	24 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,330.00
COE Rebate Amount:	\$33,456.00
Total Rebate Amount:	\$53,095.00

The information contained herein is correct as at 07 Jun 2019

OK



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

MR TEOW MEI YING
BLK. 783B WOODLANDS RISE
#11-29 SINGAPORE 732783

POLICY NO : TP PARTY CLAIM
YOUR REF : SHC 1826 S (MS FIRST CAPITAL)
OUR REF : TP 6032
VEHICLE NO : SFF 8866 M
MAKE/MODEL : MIT ECLIPSE CROSS 1.5 CVT
DATE OF ACCIDENT : 25.05.19

SURVEY BY

DATE : 29.05.19

1 PC	REAR BUMPER	DEF ✓	S\$	798.00
1 PC	REAR BUMPER SIDE RETAINER RH	nee ✓		47.00
1 PC	REAR BUMPER REFLECTOR RH	nnx ✓		191.00
1 PC	REAR BUMPER LOWER	SCR ✓		399.00
1 PC	REAR FENDER ARCH GARNISH RH	SCR ✓		189.00
				S\$ 1,624.00
LESS 10%				162.40
				S\$ 1,461.60

TO CHECK WIRING FUNCTION

S\$ 30.00 ✓

TO DISMANTLE AND REFIX REVERSE SENSOR

50.00 30

LABOUR CHARGES

350.00 300

TO PUTTY AND SPRAY PAINTING CHARGES

400.00 250

S\$ 2,291.60

SIN DOLLARS: TWO THOUSAND TWO HUNDRED NINETY-ONE AND CENTS SIXTY ONLY

YOUR FAITHFULLY,

[Signature]
7/6/19
Hwee Jia-LKK
4/6/19

CYS AUTOMOBILE SERVICES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p/p 3 days \$1899.70/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19009573/Jqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1826S	Veh. Inspected	SFF 8866M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003489MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	29/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ECLIPSE CROSS	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JMAXTGK1WJZ001785	Colour	SILVER	
Odometer	38559	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	YOKOHAMA	6 mm	
L/H Front Tyre	225/55 R18	YOKOHAMA	6 mm	
R/H Rear Tyre	225/55 R18	YOKOHAMA	6 mm	
L/H Rear Tyre	225/55 R18	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/05/2019	Inspection Date	04/06/2019	
Survey held at	CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFF 8866M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	798.00	798.00
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	47.00	47.00
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	191.00	-
1	REAR BUMPER LOWER	SCRATCHED	399.00	399.00
1	REAR FENDER ARCH GARNISH RH	SCRATCHED	189.00	189.00
	LESS 10% DISCOUNT		-162.40	-143.30
			1,461.60	1,289.70
	<u>LABOUR</u>			
	TO CHECK WIRING FUNCTION.		30.00	30.00
	TO DISMANTLE AND REFIX REVERSE SENSOR.		50.00	30.00
	LABOUR CHARGES.		350.00	300.00
	TO PUTTY AND SPRAY PAINTING CHARGES.		400.00	250.00
			830.00	610.00
	GRAND TOTAL		2,291.60	1,899.70
RECOMMENDED COST OF REPAIRS				1,899.70

Report Ref No. CS/FC19009573/Jqd3n2

ONG HWEЕ JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.