

22/03/2003

ASS. REC. BY:

REF:

CS3/AIG19009601/Ecd301

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time: 30/5/19 @ 11:35am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBM 3578M

Insured:

SKZ 2219G

at Workshop m/s

MS Car Auto

Tel:

63851838

of

8 Kaki Bukit Ave 4 # 01-07

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

28/05/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:07pm @ 30/5/19

Person Contacted:

June

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction

Estimate (X)

FBM 3578M-X

SKZ 2219G - CCG/AIG/BCUP337/Awb3y2

D.O.A. 3/5/2018

Diamondite: 12/6/2019



Steve

REF:

ASSIGNMENT


From \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV \_\_\_\_\_  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop no: \_\_\_\_\_  
at \_\_\_\_\_  
Insured \_\_\_\_\_  
Policy No \_\_\_\_\_  
Claims No \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS \_\_\_\_\_  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT \_\_\_\_\_

Veh No **FBM 3578M** Vi Regn. **10/10/17**  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: **Yamaha Xabre** C.C. **150**  
Colour **Grey** A/C Insured / Std / NI **149**  
Sp. Reading **N/A** T/Ratio: Insured / Std / NI  
Eng/No: \_\_\_\_\_  
Ci/No: **MH3RG 3710 HK026723**  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Locked / Burnt or  
Brake: Inorder / Jammed / Locked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: **110/70-17**  
R: **130/70-17**  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or **IRC**  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. **6** mm R/Bal. **6**  
L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_  
D.O.A. **28/5/19** D.O.I. **30/5/19**  
Survey held at **MCS Garage**  
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
The UIC / Chassis frame / Body Structure affected due to c



Date / Time / Action / Instruction

**MV-7500**  
**Repr. days - 5**

Date/Time, File Pass to? ☐ : Prel. Report  
4) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format: **DAR**

Lump Sum / I.B.B. (\$)

Days Of Repair: **5**  
Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech Invs (\$)  
☐ : Weekend (\$)

Survey Fee: \_\_\_\_\_  
Transportation \_\_\_\_\_

1) S.R. 2)

3) Photos

4) Video

5) \_\_\_\_\_

191

180  
11  
191



**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...**

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 5/30/2019 11:35:20 AM  
Attachments:  FBM3578M vs SKZ2219G.PDF

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



## CATHERINE LIM LLC

林 林 ADVOCATES & SOLICITORS  
翠 NOTARY PUBLIC - 公证官  
玲 COMMISSIONER FOR OATHS - 宣誓官  
律  
師 CATHERINE C.LIM  
館 DIRECTOR  
LL.B (HONS) SINGAPORE - 法律系-律師  
M.B.A. (BUSINESS LAW) - 商业系-碩士

20 Havelock Road #03-01  
Central Square Singapore 059765  
UEN No. 201310922K

Tel: (65) 6438 5500  
Fax: (65) 6438 0111  
www.catherinelimllc.com  
Email: info@catherinelimllc.com  
CATHERINE LIM LLC is a law corporation  
with limited liability

Your Ref: SKZ 2219G  
Our Ref: CL/190551/T/MSS.sg

29 May 2019

AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
78 Shenton Way  
#07-16  
Singapore 079120  
Attn: Motor Claims Department

via fax: 6415 3727 & By Hand

Wee Jiok Lin  
3 Paya Lebar Crescent  
#04-21  
Singapore 534239

### CERTIFICATE OF POSTING

(Please be informed that all supporting documents  
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO  
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING FBM 3578M / SKZ 2219G ON 28.05.2019 ALONG YISHUN AVE 3**

We are instructed by ROSLAN BIN MOHAMAD to notify you of a road traffic accident involving our client's vehicle No. FBM 3578M vehicle No. SKZ 2219G driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.


As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

MS Car Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-07  
Premier @ Kaki Bukit  
Singapore 415875  
Telephone: 6385-1838 Fax: 6386-1838

Yours faithfully



cc: clients









♥ 6 Chat Make Offer

3 days ago by hengahmok\_796  
(/hengahmok\_796)

557,888

6 Likes

Use

In Class 28 (/categories/class-2b-1595)

Revised 7-3-2017

Coe still 6-3-2027

Coe price 6801

Or call my hp 91080563 Or

Male

**Yamaha**

Time

Scooter

Insurance

**Insurance**  
Insure this vehicle with AXA.  
Premiums start from \$1206.

BUY AXA  
INSURANCE  
NOW

### Getting This

• **Meet-up**


Blk 346 Ubi Avenue 1

(<https://www.google.com/maps/place>

 **Mailing & Delivery**

### Meet The Seller



hengahmok\_796  
(/hengahmok\_796/  
joined 2 years ago  
Verified 

### Reviews

No ratings yet...

**YOU MAY ALSO LIKE**



Yamaha spark  
\$12.600  
Coe 2021 sept 21 / ex...  
Used  
[/p/yamaha-spark-230931308/?ref=product&ref\\_raric=xabre-ff110-2422367/m%20%3fref](#)

Yamaha FZ 16 "a...  
\$53,600  
2nd owner YAMAHA  
Used  
Up/yamaha fz-16-  
telling-asap-nege-  
230111016/?  
fruthejamauch...  
satre-16150-  
D...  
107

[illegible]

**Sniper150 Yamaha**  
\$58,000  
18000 Sniper150 (Ref.  
Used  
Yts/sniper150-yamaha-  
agent-warranty-1-year  
228183788/7  
direct-to-japan-usa/usa/yam  
sniper-the150-

Yamaha 125z  
\$60  
125z Cw till marsh/a  
Used  
Y/yamaha-125z-  
230359927/7  
Follow the Green and Yellow  
Yamaha-125z-  
230359927/7

**YAMAHA EXCITE**  
**\$58,181**  
**PRICE DROP | READY**  
 New  
 Vin/yamaha-exciter-  
 230918347/7  
 (Interest) Free finance in 60 days | 12.99%  
 yamaha-ifs110-



BN Kawasaki W1...  
\$59,577  
Don't miss out! Premi...  
Name  
(/p/bn-kawasaki-w175-  
cafe-racer-bike-  
Z31246007/?  
ref=product&ref\_rank=  
vabre-ffc150-  
Z31236724%25%26ref=

**Yamaha Sniper**  
\$16,000  
Coe TM 17-12-2025 p.  
Used  
V/p/yamaha-sniper-  
291272230/7  
for the [unclear] [unclear] [unclear]  
value of \$150 -  
[unclear] [unclear] [unclear] [unclear]

**Fz 16**  
\$53,600  
Refer to best listings  
used  
[www.ford.com](http://www.ford.com)

Yamaha FZ16  
\$55,500  
NIKE IS STILL IN GOOD  
Used  
V/y/yamaha-fz16-  
2306052207  
National Ave (between 4th/5th) Seattle  
yamaha-fz16-  
2306052207

**YAMAHA SNIPER**  
\$51,500  
Selling my sniper. Up  
Used  
Up/yamaha-sniper-  
29151857L/?  
sniper-rx150-  
30

**RXK**  
**\$57,000**  
Reason for Selling - No  
Use  
Vps/nk-2110R106/  
http://www.kia.com/kia/usa/engines/rxk.html



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	30/05/2019 14:42
Date Of Accident	28/05/2019 16:30
Exact Location Of Accident	ALONG YISHUN AVE 3
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBM3578M
Insured/Policyholder	
Name Of Registered Owner	ROSLAN BIN MOHAMAD
NRIC No	S1769605Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93293306
Alternative Phone No	OFFICE-93293306
Vehicle Particulars	
Manufacturer	YAMAHA
Model	TFX150
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	AN3168452
Cover Note Number	
Driver	
Name of Driver	ROSLAN BIN MOHAMAD
NRIC No	S1769605Z
Date Of Birth	31/12/1966
Occupation	INDOOR
Date Of Driving Pass	17/04/1989
Driving Experience	30 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93293306
Fax Number	
Contact Number	OFFICE-93293306
Email Address	NOEMAIL



Address	APT BLK 773 YISHUN AVE 3 #03-159
Postcode	760773
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	<b>ROAD:</b> 32 YISHUN ST 81 , <b>POSTCODE:</b> 768456 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-8522999 - <b>FAX NO:</b> 68522239
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ2219G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	ROSLAN BIN MOHAMAD
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBM3578M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	APT BLK 773 YISHUN AVE 3 #03-159
Postcode	760773



SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:







## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190528/2216

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

1 of 3

Report No. T/20190528/2216

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/05/2019 23:04		Vide Report No.:		Station Diary No.: 111	
<b>Informant's Particulars</b>					
Name of Informant: ROSLAN BIN MOHAMAD			Address: APT BLK 773 YISHUN AVENUE 3 #03-159 SINGAPORE 760773		
ID Type / ID No.: NRIC NO / S1769605Z			Contact No.: Home/Office: Mobile: 93293306		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 52	Date of Birth: 31/12/1966	Type of Informant: Rider		
Race: Javanese			Language: English		Institution / School Name:
Occupation: CLEANER			Driving Licence Information: Class: 2B Date of Expiry:		

## General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 28/05/2019 16:30	Type of Location: Straight Road
Location: Along Road 1 YISHUN AVENUE 3				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM3578M	Motorcycle	YAMAHA	XABRE TFX150	Grey	Slightly Damaged	0
SKZ2219G	Car	MAZDA		Red	Slightly Damaged	0

## Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBM3578M	AXA INSURANCE SINGAPORE PTE LTD	P2014683	11/10/2018	10/10/2019





**SINGAPORE  
POLICE FORCE**



T/20190528/2216

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

2 of 3

Report No. T/20190528/2216

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	RRoslan Bin Mohamad	ID No.	S1769605Z
Related Vehicle	FBM3578M (Motorcycle)	Contact No.	93293306
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	28/05/2019	Date Discharge	28/05/2019
No. of Days granted Medical Leave	05	Degree of Injury	NIL
<b>Driver</b>			
Name	Seet Zheng Yeung	ID No.	S9648802E
Related Vehicle	SKZ2219G (Car)	Contact No.	93898124
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 28/05/2019 at 1630hrs, I was riding my grey Yamaha MT15 motorcycle bearing registration plate number: FBM3578M on the left lane of a two lane road along Yishun Ave 3. While I was making a right turn to the car park of Yishun Swimming complex, a red Mazda car bearing registration plate number: SKZ2219G hit me from the rear.

Due to the strong impact, I fell off from my motorcycle and landed on the road. I was conscious and both the driver and I managed to exchange our particulars at the accident scene. The car driver is namely Mr Seet Zheng Yeung bearing Nric: S9648802E Contact Number: 93898124. The traffic police and ambulance came to scene and the Paramedics conveyed me to Khoo Teck Puat hospital.

I sustained abrasions on both my hand and lower back and the doctor gave me 5 days of medical leave.





**SINGAPORE  
POLICE FORCE**



T/20190528/2216

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

3 of 3



Report No. T/20190528/2216

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Staff Sgt MOHAMMAD FAZLEE BIN ZAKARIA	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 28/05/2019 23:04
Officer In Charge Of Case: TP / GIT / Sgt 2 HO JIEKANG, IVAN Contact No.: 65476170	Classification Of Case: 
Authentication Stamp NP168	



# FOR MOTORCYCLE

Vehicle No: **FBM 3578M**

## Motorcycle

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate			
3001	995065	Front Tyre			
3002	995095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard			
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp			
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing			
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror	BR	✓	
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp			
3021	992556	Meter Casing			
3022	992553	Meter Assy			
3023	991019	ERP Bracket			
3024	991020	ERP Unit			
3025	992446	Ignition Switch			
3026	992442	Ignition Key Assy			
3027	990706	Cowling Stay			
3028	994470	Steering Stem			
3029	994427	Steering Cone	MEC	✓	
3030	992299	Handle Bar	BT	✓	
3031	992312	Handle Bar Switch			
3032	992310	Handle Bar Grip			
3033	995184	Handle Bar Balancer LH			
3034	992300	Handle Bar Balancer RH	CUT	✓	
3035	992179	Fuel Tank			
3036	990438	Brake Reservoir			
3037	990621	Clutch Lever			
3038	992293	Hand Brake Lever	BT	✓	
3039	991119	Side Fairing			
3040	994220	Side Fairing Top Garnish			
3041	994219	Side Fairing Inner Garnish			
3042	991118	Fairing Shield			
3043	992047	Front Top Fairing Inner Garnish			
3044	991123	Fairing Top Garnish			
3045	990538	Center Fairing			
3046	993378	Rear Fairing			
3047	991121	Fairing Stopper			
3048	991117	Fairing Lower (Rear)	CUT	✓	

NAC	INC	Item	CON	AC	Qty
3049	995074	Radiator			
3050	992738	Radiator Cowling			
3051	994146	Seat Assy			
3052	990915	Engine Crash Bar			
3053	990928	Engine Guard			
3054	990219	Battery			
3055	990224	Battery Cover			
3056	990223	Battery Bracket			
3057	991144	Foot Brake			
3058	991154	Front Foot Rest	BT	✓	
3059	991779	Front Foot Rest Bracket			
3060	994269	Side Stand			
3061	992549	Main Stand			
3062	990615	Clutch Engine Cover			
3063	992478	Kick Starter Rubber			
3064	992477	Kick Starter Lever			
3065	991145	Foot Gear Shifter			
3066	993500	Rear Foot Rest	CUT	✓	
3067	993501	Rear Foot Rest Bracket	BT	✓	
3068	992581	Exhaust Muffler Heat Shield	CUT	✓	
3069	991058	Exhaust Muffler Assy	BT	✓	
3070	993719	Rear LH Shock Absorber			
3071	993720	Rear RH Shock Absorber			
3072	995065	Rear Tyre	CUT	✓	
3073	991200	Rear Rim	CUT	✓	
3074	994872	Rear Tyre Rim Spoke			
3075	993474	Rear Fender Wheel Guard	CUT	✓	
3076	993443	Rear Fender Mudflap			
3077	992940	Rear Brake Disc			
3078	992936	Rear Brake Caliper			
3079	995236	Rear Spocket			
3080	990585	Chain			
3081	990580	Chain Guard			
3082	994530	Swing Arm	BT	✓	
3083	993819	Rear Sub frame			
3084	995245	Rear LH Signal Lamp	BR	✓	
3085	995246	Rear RH Signal Lamp	BR	✓	
3086	995251	Rear Taillamp			
3087	993626	Rear Number Plate	BT	✓	
3088	994192	Side Box			
3089	992927	Rear Box	BR	✓	
3090	992928	Rear Box Bracket	BT	✓	
3091	991328	Emblem			
3092	990247	Sticker			
3093		Reflector (Rear)	BR	✓	

No of Items:

Assessor:

*[Signature]*  
 3/15/19



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI




































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jun 2019 <a href="#">Edit Reg</a>		30 May 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>WEE JIOK LIN</b> , ID: S1098354A, Tel: +6599999999								
Main Claimant:	<b>ROZLAN BIN MOHAMAD</b> , ID: S1769605Z								
Vehicle Reg. No.:	<b>FBM3578M</b>	Date of Loss:	28/05/2019 00:00 - :59 [19 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 4837869971SG</b>	Policy/Cover Note No.:	2100498390 (Comprehensive) Coverage: 14/01/2019 - 13/01/2020						
Vehicle Reg. No. (Insured):	<b>SKZ2219G</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Ms Car Auto Pte Ltd (HQ)</b> 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Lee, Ming-Yao</b> ] MingYao.Lee@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... [Final Rpt due 11/06/2019]								
Claimant's Solicitor:	<b>CATHERINE LIM LLC</b> - Tel: 6438 5500								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (31/05/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





















































## Claim Documents





































\*FBM3578M (4837869971SG)  
[SKZ2219G]  
TP  
ROZLAN BIN MOHAMAD  
May 28 2019 12:00AM  
[WEE JIOK LIN]  
Ms Car Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser			View
Photos/Images															3 per page			▼	☑		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print				
1	30/05/19 19:26	General View														Load JPG	☑				
2	30/05/19 19:26	General View														Load JPG	☑				
3	30/05/19 19:26	General View														Load JPG	☑				
4	30/05/19 19:26	General View														Load JPG	☑				
5	30/05/19 19:26	General View														Load JPG	☑				
6	30/05/19 19:26	General View														Load JPG	☑				
7	30/05/19 19:26	General View														Load JPG	☑				
8	30/05/19 19:26	General View														Load JPG	☑				
9	30/05/19 19:26	General View														Load JPG	☑				
10	30/05/19 19:26	General View														Load JPG	☑				
11	30/05/19 19:26	General View														Load JPG	☑				
12	30/05/19 19:26	General View														Load JPG	☑				
13	30/05/19 19:26	General View														Load JPG	☑				
14	30/05/19 19:26	General View														Load JPG	☑				
15	30/05/19 19:26	General View														Load JPG	☑				
16	30/05/19 19:26	General View														Load JPG	☑				
17	30/05/19 19:26	General View														Load JPG	☑				
18	30/05/19 19:26	General View														Load JPG	☑				
19	30/05/19 19:26	General View														Load JPG	☑				
20	30/05/19 19:26	General View														Load JPG	☑				
21	30/05/19 19:26	General View														Load JPG	☑				
22	30/05/19 19:26	General View														Load JPG	☑				
23	30/05/19 19:26	General View														Load JPG	☑				
24	30/05/19 19:26	General View														Load JPG	☑				
25	30/05/19 19:26	General View														Load JPG	☑				
26	30/05/19 19:26	General View														Load JPG	☑				
27	30/05/19 19:26	General View														Load JPG	☑				
28	30/05/19 19:26	General View														Load JPG	☑				
29	30/05/19 19:26	General View														Load JPG	☑				
30	30/05/19 19:26	General View														Load JPG	☑				
31	30/05/19 19:26	General View														Load JPG	☑				
32	30/05/19 19:26	General View														Load JPG	☑				
33	30/05/19 19:26	General View														Load JPG	☑				
34	30/05/19 19:26	General View														Load JPG	☑				
35	30/05/19 19:26	General View														Load JPG	☑				
36	30/05/19 19:26	General View														Load JPG	☑				
37	30/05/19 19:26	General View														Load JPG	☑				



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	30/05/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
39	30/05/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
40	30/05/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
41	30/05/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
42	30/05/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
43	30/05/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
44	30/05/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
45	30/05/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
46	30/05/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
47	30/05/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
48	30/05/19 19:26	General View	 Load JPG	<input checked="" type="checkbox"/>
49	30/05/19 19:26	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
50	30/05/19 19:26	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
51	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	14/06/19 09:42	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	31/05/19 09:26	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				



---



# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19009601/ECD3E2

Date: 24/06/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100498390  
**Claimant Vehicle No :** FBM3578M **Insured Vehicle No :** SKZ2219G  
 Date of Loss: 28/05/2019 Nature of Claim: TP Claim No: 4837869971SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBM3578M**  
 Make & Model: YAMAHA XABRE, 150cc TFX150 Engine No: G3G8E0035925  
 Reg. Date: 10/10/2017 (Man. Year: 2017) Chassis No: MH3RG3710HK026723  
 Colour: Grey Odometer: 0 km  
 Engine Capacity: 150 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 110/70-17 Rear Tyre Size: 130/70-17  
 Front Left Side: IRC 6 mm Rear Left Side: IRC 6 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 30/05/2019  
 Date Inspected: 30/05/2019 Inspected At: Ms Car Auto Pte Ltd (HQ)  
 8 KAKI BUKIT AVE 4 #01-07 PREMIER @  
 KAKI BUKIT  
 Singapore 415875  
 Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WING MIRROR	Broken	0.00 F	*- F
2	1		*STEERING CONE	Necessary	0.00 F	*- F
3	1		*HANDLE BAR	Bent	0.00 F	*- F
4	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
5	1		*HAND BRAKE LEVER	Bent	0.00 F	*- F
6	1		*FAIRING LOWER (REAR)	Cut	0.00 F	*- F
7	1		*FRONT FOOT REST	Bent	0.00 F	*- F
8	1		*REAR FOOT REST	Cut	0.00 F	*- F
9	1		*REAR FOOT REST BRACKET	Bent	0.00 F	*- F
10	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
11	1		*EXHAUST MUFFLER ASSY	Bent	0.00 F	*- F
12	1		*REAR TYRE	Cut	0.00 F	*- F
13	1		*REAR RIM	Cut	0.00 F	*- F
14	1		*REAR FENDER WHEEL GUARD	Crushed	0.00 F	*- F
15	1		*SWING ARM	Bent	0.00 F	*- F
16	1		*REAR LH SIGNAL LAMP	Broken	0.00 F	*- F
17	1		*REAR RH SIGNAL LAMP	Broken	0.00 F	*- F
18	1		*REAR TAILLAMP	* Check	0.00 F	*- F
19	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
20	1		*REAR BOX	Broken	0.00 F	*- F
21	1		*REAR BOX BRACKET	Bent	0.00 F	*- F
22	1		*REFLECTOR (REAR)	Broken	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >