



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|----------------------------|--|-----------------------|
| AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN | | | Ref: CC4/ASM19009612/Kes3q2 Date: 18/03/2021 Code: ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SKT 4444R | Veh. Inspected | GBJ 1583B |
| | Policy No. | P2199568 | Coverage (\$) | 0.00 |
| | Claim No. | S9M01P4V | Excess (\$) | 0.00 |
| | Assign From | | Assign Date | 30/05/2019 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | NISSAN NV200 | c.c | 1461 |
| | Engine No. | HIDDEN | Year of Reg. | 2019 |
| | Chassis No. | VSKYBAM20Z0174574 | Colour | WHITE |
| | Odometer | 12830 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | NIL |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 175/70 R14 | GOODYEAR | 9 mm |
| | L/H Front Tyre | 175/70 R14 | GOODYEAR | 9 mm |
| | R/H Rear Tyre | 175/70 R14 | GOODYEAR | 9 mm |
| | L/H Rear Tyre | 175/70 R14 | GOODYEAR | 9 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 28/05/2019 | Inspection Date | 31/05/2019 |
| | Survey held at | 385 SIN MING DRIVE | | |
| | Repairer | ESTEEM PERFORMANCE PTE LTD | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 6 Working Days |