

22/03/2019

S. REC. BY:

REF: S/EG119009617/ Jt d3

Special Instruction:

Insured:

ASSIGNMENT (Office)

From (Person): Phoebe xie of Ergo. Date/Time: 30.5.19 15.37p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XD 3017C Insured:

at Workshop m/s Lee Kuan Hwa Tel: 62699192 90282798

of 24 Sungei Kadut street 4

Policy No: DM CV185008494 Claim No:

Sum Insured: Excess: \$1500.00

Make of Veh: D.O.A. 27.5.2019
(Client's Record)

CA (REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 30.5.19 4.04 p.m. Person Contacted: Siew chen Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	XD 3017C -X	
31/6/19	Revert WA. menmen (Pending repair cost)	
1/6@14.57pm	approval by Phoebe 25K	
1/6@3:02pm	inform w/s via email authorise repair. excess \$1500-	
19/6@11:28am	Re-send. authorise to w/s jump sum \$26.500-	

REF: Ergo

ASSIGNMENT

From:

Date: 31.5.2019

Veh No:

XD 3017C

Yr Regn:

26 Aug 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XD 3017C

at Workshop m/s Lee Kuan Hwa

of 24 Sungai Kadut Street 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess: \$1500/-


(Client's Record)

Make of Veh: 96311712 Lee Kuan Hwa

(After 11.000.m)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA (REV) REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Truck / Trailer or

Make:

SCANIA

C.C. 11705

Colour

Orange

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Y52P6X40062035586

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 315/60 R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal.

7

mm

R/Bal.

7/7

mm

L/Bal.

7

mm

L/Bal.

7/7

mm

D.O.A.

21/5/19

D.O.I.

31/5/19

Survey held at

Lee Kuan Hwa

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-\$40000 (check with Marcus)

PV-\$13169

NV-\$26831

RECEIVED 30 SEP 2019

31@ 2:15pm check with Adeline still under repair.

Lump Sum \$26,500/- (Red: 79870.50, 75%)

Date/Time, File Pass to?

Preli. Report

1) 30/09 Typist

Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I.: (\$ 26,500/-)

Days Of Repair: 14

Resurvey No. of Trip:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

350

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2019 13:41 Sendback Est	30 May 2019 14:27 S\$106,370.50	30 May 2019 15:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	HUASING CONSTRUCTION & TRADING PTE LTD, Co. Reg. No.: 199102016W								
Vehicle Reg. No.:	XD3017C	Date of Loss:	27/05/2019 10:00 - :59 [129 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD	Policy/Cover Note No.:	DMCV18S008494 (Comprehensive)						
		Excess:	S\$1,500.00						
Repairer:	Lee Kuan Hwa Motor Service (Sungei Kadut) 24 Sungei Kadut Street 4, 729050 Sungei Kadut - Tel: 62699192								
Handling Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199 ... [Handled by Phoebe Xie]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/06/2019]								
Driver/Custodian:	RAMALINGAM SUNDARARAJAN (39 / Male) , NRIC: G6277248X, Tel: +6587751928 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Phoebe Xie <phoebe.xie@ergo.com.sg>
Sent: Wednesday, 19 June 2019 11:21 AM
To: Denise Tay (LKKAUTO)
Cc: SUR
Subject: RE: XD3017C / OD / DOA: 27/5/2019

Dear Denise,

Please offer up to \$26,500 before excess (\$25,000 after excess), they will check with insured if insured wants to top up to repair the vehicle.
Thank you

Warmest Regards,
Phoebe Jay Xie
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9191
phoebe.xie@ergo.com.sg

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.
Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.
ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Monday, 17 June, 2019 2:41 PM
To: Phoebe Xie
Cc: SUR
Subject: RE: XD3017C / OD / DOA: 27/5/2019

Dear Phoebe,

Any update?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 19 June 2019 11:28 AM
To: kuanhwa@singnet.com.sg
Cc: SUR
Subject: RE: XD 3017C / OD / EQ

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **XD 3017C (Excess \$1500/-). Approve at \$26,500/- by insurance before excess**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAUTO)

From: Phoebe Xie <phoebe.xie@ergo.com.sg>
Sent: Monday, 17 June 2019 2:43 PM
To: Denise Tay (LKKAUTO)
Cc: SUR
Subject: RE: XD3017C / OD / DOA: 27/5/2019

Dear Denise,

Please award to Toh Ah Swee at \$25,000 and put in writing to them. They have informed me that the rest of the repairs, the insured will undertake to bear.

Thank you

Warmest Regards,
Phoebe Jay Xie
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9191
phoebe.xie@ergo.com.sg

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.
Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.
ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Monday, 17 June, 2019 2:41 PM
To: Phoebe Xie
Cc: SUR
Subject: RE: XD3017C / OD / DOA: 27/5/2019

Dear Phoebe,

Any update?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 12 June 2019 11:28 AM
To: phoebe.xie@ergo.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: XD3017C / OD / DOA: 27/5/2019

Dear Phoebe,

Refer to our conversation.

As per instruction, we have sent tender to your authorise workshops.

They are unable to undertake the repair.

Please advise.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 17 June 2019 3:02 PM
To: kuanhwa@singnet.com.sg
Subject: XD 3017C / OD / EQ

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **XD 3017C (Excess \$1500/-). Approve at \$25,000/- BY INSURANCE**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

XD3017C

OD

May 27 2019 10:00AM

[HUASING CONSTRUCTION & TRADING PTE LTD]

Lee Kuan Hwa Motor Service

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From ERGO Insurance Pte. Ltd. (HQ) (ERGO_SG), sent on 17/06/2019 14:57 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$25000.00) - XD3017C - Claim Handler: Phoebe Xie

Approved:25000.00.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Phoebe Xie

Date: 03 Jun 2019

Preliminary Advice

Vehicle No	: XD3017C	Accident Date	: 27/05/2019
Make	: SCANIA P340CB6X4MHZ	Policy No.	: DMCV18S008494
Assignment Date	: 30/05/2019	Excess	: S\$1,500.00
Date of Inspection	: 31/05/2019	Est. Duration of Repair	: 14.00
Inspection At	: LEE KUAN HWA MOTOR SERVICE (SUNGEI KADUT) 24 SUNGEI KADUT STREET 4 SINGAPORE 729050		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	106,370.50
Revised Amount	:S\$	96,635.70
Check Items (Estimated)	:S\$	7,984.80
Total	:S\$	104,620.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	13,169.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,831.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Pending repair cost from repairer

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2016W
Vehicle Details	
Vehicle No.:	XD3017C
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jun 2019
Vehicle Make:	SCANIA
Vehicle Model:	P340CB6X4MHZ
Primary Colour:	Yellow
Manufacturing Year:	2008
Engine No.:	6371209
Chassis No.:	YS2P6X40002035586
Maximum Power Output:	-
Open Market Value:	\$126,952.00
Original Registration Date:	26 Aug 2008
First Registration Date:	26 Aug 2008
Transfer Count:	3
Actual ARF Paid:	\$6,348.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Aug 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$15,582.00
COE Rebate Amount:	\$13,169.00
Total Rebate Amount:	\$13,169.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 03 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/05/2019 12:26
Date Of Accident	27/05/2019 10:30
Exact Location Of Accident	WOODLANDS ROAD TOWARDS BUKIT TIMAH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD3017C
Insured/Policyholder	
Name Of Registered Owner	HUASING CONSTRUCTION & TRADING PTE LTD
Co Reg No	199102016W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63626362

Vehicle Particulars

Manufacturer	SCANIA
Model	P340CB6X4MHZ-11.7 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	DMCV18S008494
Cover Note Number	

Driver

Name of Driver	RAMALINGAM SUNDARARAJAN
NRIC No	G6277248X
Date Of Birth	29/05/1979
Occupation	OUTDOOR
Date Of Driving Pass	29/05/2015
Driving Experience	3 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87751928
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address

9 SUNGEI KADUK STREET 4 S(729039)

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

-

-

-

Insurance Company of Driver's Own Vehicle

-

-

-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 4

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SBS8437Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category BUS

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SG5808S

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X f.g.
Policyholder's Signature
Date & Time: 28.05.2019 10:29am



P. S. P.
Driver's Signature
(If driver is not the policyholder)
Date & Time:

李光華摩哆燒焊
LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Please refer to the police report

The ambulance and traffic police arrived at scene.

I/We declare the foregoing particulars are true in every respect.

Date & Time: 28.01.2020

(If driver is not the policyholder)

LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1142

Name: _____

NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190527/2160

1 of 3

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

Report No. T/20190527/2160

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/05/2019 18:38	Vide Report No.: J/20190527/0068	Station Diary No.: 153
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: RAMALINGAM SUNDARARAJAN			Address: 52 SUNGEI KADUT LOOP #09-132 ROXY SQUARE SINGAPORE 729476	
ID Type / ID No.: FIN NO / G6277248X			Contact No.: Home/Office:	Mobile: 87751928
Nationality: INDIAN			Email:	
Sex: Male	Age: 39	Date of Birth: 17/07/1979	Type of Informant: Driver	
Race: Indian			Language: English	Institution / School Name:
Occupation: Other heavy truck and lorry drivers			Driving Licence Information: Class: 3,4	Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 27/05/2019 10:30	Type of Location: Straight Road
Location: Along Road 1 WOODLANDS ROAD ALONG WOODLANDS ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SBS8437Y						0
SG5808S	Bus/Coach/Mi nibus					0
XD3017C	TIPPER TRUCK					0
XD9274L	TIPPER TRUCK					0



SINGAPORE POLICE FORCE



T/20190527/2160

2 of 3

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

Report No. T/20190527/2160

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	RAMALINGAM SUNDARARAJAN	ID No.	G6277248X
Related Vehicle	NIL	Contact No.	87751928
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/05/2019 at about 1030hrs, I am travelling along Woodlands Road towards Bukit Timah. As the lorry (XD9274L) in front of me suddenly brake. I tried to avoid the collision and I swerved towards the right. However, due to the distance, I hit onto the rear right of the lorry and the impact causes the lorry to hit onto the bus (SG5808S) which was at the bus stop. And my lorry hit onto the bus (SBS8437Y) which is on the right lane.

Shortly, the ambulance and traffic police arrived at scene. The ambulance then conveyed three passengers from the bus, SG5808S to the hospital

There is no video recorder installed on my lorry.



**SINGAPORE
POLICE FORCE**



T/20190527/2160

3 of 3

Report No. T/20190527/2160

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Staff Sgt TOH ZHENG YAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt SUFIYAN BIN KHAIRI

Contact No.: 65476390

Signature:

Authentication Stamp

NP168

Signature Of Informant:

R-Sun

Date/Time:

27/05/2019 18:38

Classification Of Case:

Singapore Police Force

Vehicle Registration Detail Information

Enquire Vehicle Registration Details

Page 1 of 1



Owner Particulars	
NRIC/Passport/Company Cert No.:	199102016W
Owner ID Type:	Company
Owner Name:	HUASING CONSTRUCTION & TRADING PTE LTD
Registered Address:	9 SUNGEI KADUT STREET 4 SUNGEI KADUT INDUSTRIAL ESTATE SINGAPORE 729039
Mailing Address:	-
Birth Date:	-
Vehicle Particulars	
Vehicle No.:	XD3017C
Previous Vehicle No.:	-
Effective Date of Ownership:	20 Jul 2015
Original Regn Date:	26 Aug 2008
Registration Date:	26 Aug 2008
Year of Manufacture:	2008
Vehicle Type:	Goods (Open) Tipper/Dumper Truck
Vehicle Scheme:	-
Vehicle Attachment 1:	No Attachment
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Make:	SCANIA
Vehicle Model:	P340CB6X4MHZ
Primary Colour:	Yellow
Secondary Colour:	-
Passenger Capacity:	1
Chassis No.:	YS2P6X40002035586
Engine No.:	6371209
Engine Capacity / Power Rating:	11705 cc / -
Maximum Power Output:	-
Propellant:	Diesel
Max Unladen Weight:	11160 kg
Maximum Laden Weight:	28000 kg
Open Market Value:	\$126,952.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
Minimum PARF Benefit:	-
No. of Transfers:	3
IU Label No.:	2010358958
COE No.:	2008080105000735W
COE Expiry Date:	25 Aug 2023
COE Category:	C - Goods Vehicle & Bus
COE Registration Category:	C - Goods Vehicle & Bus
Quota Premium (QP) / Prevailing Quota Premium:	\$12,659.00 / -
PQP Paid:	\$15,582.00
QP (Regn Cat):	\$12,659.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$12,659.00
Additional Registration Fee Rate:	5.00 %
Actual ARF Paid:	\$6,348.00
Vehicle Lifespan Expiry Date:	25 Aug 2028
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Message:	-

25/8/28

有9年

Print

OK

Save as PDF

LKK

Lee Kuan Hwa Motor Service (Co.Reg.No:36463500B)
 24 Sungei Kadut Street 4
 Singapore 729050
 Tel: 62699192 Fax: 62692239 Email: kuanhwa@singnet.com.sg

INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCV18S008494	Date of Loss:	27/05/2019
Vehicle Reg. No.:	XD3017C	Driveable?	NO
Driver Age/Info:	39 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HUASING CONSTRUCTION & TRADING PTE LTD		
Driver:	RAMALINGAM SUNDARARAJAN		
Make/Model:	SCANIA P340CB6X4MHZ, 11.7 D (M)	Vehicle Reg. Date:	26/08/2008
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	6371209	Chassis No:	YS2P6X40002035586
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	18		
Present Location:	LEE KUAN HWA MOTOR SERVICE (SUNGEI KADUT)		

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	99,879.80
Labour	10.70
Paintwork Labour	6,480.00
Towing	0.00
	0.00
Nett Amount (S\$)	106,370.50

This claim is handled by: **CHUA SIEW CHEN**

Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 30 May 2019)
 Parts: N/A SCANIA P340CB6X4MHZ 11.7 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Lee Kuan Hwa Motor Service/XD3017C/30/05/2019 14:27
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Cabin BUC-			
2	1		*Front Panel mis X c/w cabin	0.00	0.00	*55,000.00 F 19,999
3	2		*Front Grille mis-	0.00	0.00	*1,680.00 F X
4	2		*Front Panel Inner Bracket LH.RH BT X c/w cabin	0.00	0.00	*540.00 F X
5	2		*Front Cornel Panel LH.RH CRA-RH, mis-LH-X c/w cabin	0.00	0.00	*2,310.00 F X
6	1		*Front Cabin Alloy Bracket LH CRA-X c/w cabin	0.00	0.00	*630.00 F X
7	1		*Front Cabin Alloy Absorber LH mis-	0.00	0.00	*1,164.00 F X
8	1		*Front Cabin Top Pump BT-	0.00	0.00	*760.00 F X
9	1		*Front Radiator ? X NM	0.00	0.00	*1,670.00 F X
10	1		*Front Radiator Pipe Upper BT-	0.00	0.00	*2,054.00 F X
11	4		*Front Moonshape Mudguard LH.RH CRA c/w cabin	0.00	0.00	*380.00 F X
12	4		*Front Moonshape Mudguard Top Garnish LH.RH CRA c/w cabin	0.00	0.00	*1,752.00 F X
13	2		*Front Step Panel LH.RH CRA-LH, BT-RH	0.00	0.00	*756.00 F X
14	2		*Front Step Top Garnish LH.RH CRA-	0.00	0.00	*1,360.00 F X
15	2		*Front Step Lower Garnish LH.RH CRA-	0.00	0.00	*460.00 F X
16	2		*Front Headlamp LH.RH SCR-LH, CRA-RH	0.00	0.00	*242.00 F X
17	2		*Front Headlamp Inner Garnish LH.RH CRA-	0.00	0.00	*726.00 F X
18	2		*Front Headlamp Upper Garnish LH.RH CRA-	0.00	0.00	*566.00 F X
19	1		*Front Step Alloy LH CRA-	0.00	0.00	*252.00 F X
20	1		*Front Air-Con Condensor & Cooler (1 Set) CRA-	0.00	0.00	*271.00 F X
21	2		*Rear Cabin Absorber LH.RH BUC-	0.00	0.00	*3,880.00 F X
22	1		*Rear Engine Air Pipe BT-	0.00	0.00	*1,520.00 F X
23	2		*Front Bumper LH.RH BUC-	0.00	0.00	*1,408.00 F X
24	1		*Front Cable & Head (1 Set) BUC- c/w cabin	0.00	0.00	*720.00 F X
25	1		*Front CPU (1 Set) ? X NM	0.00	0.00	*1,871.00 F X
				0.00	0.00	*4,880.00 F X

F=Franchise part.

Sub Total (\$\$) 86,852.00
 + Margin on L,N Items 15.00% (\$\$) 13,027.80

Total Parts (\$\$) 99,879.80

Lee Kuan Hwa Motor Service/XD3017C/30/05/2019 14:27. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

33,755
 - 15%
 28,691.75

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.70
Sub Total (S\$)			10.70

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To Towing Services	New	180.00 ✓
2	To Wiring Services	New	500.00 250
3	To Crane Remove Cabin Services	New	200.00 ✓
4	To Replace Cabin , Repair & Replace Labour Charges	New	3,800.00 2800
5	To Putty & Spray Painting	New	1,800.00 1300
Gross Labour Cost (S\$)			6,480.00

Lee Kuan Hwa Motor Service/XD3017C/30/05/2019 14:27. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

P- 28,691.75

L- 4730

33,421.75

L/S- 26,737.40

= 26,750.00


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

 3/6/19
Hwa Jie-LKK

31/5/19

L/S 14 days.

Not Authorise

Excess: \$1500/-

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2019 13:41 Sendback Est	30 May 2019 14:27 \$106,370.50	30 May 2019 15:37 Edit Adj Rpt	\$26,500.00 Edit Estimates	\$26,500.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	HUASING CONSTRUCTION & TRADING PTE LTD, Co. Reg. No.: 199102016W		
Vehicle Reg. No.:	XD3017C	Date of Loss:	27/05/2019 10:00 - :59 [129 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No.:	DMCV18S008494 (Comprehensive)
		Excess:	S\$2,000.00
Repairer:	Lee Kuan Hwa Motor Service (Gul Crescent) 20 Gul Crescent, 629529 Pioneer - Tel: 62699192		
Handling Insurer:	ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199 ... [Handled by Phoebe Xie - 6829 9191]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 11/06/2019]		
Driver/Custodian:	RAMALINGAM SUNDARARAJAN (39 / Male) , NRIC: G6277248X, Tel: +6587751928 Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- ERGO_SG (30/09/2019): Alert - Adj Mandate Approved (S\$26500.00) - XD3017C - Claim Handler: Phoebe Xie
- ERGO_SG (17/06/2019): Alert - Adj Mandate Approved (S\$25000.00) - XD3017C - Claim Handler: Phoebe Xie

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

XD3017C

OD

May 27 2019 10:00AM

[HUASING CONSTRUCTION & TRADING PTE LTD]

Lee Kuan Hwa Motor Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#)
[View in Browser](#)

Assessment Reports

1 per page
☒

No	Finalized On	Lee Kuan Hwa Motor Service (Gul Crescent)	Thumbnail	Print
1	30/05/19 14:27	Repairer Estimates	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/06/19 13:38	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>

Photos/Images

3 per page
☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
2	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
3	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
4	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
5	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
6	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
7	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
8	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
9	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
10	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
11	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
12	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
13	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
14	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
15	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
16	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
17	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
18	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
19	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
20	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
21	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
22	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
23	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
24	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
25	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
26	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
27	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
28	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
29	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
30	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
31	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
32	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
33	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
34	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
35	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
36	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>
37	03/06/19 09:18	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	Lee Kuan Hwa Motor Service (Gul Crescent)	Thumbnail	Print
38	03/06/19 09:18	General View	Load JPG	✓
39	03/06/19 09:18	General View	Load JPG	✓
40	03/06/19 09:18	General View	Load JPG	✓
41	03/06/19 09:18	General View	Load JPG	✓
42	03/06/19 09:18	General View	Load JPG	✓
43	03/06/19 09:18	General View	Load JPG	✓
44	03/06/19 09:18	General View	Load JPG	✓
45	03/06/19 09:18	General View	Load JPG	✓
46	03/06/19 09:18	General View	Load JPG	✓
47	03/06/19 09:18	General View	Load JPG	✓
48	03/06/19 09:18	General View	Load JPG	✓
49	03/06/19 09:18	General View	Load JPG	✓
50	03/06/19 09:18	General View	Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/06/19 13:41	ESTIMATE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985

Our File No: CS/EG19009617/ETD3S2

Date: 30/09/2019

REFERENCE

Insured/Claimant: HUASING CONSTRUCTION & TRADING PTE LTD
Date of Loss: 27/05/2019

Policy No: DMCV18S008494

Nature of Claim: OD

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD3017C	Engine No:	6371209
Make & Model:	SCANIA P340CB6X4MHZ, 11.7 D (M)	Chassis No:	YS2P6X40002035586
Reg. Date:	26/08/2008 (Man. Year: 2008)	Odometer:	0 km
Colour:	Orange		
Engine Capacity:	11705 cc		
Market Value/New Car Price:	S\$40,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	315/80 R22.5	Rear Tyre Size:	315/80 R22.5 (D)
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7/7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	99,879.80	38,818.25	61,061.55	61.14
Miscellaneous Items	10.70	10.70	0.00	0.00
Labour	6,480.00	4,730.00	1,750.00	27.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	106,370.50	43,558.95	62,811.55	59.05
Approved Total (Overridden) (S\$)		26,500.00		
- Excess (S\$)	0.00	1,500.00	-1,500.00	
Nett Amount (S\$)	106,370.50	25,000.00	81,370.50	76.50

INSPECTION

Date of Assignment:	30/05/2019	Present Location:	Lee Kuan Hwa Motor Service (Sungei Kadut)
Date Inspected:	31/05/2019	Inspected At:	Lee Kuan Hwa Motor Service (Sungei Kadut)
			24 Sungei Kadut Street 4
			Singapore 729050
Estimated Period of Repair:	14.0 days		

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 30 Sep 2019)	
Parts:	N/A	SCANIA P340CB6X4MHZ 11.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD3017C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*Front Cabin (WCP)	Buckled	55,000.00 F	*19,000.00 F
2	1	*Front Panel (WCP)		1,680.00 F	*- F
3	2	*Front Grille (WCP)	Missing	540.00 F	*540.00 F
4	2	*Front Panel Inner Bracket LH.RH (WCP)		2,310.00 F	*- F
5	2	*Front Cornel Panel LH.RH (WCP)		630.00 F	*- F
6	1	*Front Cabin Alloy Bracket LH (WCP)		1,164.00 F	*- F
7	1	*Front Cabin Alloy Absorber LH (WCP)	Missing	760.00 F	*760.00 F
8	1	*Front Cabin Top Pump (WCP)	Bent	1,670.00 F	*1,670.00 F
9	1	*Front Radiator (WCP)	Not Necessary	2,054.00 F	*- F
10	1	*Front Radiator Pipe Upper (WCP)	Bent	380.00 F	*380.00 F
11	4	*Front Moonshape Mudguard LH.RH (WCP)		1,752.00 F	*- F
12	4	*Front Moonshape Mudguard Top Garnish LH.RH (WCP)		756.00 F	*- F
13	2	*Front Step Panel LH.RH (WCP)	N/s Cracked / O/s Bent	1,360.00 F	*1,360.00 F
14	2	*Front Step Top Garnish LH.RH (WCP)	Cracked	460.00 F	*460.00 F
15	2	*Front Step Lower Garnish LH.RH (WCP)	Cracked	242.00 F	*242.00 F
16	2	*Front Headlamp LH.RH (WCP)	N/s Scratched / O/s Cracked	726.00 F	*726.00 F
17	2	*Front Headlamp Inner Garnish LH.RH (WCP)	Cracked	566.00 F	*566.00 F
18	2	*Front Headlamp Upper Garnish LH.RH (WCP)	Cracked	252.00 F	*252.00 F
19	1	*Front Step Alloy LH (WCP)	Cracked	271.00 F	*271.00 F
20	1	*Front Air-Con Condensor & Cooler (1 Set) (WCP)	Buckled	3,880.00 F	*3,880.00 F
21	2	*Rear Cabin Absorber LH.RH (WCP)	Bent	1,520.00 F	*1,520.00 F
22	1	*Rear Engine Air Pipe (WCP)	Buckled	1,408.00 F	*1,408.00 F
23	2	*Front Bumper LH.RH (WCP)	Buckled	720.00 F	*720.00 F
24	1	*Front Cable & Head (1 Set) (WCP)		1,871.00 F	*- F
25	1	*Front CPU (1 Set) (WCP)	Not Necessary	4,880.00 F	*- F

F=Franchise part.

Sub Total (\$\$) 86,852.00 33,755.00
+ Margin on L,N Items 15.00/15.00% (\$\$) 13,027.80 5,063.25

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						99,879.80 38,818.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	-	10.70
2	1	OD/TP Case (Insurer)	10.70	0.00
Sub Total (S\$)			10.70	10.70

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	To Towing Services	New	180.00	180.00
2	To Wiring Services	New	500.00	250.00
3	To Crane Remove Cabin Services	New	200.00	200.00
4	To Replace Cabin , Repair & Replace Labour Charges	New	3,800.00	2,800.00
5	To Putty & Spray Painting	New	1,800.00	1,300.00
Gross Labour Cost (S\$)			6,480.00	4,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >