

22/03/2012

ASS. REC. BY:

REF: CS/TMI/9009619/K1vd3e2

Special Instruction:

Surveyor: Kalin

ASSIGNMENT (Office)

From (Person): Eliza Ho Tung Boon

of

TMI

Date/Time: 30.5.19 16.07p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 7089H

Insured: SJS 6889U

at Workshop m/s Comfort delgion

Tel: 62148300

of 59 Loyang Drive

Policy No: MX 006470

Claim No: M1903957

Sum Insured:

Excess:

Make of Veh:

D.O.A. 28.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 30.5.19 4.13p.m

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (V)
	SHD 7089H - NA/INC 7018471/24	D.O.A - 25/09/2014
	SJS 6889U - NA/MSG12005056/K	D.O.A - 12/03/2012

261

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 May 2019 15:10 Sendback Est	30 May 2019 15:12 S\$3,839.82	30 May 2019 16:07 Assign				<b>New Assignment</b> Cancel Case

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

Insured:	CTPL, Co. Reg. No.: 199303821R		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHD7089H	Date of Loss:	28/05/2019 17:00 - :59 [30 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M1903957	Policy/Cover Note No.:	MX006470 (Comprehensive) Coverage: 28/08/2018 - 27/08/2019
Vehicle Reg. No. (Insured):	SJS6889U	Policy No. (Claimant):	
		Excess:	S\$100.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ho Teng Boon Eliza]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/06/2019]		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/05/2019 11:29
Date Of Accident	28/05/2019 17:15
Exact Location Of Accident	BUKIT TIMAH TWDS UPP BUKIT TIMAH RD.
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD7089H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 4G
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	SIM YU JEN MELVIN (SHEN YOUQIANG MELVIN)
NRIC No	S7730120H
Date Of Birth	10/10/1977
Occupation	OUTDOOR
Date Of Driving Pass	18/10/2001
Driving Experience	17 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96193106
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 286 YISHUN AVE 6 #12-100
Postcode	760286
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED \* TYPE OF ACCIDENT :- HEAD TO SIDE

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS6889U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WEST ELIZABETH JANE
NRIC/Passport Number	G338727U
Contact Number	83162783
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	RH REAR
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON. 28 May 2019 @ 17:15 hr. I. vert A.

about to follow to give love. I vent it

GHIC there was no vehicle on the gate

love the moment I just move out

Suddenly vet B from 3rd lane dash in

to 2nd lane and hit vert A left front.

at the point of accident vehicle was parked.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature

Date &amp; Time:

Driver's Signature

(If driver is not the policyholder)

Date &amp; Time:

Reporting Centre Personnel's Signature

Name: \_\_\_\_\_

NRIC/FIN No.:


Team: ARC Repair TP(CLSO)1      **JOB CARD**      Sales Order:      JC NO.: 305299426

OMER S OMER NO. ESS (R) (P) UNT CARD NO.	COMFORT TRANSPORTATION PTE LTD	REGN NO.: SHD7089H	MILEAGE
	7010045	MAKE: TOYOTA	FUEL
	383 SIN MING DRIVE	MODEL PRIUS HYBRID(G4)	E 1/2 F
	Singapore SINGAPORE 575717	DATE/TIME IN 30.05.2019 12:00	
	65508755	YR OF MANU 11.11.2016	TARGET DATE
	(O)	CHASSIS CODE JTDKB3FU303536910	COMPLETION DATE/TIME

Accident Date: 28.05.2019  
NATURE: 3P 28.05.19/C

JOB DESCRIPTION

S/NO      LABOR CODE      DESCRIPTION



KED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
SERVICE ADVISOR      CUSTOMER'S SIGNATURE

Lodgement Slip		Exit Pass	
No.: SHD7089H	LIMITS	Vehicle No.: SHD7089H	
Signature/Date		Name of Service Advisor	Date
turned to Service Reception upon collection		To be kept by Security Guard	



COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.05.2019

Time: 12:52:42

Page: 1/2

IS

Tyre Duratur  
195/65 R15

REPAIR ESTIMATE

Tokio Marine CP/P  
LKK - Kalvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305299426  
 REGN NO : SHD7089H  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4)  
 DATE OF REGN : 11.11.2016  
 DATE/TIME IN : 30.05.2019 12:00  
 ACCIDENT DATE : 28.05.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0302-2292-A	FRONT BUMPER	1	490.50	25.00	367.87	— cut
0002 04-01-0302-2871-G	FRT BUMPER SIDE BRKT LH	1	82.30	25.00	61.72	x sur
0003 04-01-0302-2815-G	HEADLAMP LH	1	2,530.10	25.00	1,897.57	— cut
0004 04-01-0302-4891-G	FOG LAMP LH	1	910.20	25.00	682.65	— cut

Front LH fender x repair

SUB-TOTAL : 3,009.81

## JOB NATURE

0000 PB	PANEL BEATING	<del>280.00</del>	200
0001 SP	SPRAYPAINT CHARGE	<del>500.00</del>	400
0002 17-01	CHECK ALL LIGHTING	<del>40.00</del>	x 20
0003 20-05	TP MERIMEN	<del>11.00</del>	10.00

SUB-TOTAL : 580.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.05.2019

REPAIR ESTIMATE

ToK-Marine (P/P)  
LK - Kalvir

Time: 12:52:42

Page: 2

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305299426  
REGN NO : SHD7089H  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(C  
DATE OF REGN : 11.11.2016  
DATE/TIME IN : 30.05.2019 12:00  
ACCIDENT DATE : 28.05.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

Ump

TOTAL : 3,589.81

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

Kalvir 10/10/19  
20/5/19 1310L  
3 Pys.  
P/P  
Before Part photo.



# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305299426

Date : 03/06/19

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHD7089H

Date of Accident : 28-May-19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SJS6889U

2. The finalized amount shall be:

(a) Spare Parts after List discount \$2,948.10

(b) Labour Charges \$631.00

**Total for Part-By-Part Repair Cost \$3,579.10**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

**Final Lumpsum Repair cost**

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : KALVIN

Tel : 62148398

Date : 6/6/19

Fax : 65468156

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305299426  
REGN NO : SHD7089H  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 11.11.2016  
DATE/TIME IN : 30.05.2019 12:00  
ACCIDENT DATE : 28.05.2019

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0302-2292-A	FRONT BUMPER	1	490.50	25.00	367.87
0002 04-01-0302-2815-G	HEADLAMP LH	1	2,530.10	25.00	1,897.57
0003 04-01-0302-4891-G	FOG LAMP LH	1	910.20	25.00	682.65

SUB-TOTAL : 2,948.09

## JOB NATURE

0000 PB	PANEL BEATING	200.00
0001 SP	SPRAYPAINT CHARGE	400.00
0002 17-01	CHECK ALL LIGHTING	20.00
0003 20-05	TP MERIMEN	10.00

SUB-TOTAL : 630.00

TOTAL : 3,578.09

  
MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE : AUTHORIZED : YES / NO

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 May 2019 15:10 <a href="#">Sendback Est</a>	30 May 2019 15:12 <b>S\$3,839.82</b>	30 May 2019 16:07 <a href="#">Edit Adj Rpt</a>	<b>S\$3,579.10</b> <a href="#">Edit Estimates</a>	<b>S\$3,579.10</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured: <b>CTPL</b> , Co. Reg. No.: 199303821R									
Main Claimant: <b>CTPL</b>									
Vehicle Reg. No.: <b>SHD7089H</b>		Date of Loss: 28/05/2019 17:00 - :59 [30 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / M1903957</b>		Policy/Cover Note No.: MX006470 (Comprehensive) Coverage: 28/08/2018 - 27/08/2019							
Vehicle Reg. No. (Insured): <b>SJS6889U</b>		Policy No. (Claimant):							
		Excess: S\$100.00							
Repairer: <b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300									
Handling Insurer: <b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Ho Teng Boon Eliza</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [Final Rpt due 11/06/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

SHD7089H (M1903957)

[SJS6889U]


































TP

CTPL

May 28 2019 5:00PM

[CTPL]

ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print				
1	30/05/19 15:12	Repairer Estimates			Load HTM				
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print				
1	30/05/19 16:07	Accident Statement From: SC - Reg. No: SJS6889U, Claimant: A A 24 HRS EXPAT'S CHOICE			Load HTM				
2	30/05/19 16:07	Addendum Sheet From: SC - Reg. No: SJS6889U, Claimant: A A 24 HRS EXPAT'S CHOICE			Load JPG	<input checked="" type="checkbox"/>			
3	30/05/19 16:07	Accident Statement Addm. #1 From: SC - Reg. No: SJS6889U, Claimant: A A 24 HRS EXPAT'S CHOICE			Load HTM				
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print				
1	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
2	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
3	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
4	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
5	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
6	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
7	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
8	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
9	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
10	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
11	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
12	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
13	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
14	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
15	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
16	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
17	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
18	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
19	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
20	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
21	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
22	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
23	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
24	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
25	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
26	31/05/19 09:09	General View			Load JPG	<input checked="" type="checkbox"/>			
27	04/06/19 08:35	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>			
28	04/06/19 08:35	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>			
29	04/06/19 08:35	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>			

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	30/05/19 15:12	E-filed GIA report		 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>	
<div></div>	
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI19009619/K1VD3E2

Date: 11/06/2019

## REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MX006470

Claimant Vehicle No : SHD7089H

Insured Vehicle No : SJS6889U

Date of Loss: 28/05/2019

Nature of Claim: TP

Claim No: M1903957

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SHD7089H

Make &amp; Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRR959703

Reg. Date: 11/11/2016 (Man. Year: 2016)

Chassis No: JTDKB3FU303536910

Colour: Blue

Odometer: 237993 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition: Good

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: DURATURN 7 mm

Rear Left Side: DURATURN 7 mm

Front Right Side: DURATURN 7 mm

Rear Right Side: DURATURN 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,009.82	2,948.10	61.72	2.05
Miscellaneous Items	10.00	11.00	-1.00	-10.00
Labour	820.00	620.00	200.00	24.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,839.82</b>	<b>3,579.10</b>	<b>260.72</b>	<b>6.79</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>268.79</b>	<b>250.54</b>	<b>18.25</b>	<b>6.79</b>
<b>Nett Amount (S\$)</b>	<b>4,108.61</b>	<b>3,829.64</b>	<b>278.97</b>	<b>6.79</b>

## INSPECTION

Date of Assignment: 30/05/2019 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 30/05/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: VERON CHEN



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jun 2019)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD7089H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	490.50 FL	*490.50 FL
2	1		*FRT BUMPER SIDE BRKT LH	Serviceable	82.30 FL	*- FL
3	1		*HEADLAMP LH	Cut	2,530.10 FL	*2,530.10 FL
4	1		*FOG LAMP LH	Cut	910.20 FL	*910.20 FL
5	1		*FRONT LH FENDER (NPA)	Repair	-	*- FL
					<b>Sub Total (S\$)</b>	<b>4,013.10</b>
					<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>1,003.28</b>
					<b>Total Parts (S\$)</b>	<b>3,009.82</b>
						<b>2,948.10</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	11.00
Sub Total (S\$)			10.00	11.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	280.00	200.00
2	SPRAY PAINTING	New	500.00	400.00
3	CHECK ALL LIGHTINGS	New	40.00	20.00
Gross Labour Cost (S\$)			820.00	620.00

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;