

20190201

ASS. REC. BY:

REP:

CS/III 19002557/41d31

and Instructions:

Surveyor
Munir

Munir

ASSIGNMENT (Office)

From (Person):

Stanley Bell

of

III

Date/Time:

29/05/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 374

Insured:

SHA 7875X

at Workshop m/s

Tick Hui Motor

Tel:

6842 9049

of

1 Leeki Bkt Ave 6 # 01-54

Policy No:

MCOM0015

Claim No:

MCT19010929

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A

31/01/2019

CA / REV / REP / REV 24 HRS

Cap

H.O.D. Endorsement

Date/Time:

11:11am @ 10/2/19

Person Contacted:

Connie

Vehicle

IN / OUT

Date/Time

Action/Instruction (X) Estimate

SLK 374 - X

SHA 7875X - CS / AIG 13012780 / H11g2 / 2w2 DVA: 12/7/13

Dismantle: 15/2/2019 10.55am

19/2/2019 11.58am

After repair: 14/3/2019 11.55am

11/6/19

Sumat 2/s 28500 confirmed with connie.
28dy. (Red. 10890 : 27%)

RECEIVED 12 JUN 2019

490 710 + 460

(08/11/93) waf

ASS. REC. BY: *Marcus*

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: *SLK374*

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

01681/-

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLK374

Yr Regn:

*6.17*Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

BMW 430i convertible 1998

Colour:

*Black*A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading

*25242*T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No:

C/No:

*WBA4U32030 E A25530*Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Good / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Good / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

R:

225/45 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

3/1/19

D.O.I.

12/2/19 1124pm

Survey held at

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or*Rear L Rf.*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PAS in letter. Rep 16
LTA 93691 byrs. 4th.

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

3

Survey Fee:

120

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

*10**130*

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

PRE

Lump Sum / I.B.I. (\$

Nivitha (LKK Auto)

From: Stanley Lai <stanley.lai@iii.com.sg>
Sent: Wednesday, 29 May 2019 5:27 PM
To: admin-d@lkkauto.com; 'sur@lkkauto.com'
Cc: Manivel Priyadarshini; Mekavathanan Sarangapani; Hsiao Tong (chewht@lkkauto.com); Olivia Lau (olivialau@lkkauto.com)
Subject: RE: MCT19010929

Dear Sir/Mdm,

Rights granted in Merimen for the above LOD. Kindly proceed with the paper survey.

TP Veh No. : SLK37U

Warmest regards,

Stanley Lai

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext.206 Fax: 6224 4174

S&P 'A-' rated Company



From: Mekavathanan Sarangapani
Sent: Tuesday, 28 May, 2019 9:29 AM
To: Hsiao Tong (chewht@lkkauto.com) <chewht@lkkauto.com>; Olivia Lau (olivialau@lkkauto.com) <olivialau@lkkauto.com>
Cc: Manivel Priyadarshini <manivel@iii.com.sg>; Stanley Lai <stanley.lai@iii.com.sg>
Subject: MCT19010929

Paper survey please

Meka

Nivitha (LKK Auto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 29 May 2019 6:20 PM
To: sur@lkkauto.com; assignments@lkkauto.com
Subject: Incoming New Document for SLK37U

This mail is associated with :
***SLK37U (MCT19010929)**
[SHA7875X]
TP
YEW SWEE FONG
Jan 31 2019 3:00PM
[-]
Tick Hai Motor

The following new document(s) has been shared with you by India International Insurance for SLK37U :

- Letter of Demand from Third Party
- Letter of Demand from Third Party
- Letter of Demand from Third Party
- Letter of Demand from Third Party
- Letter of Demand from Third Party

This is an auto-generated email. Do not reply to this email.

Sent by : Priya (India International Insurance Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

MGT/14010929

RESERVES

TPPD

PRESERVE

20K

TPPI

PRESERVE

UNINSURED LOSS

PRESERVE

SUBRO

PRESERVE

LPPN

INVESTIGATION FEE

SURVEY FEES

6w-

LEGAL FEES

OTHERS

FRAUD CHECK

UPLOAD TO MERIMEN

GRANT RIGHTS

 *** TX REPORT ***

TRANSMISSION OK

TX/RX NO 0899
 RECIPIENT ADDRESS 63382713
 DESTINATION ID
 ST. TIME 28/05 10:01
 TIME USE 00'32
 PAGES SENT 2
 RESULT OK

**ARIDAS & ASSOCIATES**

ACRA REG. NO : 53131060D
 NOTARY PUBLIC
 COMMISSIONER FOR OATHS
 ADVOCATES & SOLICITORS

75 BUKIT TIMAH ROAD, #03-13, BOON SIEW BUILDING, SINGAPORE 229833

TEL : 6337 6359 (3 LINES) FAX : 6338 2713

E-mail: aridas@singnet.com.sg.

*Tick
 Has Motv plc*

VYILINGAM ARIDAS
 LLB (Hons) Lond. M.A.
 Barrister, (Lincoln's Inn)



Service of Court Documents
 By Fax
 Is Not Acceptable

Our Ref : AA.21528.19.159
 Your Ref: Please advise

15 MAY 2019

**CERTIFICATE OF POSTING
 WITHOUT PREJUDICE****COMFORT TRANSPORTATION
 PTD LTD**

383 SIN MING DRIVE
 GAS BUILDING
 SINGAPORE 575717
 Owner of vehicle: **SHA 7875X**

INDIA INT'L INS PTE LTD

64 CECIL STREET
 #04/#05, IOB BLDG.
 SINGAPORE 049711
ATTN: CLAIMS DEPT

**KOH CHEE SIN (Please see form attach for driver's particulars)**Driver of vehicle: **SHA 7875X**

Dear Sirs,

CLAIMANT : YEW SWEE FONG
ADDRESS : 37 SUNBIRD AVENUE
SINGAPORE 487347

We are in receipt of your letter, which is receiving our attention.
 We shall revert shortly. Kindly note that we are preserving our
 rights to conduct a medical re-examination on your client where
 necessary.

Our Ref: MCT/19010929

Name: Priya

Date: 28/5/19

We are instructed by the above named to claim damages against you in connection
 with a road traffic accident on 31 JANUARY 2019 at 15:30 at PIE TWDS TLAS NEAR
 UPP THOMSON RD EXIT involving our client's vehicle registration number **SLK 37U**
 and vehicle registration number **SHA 7875X** driven by you at the material time.

We are instructed that the accident was caused by your negligent driving and/or

ARIDAS & ASSOCIATES

ACRA REG. NO : 53131060D

NOTARY PUBLIC

COMMISSIONER FOR OATHS

ADVOCATES & SOLICITORS

75 BUKIT TIMAH ROAD, #03-13, BOON SIEW BUILDING, SINGAPORE 229833

TEL : 6337 6359 (3 LINES) FAX : 6338 2713

E-mail: aridas@singnet.com.sg.

VYILINGAM ARIDAS

LLB (Hons) Lond. M.A.
Barrister, (Lincoln's Inn)



Service of Court Documents
By Fax
Is Not Acceptable

Our Ref : AA.21528.19.159

Your Ref: Please advise

15 MAY 2019

CERTIFICATE OF POSTING WITHOUT PREJUDICE

**COMFORT TRANSPORTATION
PTD LTD**

383 SIN MING DRIVE

GAS BUILDING

SINGAPORE 575717

Owner of vehicle: **SHA 7875X**

INDIA INT'L INS PTE LTD

64 CECIL STREET

#04/#05, IOB BLDG.

SINGAPORE 049711

ATTN: CLAIMS DEPT



KOH CHEE SIN (Please see form attach for driver's particulars)

Driver of vehicle: **SHA 7875X**

Dear Sirs,

CLAIMANT :

YEW SWEE FONG

ADDRESS :

**37 SUNBIRD AVENUE
SINGAPORE 487347**

We are in receipt of your letter, which is receiving our attention.
We shall revert shortly. Kindly note that we are preserving our
rights to conduct a medical re-examination on your client where
necessary.

Our Ref: MCT/19010929

Name Priya

Date 28/5/2019

We are instructed by the above named to claim damages against you in connection with a road traffic accident on 31 JANUARY 2019 at 15:30 at PIE TWDS TUAS NEAR UPP THOMSON RD EXIT involving our client's vehicle registration number **SLK 37U** and vehicle registration number **SHA 7875X** driven by you at the material time.

We are instructed that the accident was caused by your negligent driving and/or management of your vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows :

1.	Cost of repair	\$39,390.00
2.	Rental \$180.00 x 41 days	\$ 7,380.00
3.	Assessor's fees	\$ 1,750.00
4.	LTA search fees	\$ 7.49
5.	GIA (SHA7875X/SLG 476D)	\$ 58.00
6.	Legal costs and disbursements	\$ 900.00
		\$49,485.49

A copy each of the following supporting documents is enclosed :

1. GIA report;
2. Final repair bill & rental receipt;
3. Assessor's report and invoice;
4. 91 original photographs for your perusal and return;
5. A copy of the LTA search particulars;


We have on 11/2/2019 notified your insurers, INDIA INTERNATIONAL PTE LTD INSURANCE LTD., of the accident and a pre-repair survey of our client's vehicle was carried out. In the meantime, the parties will commence negotiation to resolve the matter amicably.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully,



ARIDAS & ASSOCIATES
encls

ARIDAS & ASSOCIATES

ACRA REG. NO : 53131060D
NOTARY PUBLIC
COMMISSIONER FOR OATHS
ADVOCATES & SOLICITORS

75 BUKIT TIMAH ROAD, #05-18, BOON SIEW BUILDING, SINGAPORE 229833
TEL : 6337 6359 (3 LINES) FAX : 6338 2713
E-mail : aridasv @ singnet.com.sg.

VYILINGAM ARIDAS
LLB (Hons) Lond. M.A.
Barrister, (Lincoln's Inn)

*Service of Court Documents
By Fax
Is Not Acceptable*

Our Ref : AA.21528.19.159
Your Ref: Please advise

15 MAY 2019

**COMFORT TRANSPORTATION
PTD LTD**
383 SIN MING DRIVE
GAS BUILDING
SINGAPORE 575717
Owner of vehicle: **SHA 7875X**

CERTIFICATE OF POSTING WITHOUT PREJUDICE

INDIA INT'L INS PTE LTD
64 CECIL STREET
#04/#05, IOB BLDG.
SINGAPORE 04971
ATTN: CLAIMS DEPT

KOH CHEE SIN (Please see form attach for driver's particulars)
Driver of vehicle: **SHA 7875X**

Dear Sirs

ACCIDENT INVOLVING VEHICLE REGISTRATION NOS. SLK 37U AND SHA 7875X AT PIE TWDS TUAS NEAR UPP THOMSON RD EXIT ON 31 JANUARY 2019 AT 15:30.

We act for the owner of **SLK 37U** and refer to the above matter.

Our investigation reveals that you were the owner of vehicle no. **SHA 7875X** at the material time of the accident. The accident was caused solely by the negligence of your driver.

Kindly let us have the following particulars of the driver of your said motor vehicle at the time of the above accident : -

1. Name :
2. NRIC No :
3. Address :
4. Residential Phone No. / Handphone No. :
5. **A copy of the GIA report (Accident Statement) and / or Police report made by the driver of SLK 37U**

Please note that we take the view, firstly, that you are obliged by law to provide the above particulars, and secondly, that in the absence of a response to such a query, we shall be at liberty to assume that the driver of your motor vehicle at the time of the above accident was, either yourself or your **servant and / or agent**.

In the event if we do name you as a Defendant to the proceedings relating to this matter, we shall not be liable for any costs and expenses incurred by us, including any decision/judgment of the Court that you are not a party to the proceedings. We will hold responsible for all costs and expenses incurred by us.

Kindly let us have your reply within the next seven (7) days, failing which we shall take all necessary steps to protect our client's interest, including naming you as a Defendant to the proceedings to be commenced by us.

We would also suggest that you notify your insurers of the above accident if you have not done so, failing which, your insurers would repudiate liability under the policy. As such, you will be liable for all the third party's claim against you.

Yours faithfully,


ARIDAS & ASSOCIATES
encls

Enquire Vehicle & Owner Information (Vehicle No. SHA7875X As At 31 Jan 2019 / 15:30:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: 159

Current Owner Details

Owner ID Type: Company
Owner ID: 199303821R
Owner Name: COMFORT TRANSPORTATION PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 383
Registered Street Name: SIN MING DRIVE
Registered Unit No.: -
Registered Building Name: GAS BUILDING
Registered Postal Code: 575717

Planned Vehicle Details

Vehicle No.: SHA7875X
Make Description/Model: HYUNDAI / I40 1.7L CRDI AT ABS AIRBAG 4DR
Insurance Company Name: INDIA INT'L INS PTE LTD

RECEIVED
DATE: 11.2.19

MSME19015565 / SME Motor Pte Ltd - Kaiti Bullit
ENTRY DATE & TIME: 01/02/2019 16:24
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

159 Tick Ha Motor

ACCIDENT STATEMENT

Date Of Report 01/02/2019 16:24
Date Of Accident 31/01/2019 15:30
Exact Location Of Accident PIE TWDS TUAS NEAR UPP THOMSON RD EXIT
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLK37U
Insured/Policyholder
Name Of Registered Owner YEW SWEE FONG
NRIC No S1812679F
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96972909
Alternative Phone No OFFICE-96972909
Vehicle Particulars
Manufacturer BMW
Model 430i
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company LIBERTY INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number C0081216
Cover Note Number
Driver
Name of Driver LEE WEI XUAN
NRIC No S9628393H
Date Of Birth 11/08/1996
Occupation INDOOR
Date Of Driving Pass 23/10/2015
Driving Experience 3 YEARS AND 3 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-84482885
Fax Number
Contact Number
Email Address NOEMAIL

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLG4762D

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LEE WEI XUAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLK37U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

POH QI WEN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLK37U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

ETCH PLAN

Vehicle A: SLK37U

Pie towards Tvas

Vehicle B: SHA7875X

Vehicle C: SLG4762D



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving on lane 1 on PIE towards Tvas
 The traffic slow down I decelerate until I stop behind the Vehicle C
 (SLG4762D) Few seconds later Vehicle B (SHA7875X)
 Violently hit the rear of my vehicle and push it into collision
 with the vehicle C in front of me. I want to highlight that
 I never hit the Vehicle C until the Vehicle B collide into me
 Both front and back of my car are damaged I and my
 girlfriend suffer from injury and were given each
 two days of MC

Police report attached

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time: 1 February 2014

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SINGAPORE ACCIDENT STATEMENT

3rd Party
(3rd vehicle)
SHA7875X

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/02/2019 13:41
Date Of Accident	31/01/2019 15:30
Exact Location Of Accident	ALONG PIE TWDS BKE BEFORE TOA PAYOH EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7875X
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCQM0015
Cover Note Number	

Driver

Name of Driver	KOH CHEE SIN
NRIC No	S1149649J
Address	BLK 138 JALAN BUKIT MERAH #02-1408

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	2

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK37U
Vehicle Make/Model/Colour	BMW
Name of Driver	TAN JIANHUI
Insurance Company Name	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLG4762D
Vehicle Make/Model/Colour	NISSAN
Name of Driver	UNKNOWN
Insurance Company Name	

DETAILS OF INJURED PERSON 1

Name	UNKNOWN(PAX)
Injured person in which vehicle?	SHA7875X

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R


Loke Wei Yiong

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31/1/19 at about 15:30 hrs, I Veh A driving on above said location with a female passenger. Shortly traffic in front braked to stopped in sudden. I immediately applied brake upon noticed it but it was too late. As a result, my taxi front portion collided onto rear portion of Veh B. Subsequently Veh B surged forward hit onto Veh C. After that, my passenger said her knee suffered pain but she refuses to get any medical assistance. No police no ambulance came to scene.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Loke Wei Yiong

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

11/2/19

COMFORT TRANSPORTATION PTE LTD

Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo



Accident Photo




SCENE



SCENE




SCENE




SCENE




SCENE



SCENE




SCENE



SCENE



SCENE





RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-071711
Date of Request: 07/05/2019

Your Ref No: 21383

ARIDAS & ASSOCIATES
75 Bukit Timah Road #03-13
Boon Siew Building
Singapore 229833

Dear Sir/Madam,

Date of Accident: 31/01/2019
Vehicle No: SLK37U
Place of Accident: PIE TWDS TUAS NEAR UPP THOMSON RD EXIT
Involving Vehicle No: SHA7875X

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHA7875X	PIE TWDS TUAS NEAR UPP THOMSON RD EXIT	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-19-071706
Date of Request: 07/05/2019

Your Ref No: 21383

ARIDAS & ASSOCIATES
75 Bukit Timah Road #03-13
Boon Siew Building
Singapore 229833

Dear Sir/Madam,

Your Search Criteria:Date of Accident: 31/01/2019
Place of Accident: PIE TWDS UPP THOMSON RD EXIT
Client Vehicle No: SLK37U

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SHA7875X	ALONG PIE TWDS BKE BEFORE TOA PAYOH EXIT	31/01/2019 15:30

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-071706
Date of Request: 07/05/2019

Your Ref No: 21383

ARIDAS & ASSOCIATES
75 Bukit Timah Road #03-13
Boon Siew Building
Singapore 229833

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 31/01/2019
Place of Accident: PIE TWDS UPP THOMSON RD EXIT
Client Vehicle No: SLK37U

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You,

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

(1st vehicle)
SLG 4762D

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/02/2019 17:27
Date Of Accident	31/01/2019 15:40
Exact Location Of Accident	PIE (TUAS) BEFORE UPP THOMSON EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG4762D
Insured/Policyholder	
Name Of Registered Owner	PLATINUM RENTALS PTE LTD

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2217994
Cover Note Number	

Driver

Name of Driver	TAN JIANHUI
NRIC No	S8233973F
Address	BLK 540 HOUGANG AVE 8 #02-1229

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	1

Circumstances of Accident

VEHICLE A WAS TRAVELLING ALONG PIE (TUAS) BEFORE UPPER THOMSON EXIT. DUE TO TRAFFIC, MY VEHICLE A CAME TO A COMPLETE STOP. SUDDENLY, VEHICLE B HAD COLLIDED ONTO THE REAR PORTION. I ALIGHT AND REALISED IT'S A 3 CARS CHIAN COLLISION WITH VEHICLE C INVOLVED BEHIND VEHICLE B.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLK37U
Vehicle Make/Model/Colour
Name of Driver
Insurance Company Name

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHA7875X
Vehicle Make/Model/Colour
Name of Driver
Insurance Company Name

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I Vehicle A was travelling along PIE(TUAS) before Upp Thomson Exit. ~~During~~ Due to traffic my Vehicle A have come to a complete stop. Suddenly Vehicle B have collided on to my rear partition. I shock and not realise it a 3 car chain collision with Vehicle C involved behind Vehicle B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Date & Time:

(SIA/MS Sketch) Form V3

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

12 10 hrs.
1/2/2009

LETTER OF UNDERTAKING

I/We, PLATINUM RENTALS PTB LTD, the owner of vehicle no. SL9 4762D

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handled by my/our preferred workshop PLATINUM AUTO SERVICES

Signed and Acknowledge by:



Print no. and signature of policyholder

Company Stamp

Date

01/02/2029

Platinum Rentals Pte Ltd

8 Kaki Bukit Avenue 4 #04-07 Premier @ Kaki Bukit Singapore 415875

Tel: (65) 6917 7880

Fax: (65) 6926 2686

Company Registration No. : 201701221K

COPY

VEHICLE RENTAL AGREEMENT (LIMOUSINE SERVICE)

REF. NO.: PR/2018/0066

AN AGREEMENT made on the **27 DECEMBER 2018** Between **PLATINUM RENTALS PTE LTD** (the Owner) a company incorporated in the Republic of Singapore and having its registered office at **8 KAKI BUKIT AVENUE 4 #04-07, PREMIER @ KAKI BUKIT SINGAPORE 415875** of the one part AND **MR. TAN JIANHUI** (the Hirer) residing at **APT BLK 540 HOUGANG AVENUE 8 #02-1229 SINGAPORE 530540** the other part.

THE SCHEDULE TO THIS AGREEMENT

I DESCRIPTION OF VEHICLE

- | | | |
|-----------------------|---|---------------------------------|
| (a) Model/Type | : | 1 Unit of NISSAN SLYPHY 1.6 CVT |
| (b) Accessories | : | BASIC |
| (c) Registered Number | : | SLG 4762 D |

II PERIOD OF RENT : Commencing from **27 DECEMBER 2018** to **29 SEPTEMBER 2026**

III DEPOSIT : **S\$ 500.00**

IV RENTAL AMOUNT : **S\$ 420.00 per week.**

V TERMS OF PAYMENTS

As stipulated in Clause No. 3.1 and 3.2 of the Term Rental Agreement unless otherwise stated.

VI INSURANCE

Comprehensive Coverage subjected to conditions and clauses as per schedule 2.

- | | |
|---------------------------------|--|
| COLLISION DAMAGE WAIVER (CDW) : | Not Applicable |
| Unwaiverable Excess : | For Singapore Usage |
| | - 3 RD Party Damage S\$ 2,000.00 excess |
| | - Own Damage S\$ 2,000.00 excess / Self (Pay by Hirer) |
| | For Malaysia (Johor Bahru only) Usage |
| | - 3 RD Party Damage S\$ 3,500.00 excess |
| | - Own Damage S\$ 3,500.00 excess / Self (Pay by Hirer) |

AGREED BY :
PLATINUM RENTALS PTE LTD (Owner)

MR. TAN JIANHUI (Hirer)

BENNY LAI

NRIC No.: SB233973F

Platinum Rentals Pte Ltd

INCORPORATION IN THE REPUBLIC OF SINGAPORE

8 Kaki Bukit Avenue 4 #04-07
Premier @ Kaki Bukit Singapore 415875
Tel: (65) 6917 7880 Fax: (65) 6926 2686

Our Ref No. : PR/2018/0066
Date : 27 DECEMBER 2018

MR. TAN JIANHUI
APT BLK 540 HOUGANG AVENUE 8
#02-1229 SINGAPORE 530540

Dear Sir/Mdm,

Re: Rental of One Unit NISSAN SLYPHY 1.6 CVT for the period commencing 27 DECEMBER 2018 to 29 SEPTEMBER 2026

As per our discussion, we are pleased to confirm the following: -

Make & Model : 1 Unit of NISSAN SLYPHY 1.6 CVT
Weekly Charges : S\$ 420.00 per week.

The above package is inclusive of: -

- a. Unlimited mileage (for Singapore usage)
- b. Road tax and radio license
- c. Insurance coverage with an excess of S\$ 2000.00 (for Singapore Usage) for each and every damage and/or accident during the period of rent. Excess shall be doubled for any driver's age less than 26 years old, and/or driving license not more than 2 years. The vehicle shall not be permitted to be driven by any person with age less than 25 years old.
- d. Radio cassette/CD player
- e. Regular vehicle maintenance at every 10,000KM mileage interval (Monitor By Hirer) at:
PLATINUM TYRES & BATTERIES (8 KAKI BUKIT AVENUE 4 #03-36 PREMIER @ KAKI BUKIT 5415875)
- f. 24/7 vehicle breakdown support.
- g. Loss-of-Use Rental Waiver:
 - Half (0.5) Day Rental Deduction for between Eight (8) to twelve (12) hours of Downtime
 - Full Day Rental Deduction for more than twelve (12) hours of Downtime

But excludes: -

- h. Maintenance (Due to Driver's Negligence)
- i. Petrol
- j. Traffic offence fines and summons
- k. ERP (Electronic Road Pricing) and parking charges
- l. Tyre puncture and any cost related to tyre puncture (i.e. Towing, Replacement of Tyre, etc.)

Accident Sketch Plan Pg. 1

Based on the contract, upon confirmation of the agreement, there will be: -

1. Restricted Driver is applied for this rental. Hirer will be required to furnish additional Named Driver's Details
2. Cash/Cheque is acceptable for all payments. One Thousand (S\$ 1000.00) security deposit and 1-week rental premium will be required, upon signing of this confirmation.
3. The (Hirer) shall be charged the rental fee as set out in clause IV to this Agreement (the "[Rental Fee]").
4. PLATINUM RENTALS PTE LTD reserves the Right to Repossess the Rental Vehicle in whichever way the company deems fit if the Outstanding Rental amount is more than two (2) weeks. In addition, the Hirer will have to bear all the Recovery Costs incurred. The Security Deposit will also be forfeited.
5. Spray Painting Charges Damage incurred by Hirer will not be more than:
 - 5a. SGD \$130 per panel for Japanese & Korean makes;
 - 5b. SGD \$180 per panel for Continental makes;
 - 5c. SGD \$130 per bonnet for Japanese & Korean makes;
 - 5d. SGD \$180 per bonnet for Continental makes
6. For termination of contract, which would have to be incurred by the said Hirer at any point during the rental period, a penalty clause of full rental premium of remaining period will be chargeable to Hirer. All penalties mentioned do not include the Security Deposit.
7. Deposit shall be refunded two (2) weeks after return of vehicle, subject to clearance of summons and traffic offences.
8. The Hirer or the Owner reserves the Rights to terminate this Rental Agreement by giving One (1) Month Notice either by verbal/written.

We trust the above terms and conditions have meet your kind approval and we look forward to be of service to you.

Yours Faithfully,

Accepted By,

PLATINUM RENTALS PTE LTD (Owner)

MR. TAN JIANHUI (Hirer)

BENNY LAI

NRIC No.: S8233973F

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



TAX INVOICE

Our Ref No: GR-19-071712

Date of Request: 07/05/2019

Your Ref No: 21383

ARIDAS & ASSOCIATES
75 Bukit Timah Road #03-13
Boon Siew Building
Singapore 229833

Dear Sir/Madam,

Date of Accident: 31/01/2019

Vehicle No: SLK37U

Place of Accident: PIE TWDS TUAS NEAR UPP THOMSON RD EXIT

Involving Vehicle No: SLG4762D

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLG4762D	PIE TWDS TUAS NEAR UPP THOMSON RD EXIT	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

SEARCH RESULTS

Our Ref No: GR-19-071707
Date of Request: 07/05/2019

ARIDAS & ASSOCIATES
75 Bukit Timah Road #03-13
Boon Siew Building
Singapore 229833

Your Ref No: 21383

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 31/01/2019
Place of Accident: PIE TWDS TUAS UPP THOMSON EXIT
Client Vehicle No: SLK37U

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SLG4762D	PIE (TUAS) BEFORE UPP THOMSON EXIT	31/01/2019 15:40

Thank You,

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

^

TAX INVOICE

Our Ref No: GR-19-071707
Date of Request: 07/05/2019

Your Ref No: 21383

ARIDAS & ASSOCIATES
75 Bukit Timah Road #03-13
Boon Siew Building
Singapore 229833

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 31/01/2019
Place of Accident: PIE TWDS TUAS UPP THOMSON EXIT
Client Vehicle No: SLK37U

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	
GST Amount	14.02
Total Amount Due (GST Inclusive)	0.98
	15.00

Thank You,

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ G/RO ☐ Cash ☐ Cheque

159 TICK HAI MOTOR

1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 417883

TEL: 68429089 FAX: 68412869

Reg No :53033608A

Date: 28 March 2019


Yew Swee Fong
37 Sunbird Avenue
Singapore 487347

FINAL REPAIR BILL FOR VEHICLE NO SLK37U

To repair the above mentioned vehicle at a lump sum of \$ 39,390.00

Total : \$ 39,390.00

(Singapore dollars: Thirty-Nine Thousand Three Hundred and Ninety only)



RECEIVED
DATE: 2/5/19 3.38p.m.



SLK374

Invoice

YEW SWEE FONG
37 SUNBIRD AVENUE
S(487347)

Invoice No : GPLIN0001221
Invoice Date : 15/3/2019
Due Date : 15/3/2019
VHA No : 1396
Referral ID : T010

Description :	Amount
Rental for 41 Day/s @ \$180 per Day \$	7,380.00

Vehicle No : SLZ4239Z

Vehicle Description : Mazda 6

Rental Period : 01/02/2019 to 14/03/2019

Total Amount Payable : \$ 7,380.00

RECEIVED
DATE: 3/5/19 3.38 p.m



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529690)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasves@hotmail.com

Business Reg 2014044340

Invoice Summary

Date : 08/02/2019

Bill To : M/s. 159 Tick Hai Motor

Address : 1 Kaki Bukit Ave 6
Autobay #01-20
Singapore 417883

Tel : 6747 4676

Fax: 6841 2869

Attn : Account Department

Invoice Summary of February 2019.

No.	Vehicle No.	Date of Inspect.	Type of Claim	Report No.	Invoice No.	Invoice Date.	Report Fee.
1	SLK37U	12/02/2019	Third Party Claim	PAS/TP/0040219	HA/1904-37	26/04/2019	\$ 1,750.00
Total:							\$ 1,750.00

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.

For PROMINENT APPRAISER SERVICES PTE LTD



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0040219

Date of Report : 26/04/2019

To : Mr Yew Swee Fong
C/o. 1 Kaki Bukit Ave 6
Autobay #01-20
Singapore 417883

Date of Assignment : 12/02/2019
Report requested by : Mr Yew Swee Fong
Date of Accident : 31/01/2019
Date of Inspection : 12/02/2019
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SLK37U
Make & Model : BMW 430i Convertible
Date of Registration : 28/06/2017
Colour : Met. Black

Engine Capacity (cc) : 1998cc
Mileage (km) : 25242km
Chassis / Frame No. : WBA4V32030EA25530
Engine No. : F6131700B48B20B

TYRE CONDITION

Front LH : 5 mm
Make : Pirelli

Front RH : 5 mm
Make : Pirelli

Rear LH : 5 mm
Make : Pirelli

Rear RH : 5 mm
Make : Pirelli

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. 159 Tick Hai Motor
1, Kaki Bukit Ave 6, Autobay @ Kaki Bukit, #01-20, Singapore 417883

ASSESSMENT

Repairer's Estimate : \$ 53,016.08
Revised Amount : \$ 46,338.99
Less Excess : \$ -
Recommended Reserve : \$ 39,390.00 (Lump Sum)

Estimated Normal Period of Repairs : 32 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simexi St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No : SLK37U

Report No. : PAS/TP/0040219

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. 159 Tick Hai Motor, 1, Kaki Bukit Ave 6, Autobay @ Kaki Bukit, #01-20, Singapore 417883.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the front and rear portions.

DAMAGES

The bonnet, front support panels, front chassis members, front bumper, front fenders, headlamps, radiator assy, intercooler assy, front grilles, boot lid, rear bumper, rear end panel, rear floor panels, rear chassis members, rear fenders, amplifier sound system, active sound system control unit, rear roof retractable mechanisms, center exhaust pipe, rear exhaust muffler, taillamps, rear reflectors, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$46,338.99.

CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$39,390.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,
Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No.: SLK37U

Report No.: PAS/TP/0040219

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Repairer's Estimate (\$S)	Our Assessment (\$S)
1	1 pc	Bonnet	Dented/Distorted		\$ 1,405.70	\$ 1,405.70 X
2	2 pcs	Bonnet hinge R/L	Bent/Repair	\$ 82.40	\$ 164.80	\$ - X
3	2 pcs	Bonnet lock R/L	Dented/Jammed	\$ 98.80	\$ 197.60	\$ 197.60 ✓
4	1 pc	Bonnet seal	Torn/Necessary		\$ 32.20	\$ 32.20 X
5	2 pcs	Headlamp (Adaptive LED) R/L	Cracked/Broken	\$ 3,105.40	\$ 6,210.80	\$ 6,210.80 ✓
6	2 pcs	Frt grille R/L	Dented/Cracked	\$ 133.20	\$ 266.40	\$ 266.40 ✓
7	1 pc	Frt bumper (M/sport)	Dented/Damaged		\$ 1,427.80	\$ 1,427.80 ✓
8	1 pc	Frt bumper emblem	Cracked/Necessary		\$ 80.10	\$ 80.10 ✓
9	1 pc	Frt bumper tow cover	Dented/Cracked		\$ 48.60	\$ 48.60 ✓
10	4 pcs	Frt bumper PDC sensor	Dented/Damaged	\$ 382.60	\$ 1,530.40	\$ 765.20 2pc ✓
11	4 pcs	Frt bumper PDC sensor seal	Necessary	\$ 6.20	\$ 24.80	\$ 24.80 ✓
12	1 pc	Frt bumper PDC wireharness	Torn/Repair		\$ 77.90	\$ - X
13	1 pc	Frt bumper center grille	Dented/Cracked		\$ 102.30	\$ 102.30 ✓
14	2 pcs	Frt bumper fog lamp grille R/L	Loop Broken/Cracked	\$ 76.90	\$ 153.80	\$ 153.80 ✓
15	2 pcs	Frt bumper fog lamp R/L	Cracked	\$ 450.70	\$ 901.40	\$ 901.40 ✓
16	2 pcs	Frt bumper fog lamp support R/L	Cracked	\$ 43.30	\$ 86.60	\$ 86.60 ✓
17	1 pc	Frt bumper absorber	Dented/Cracked		\$ 80.10	\$ 80.10 ✓
18	1 pc	Frt bumper carrier	Dented		\$ 482.30	\$ 482.30 ✓
19	2 pcs	Frt bumper carrier bracket R/L	Dented/Bent	\$ 132.70	\$ 265.40	\$ 265.40 ✓
20	1 pc	Frt bumper beam	Dented		\$ 287.60	\$ 287.60 ✓
21	2 pcs	Frt bumper beam bracket R/L	Dented/Bent	\$ 95.30	\$ 190.60	\$ 190.60 ✓
22	1 pc	Radiator air duct	Dented/Cracked		\$ 106.20	\$ 106.20 ✓
23	1 pc	Radiator bottom air duct	Dented/Cracked		\$ 97.60	\$ 97.60 ✓
24	2 pcs	Radiator brake air duct R/L	Refit	\$ 59.50	\$ 119.00	\$ - X
25	1 pc	Frt support panel	Dented		\$ 257.30	\$ 257.30 X
26	2 pcs	Frt support side panel R/L	LH Dented/Repair	\$ 304.00	\$ 608.00	\$ 304.00 X
27	2 pcs	Frt bonnet lock support R/L	Dented/Bent	\$ 75.60	\$ 151.20	\$ 151.20 X
28	2 pcs	Frt lock bracket R/L	Dented/Bent	\$ 26.40	\$ 52.80	\$ 52.80 ✓
29	1 pc	Frt V-brace	Dented/Bent		\$ 153.80	\$ 153.80 ✓
30	2 pcs	Frt end brace R/L	Dented/Bent	\$ 72.10	\$ 144.20	\$ 144.20 ✓
31	1 pc	Frt diagonal brace	Dented/Bent		\$ 116.70	\$ 116.70 ✓
32	1 pc	Intercooler assy	Dented/Bent		\$ 810.40	\$ 810.40 X
33	1 pc	Radiator assy	Dented/Bent		\$ 842.70	\$ 842.70 X
34	1 pc	Radiator top support	Cracked/Broken		\$ 85.60	\$ 85.60 X
35	2 pcs	Radiator side support R/L	Cracked/Broken	\$ 92.20	\$ 184.40	\$ 184.40 ✓
36	1 pc	Radiator cooling assy	Refit		\$ 955.70	\$ - X
37	1 pc	Frt phone antenna	Dented/Damaged		\$ 126.30	\$ 126.30 ✓
38	1 pc	Boot lid	Dented		\$ 1,388.50	\$ 1,388.50 ✓
39	2 pcs	Boot hinge R/L	Bent	\$ 31.60	\$ 63.20	\$ 63.20 ✓
40	2 pcs	Boot hinge stay R/L	Refit	\$ 128.20	\$ 256.40	\$ - X
41	1 pc	Boot 3rd brake lamp	Cracked		\$ 253.10	\$ 253.10 ✓
42	1 pc	Boot emblem (Logo)	Cracked/Necessary		\$ 80.10	\$ 80.10 ✓
43	1 pc	Boot emblem (430i)	Necessary		\$ 72.90	\$ 72.90 ✓
44	2 pcs	Boot reflector R/L	Broken/Cracked	\$ 401.40	\$ 802.80	\$ 802.80 ✓
45	2 pcs	Boot reflector inner cover R/L	LH Cracked	\$ 45.90	\$ 91.80	\$ 45.90 1pc
					\$ 21,837.90	\$ 19,149.00



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No.: SLK37U

Report No.: PAS/TP/0040219

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
				\$ 21,837.90	\$ 19,149.00
46	1 pc	Boot weatherstrip	Torn/Necessary	\$ 142.90	\$ 142.90 ✓
47	2 pcs	Boot no.plate lamp R/L	Cracked	\$ 106.40	\$ 106.40 ✓
48	1 pc	Boot lock switch	Dented/Cracked	\$ 54.40	\$ 54.40 ✓
49	1 pc	Boot reverse camera	Dented/Damaged	\$ 784.90	\$ 784.90 ✓
50	1 pc	Boot lock (w/control system)	Dented/Jammed	\$ 1,041.60	\$ 1,041.60 ✓
51	1 pc	Boot inner trim	Torn/Deformed	\$ 123.20	\$ 123.20 ✓
52	2 pcs	Taillamp R/L	Broken/Cracked	\$ 573.40	\$ 1,146.80 ✓
53	2 pcs	Taillamp drip rail R/L	LH Cracked	\$ 55.60	\$ 55.60 ✓
54	1 pc	Rr bumper (M/sport)	Dented	\$ 1,457.10	\$ 1,457.10 ✓
55	1 pc	Rr bumper tow cover	Dented/Cracked	\$ 48.60	\$ 48.60 ✓
56	2 pcs	Rr bumper reflector R/L	Cracked/Broken	\$ 39.20	\$ 78.40 ✓
57	1 pc	Rr bumper lower trim	Dented/Cracked	\$ 244.90	\$ 244.90 ✓
58	4 pcs	Rr bumper PDC sensor	Dented/Damaged	\$ 382.60	\$ 1,530.40 3pcs ✓
59	4 pcs	Rr bumper PDC sensor seal	Necessary	\$ 6.20	\$ 24.80 ✓
60	1 pc	Rr bumper center guide	Dented/Cracked	\$ 82.70	\$ 82.70 ✓
61	1 pc	Rr bumper adapter	Dented/Cracked	\$ 92.40	\$ 92.40 ✓
62	2 pcs	Rr bumper side guide R/L	Cracked/Necessary	\$ 72.60	\$ 145.20 ✓
63	1 pc	Rr bumper carrier	Dented	\$ 498.30	\$ 498.30 ✓
64	1 pc	Rr underbody cover LH	Cracked/Deformed	\$ 73.80	\$ 73.80 ✓
65	1 pc	Rr end panel	Dented	\$ 689.70	\$ 689.70 ✓
66	1 pc	Rr end panel garnish	Dented/Cracked	\$ 92.80	\$ 92.80 ✓
67	1 pc	Rr floor trim cover	Serviceable	\$ 499.30	\$ - ✓
68	1 pc	Rr compartment sponge tray	Dented/Cracked	\$ 95.10	\$ 95.10 ✓
69	1 pc	Rr floor panel	Dented/Distorted	\$ 320.40	\$ 320.40 ✓
70	1 pc	Rr floor panel insulator	Affected/Necessary	\$ 81.70	\$ 81.70 ✓
71	1 pc	Rr floor compartment panel	Dented/Distorted	\$ 476.40	\$ 476.40 ✓
72	1 pc	Rr exhaust muffler	Dented/Bent	\$ 1,206.30	\$ 1,206.30 ✓
73	2 pcs	Rr exhaust muffler pipe trim R/L	Dented	\$ 136.00	\$ 272.00 ✓
74	1 pc	Rr exhaust muffler actuator	Damaged	\$ 187.40	\$ 187.40 ✓
75	2 pcs	Rr exhaust mounting	Torn	\$ 28.00	\$ 56.00 ✓
76	1 pc	Center exhaust pipe	Dented/Bent	\$ 1,283.40	\$ 1,283.40 ✓
77	1 pc	Rr exhaust heat shield top	Dented/Cracked	\$ 41.20	\$ 41.20 ✓
78	1 pc	Rr exhaust heat shield rr	Dented/Cracked	\$ 76.40	\$ 76.40 ✓
79	1 pc	Rr exhaust heat shield LH	Dented	\$ 32.10	\$ 32.10 ✓
80	2 pcs	Rr fender R/L	LH Dented/Distorted	\$ 1,757.20	\$ 3,514.40 ✓
81	1 pc	Rr fender air vent LH	Cracked	\$ 42.70	\$ 42.70 ✓
82	2 pcs	Rr fender cowling R/L	LH Torn/Deformed	\$ 160.70	\$ 321.40 ✓
83	2 pcs	Rr fender inner trim R/L	Torn/Deformed	\$ 185.40	\$ 370.80 ✓
84	2 pcs	Rr roof retractable mechanism R/L	Bent/Distorted	\$ 1,326.80	\$ 2,653.60 ✓
85	1 pc	Active sound system control unit	Dented/Damaged	\$ 628.20	\$ 628.20 ✓
86	1 pc	Amplifier sound system	Dented/Damaged	\$ 2,601.30	\$ 2,601.30 ✓
87	1 pc	Amplifier bracket	Dented/Bent	\$ 57.40	\$ 57.40 ✓
88	1 pc	Rr phone antenna	Dented/Damaged	\$ 126.30	\$ 126.30 ✓
89	1 pc	Rr comfort access antenna	Dented/Damaged	\$ 96.30	\$ 96.30 ✓
				\$ 45,448.50	\$ 39,904.20



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SLK37U

Report No. : PAS/TP/0040219

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
				\$ 45,448.50	\$ 39,904.20
90	1 pc	Frt support side panel RH	Dented/Repair		(Refer labour no. 5 & 6)
91	1 pc	Frt fender R/L	Dented/Repair		(Refer labour no. 5 & 6)
92	1 pc	Frt chassis member R/L	Dented/Repair		(Refer labour no. 5, 6 & 7)
93	1 pc	Rr fender RH	Dented/Repair		(Refer labour no. 12, 14 & 15)
94	1 pc	Rr chassis member R/L	Dented/Repair		(Refer labour no. 7, 12, 14 & 15)
				\$ 45,448.50	\$ 39,904.20
			Less Discount : 5%	\$ 2,272.43	5% \$ 1,995.21
			List Parts Sub-Total :	\$ 43,176.08	\$ 37,908.99
1	1 set	Frt no.plate (3D, w/bracket)	Dented/Cracked	S/N \$ 120.00	120.00 100
2	1 pc	Radiator coolant	Necessary	S/N \$ 80.00	80.00 X
3	1 set	Rr no.plate (3D, w/bracket)	Broken	S/N \$ 120.00	120.00 100
4	1 pc	Rr fender sealant	Necessary	S/N \$ 50.00	50.00 X
5	2 pcs	Rr floor panel sealant	Necessary	S/N \$ 100.00	100.00 X
			Special Nett Sub-Total :	\$ 470.00	\$ 420.00
			Parts Total :	\$ 43,646.08	\$ 38,328.99



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SLK37U

Report No. : PAS/TP/0040219

S/No.	Labour Descriptions	Repairer's Estimate (\$)	Our Assessment (\$)
1	To check front electrical system and calibrate/focus headlamp.	\$ 80.00 30	\$ 60.00
2	To remove, replace and/or transfer front PDC sensors to new bumper.	\$ 40.00	\$ 40.00 ✓
3	To remove, replace and reinstall radiator & cooling system. (Include pressure test cooling system)	\$ 120.00	\$ 100.00 ✓
4	To remove, replace and reinstall intercooler assy & pipings. (Include pressure test air intake system)	\$ 100.00 ^	\$ 80.00 X
5	To straighten, repair, realign on front affected area and replace damaged parts.	\$ 1,200.00 500	\$ 880.00
6	To spray painting, blending on front affected and adjacent area.	\$ 1,400.00 600	\$ 1,200.00
7	To conduct chassis alignments.	\$ 320.00 11	\$ 300.00 X
8	To check rear electrical wiring system.	\$ 80.00 30	\$ 50.00
9	To transfer boot component parts to new boot.	\$ 100.00	\$ 80.00 ✓
10	To remove, replace and/or transfer rear PDC sensors to new bumper.	\$ 40.00	\$ 40.00 ✓
11	To remove, replace and reinstall center exhaust and exhaust silencer.	\$ 120.00	\$ 120.00 ✓
12	To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs.	\$ 150.00 100	\$ 140.00
13	To remove and reinstall hardtop frames & retractable mechanisms for necessary repairs. To remove, replace and reinstall rear hardtop retractable mechanism & boot lock system.	\$ 1,500.00 400	\$ 1,200.00
14	To straighten, repair, realign on rear affected area and replace damaged parts.	\$ 2,000.00 1200	\$ 1,760.00
15	To spray painting, blending on rear affected and adjacent area.	\$ 1,500.00 1100	\$ 1,400.00
16	To spray anti-rust coating on new and affected panels.	\$ 150.00	\$ 120.00 ✓
17	To inspection, diagnose, reset and perform coding programming on:- 17.1) Front and Rear PDC sensor module. 17.2) Amplifier sound system. 17.3) ConnectedDrive & Phone antenna systems. 17.4) Hardtop convertible operating system. 17.5) Boot lock control system. 17.6) Rear comfort access system. 17.7) Driving stabilisation control module.	\$ 350.00	\$ 320.00 250
18	Towing.	\$ 120.00	\$ 120.00 ✓
Labour Total :		\$ 9,370.00	\$ 8,010.00

2030



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SLK37U

Report No. : PAS/TP/0040219

S/No. Labour Descriptions

Repairer's Our
Estimate (S\$) Assessment (S\$)

Total (Parts & Labour) : \$ 53,016.08 \$ 46,338.99

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 39,390.00

Under normal circumstances, the repairs should be completed within a reasonable period
of 32 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

60 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III19002557/Utd3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 12-06-2019



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7875X	Veh. Inspected	SLK 37U
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19010929	Excess (\$)	0.00
Assign From	STANLEY LAI	Assign Date	29/05/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 430I CONVERTIBLE (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBA4V32030EA25530	Colour	BLACK
Odometer	25242	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	PIRELLI	6 mm
L/H Front Tyre	225/45 R18	PIRELLI	6 mm
R/H Rear Tyre	225/45 R18	PIRELLI	6 mm
L/H Rear Tyre	225/45 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/01/2019	Inspection Date	12/02/2019
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	28 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 37U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	TO REPAIR SEE LABOUR	1,405.70	-
2	BONNET HINGE R/L @\$82.40	NOT NECESSARY	164.80	-
2	BONNET LOCK R/L @\$98.80	TWISTED	197.60	197.60
1	BONNET SEAL	NOT NECESSARY	32.20	-
2	HEADLAMP (ADAPTIVE LED) R/L @\$3105.40	CRACKED	6,210.80	6,210.80
2	FRT GRILLE R/L @\$133.20	CRACKED	266.40	266.40
1	FRT BUMPER (M/SPORT)	DENTED	1,427.80	1,427.80
1	FRT BUMPER EMBLEM	CRACKED	80.10	80.10
1	FRT BUMPER TOW COVER	DEFORMED	48.60	48.60
4	FRT BUMPER PDC SENSOR @\$382.60	SHORTED-2PCS ONLY	1,530.40	765.20
4	FRT BUMPER PDC SENSOR SEAL @\$6.20	NECESSARY	24.80	24.80
1	FRT BUMPER PDC WIREHARNES	NOT NECESSARY	77.90	-
1	FRT BUMPER CENTER GRILLE	CRACKED	102.30	102.30
2	FRT BUMPER FOG LAMP GRILLE R/L @\$76.90	CRACKED	153.80	153.80
2	FRT BUMPER FOG LAMP R/L @\$450.70	CRACKED	901.40	901.40
2	FRT BUMPER FOG LAMP SUPPORT R/L @\$43.30	CRACKED	86.60	86.60
1	FRT BUMPER ABSORBER	DENTED	80.10	80.10
1	FRT BUMPER CARRIER	BENT	482.30	482.30
2	FRT BUMPER CARRIER BRACKET R/L @\$132.70	BENT	265.40	265.40
1	FRT BUMPER BEAM	DENTED	287.60	287.60
2	FRT BUMPER BEAM BRACKET R/L @\$95.30	BENT	190.60	190.60
1	RADIATOR AIR DUCT	DEFORMED	106.20	106.20
1	RADIATOR BOTTOM AIR DUCT	CRACKED	97.60	97.60
2	RADIATOR BRAKE AIR DUCT R/L @\$59.50	NOT NECESSARY	119.00	-
1	FRT SUPPORT PANEL	TO REPAIR SEE LABOUR	257.30	-
2	FRT SUPPORT SIDE PANEL R/L @\$304.00	TO REPAIR SEE LABOUR	608.00	-
2	FRT BONNET LOCK SUPPORT R/L @\$75.60	NOT NECESSARY	151.20	-
2	FRT LOCK BRACKET R/L @\$26.40	BENT	52.80	52.80

Report Ref No. CS3/III19002557/Utd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT V-BRACE	BENT	153.80	153.80
2	FRT END BRACE R/L @\$72.10	BENT	144.20	144.20
1	FRT DIAGONAL BRACE	BENT	116.70	116.70
1	INTERCOOLER ASSY	NOT NECESSARY	810.40	-
1	RADIATOR ASSY	NOT NECESSARY	842.70	-
1	RADIATOR TOP SUPPORT	NOT NECESSARY	85.60	-
2	RADIATOR SIDE SUPPORT R/L @\$92.20	CRACKED	184.40	184.40
1	RADIATOR COOLING ASSY	NOT NECESSARY	955.70	-
1	FRT PHONE ANTENNA	DAMAGED	126.30	126.30
1	BOOT LID	DENTED	1,388.50	1,388.50
2	BOOT HINGE R/L @\$31.60	BENT	63.20	63.20
2	BOOT HINGE STAY R/L @\$128.20	NOT NECESSARY	256.40	-
1	BOOT 3RD BRAKE LAMP	CRACKED	253.10	253.10
1	BOOT EMBLEM (LOGO)	NECESSARY	80.10	80.10
1	BOOT EMBLEM (430I)	NECESSARY	72.90	72.90
2	BOOT REFLECTOR R/L @\$401.40	BROKEN / CRACKED	802.80	802.80
2	BOOT REFLECTOR INNER COVER R/L @\$45.90	N/S CUT	91.80	45.90
1	BOOT WEATHERSTRIP	TWISTED	142.90	142.90
2	BOOT NO. PLATE LAMP R/L @\$53.20	CRACKED	106.40	106.40
1	BOOT LOCK SWITCH	SHORTED	54.40	54.40
1	BOOT REVERSE CAMERA	SHORTED	784.90	784.90
1	BOOT LOCK (W/CONTROL SYSTEM)	DENTED / JAMMED	1,041.60	1,041.60
1	BOOT INNER TRIM	NOT NECESSARY	123.20	-
2	TAILLAMP R/L @\$573.40	BROKEN / CRACKED	1,146.80	1,146.80
2	TALLAMP DRIP RAIL R/L @\$55.60	N/S CUT	111.20	55.60
1	RR BUMPER (M/SPORT)	DISTORTED	1,457.10	1,457.10
1	RR BUMPER TOW COVER	TORN	48.60	48.60
2	RR BUMPER REFLECTOR R/L @\$39.20	CRACKED	78.40	78.40
1	RR BUMPER LOWER TRIM	DISTORTED	244.90	244.90
4	RR BUMPER PDC SENSOR @\$382.60	SHORTED-3PCS ONLY	1,530.40	1,147.80
4	RR BUMPER PDC SENSOR SEAL @\$6.20	NECESSARY	24.80	24.80

Report Ref No. CS3/III19002557/Utd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RR BUMPER CENTER GUIDE	CRACKED	82.70	82.70
1	RR BUMPER ADAPTER	CRACKED	92.40	92.40
2	RR BUMPER SIDE GUIDE R/L @\$72.60	CRACKED	145.20	145.20
1	RR BUMPER CARRIER	BENT	498.30	498.30
1	RR UNDERBODY COVER LH	DEFORMED	73.80	73.80
1	RR END PANEL	DENTED	689.70	689.70
1	RR END PANEL GARNISH	CRACKED	92.80	92.80
1	RR FLOOR TRIM COVER	NOT NECESSARY	499.30	-
1	RR COMPARTMENT SPONGE TRAY	CRACKED	95.10	95.10
1	RR FLOOR PANEL	TO REPAIR SEE LABOUR	320.40	-
1	RR FLOOR PANEL INSULATOR	NECESSARY	81.70	81.70
1	RR FLOOR COMPARTMENT PANEL	TO REPAIR SEE LABOUR	476.40	-
1	RR EXHAUST MUFFLER	DISTORTED	1,206.30	1,206.30
2	RR EXHAUST MUFFLER PIPE TRIM R/L @\$136.00	DENTED	272.00	272.00
1	RR EXHAUST MUFFLER ACTUATOR	DAMAGED	187.40	187.40
2	RR EXHAUST MOUNTING @\$28.00	TORN	56.00	56.00
1	CENTER EXHAUST PIPE	BENT	1,283.40	1,283.40
1	RR EXHAUST HEAT SHIELD TOP	DISTORTED	41.20	41.20
1	RR EXHAUST HEAT SHIELD RR	DISTORTED	76.40	76.40
1	RR EXHAUST HEAT SHIELD LH	DISTORTED	32.10	32.10
2	RR FENDER R/L @\$1757.20	TO REPAIR SEE LABOUR	3,514.40	-
1	RR FENDER AIR VENT LH	CRACKED	42.70	42.70
2	RR FENDER COWLING R/L @\$160.70	N/S TORN	321.40	160.70
2	RR FENDER INNER TRIM R/L @\$185.40	NOT NECESSARY	370.80	-
2	RR ROOF RETRACTABLE MECHANISM R/L @\$1326.80	BENT	2,653.60	2,653.60
1	ACTIVE SOUND SYSTEM CONTROL UNIT	SHORTED	628.20	628.20
1	AMPLIFIER SOUND SYSTEM	SHORTED	2,601.30	1,880.00
1	AMPLIFIER BRACKET	SHORTED	57.40	57.40
1	RR PHONE ANTENNA	DAMAGED	126.30	126.30
1	RR COMFORT ACCESS ANTENNA	DAMAGED	96.30	96.30

Report Ref No. CS3/III19002557/Utd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT SUPPORT SIDE PANEL RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRT FENDER R/L (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRT CHASSIS MEMBER R/L (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR CHASSIS MEMBER R/L (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 5% DISCOUNT		-2,272.43	-1,612.29
			43,176.07	30,633.51
	SPECIAL NETT ITEMS			
1	SET FRT NO. PLATE (3D, W/BRACKET) (SN)	CRACKED	120.00	100.00
1	RADIATOR COOLANT (SN)	NOT NECESSARY	80.00	-
1	SET RR NO. PLATE (3D, W/BRACKET) (SN)	BROKEN	120.00	100.00
1	RR FENDER SEALANT (SN)	NOT NECESSARY	50.00	-
2	RR FLOOR PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
			470.00	200.00
	LABOUR			
	TO CHECK FRONT ELECTRICAL SYSTEM AND CALIBRATE / FOCUS HEADLAMP.		80.00	30.00
	TO REMOVE, REPLACE AND / OR TRANSFER FRONT PDC SENSORS TO NEW BUMPER.		40.00	40.00
	TO REMOVE, REPLACE AND REINSTALL RADIATOR & COOLING SYSTEM. (INCLUDE PRESSURE TEST COOLING SYSTEM)		120.00	100.00
	TO REMOVE, REPLACE AND REINSTALL INTERCOOLER ASSY & PIPINGS. (INCLUDE PRESSURE TEST AIR INTAKE SYSTEM)	NOT NECESSARY	100.00	-
	TO STRAIGHTEN, REPAIR, REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS.		1,200.00	500.00
	TO SPRAY PAINTING, BLENDING ON FRONT AFFECTED AND ADJACENT AREA.		1,400.00	600.00
	TO CONDUCT CHASSIS ALIGNMENTS.	NOT NECESSARY	320.00	-
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		80.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER BOOT COMPONENT PARTS TO NEW BOOT.		100.00	80.00
	TO REMOVE, REPLACE AND / OR TRANSFER REAR PDC SENSORS TO NEW BUMPER.		40.00	40.00
	TO REMOVE, REPLACE AND REINSTALL CENTER EXHAUST AND EXHAUST SILENCER.		120.00	120.00
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, SEATS, ETC. FOR NECESSARY REPAIRS.		150.00	100.00
	TO REMOVE AND REINSTALL HARDTOP FRAMES & RETRACTABLE MECHANISMS FOR NECESSARY REPAIRS. TO REMOVE, REPLACE AND REINSTALL REAR HARDTOP RETRACTABLE MECHANISM & BOOT LOCK SYSTEM.		1,500.00	400.00
	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF BONNET, FRT SUPPORT PANEL, FRT SUPPORT SIDE PANEL R/L, RR FLOOR PANEL, RR FLOOR COMPARTMENT PANEL, RR FENDER R/L, FRT SUPPORT SIDE PANEL RH, FRT FENDER R/L, FRT CHASSIS MEMBER R/L, RR FENDER RH AND RR CHASSIS MEMBER R/L.		2,000.00	1,200.00
	TO SPRAY PAINTING,BLENDING ON REAR AFFECTED AND ADJACENT AREA.		1,500.00	1,100.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		150.00	120.00
	TO INSPECTION, DIAGNOSE, RESET AND PERFORM CODING PROGRAMMING ON :- 17.1)FRONT AND REAR PDC SENSOR MODULE. 17.2)AMPLIFIER SOUND SYSTEM. 17.3)CONNECTEDDRIVE & PHONE ANTENNA SYSTEMS. 17.4)HARDTOP CONVERTIBLE OPERATING SYSTEM. 17.5)BOOT LOCK CONTROL SYSTEM. 17.6)REAR COMFORT ACCESS SYSTEM. 17.7) DRIVING STABILISATION CONTROL MODULE.		350.00	250.00
	TOWING.		120.00	120.00
			-	-
			-	-
			9,370.00	4,830.00
	GRAND TOTAL		53,016.07	35,663.51
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			28,500.00

Report Ref No. CS3/III19002557/Utd3e2-1



Report Ref No. CS3/III19002557/Utd3e2-1

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.