

ASS. REC. BY: _____ REF: CITPD19009627/NC Special Instruction: _____
Surveyor: _____ ASSIGNMENT (Office)
From (Person): Kamaliah Kanke of SPF Date/Time: 28/5/2019
Estimated Cost: _____ Bill to: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
To Inspect Vehicle No: FBK 4678 L Insured: _____
at Workshop m/s _____ Tel: _____
of _____
Policy No: MHASPF06000018978 Claim No: TP/1P/22027/2019
Sum Insured: _____ Excess: _____
Make of Veh: _____ D.O.A. 28/5/2019
(Client's Record)
CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____
Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
-----------	---------------------------------

	FBK 4678 L - X

45019

g) Case IAFP-IB-20190522 - Mechanical Inspection of Motorcycle, FBK4678L (TP/IP/32027/2019)

On 20 May 2019 at about 8.57 pm, the road traffic accident involved one motorcycle self-skidded, which occurred along ECP towards Airport. Due to the accident, the pillion (deceased) of the said motorcycle was reported to be in a conscious state, sustained neck injuries, broken tooth and had breathing difficulties. She was conveyed to Singapore General Hospital (SGH) by ambulance. The deceased condition deteriorated and she became unconscious due to loss of blood while at the hospital A&E. On the same day, she succumbed to her injuries and pronounced dead by doctor Khor Shao Nan on 21 May 2019 at 0112hrs.

Vehicle to be inspected: FBK4678L (Potential Defendant)

IO In-Charge: SIO Kamaliah

h) Case IAFP-IB-20190522 - Mechanical Inspection of Police Land Rover, GZ8901C (TP/IP/29777/2019)

On 9 May 2019 at about 0819 hrs, the said land rover was travelling straight along CTE (AYE), 5.7km on lane 4 of the 4-lanes road when he heard a weird sound coming from his land rover and the land rover suddenly slowed down. As the land rover was slowing down, the driver tried to drive at the road shoulder but he was unable to do so and at the same time, smokes were seen coming from the rear portion of the land rover. Moments later, the land rover was hit from the rear by an incoming motor car.

Vehicle to be inspected: GZ8901C (Potential Defendant)

IO In-Charge: SIO Kamaliah

2. These request has been approved by my management.
3. Thank you Sirs.

Cc: FAIT Team, IO Norameera & SIO Affendy, fyip

Best regards,

Kamaliah Kamis (Miss)
Senior Investigation Officer | Fatal Accident Investigation Team
Traffic Police Department | Singapore Police Force
DID: (65) 6547 6435 | FAX: (65) 6547 6352