



Your Ref: 18.24590

Date: 19th June 2019

Our Ref: CS1/LAW19009647/R1vd3s2

M/s Seah Ong & Partners LLP

36 Robinson Road
#12-03 City House
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SGS 1884B INSURED VEHICLE: SHC 5658J ACCIDENT DATE: 15/04/2017**

We thank you for your instruction on 28/03/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGS 1884B from M/s Sincere Appraisal Services.
- b) Survey report by FormTeam Consultancy Pte Ltd with colour photographs.
- c) Final Repair Bill of SGS 1884B from M/s Ah Chang Motor Service Centre.
- d) Singapore Accident Statement of Vehicles SGS 1884B and SHC 5658J.
- e) Colour damaged vehicle photographs of SGS 1884B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SGS 1884B
Make & Model	: Toyota Wish 1.8 A
Year of Registration	: 2007
Chassis Number	: ZNE100352156
Engine Capacity	: 1794 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.