

22/03/2019

ASS. REC. BY:

REF: CS/GAI/9009662/Eq d3b

Special Instruction:

Surveyor: Sharon Ng

ASSIGNMENT (Office)

From (Person): Sharon Ng

of

GAIDate/Time: 30/5/19 @ 6:59pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJY 5702A

Insured:

GY 7684R

at Workshop m/s

TC Auto clinic

Tel:

96450023

of

25 Leng Kee Road

Policy No:

Claim No:

CLMOMVC000007669

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 28/05/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:09am @ 31/05/19

Person Contacted:

Shawn

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	Have surveyor's comments whether the damage are consistent.
		<u>SJY 5702A - X</u>	
		<u>GY 7684R - NJA / AVS09001644 / Y1</u>	<u>DVA 31/01/2019</u>
<u>07/6/19 @ 3:26pm</u>	<u>visited to Sharon Ng by email.</u>		
<u>20/7/19 @ 8:20am</u>	<u>Shawn informed that they still awaiting liability issued from Ins</u>		
<u>30/7/19</u>	<u>submit Prelim. report.</u>		

29/8/19 Finalize Confir \$1838, 3 days (Shawn) (Red \$ 2138.04, 54%.)
29/8/19 Re-open ref. for submit from Report. (After re-open. please assist to pass the file to transit.) Before 29/8/19
2/11/19 reopen ref only * 1st DOZ 6/8/19 ↓

ASSIGNMENT

From: _____

Date: 6.6.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJY 5702Aat Workshop m/s TC Autoclinicof 25 Long Ke Rd

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: 200 - 4.00pm ONVR waiting

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
<u>X</u>	<u>X</u>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"rmp"

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJY 5702AYr Regn: 15/09/10Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Sylphyc.c. 1498Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 246983

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN 18AA 6112 0111 224Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 28/5/19D.O.I. 6/6/19Survey held at TC AutoclinicDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-20X

RECEIVED 30 JUL 2019

Date/Time, File Pass to?

1) 2019-07-01

Date/Time, File Return to?

2) _____

☒ : Preli. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 250Transportation: S + RS, SI

Photos

Others

TOTAL 250

Report Format : _____

Lump Sum / I.B.I: (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2205K
Vehicle Details	
Vehicle No.:	SJY5702A
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jun 2019
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	HR15390637B
Chassis No.:	JN1BAAG11Z0111224
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,230.00
Original Registration Date:	15 Sep 2010
First Registration Date:	15 Sep 2010
Transfer Count:	0
Actual ARF Paid:	\$17,230.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2020
PARF Rebate Amount:	\$9,476.00
Intended COE Rebate Details	
COE Expiry Date:	14 Sep 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$33,089.00
COE Rebate Amount:	\$4,209.00
Total Rebate Amount:	\$13,685.00

The information contained herein is correct as at 06 Jun 2019

OK

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 067/IC/TCAC/CCR/2019
DATE : 29-MAY-2019

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
S(039190)
TEL : 68046059
FAX : 62353354
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : NISSEI ASB PTE LTD
ADDRESS : 85 SCIENCE PARK DRIVE
#01-03 CAVENDISH, THE
S(118259)
TELEPHONE NO : 67784633/96206862

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100228380-08
VEHICLE NO : SJY5702A
MODEL CODE : BDUARCAG11EHA-----
MODEL/YEAR : SYLPHY 1.5 4A/T SEDAN (II)
ENGINE NO : HR15390637B
CHASSIS NO : JN18AAG11Z0111224
MILEAGE : 246752 KM
DATE IN : 29/05/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 28/05/2019

JC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJY5702A

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	/
2 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
3 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
4 ZZ/001	REPLACE REAR BUMPER & MOULDING, REAR UPPER PANEL STRIKER ETC. REPAIR PANELS	1560.00	585
5 ZZ/002	RESPRAY REAR BUMPER, REAR UPPER PANEL ETC	750.00	350
6 ZZ/003	QC, RETUNE & CONSULT CHECK		
7 ZZ/004	COMPLIMENTARY WASH & VACUUM		
	TOTAL LABOUR CHARGES	2585.00	

JC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJY5702A

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	REVERSE SENSOR ? HW	SENSOR-TE5140		180.00
2	ENERGY ABSORBER ? HW	85090-EW000	37.00	
3	RIGHT BUMPER STAY / OR	85212-AX010	43.30	
4	LEFT BUMPER STAY / OR	85213-AX010	43.30	
5	RIGHT BUMPER BRACKET X AN	85226-EW000	36.60	
6	LEFT BUMPER BRACKET X AN	85227-EW000	36.60	
7	REAR BUMPER CHROME MOULDING / REC	85072-EW000	162.80	
8	REAR BUMPER / 00	85022-EW025	660.60	
9	STRIKER ? HW	84621-ED40A	56.90	
10	REAR UPPER PANEL X R	79110-EW400	436.70	
SUB TOTAL			1513.80	0.00 180.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			302.76	0.00 0.00
GRAND TOTAL			1211.04	0.00 180.00
OVERALL TOTAL			1391.04	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJY5702A

TOTAL LABOUR CHARGES	2585.00
TOTAL SPARE PARTS CHARGES	1391.04
GRAND TOTAL	3976.04 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Steve (LKK) WIL include 6/6/19, 2:27pm
3 days
P/P
Ry bet spray

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 067/IC/TCAC/CCR/2019
DATE : 29-MAY-2019

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
S(039190)
TEL : 68046059
FAX : 62353354
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : NISSEI ASB PTE LTD
ADDRESS : 85 SCIENCE PARK DRIVE
#01-03 CAVENDISH, THE
S(118259)
TELEPHONE NO : 67784633/96206862

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100228380-08
VEHICLE NO : SJY5702A
MODEL CODE : BDUARCAG11EHA-----
MODEL/YEAR : SYLPHY 1.5 4A/T SEDAN (II)
ENGINE NO : HR15390637B
CHASSIS NO : JN1BAAG11Z0111224
MILEAGE : 246752 KM
DATE IN : 29/05/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 28/05/2019

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJY5702A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	120.00
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	55.00
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	.00
4	ZZ/001	REPLACE REAR BUMPER & MOULDING,BUMPER STAYS REPAIR REAR UPPER PANEL	1560.00	585.00
5	ZZ/002	RESPRAY REAR BUMPER,REAR UPPER PANEL	750.00	350.00
6	ZZ/003	QC, RETUNE & CONSULT CHECK		
7	ZZ/004	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			2585.00	1110.00

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJY5702A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	STRIKER	84621-ED40A	56.90			X
2	RIGHT BUMPER BRACKET	85226-EW000	36.60			X
3	REVERSE SENSOR	SENSOR-TE5140			180.00	X
4	ENERGY ABSORBER	85090-EW000	37.00			X
5	RIGHT BUMPER STAY	85212-AX010	43.30			OK
6	LEFT BUMPER STAY	85213-AX010	43.30			OK
7	LEFT BUMPER BRACKET	85227-EW000	36.60			X
8	REAR BUMPER CHROME MOULDING	85072-EW000	162.80			OK
9	REAR BUMPER	85022-EW025	660.60			OK
10	REAR UPPER PANEL	79110-EW400	436.70			X
SUB TOTAL			910.00	0.00	0.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			182.00	0.00	0.00	
GRAND TOTAL			728.00	0.00	0.00	
OVERALL TOTAL			728.00			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SJY5702A

NETT ITEM	910.00
LESS 20.00%)	-182.00
NETT AMOUNT	728.00

LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	0.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	0.00

TOTAL LABOUR CHARGES	1110.00
TOTAL SPARE PARTS CHARGES	728.00

TOTAL CHARGES	1838.00
ADD 7 % GST	128.66

GRAND TOTAL	1966.66
-------------	---------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 5702A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	ENERGY ABSORBER (N)	NOT NECESSARY	37.00	-
1	RIGHT BUMPER STAY (N)	BROKEN	43.30	43.30
1	LEFT BUMPER STAY (N)	BROKEN	43.30	43.30
1	RIGHT BUMPER BRACKET (N)	NOT NECESSARY	36.60	-
1	LEFT BUMPER BRACKET (N)	NOT NECESSARY	36.60	-
1	REAR BUMPER CHROME MOULDING (N)	NECESSARY	162.80	162.80
1	REAR BUMPER (N)	DENTED	660.60	660.60
1	STRIKER (N)	NOT NECESSARY	56.90	-
1	REAR UPPER PANEL (N)	TO REPAIR SEE LABOUR	436.70	-
	LESS 20% DISCOUNT		-302.76	-182.00
			1,211.04	728.00
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	NOT NECESSARY	180.00	-
			180.00	-
LABOUR				
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.		120.00	120.00
	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST.		55.00	55.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	NOT NECESSARY	100.00	-
	REPLACE REAR BUMPER & MOULDING, REAR UPPER PANEL, STRIKER ETC. REPAIR PANELS. INCLUSIVE OF THE REPAIR OF REAR UPPER PANEL.		1,560.00	585.00
	RESPRAY REAR BUMPER, REAR UPPER PANEL ETC.		750.00	350.00
			-	-
			-	-
			2,585.00	1,110.00
GRAND TOTAL			3,976.04	1,838.00
RECOMMENDED COST OF REPAIRS				1,838.00

Report Ref No. CS/GAI19009662/Eqd3e2



Report Ref No. CS/GAI19009662/Eqd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.