

22/03/2019

ASS. REC. BY:

REF:

CS/GAI19009662/Eq d3m

Special Instruction:

Surveyor: Sharon Ng

ASSIGNMENT (Office)

From (Person):

Sharon Ng

of

GAI

Date/Time:

30/5/19 @ 6.59pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SY 5702A

Insured:

GY 7684R

at Workshop m/s

1c Autoclinic

Tel:

96450023

of

25 Leng Kee Road

Policy No:

Claim No:

CLMOMVC000007669

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/05/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10.09am @ 31/05/19

Person Contacted:

Sharon

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate	Have surveyor's comments whether the damage are consistent.
	SY 5702A - X		
	GY 7684R - N/A / AKIO9001644 / Y /		D.O.A: 31/01/2019
07/6/19 @	3.26pm	revised to Sharon Ng by email.	
30/7/19 @	8.20am	Sharon informed that they still awaiting liability moved from Ins	
30/7/19	Submit Prelim. Report.		

GAI

[illegible]

Nivitha (LKK Auto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Thursday, 30 May 2019 6:59 PM
To: SUR
Cc: assignments
Subject: FW: Accident Involving SJY5702A & GY7684R On 28/05/19
Attachments: SJY5702A GIA Report.PDF; Estimate Before Survey.pdf; GY7684R (OI).PDF

Hi LKK team

Please make arrangement with repairer for the TP survey. Kindly let us have your surveyors' comments whether the damages are consistent.

Thanks and Regards

Sharon Ng, Assistant Manager | Claims, P&C | P. +65 6804 7845 | F. +65 6235 3354 | sharon.ng@sg.gaig.com



Claims Division | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Tan, Rachel <Rachel.Tan@sg.gaig.com> **On Behalf Of** General Claims
Sent: Thursday, May 30, 2019 1:40 PM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Subject: FW: Accident Involving SJY5702A & GY7684R On 28/05/19

Hi Sharon

Please assist. Thank you.

From: Shawn Chua <shawnychua@tanchong.com>
Sent: 30 May 2019 12:50 PM
To: General Claims <GeneralClaims@sg.gaig.com>
Cc: Kelvin Heng <kelvinheng@tanchong.com>
Subject: [External] Accident Involving SJY5702A & GY7684R On 28/05/19

Dear Sir/Madam,

Our customer holds your insured driver, **GY7684R** liable for the accident on **28/05/19** and would like to claim against your insured driver. We hereby inquire whether you would like to have a direct settlement with our claimant, **SJY5702A**.

If you minded to reach an amicable direct settlement with our customer, please let us have your substantive reply strictly by **04/06/19**. Otherwise our customer will proceed in a manner that he deems fit.

Kindly let me know when I can arrange for an accident survey.

Attached herewith the **GIA Report** and **estimate of repair cost** for **SJY5702A**.

Shawn Chua
Service Executive
TC AutoClinic Pte Ltd
25 Leng Kee Road
Singapore 159097
DID: +65 67038515
HP: +65 96450023
Fax: +65 64795019



The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shiau Chan (LKKAuto)

From: Shawn Chua <shawnychua@tanchong.com>
Sent: Tuesday, 30 July 2019 8:20 AM
To: Shiau Chan (LKKAuto)
Subject: RE: FINALISE OF TP VEHICLE SJY 5702A (DOA: 28/05/2019)

Good morning.

Great American has not got back to me with regards to SJY5702A liability.

Shawn Chua
Service Executive
TC AutoClinic Pte Ltd
25 Leng Kee Road
Singapore 159097
DID: +65 67038515
HP: +65 96450023
Fax: +65 64795019



From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Monday, July 29, 2019 3:27 PM
To: Shawn Chua <shawnychua@tanchong.com>
Subject: FINALISE OF TP VEHICLE SJY 5702A (DOA: 28/05/2019)

Dear Shawn,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 7 June 2019 3:26 PM
To: Ng, Sharon; SUR
Cc: assignments
Subject: RE: Accident Involving SJY5702A & GY7684R On 28/05/19 || Our ref: CLMOMVC000003669
Attachments: CSGAI19009662Eqd3.pdf

Dear Sharon,

Enclosed herewith preliminary advice of SJY 5702A.
Damages consistent.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Friday, 7 June 2019 11:03 AM
To: SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: Accident Involving SJY5702A & GY7684R On 28/05/19 || Our ref: CLMOMVC000003669

Dear Steve

Based on your assessment, please comment whether the damages sustained to SJY5720A was indeed caused by GY7684R (OI). OI was unsure if the damages was caused by his driver. TP only discovered damages on the following day.

Thanks and Regards

Sharon Ng, Assistant Manager | Claims, P&C | P. +65 6804 7845 | F. +65 6235 3354 | sharon.ng@sg.gaig.com



Claims Division | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GY 7684R

Date: 07 June 2019

Our Ref: CS/GAI19009662/Eqd3

The Motor Claims Department
Great American Insurance Company

Attn: Sharon

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SJY 5702A .

We thank you for the instruction on 30/05/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/06/2019 at the premises of M/s TC AUTOCLINIC and have the following to report:-

Workshop Estimate Amount	: S\$	<u>3,976.04</u>	.
Revised Estimate Amount	: S\$	<u>1,838.00</u>	.
"Check" Items Amount	: S\$	<u>255.12</u>	.
Market Value	: S\$	<u>-</u>	.
Salvage Value	: S\$	<u>-</u>	.
Nett Value	: S\$	<u>-</u>	.

Description of Damage:
The vehicle sustained damages at the rear portion.



Comments/ Present Status:
Damages consistent.
Recommend days of repair: 3 days.
We have NOT authorise repair.

Yours faithfully

Steve
Automotive Assessor

Shiau Chan (LKKAuto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Friday, 7 June 2019 11:03 AM
To: SUR
Cc: assignments
Subject: RE: Accident Involving SJY5702A & GY7684R On 28/05/19 || Our ref: CLMOMVC000003669

Dear Steve

Based on your assessment, please comment whether the damages sustained to SJY5720A was indeed caused by GY7684R (OI). OI was unsure if the damages was caused by his driver. TP only discovered damages on the following day.

Thanks and Regards

Sharon Ng, Assistant Manager | Claims, P&C | P. +65 6804 7845 | F. +65 6235 3354 | sharon.ng@sg.gaig.com



Claims Division | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Ng, Sharon
Sent: Thursday, May 30, 2019 6:59 PM
To: SUR <sur@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>
Subject: FW: Accident Involving SJY5702A & GY7684R On 28/05/19

Hi LKK team

Please make arrangement with repairer for the TP survey. Kindly let us have your surveyors' comments whether the damages are consistent.

Thanks and Regards

Sharon Ng, Assistant Manager | Claims, P&C | P. +65 6804 7845 | F. +65 6235 3354 | sharon.ng@sg.gaig.com

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2205K
Vehicle Details	
Vehicle No.:	SJY5702A
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jun 2019
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	HR15390637B
Chassis No.:	JN1BAAG11Z0111224
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,230.00
Original Registration Date:	15 Sep 2010
First Registration Date:	15 Sep 2010
Transfer Count:	0
Actual ARF Paid:	\$17,230.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2020
PARF Rebate Amount:	\$9,476.00
Intended COE Rebate Details	
COE Expiry Date:	14 Sep 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$33,089.00
COE Rebate Amount:	\$4,209.00
Total Rebate Amount:	\$13,685.00

The information contained herein is correct as at 06 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	29/05/2019 16:40
Date Of Accident	28/05/2019 19:45
Exact Location Of Accident	JLN AHMAD IBRAHIM TURNING RIGHT TO JLN BOON LAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJY5702A
Insured/Policyholder	
Name Of Registered Owner	NISSEI ASB PTE LTD
Co Reg No	199302205K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67784633
Vehicle Particulars	
Manufacturer	NISSAN
Model	SYLPHY-1.5 4AT ABS D/AB 2WD 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100228380-08
Cover Note Number	15/09/2018 - 14/09/2019
Driver	
Name of Driver	KOH KWEE FONG
NRIC No	S1642303C
Date Of Birth	09/09/1964
Occupation	INDOOR
Date Of Driving Pass	03/05/1991
Driving Experience	28 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97816328
Fax Number	
Contact Number	
EEmail Address	KAREN@NISSEIASB.COM.SG

Address	BLK 661D #11-448 JURONG WEST ST 64
Postcode	S644661
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to attached sketch plan

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY7684R
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MAHENDRAN
NRIC/Passport Number	
Contact Number	91338412
Address	
Postcode	
Insurance Company Name	GREAT AMERICAN INSURANCE COMPANY
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attached

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE** within the stipulated time frame from the day of the occurrence.

	- Reporting Only
	- Claim OD
	- Claim TP
	- Claim OD/ TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.



Policyholder's signature
Date & Time

Driver's Signature (on behalf of
(if driver not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
Nric/Fin No.



Sketch Plan Pg. 2

29th May 2019

To whom it may concern

Accident at Jurong Bird Park traffic junction at about 7.45pm, 28th May 2019 (Tuesday) for car no GY7684R vs SJY5702A

On 28th May 2019 at about 7.45pm, I was waiting at Jurong Bird Park traffic light junction for green light to turn right to Jalan Boon Lay.


While I am about to drive off when the green light turn green, I heard a sound at the back of the car and felt the car jerked.

I carried on with my turning as I did not want to obstruct traffic. I stopped at the first bus stop after turning right. A pickup with plate no GY7684R stopped behind me.

The pickup driver informed me that a small lorry behind him knocked into his pick up and caused his pick up to bump into my car. He could not catch the lorry driver as it drove off very fast.

As the light at the bus stop was not so good, I could not see any damage to my car. So I only took a picture of pick up and exchanged handphone no with the pickup driver. The pickup also has no damage in the front.

This morning I checked the back part of the car and found the back bumper has a crack line on top.



Thanks

Yours faithfully,

Karen Koh (car no SJY5702A)
97816328

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature (On Behalf of Koh Kwee Fong)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 067/IC/TCAC/CCR/2019
DATE : 29-MAY-2019

GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
S(039190)
TEL : 68046059
FAX : 62353354
ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : NISSEI ASB PTE LTD
ADDRESS : 85 SCIENCE PARK DRIVE
#01-03 CAVENDISH, THE
S(118259)
TELEPHONE NO : 67784633/96206862

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100228380-08
VEHICLE NO : SJY5702A
MODEL CODE : BDUARCAG11EHA-----
MODEL/YEAR : SYLPHY 1.5 4A/T SEDAN (II)
ENGINE NO : HR15390637B
CHASSIS NO : JN18AAG11Z0111224
MILEAGE : 246752 KM
DATE IN : 29/05/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 28/05/2019

JC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJY5702A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	/
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
4	ZZ/001	REPLACE REAR BUMPER & MOULDING, REAR UPPER PANEL STRIKER ETC. REPAIR PANELS	1560.00	585
5	ZZ/002	RESPRAY REAR BUMPER, REAR UPPER PANEL ETC	750.00	350
6	ZZ/003	QC, RETUNE & CONSULT CHECK		
7	ZZ/004	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			2585.00	

JC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJY5702A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	REVERSE SENSOR ? HW	SENSOR-TE5140			180.00
2	ENERGY ABSORBER ? HW	85090-EW000	37.00		
3	RIGHT BUMPER STAY / BR	85212-AX010	43.30		
4	LEFT BUMPER STAY / BR	85213-AX010	43.30		
5	RIGHT BUMPER BRACKET X m	85226-EW000	36.60		
6	LEFT BUMPER BRACKET X m	85227-EW000	36.60		
7	REAR BUMPER CHROME MOULDING / n/c	85072-EW000	162.80		
8	REAR BUMPER / 00	85022-EW025	660.60		
9	STRIKER ? HW	84621-ED40A	56.90		
10	REAR UPPER PANEL X R	79110-EW400	436.70		
SUB TOTAL			1513.80	0.00	180.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			302.76	0.00	0.00
GRAND TOTAL			1211.04	0.00	180.00
OVERALL TOTAL			1391.04		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJY5702A

TOTAL LABOUR CHARGES	2585.00
TOTAL SPARE PARTS CHARGES	1391.04
GRAND TOTAL	3976.04 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Steve (LKK) WIL 6/6/19, 2:30pm
3 days
P/P
Ry bel spray

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI19009662/Eqd3e2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 06-08-2019		
		Code : GAI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GY 7684R	Veh. Inspected	SJY 5702A	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000003669	Excess (\$)	0.00	
Assign From	SHARON NG	Assign Date	30/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JN1BAAG11Z0111224	Colour	SILVER	
Odometer	246983	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/05/2019	Inspection Date	06/06/2019	
Survey held at	TC AUTOCLINIC PTE LTD 25 LENG KEE RD SINGAPORE 159097			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 5702A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	ENERGY ABSORBER (N)	* CHECK	37.00	-
1	RIGHT BUMPER STAY (N)	BROKEN	43.30	43.30
1	LEFT BUMPER STAY (N)	BROKEN	43.30	43.30
1	RIGHT BUMPER BRACKET (N)	NOT NECESSARY	36.60	-
1	LEFT BUMPER BRACKET (N)	NOT NECESSARY	36.60	-
1	REAR BUMPER CHROME MOULDING (N)	NECESSARY	162.80	162.80
1	REAR BUMPER (N)	DENTED	660.60	660.60
1	STRIKER (N)	* CHECK	56.90	-
1	REAR UPPER PANEL (N)	TO REPAIR SEE LABOUR	436.70	-
	LESS 20% DISCOUNT		-302.76	-182.00
			1,211.04	728.00
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	* CHECK	180.00	-
			180.00	-
LABOUR				
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.		120.00	120.00
	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST.		55.00	55.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	NOT NECESSARY	100.00	-
	REPLACE REAR BUMPER & MOULDING, REAR UPPER PANEL, STRIKER ETC. REPAIR PANELS. INCLUSIVE OF THE REPAIR OF REAR UPPER PANEL.		1,560.00	585.00
	RESPRAY REAR BUMPER, REAR UPPER PANEL ETC.		750.00	350.00
			2,585.00	1,110.00
GRAND TOTAL			3,976.04	1,838.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$255.12 NETT)				1,838.00

Report Ref No. CS/GAI19009662/Eqd3e2



Report Ref No. CS/GAI19009662/Eqd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.