

REF: CS3/MSG190059M / Gsd 3021

ASSIGNMENT (Office)

From/Person: Guo Ailing
Katherine Wong M81G Date/Time: 30/5/2019

Estimated Cost: Nil

OD: (1) MS/TP RST/OD RST/KYA/INV/IMV/CB

To: Inspected Vehicle No: S6X 2233Y Insured: yp 3430S

at Workshop ref: Huck Motors Tel:

at: 1 Kaki Bukit Ave 6 # 02-38

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

Q-Tech's Record:

CA / REV / REP / REV 24 HRS

Date/Time: 10:43am 3/4/19 Person Contacted: kelvin ROAD Enhancement Vehicle: (IN)OUT

Date/Time	Action/Instruction (X) Estimate
	S6X 2233Y - NA/NAJ 13014322/21 DOR - 14/02/2013
	YP 3430 S - Y
	Dismantle: 4/4/2019
	\$5550, 5 Days. 25/6/2019
	(\$3,050/- Red - 36%)

[Signature]


Do Not Finalise

RECEIVED 25 JUN 2019

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Hock Motor
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. on Market Value: \$41K.
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lump Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SGX2233 Y Yr Regn: 15 oct 2010
 Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Lexus RX450H
 Colour: Grey A/C Insured / Std / NI / NA
 Sp. Reading: 191335 T/Radio: Insured / Std / NI / NA
 Eng No: _____
 C/No: JTJBC11A302034920
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / R/Rim or
 Tyre Size: F: 235/60 R18
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: _____ D.O.I: 03-04-19
 Survey held at: w/s 4:50pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$5000 - \$6000
	7/14/2019

Date/Time, File Pass In?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 5
 Resurvey No. of Trip: 1

Add Fee:
 ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$

Survey Fee:
 Transportation:
) \$ + RS. \$
) Phone
) Other

Report Format: PRS
 Lump Sum / I.B.I: (\$)

TOTAL

120
 10
 130

Nivitha (LKK Auto)

From: Accounts (LKKAuto) <account@lkkauto.com>
Sent: Friday, 31 May 2019 2:38 PM
To: Admin-D (LKKAuto)
Cc: Accounts (LKKAuto)
Subject: Report Send Back Alerts - SGX2233Y (TP)

Dear Nivitha,

FYNA Please...

Pending for Survey Report- CS3/MSG19005919/GCD3E2

20	30 May 2019 14:30	Ins Send Back Adj Rpt	For paper survey	[1] Katherine Wong
21	30 May 2019 14:30	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/03	[1] Merimen Administrator
22	30 May 2019 14:30	Adj Mandate Set	Maintained.	[1] Merimen Administrator

Thank You

Best Regards,



SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6841 1891 | email: account@lkkauto.com | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]

Sent: Thursday, 30 May 2019 2:40 PM

To: account@lkkauto.com

Subject: Report Send Back Alerts - SGX2233Y (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.

Thanks,
The Merimen Team



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Chan Peng Wai
C/o: Hock Motors Workshop
No.1 Kaki Bukit Ave 6 #02-02
AutoBay, Singapore 417883

Invoice No: CL/190436

Ref No: HM/04/1901/TP

Date: 10 April 2019

DESCRIPTION

AMOUNT

OUR SERVICE FEE CHARGES:

- SURVEY INSPECTION FOR VEHICLE NO. SGX 2233 Y
- RESURVEY INSPECTION
- DIGITAL PHOTOGRAPHS SERVICES
(INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)
- TRANSPORTATION

GRAND TOTAL

S\$ 695.00

E & O. E

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Chan Peng Wai
C/o: Hock Motors Workshop
No.1 Kaki Bukit Ave 6 #02-02
AutoBay, Singapore 417883

Date : 10 April 2019
Our ref : HM/04/1901/TP

Accident Date : 01 April 2019
Inspection Date : 02 April 2019
Repairer Name : Hock Motors Workshop
No.1 Kaki Bukit Ave 6 #02-02
AutoBay, Singapore 417883

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SGX 2233 Y
Make / Model : Toyota Lexus RX450H
Chassis No : JTJBC11A302034920
Engine No : 2GRJ335607

Year / Capacity : 2010 / 3456 cc
Colour : Black
Mileage : 191335

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	Michelin	235/60 R18	5 mm	Sport
Front Offside	Michelin	235/60 R18	5 mm	Sport
Rear Nearside	Michelin	235/60 R18	5 mm	Sport
Rear Offside	Michelin	235/60 R18	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 75 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of S 8,600.00** on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.

Vehicle Registration No: SGX 2233 Y

Our Ref No: HM/04/1901/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Rear windscreen inner seal	Necessary	\$ 189.70	\$ 189.70 ✓
1	Rear tailgate	Damage	\$ 1,899.30	\$ 1,899.30 ✓
2	Rear tailgate dampers	Intact	\$ 443.20	NN ✓
1	Rear tailgate inner board	Damage	\$ 780.10	\$ 780.10 X NN ✓
2	Rear tailgate lamps < LH X NN RH - CMA	Damage	\$ 653.00	\$ 653.00 326.5 ✓
1	Rear tailgate lock	Damage	\$ 509.70	\$ 509.70 X NN ✓
1	Rear tailgate logo	Necessary	\$ 108.60	\$ 108.60 - 69.37 ✓
1	Rear tailgate "RX450h" emblem	Necessary	\$ 89.70	\$ 89.70 ✓
1	Rear tailgate "HYBRID" emblem	Necessary	\$ 81.50	\$ 81.50 ✓
1	Rear tailgate "LEXUS" emblem	Necessary	\$ 89.70	\$ 89.70 ✓
1	Rear tailgate outer chrome moulding	Necessary	\$ 184.00	\$ 184.00 ✓
2	Rear taillamps	O/S Damage	\$ 1,309.60	\$ 654.80 ✓
1	Rear end panel	Damage	\$ 659.20	\$ 659.20 X 182.6 ✓
1	Rear end panel inner garnish	Damage	\$ 243.00	\$ 243.00 X NN ✓
1	Rear bumper	Damage	\$ 1,385.90	\$ 1,385.90 - 387.4 ✓
1	Rear bumper inner sponge	Damage	\$ 157.00	\$ 157.00 - 125.8 ✓
2	Rear bumper reflectors	O/S Damage	\$ 279.80	\$ 139.90 ✓
1	Rear bumper reinforcement	Damage	\$ 759.00	\$ 759.00 ✓
2	Rear bumper side retainers	Necessary	\$ 98.00	\$ 98.00 ✓
1	Rear exhaust silencer	Intact	\$ 936.10	NN ✓
			\$ 10,856.10	\$ 8,682.10 5694.73 ✓
			Less 10%	\$ 1,085.61 \$ 868.21
Total Cost - List Items			\$ 9,770.49	\$ 7,813.89 5125.25 ✓

SPECIAL NETT ITEMS

1	Rear windscreen sealant	Necessary	\$ 80.00	\$ 50.00 ✓
1	Rear bumper clip (1 set)	Necessary	\$ 60.00	\$ 60.00 40 ✓
1	Rear bumper protector (1 set)	Damage	\$ 120.00	\$ 120.00 80 ✓
1	Rear number plate with holder	Damage	\$ 50.00	\$ 50.00 X NN ✓
1	Rear reverse sensor (1 set)	Damage	\$ 350.00	\$ 280.00 200 ✓
1	Rear reverse camera	Damage	\$ 450.00	\$ 450.00 X NN ✓
Total Cost - Special Nett items			\$ 1,110.00	\$ 1,010.00 370 ✓

Total cost of parts

\$ 10,880.49 \$ 8,823.89

Vehicle Registration No: SGX 2233 Y

Our Ref No: HM/04/1901/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 10,880.49	\$ 8,823.89

LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00 <i>30</i>
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 120.00 <i>60</i>
3	To remove and refit rear reverse sensor and camera.	\$ 120.00	\$ <i>40</i> 120.00 <i>0</i>
4	To transfer rear tailgate mechanism and wiring assembly to assist repair.	\$ 80.00	\$ 60.00 <i>/</i>
5	To remove and refit rear windscreen glass.	\$ 180.00	\$ 120.00 <i>/</i>
6	To apply undercoating on repaired and replaced panel.	\$ 120.00	\$ 90.00 <i>60</i>
7	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,080.00	\$ 750.00 <i>50</i>
8	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,000.00	\$ <i>600</i> 600.00 <i>0</i>

1470

GRAND TOTAL

\$ 13,690.49	\$ 10,793.89
---------------------	---------------------

6965.25

20% 5550

Vehicle Registration No: SGX 2233 Y

Our Ref No: HM/04/1901/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : S 8,600.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H
Automotive Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/04/2019 09:57
Date Of Accident	01/04/2019 07:35
Exact Location Of Accident	ROCHOR ROAD / NORTH BRIDGE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX2233Y
Insured/Policyholder	
Name Of Registered Owner	CHAN PENG WAI (CHEN BINGWEI)
NRIC No	S7239716I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93896155
Alternative Phone No	OFFICE-93896155

Vehicle Particulars

Manufacturer	LEXUS
Model	LEXUS RX450H

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088404232-01 CLASSIC
Cover Note Number	

Driver

Name of Driver	CHAN PENG WAI (CHEN BINGWEI)
NRIC No	S7239716I
Date Of Birth	26/10/1972
Occupation	INDOOR
Date Of Driving Pass	04/08/1995
Driving Experience	23 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93896155
Fax Number	
Contact Number	OFFICE-93896155
EEmail Address	NOEMAIL

Address	BLK 46 #0950 MARINE CRESCENT
Postcode	440046
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : EMILY HO GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP3430S
Vehicle Make/Model/Colour	MITSUBISHI FUSO FK62FMZ1RDEB
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

1/4/19 10am

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: workbk@singnet.com.sg
Name:
NRIC/FIN No.:

SKETCH PLAN



A - Sg 2233Y
B - YP 34305

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/19 at around 7.35am, my car sgx 2233y was slowing down and ~~about~~ to start to filter to left lane and all the front cars are slowing down due to red traffic light.

As it was raining, the lorry behind failed to keep safe distance and hit back of my car even though it braked.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:

Date & Time:

11/4/19
10am

Driver's Signature:

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: yackb@singnet.com.sg

Reporting Centre Personnel's Signature:

Name:

NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/04/2019 16:44
Date Of Accident 01/04/2019 07:30
Exact Location Of Accident ROCHER ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number YP3430S
Insured/Policyholder
Name Of Registered Owner PERFECTWORKS_TTL@YAHOO.COM.SG
Co Reg No 200105220W
Email Address PERFECTWORKS_TTL@YAHOO.COM.SG
Mobile Phone No
Alternative Phone No Office-94962930
Vehicle Particulars
Manufacturer MITSUBISHI
Model FUSO FIGHTER-7.5 D FK62 SERIES (FK62FMZ1RDEB) (M)
Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken REPORTING ONLY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy YES
Policy Number
Cover Note Number

Driver

Name of Driver CHEN DONG YUAN
Passport No/FIN G2747492L
Date Of Birth 15/08/1988
Occupation OUTDOOR
Date Of Driving Pass 26/04/2016
Driving Experience 2 YEARS AND 11 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-94692930

Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLK 180 TAMPINES ST 11 10-12
Postcode	520180
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED COPY

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGX2233Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHAN PENG WAI
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

192

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firm/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firm/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firm/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Perfectworks Pte Ltd

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

North Bridge Road

Traffic Light

Rocher Road

AKA

Describe Circumstances of the Accident

I was driving along Rocher Road at centre lane. A vehicle (SGX 2233Y) in front of my lorry (YP 3430S),

suddenly brake. I 'quickly' brake,
but hit onto ^{Chen Dong Yuan} Rear portion of
his vehicle.

Chen Dong Yuan

Declaration

We declare the foregoing particulars are true in every respect.



Perfectworks Pte Ltd

Chen Dong Yuan

03/04/19



Treife

Policyholder's Signature / Date &
Time

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class	Description	Valid Until	Category
Class 1	DRIVER'S LICENCE FOR MOTOR VEHICLES (DRIVER'S LICENCE)	31 Aug 2024	1
Class 2	DRIVER'S LICENCE FOR MOTOR VEHICLES (DRIVER'S LICENCE)	31 Aug 2024	2
Class 3	DRIVER'S LICENCE FOR MOTOR VEHICLES (DRIVER'S LICENCE)	31 Aug 2024	3

GPVMS

S / No. 9000247199

NP 426A



VISIT PASS

Immigration Regulations

14-02-2024

CHEN DONGYUAN



IC No.
G274792L

Date of Birth
15-08-1988

Gender
M

Nationality
CHINESE

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO Surrender THIS CARD WHEN IT IS CANCELLED

OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

Download SG Visit Pass App to check status



REPUBLIC OF SINGAPORE DRIVING LICENCE



IC No. G2747492L

CHEN DONGYUAN

Date of Birth 15 Aug 1988

Issue Date 28 Jan 2018

Valid Till 27-01-2025



WORK PERMIT

Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
PERFECTWORKS PTE LTD



Name
CHEN DONGYUAN

Work Permit No.
G 7897916

Category
MANUFACTURING

7897916

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	YP343D5
Vehicle Type:	A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1:	With Power Tailgate
Vehicle Scheme:	Normal
Vehicle Make:	MITSUBISHI
Vehicle Model:	FUSO FK62FMZ1RDEB
Chassis No.:	FK62FMA30120
Propellant:	Diesel
Engine No.:	6M60215429
Engine Capacity:	7545 cc
Maximum Power Output:	-
Maximum Laden Weight:	11900 kg
Unladen Weight:	6740 kg
Year Of Manufacture:	2016
Original Registration Date:	01 Aug 2016
Lifespan Expiry Date:	31 Jul 2036
COE Category:	C - Goods Vehicle & Bus
Quota Premium:	\$42,302.00
COE Expiry Date:	31 Jul 2026
Road Tax Expiry Date:	31 Jul 2019
Inspection Due Date:	31 Jul 2019
Intended Transfer Date:	03 Apr 2019
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

[OK](#)
[Print](#)



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SCX Centre 2, Singapore 068807
Tel: +65 6827 7888 Fax: +65 6827 7880
Co. Reg. No. 200412212C GST Reg. No. Z6-D4122175

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1969 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.2.300

GOODS CARRYING VEHICLE - SCR 1

COMMERCIAL VEHICLE - FLEET

Comprehensive

Certificate No. B 29869772 MXP

Excess: SGD600

1. Index Mark and Registration Number of Vehicle

YP343CS

2. Name of Policyholder

Perfectworks Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act

20/01/2018

4. Date of Expiry of Insurance

31/01/2019

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use in connection with the Policyholder's business.

Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover

(1) Use for hire or reward or for racing pace-making reliability trial or speed-testing.

(2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	03 Apr 2019 17:47		04 Apr 2019 11:04 Edit Adj Rpt	S\$5,550.00 Edit Estimates	S\$5,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PERFECTWORKS PTE LTD, Co. Reg. No.: 200105220W								
Main Claimant:	CHAN PENG WAI (CHEN BINGWEI), ID: S72397161								
Vehicle Reg. No.:	SGX2233Y	Date of Loss:	01/04/2019 07:00 - :59 [101 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 589473	Policy/Cover Note No.:	29069772MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	YP3430S	Policy No. (Claimant):							
		Excess:							
Repairer:	Hock Motors Workshop (HQ) NO 1 KAKI BUKIT AVENUE 6, #02-38 AUTOBAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel: 68469707								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/06/2019]								
Driver/Custodian (Insured):	CHEN DONG YUAN (), NRIC: G2747492L Email:								
Adj. Asg. Remarks:	on WP. MANUALLY ASSIGNED. TP DISAGREE ON SJE - ASSIGN LKK. CONTACT : KELVIN KHOO @ 9784 5529.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (30/05/2019): Report Send Back Alerts - SGX2233Y (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGX2233Y (589473)

[YP3430S]



































TP















































CHAN PENG WAI (CHEN BINGWEI)

Apr 1 2019 7:00AM

[PERFECTWORKS PTE LTD]

Hock Motors Workshop

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print			
1	03/04/19 18:07	Accident Statement From: SC - Reg. No: YP3430S, Claimant: PERFECTWORKS_TTL@YAHOO.COM.SG			Load HTML			
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
2	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
3	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
4	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
5	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
6	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
7	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
8	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
9	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
10	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
11	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
12	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
13	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
14	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
15	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
16	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
17	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
18	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
19	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
20	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
21	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
22	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
23	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
24	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
25	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
26	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
27	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
28	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
29	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
30	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
31	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
32	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		
33	05/04/19 12:58	General View			Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	05/04/19 13:00	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/04/19 18:10	SGX2233Y GIA Rpt	 Load PDF	
2	04/04/19 08:11	TP DISAGREE ON SJE	 Load PDF	
3	30/05/19 13:13	TPD SGX2233Y - SURVEY REPORT & INVOICE	 Load PDF	
4	30/05/19 13:13	TPD SGX2233Y - COLOUR PHOTO A	 Load PDF	
5	30/05/19 13:13	TPD SGX2233Y - COLOUR PHOTO B	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	04/04/19 11:02	Manually Assigned email	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/06/19 17:49	Colour Photo	 Load PDF	
2	25/06/19 17:49	PRS Invoice	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19005919/GSD3E2-1

Date: 26/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29069772MKF

Claimant Vehicle No : SGX2233Y

Insured Vehicle No : YP3430S

Date of Loss: 01/04/2019

Nature of Claim: TP

Claim No: 589473

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGX2233Y

Make & Model: TOYOTA LEXUS, 3.5 RX450 (A)

Engine No: 2GRJ335607

Reg. Date: 15/10/2010 (Man. Year: 2010)

Chassis No: JTJBC11A302034920

Colour: Grey

Odometer: 191335 km

Engine Capacity: 3456 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18

Rear Tyre Size: 235/60 R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,880.49	5,495.26	5,385.23	49.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,810.00	1,470.00	1,340.00	47.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,690.49	6,965.26	6,725.23	49.12
Approved Total (Overridden) (S\$)		5,550.00		
Nett Amount (S\$)	13,690.49	5,550.00	8,140.49	59.46

INSPECTION

Date of Assignment: 04/04/2019

Date Inspected: 03/04/2019 Inspected At:

Hock Motors Workshop (HQ)
NO 1 KAKI BUKIT AVENUE 6, #02-38
AUTOBAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jun 2019)
Parts:	143	TOYOTA LEXUS 3.5 RX450 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGX2233Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN INNER SEAL	Necessary	189.70 FL	*189.70 FL
2	1		*REAR TAILGATE	Damaged	1,899.30 FL	*1,899.30 FL
3	2		*REAR TAILGATE DAMPERS	Not Necessary	443.20 FL	*- FL
4	1		*REAR TAILGATE INNER BOARD	Not Necessary	780.10 FL	*- FL
5	1		*REAR TAILGATE LAMPS	N/S Not Necessary /O/S Cracked	653.00 FL	*326.50 FL
6	1		*REAR TAILGATE LOCK	Not Necessary	509.70 FL	*- FL
7	1		*REAR TAILGATE LOGO	Necessary	108.60 FL	*69.37 FL
8	1		*REAR TAILGATE RX450H EMBLEM	Necessary	89.70 FL	*89.70 FL
9	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	81.50 FL	*81.50 FL
10	1		*REAR TAILGATE LEXUS EMBLEM	Necessary	89.70 FL	*89.70 FL
11	1		*REAR TAILGATE OUTER CHROME MOULDING	Necessary	184.00 FL	*184.00 FL
12	1		*REAR TAILLAMPS	O/S Damaged	1,309.60 FL	*654.80 FL
13	1		*REAR END PANEL	Repair	659.20 FL	*- FL
14	1		*REAR END PANEL INNER GARNISH	Not Necessary	243.00 FL	*- FL
15	1		*REAR BUMPER	Damaged	1,385.90 FL	*987.46 FL
16	1		*REAR BUMPER INNER SPONGE	Damaged	157.00 FL	*125.80 FL
17	1		*REAR BUMPER REFLECTORS	O/S Damaged	279.80 FL	*139.90 FL
18	1		*REAR BUMPER REINFORCEMENT	Damaged	759.00 FL	*759.00 FL
19	2		*REAR BUMPER SIDE RETAINERS	Necessary	98.00 FL	*98.00 FL
20	1		*REAR EXHAUST SILENCER	Not Necessary	936.10 FL	*- FL
21	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*50.00 FS
22	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*40.00 FS
23	1		*SET REAR BUMPER PROTECTOR	Damaged	120.00 FS	*80.00 FS
24	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
25	1		*SET REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
26	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,966.10 6,064.73
 - List Item Discount on L Items 10.00/10.00% (\$\$) 1,085.61 569.47

Total Parts (\$\$) 10,880.49 5,495.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	120.00	40.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR	New	80.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
7	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,080.00	500.00
8	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
Gross Labour Cost (S\$)			2,810.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >