

ASS. REC. BY:

REF: CS/FCI 19009685/Kg d3

Special Instruction:

Surveyor:

**ASSIGNMENT (Office)**From (Person): man chua

of

FCIDate/Time: 31.5.2019 3.52p.m

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**To Inspect Vehicle No: SKM 1566D

Insured:

SHC 3800Cat Workshop m/s compute vms

Tel:

64550012of 176 sin ming drive #03-14

Policy No:

Claim No:

D1900 3586M F34

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30.05.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 31.5.19 4.00 p.m

Person Contacted:

Li HuiVehicle IN/OUT

| Date/Time       | Action/Instruction ( ✓ ) Estimate.                      |
|-----------------|---------------------------------------------------------|
|                 | SKM 1566D - CS/INC 16007247/ Gqbd                       |
|                 | SHC 3800C - CS/FCI 15012528/ Rqbd 1                     |
| 06/6/19 07.35pm | revised to Man Chua by email.                           |
| 21/6            | LI Hui @ 11, 400 email & confirmed ched \$ 6577.70, 37% |

10/11/19

REF: PC1

Surveyor

## ASSIGNMENT

From:

Date: 3.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKM 1566D

at Workshop m/s Complete VMS  
of 176 Sh Ming Drive #03-14

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh: After 10-30 a.m

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \$108k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKM 1566D

Yr Regn:

03 / 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Rays Ron Evoque S14 1999

Colour:

M. Silver / Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

105024

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SALVA2AGOODH7499H

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / RIM or

Tyre Size: F:

R:

265/45R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 30/5/19

D.O.I. 3/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5/19

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 24 JUN 2019

Date/Time, File Pass to?

☐

Preli. Report

11/24/6 M. M. M.

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format: 7P

Lump Sum / I.B.F. (\$) 11400

Survey Fee:

Transportation:

S + RS. S

Photos: 500

Other: 24/6/19

TOTAL

TX15 = 105

170 + 105

50

50 + 50

30

455



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003586MFSH

Date: 06 June 2019

Our Ref: CS/FCI19009685/Kqd3

The Motor Claims Department  
MS First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SKM 1566D.**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/06/2019 at the premises of M/s COMPLETE VMS, and have the following to report:-

|                          |                   |
|--------------------------|-------------------|
| Workshop Estimate Amount | : S\$ 17,514.70 . |
| Revised Estimate Amount  | : S\$ 4,987.40 .  |
| "Check" Items Amount     | : S\$ 10,620.80 . |
| Market Value             | : S\$ - .         |
| LTA Reimbursement Value  | : S\$ - .         |
| Nett Value               | : S\$ - .         |

**Description of Damage:**

The vehicle sustained damages at the o/s front portion.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

|                    |                                                    |                               |
|--------------------|----------------------------------------------------|-------------------------------|
| Date               | 30-05-2019                                         | Our Ref No. D19003586MFSH     |
| Accident Date      | 30-05-2019                                         | Claim Type. Third Party       |
| Insured Vehicle    | SHC3800C                                           | Third Party Vehicle. SKM1566D |
| Survey Location    | 176 SIN MING DRIVE #03-14SIN MING AUTOCARE COMPLEX |                               |
| Contact Person.    | LILY/LI HUI (TEL: 64539622)                        |                               |
| Contact No.        | 64550012/ 00                                       | Fax No. 65540012              |
| Survey Type        | WITHOUT PREJUDICE:                                 |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                       |                               |
| Contact Person     | NA                                                 | Fax No. 68416315              |
| Contact Number.    | NA                                                 |                               |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                      |                         |
|-------------------|----------------------|-------------------------|
| Cc : Workshop     | COMPLETE VMS PTE LTD | Attention. NIL          |
| Cc : TP Solicitor | NA                   | TP Solicitor Fax No. NA |
| Officer Incharge  | MAY CHUA             |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 6 June 2019 2:55 PM  
**To:** 'CWS Motor Claims'; assignments; SUR  
**Cc:** 'May Chua Hui Chin'  
**Subject:** RE: SURVEY ASSESSMENT - D19003586MFSH/1  
**Attachments:** CSFCI19009685Kqd3.pdf

Dear May,

Enclosed herewith preliminary advice of SKM 1566D.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Friday, 31 May 2019 4:06 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** 'May Chua Hui Chin' <[maychua@msfirstcapital.com.sg](mailto:maychua@msfirstcapital.com.sg)>  
**Subject:** RE: SURVEY ASSESSMENT - D19003586MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed that repairer agreed to survey on 03/06/2019.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 31 May, 2019 3:52 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; May Chua Hui Chin <[maychua@msfirstcapital.com.sg](mailto:maychua@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19003586MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                          |
|-------------------------------------|------------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                          |
| Owner ID Type:                      | Singapore NRIC                           |
| Owner ID:                           | 3158D                                    |
| <b>Vehicle Details</b>              |                                          |
| Vehicle No.:                        | SKM1566D                                 |
| Vehicle to be Exported:             | No                                       |
| Intended Deregistration Date:       | 04 Jun 2019                              |
| Vehicle Make:                       | LAND ROVER                               |
| Vehicle Model:                      | RANGE ROVER EVOQUE 2.0 AT ABS 4WD HID SR |
| Primary Colour:                     | Blue                                     |
| Manufacturing Year:                 | 2012                                     |
| Engine No.:                         | 271112080143204PT                        |
| Chassis No.:                        | SALVA2AG0DH749911                        |
| Maximum Power Output:               | 177.0 kW (237 bhp)                       |
| Open Market Value:                  | \$57,750.00                              |
| Original Registration Date:         | 26 Mar 2013                              |
| First Registration Date:            | 26 Mar 2013                              |
| Transfer Count:                     | 3                                        |
| Actual ARF Paid:                    | \$75,950.00                              |
| <b>Intended PARF Rebate Details</b> |                                          |
| PARF Eligibility:                   | Yes                                      |
| PARF Eligibility Expiry Date:       | 25 Mar 2023                              |
| PARF Rebate Amount:                 | \$49,367.00                              |
| <b>Intended COE Rebate Details</b>  |                                          |
| COE Expiry Date:                    | 25 Mar 2023                              |
| COE Category:                       | B - Car (1601cc & above)                 |
| COE Period(Years):                  | 10                                       |
| QP Paid:                            | \$58,090.00                              |
| COE Rebate Amount:                  | \$22,111.00                              |
| <b>Total Rebate Amount:</b>         | <b>\$71,478.00</b>                       |

The information contained herein is correct as at 04 Jun 2019

OK



Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

HADIDI FAIZAL BIN ZAINUDDIN  
274D PUNGGOL PLACE #15-838  
SINGAPORE 824274

Estimate : ES006684

Attention : Motor Claim Department  
Contact : 94526266

*Not Authorized*  
*Returning After Repair*

Date : 30/05/2019  
Vehicle Num. : SKM1566D  
Make/Model : LAND ROVER RANGE ROVER EVOQ  
Chassis/Eng# : SALVA2AG0DH749911/271112080143  
Accident Date : 30/05/2019  
Claim No. :  
Reference :  
Policy No. :

*1.3.1, 1/1 Sep 8?*

*4-5 days*

S/N Quantity Particular Unit Price Amount S\$

|                      |    |                                  |
|----------------------|----|----------------------------------|
| SPECIAL NETT ITEMS : |    |                                  |
| 1.                   | 1  | FRONT FENDER R/H                 |
| 2.                   | 1  | FRONT FENDER OUTER PROTECTOR R/H |
| 3.                   | 1  | FRONT FENDER INNER SHIELD R/H    |
| 4.                   | 1  | HEADLAMP R/H                     |
| 5.                   | 1  | FRONT BUMPER                     |
| 6.                   | 16 | FRONT BUMPER CLIP                |
| 7.                   | 1  | FRONT BUMPER SIDE RETAINER R/H   |
| 8.                   | 1  | HEADLAMP LOWER BRACKET R/H       |
| 9.                   | 1  | FRONT BUMPER LOWER LIP           |
| 10.                  | 1  | FRONT FOG LAMP R/H               |
| 11.                  | 1  | FOG LAMP TOP GARNISH R/H         |
| 12.                  | 10 | FRONT FENDER PROTECTOR CLIP R/H  |
| 13.                  | 1  | FRONT LOWER LIP SENSOR R/H       |
| 14.                  | 1  | FRONT BUMPER REINFORCEMENT       |
| 15.                  | 1  | FRONT BUMPER BRACKET R/H         |
| 16.                  | 1  | FRONT SPORT RIM R/H              |
| 17.                  | 1  | FRONT SHOCK ABSORBER R/H         |
| 18.                  | 1  | FRONT WHEEL BEARING R/H          |
| 19.                  | 1  | FRONT LOWER ARM R/H              |
| 20.                  | 1  | FRONT KNUCKLE ARM R/H            |

|           |          |   |
|-----------|----------|---|
| CRK       | 983.00   | ✓ |
| NU        | 235.00   | ✓ |
| CHA       | 365.00   | ✓ |
| WY        | 2,780.00 | ✓ |
| BY        | 2,350.00 | ✓ |
| 6.50      | 104.00   | ✓ |
| NU        | 75.30    | ✓ |
| BY        | 1,008.00 | ✓ |
| CU        | 451.10   | ✓ |
| CM        | 552.00   | ✓ |
| SM        | 101.50   | X |
| 6.50      | 65.00    | X |
| NU        | 280.00   | X |
| R         | 642.30   | X |
| N         | 45.00    | X |
| MS        | 1,650.00 | X |
| BT        | 594.10   | X |
| WCC       | 328.10   | X |
| MS        | 792.00   | X |
| BT        | 983.30   | X |
| 14,384.70 |          |   |

Special Nett Total S\$ :

LABOUR :  
RUST PROOFING TREATMENT  
REMOVE & REINSTALL FRONT SUSPENSION R/H  
CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION  
COMPUTER WHEEL ALIGNMENT  
SPRAY PAINT DAMAGED AREA AFFECTED

|     |          |   |
|-----|----------|---|
| NU  | 100.00   | X |
| WCC | 280.00   | X |
| 80  | 150.00   | X |
|     | 120.00   | X |
|     | 1,100.00 | X |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

CONTINUE / ...



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre  
 176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721  
 (Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ( )  
 lily@completevms.com.sg ( )  
 lihui@completevms.com.sg ( )

HADIDI FAIZAL BIN ZAINUDDIN  
 274D PUNGGOL PLACE #15-838  
 SINGAPORE 824274

Attention : Motor Claim Department  
 Contact : 94526266

Estimate : ES006684

Date : 30/05/2019  
 Vehicle Num. : SKM1566D  
 Make/Model : LAND ROVER RANGE ROVER EVOQ  
 Chassis/Eng# : SALVA2AG0DH749911/271112080143  
 Accident Date : 30/05/2019  
 Claim No. :  
 Reference :  
 Policy No. :

| S/N | Quantity | Particular                                                                                     | Unit Price | Amount S\$ |
|-----|----------|------------------------------------------------------------------------------------------------|------------|------------|
|     |          | TO KNOCK AND STRAIGHTEN FRONT SUPPORT PANEL,FRONT CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS |            | 1,380.00   |
|     |          | Labour Total S\$ :                                                                             |            | 3,130.00   |

500/

SingDollars : Seventeen Thousand Five Hundred Fourteen & Cents Seventy Only

Total S\$ : 17,514.70  
 =====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

17,514.70





Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

HADIDI FAIZAL BIN ZAINUDDIN  
274D PUNGGOL PLACE #15-838  
SINGAPORE 824274

Estimate : ES006684

Attention : Motor Claim Department  
Contact : 94526266

*Not Notified*

*Returning After Repair*

*4-5 days*

*4-5 days*  
*L1 Syg @ 11,400*

Date : 30/05/2019  
Vehicle Num. : SKM1566D  
Make/Model : LAND ROVER RANGE ROVER EVOQ  
Chassis/Eng# : SALVA2AG0DH749911/271112080143  
Accident Date : 30/05/2019  
Claim No. :  
Reference :  
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

|                      |    |                                  |
|----------------------|----|----------------------------------|
| SPECIAL NETT ITEMS : |    |                                  |
| 1.                   | 1  | FRONT FENDER R/H                 |
| 2.                   | 1  | FRONT FENDER OUTER PROTECTOR R/H |
| 3.                   | 1  | FRONT FENDER INNER SHIELD R/H    |
| 4.                   | 1  | HEADLAMP R/H                     |
| 5.                   | 1  | FRONT BUMPER                     |
| 6.                   | 16 | FRONT BUMPER CLIP                |
| 7.                   | 1  | FRONT BUMPER SIDE RETAINER R/H   |
| 8.                   | 1  | HEADLAMP LOWER BRACKET R/H       |
| 9.                   | 1  | FRONT BUMPER LOWER LIP           |
| 10.                  | 1  | FRONT FOG LAMP R/H               |
| 11.                  | 1  | FOG LAMP TOP GARNISH R/H         |
| 12.                  | 10 | FRONT FENDER PROTECTOR CLIP R/H  |
| 13.                  | 1  | FRONT LOWER LIP SENSOR R/H       |
| 14.                  | 1  | FRONT BUMPER REINFORCEMENT       |
| 15.                  | 1  | FRONT BUMPER BRACKET R/H         |
| 16.                  | 1  | FRONT SPORT RIM R/H              |
| 17.                  | 1  | FRONT SHOCK ABSORBER R/H         |
| 18.                  | 1  | FRONT WHEEL BEARING R/H          |
| 19.                  | 1  | FRONT LOWER ARM R/H              |
| 20.                  | 1  | FRONT KNUCKLE ARM R/H            |

*wheel*  
*Alignment*

Special Nett Total S\$ :

LABOUR :  
RUST PROOFING TREATMENT  
REMOVE & REINSTALL FRONT SUSPENSION R/H  
CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION  
COMPUTER WHEEL ALIGNMENT  
SPRAY PAINT DAMAGED AREA AFFECTED

|           |          |   |
|-----------|----------|---|
| CM        | 983.00   | ✓ |
| ND        | 235.00   | ✓ |
| CM        | 365.00   | ✓ |
| mgcm      | 2,780.00 | ✓ |
| BT        | 2,350.00 | ✓ |
| 6.50      | 104.00   | ✓ |
| ND        | 75.30    | ✓ |
| SM        | 1,008.00 | X |
| GM        | 451.10   | ✓ |
| CM        | 552.00   | ✓ |
| SM        | 101.50   | X |
| 6.50      | 65.00    | ✓ |
| SM        | 280.00   | X |
| R         | 642.30   | X |
| ND        | 45.00    | X |
| BT        | 1,650.00 | ✓ |
| ND        | 594.10   | ✓ |
| ND        | 328.10   | ✓ |
| BT        | 792.00   | ✓ |
| BT        | 983.30   | ✓ |
| 14,384.70 |          |   |

|     |          |     |
|-----|----------|-----|
| ND  | 100.00   | X   |
| 220 | 280.00   | ✓   |
| 80  | 150.00   | ✓   |
|     | 120.00   | 60  |
|     | 1,100.00 | 660 |

CONTINUE / ...



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre  
 176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721  
 (Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ( )  
 lily@completevms.com.sg ( )  
 lihui@completevms.com.sg ( )

HADIDI FAIZAL BIN ZAINUDDIN  
 274D PUNGGOL PLACE #15-838  
 SINGAPORE 824274

Attention : Motor Claim Department  
 Contact : 94526266

Estimate : ES006684

Date : 30/05/2019  
 Vehicle Num. : SKM1566D  
 Make/Model : LAND ROVER RANGE ROVER EVOQ  
 Chassis/Eng# : SALVA2AG0DH749911/271112080143  
 Accident Date : 30/05/2019  
 Claim No. :  
 Reference :  
 Policy No. :

| S/N | Quantity | Particular                                                                                     | Unit Price | Amount S\$ |
|-----|----------|------------------------------------------------------------------------------------------------|------------|------------|
|     |          | TO KNOCK AND STRAIGHTEN FRONT SUPPORT PANEL,FRONT CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS |            | 1,380.00   |
|     |          | Labour Total S\$ :                                                                             |            | 3,130.00   |

500/

SingDollars : Seventeen Thousand Five Hundred Fourteen & Cents Seventy Only

Total S\$ : 17,514.70

=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre  
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721  
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

HADIDI FAIZAL BIN ZAINUDDIN  
274D PUNGGOL PLACE #15-838  
SINGAPORE 824274

Attention : THE OWNER  
Contact : 94526266

### Supplementary Estimate : ES006685

Date : 04/06/2019  
Vehicle Num. : SKM1566D  
Make/Model : LAND ROVER RANGE ROVER EVOQ  
Chassis/Eng# : SALVA2AG0DH749911/271112080143  
Accident Date : 30/05/2019  
Claim No. :  
Reference :  
Policy No. :

| S/N | Quantity | Particular                                        | Unit Price | Amount S\$   |
|-----|----------|---------------------------------------------------|------------|--------------|
| 1.  | 1        | SPECIAL NETT ITEMS :<br>W/SCREEN WASHER TANK ASSY |            | Net 463.00 ✓ |
|     |          | Special Nett Total S\$ :                          |            | 463.00       |

SingDollars : Four Hundred Sixty-Three Only

Total S\$ : 463.00  
=====

### COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

Work Order: R031902  
 VIN: SKM1566D  
 Year: 11  
 Date: 3.6.19 23:06



SKM1566D

# Land Rover : Range Rover Evoque L538 4X4

## Front : Left

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -0°39' | -0°40' | -1°16' 0°14'    |
| 3°22'  | 3°22'  | 2°25' 3°55'     |
| 0°09'  | 0°09'  | 0°01' 0°13'     |
| 13°18' | 13°19' |                 |
| 12°39' | 12°39' |                 |
|        |        |                 |

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

## Front : Right

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -2°51' | -2°42' | -1°16' 0°14'    |
| 3°28'  | 3°28'  | 2°25' 3°55'     |
| -0°30' | -0°07' | 0°01' 0°13'     |
| 15°14' | 15°05' |                 |
| 12°23' | 12°23' |                 |
|        |        |                 |

## Front

Cross Camber  
 Cross Caster  
 Cross SAI  
 Total Toe  
 Cross Turn Diff.

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| 2°12'  | 2°02'  | -0°45' 0°45'    |
| -0°07' | -0°07' | -0°45' 0°45'    |
| -1°56' | -1°46' |                 |
| -0°21' | 0°01'  | 0°01' 0°25'     |
|        |        |                 |

## Rear : Left

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -1°02' | -1°02' | -2°00' -0°30'   |
| -0°09' | -0°08' | -0°02' 0°14'    |

Camber  
 Toe

## Rear : Right

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -1°33' | -1°33' | -2°00' -0°30'   |
| 0°01'  | 0°01'  | -0°02' 0°14'    |

## Rear

Cross Camber  
 Total Toe  
 Thrust Angle

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| 0°31'  | 0°31'  |                 |
| -0°08' | -0°07' | -0°01' 0°23'    |
| -0°05' | -0°05' | -0°08' 0°08'    |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                  |                                                                                                        |                       |                             |                                                                                     |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|-----------------------|-----------------------------|-------------------------------------------------------------------------------------|
| MS FIRST CAPITAL INSURANCE LTD                                                                                                                                                     |                                                                                                        |                       | Ref : CS/FCI19009685/Kqd3n2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                              |                                                                                                        |                       | Date : 27-06-2019           |  |
|                                                                                                                                                                                    |                                                                                                        |                       | Code : FCI2                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                  |                                                                                                        |                       |                             |                                                                                     |
| Insured Veh.                                                                                                                                                                       | SHC 3800C                                                                                              | Veh. Inspected        | SKM 1566D                   |                                                                                     |
| Policy No.                                                                                                                                                                         |                                                                                                        | Coverage (\$)         | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                                                          | D19003586MFSH                                                                                          | Excess (\$)           | 0.00                        |                                                                                     |
| Assign From                                                                                                                                                                        | MAY CHUA                                                                                               | Assign Date           | 31/05/2019                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                      |                                                                                                        |                       |                             |                                                                                     |
| Make & Model                                                                                                                                                                       | LAND ROVER EVOQUE                                                                                      | c.c                   | 1999                        |                                                                                     |
| Engine No.                                                                                                                                                                         | HIDDEN                                                                                                 | Year of Reg.          | 2013                        |                                                                                     |
| Chassis No.                                                                                                                                                                        | SALVA2AG0DH749911                                                                                      | Colour                | METALLIC SILVER/BLUE        |                                                                                     |
| Odometer                                                                                                                                                                           | 105024                                                                                                 | Steering              | IN ORDER                    |                                                                                     |
| Brakes                                                                                                                                                                             | IN ORDER                                                                                               | Modification          | STANDARD ALLOY RIM          |                                                                                     |
| General                                                                                                                                                                            | GOOD                                                                                                   |                       |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                      |                                                                                                        |                       |                             |                                                                                     |
|                                                                                                                                                                                    | Size                                                                                                   | Make                  | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                                                                     | 265/45 R20                                                                                             | MICHELIN              | 6 mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                                                                     | 265/45 R20                                                                                             | MICHELIN              | 6 mm                        |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                      | 265/45 R20                                                                                             | MICHELIN              | 6 mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                      | 265/45 R20                                                                                             | MICHELIN              | 6 mm                        |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                   |                                                                                                        |                       |                             |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.<br>DAMAGES SEE DEATAILS.                                                                                                   |                                                                                                        |                       |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                      |                                                                                                        |                       |                             |                                                                                     |
| Accident Date                                                                                                                                                                      | 30/05/2019                                                                                             | Inspection Date       | 03/06/2019                  |                                                                                     |
| Survey held at                                                                                                                                                                     | COMPLETE VMS PTE LTD<br>BLK 176 SIN MING DRIVE<br>#03-14<br>SIN MING AUTOCARE COMPLEX SINGAPORE 575721 |                       |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                 |                                                                                                        |                       |                             |                                                                                     |
| A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                        |                       |                             |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                 |                                                                                                        |                       |                             |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                |                                                                                                        | <b>5 Working Days</b> |                             |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 1566D

| Qty                         | Description of Parts                               | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|----------------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                    |                      |                           |                   |
| 1                           | FRONT FENDER R/H (SN)                              | CRACKED              | 983.00                    | 983.00            |
| 1                           | FRONT FENDER OUTER PROTECTOR R/H (SN)              | DENTED               | 235.00                    | 235.00            |
| 1                           | FRONT FENDER INNER SHIELD R/H (SN)                 | CRACKED              | 365.00                    | 365.00            |
| 1                           | HEADLAMP R/H (SN)                                  | MTG CRACKED          | 2,780.00                  | 2,780.00          |
| 1                           | FRONT BUMPER (SN)                                  | BENT                 | 2,350.00                  | 2,350.00          |
| 16                          | FRONT BUMPER CLIP @\$6.50 (SN)                     | NECESSARY            | 104.00                    | 104.00            |
| 1                           | FRONT BUMPER SIDE RETAINER R/H (SN)                | DISTORTED            | 75.30                     | 75.30             |
| 1                           | HEADLAMP LOWER BRACKET R/H (SN)                    | SERVICEABLE          | 1,008.00                  | -                 |
| 1                           | FRONT BUMPER LOWER LIP (SN)                        | CUT                  | 451.10                    | 451.10            |
| 1                           | FRONT FOG LAMP R/H (SN)                            | CRACKED              | 552.00                    | 552.00            |
| 1                           | FOG LAMP TOP GARNISH R/H (SN)                      | SERVICEABLE          | 101.50                    | -                 |
| 10                          | FRONT FENDER PROTECTOR CLIP R/H @\$6.50 (SN)       | NECESSARY            | 65.00                     | 65.00             |
| 1                           | FRONT LOWER LIP SENSOR R/H (SN)                    | SERVICEABLE          | 280.00                    | -                 |
| 1                           | FRONT BUMPER REINFORCEMENT (SN)                    | TO REPAIR SEE LABOUR | 642.30                    | -                 |
| 1                           | FRONT BUMPER BRACKET R/H (SN)                      | TO REPAIR SEE LABOUR | 45.00                     | -                 |
| 1                           | FRONT SPORT RIM R/H (SN)                           | DENTED               | 1,650.00                  | 1,650.00          |
| 1                           | FRONT SHOCK ABSORBER R/H (SN)                      | BENT                 | 594.10                    | 594.10            |
| 1                           | FRONT WHEEL BEARING R/H (SN)                       | NECESSARY            | 328.10                    | 328.10            |
| 1                           | FRONT LOWER ARM R/H (SN)                           | DISTORTED            | 792.00                    | 792.00            |
| 1                           | FRONT KNUCKLE ARM R/H (SN)                         | BENT                 | 983.30                    | 983.30            |
| 1                           | W/SCREEN WASHER TANK ASSY (ADDITIONAL) (SN)        | DENTED               | 463.00                    | 463.00            |
|                             |                                                    |                      | 14,847.70                 | 12,770.90         |
| <b>LABOUR</b>               |                                                    |                      |                           |                   |
|                             | RUST PROOFING TREATMENT.                           | NOT NECESSARY        | 100.00                    | -                 |
|                             | REMOVE & REINSTALL FRONT SUSPENSION R/H.           |                      | 280.00                    | 220.00            |
|                             | CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION. |                      | 150.00                    | 80.00             |
|                             | COMPUTER WHEEL ALIGNMENT.                          |                      | 120.00                    | 60.00             |
|                             | SPRAY PAINT DAMAGED AREA AFFECTED.                 |                      | 1,100.00                  | 660.00            |

Report Ref No. CS/FCI19009685/Kqd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                  | Description of Parts                                                                                                                                                                 | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
|                                                                      | TO KNOCK AND STRAIGHTEN FRONT SUPPORT PANEL, FRONT CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT BUMPER BRACKET R/H. |           | 1,380.00                  | 500.00            |
|                                                                      |                                                                                                                                                                                      |           | 3,130.00                  | 1,520.00          |
| GRAND TOTAL                                                          |                                                                                                                                                                                      |           | 17,977.70                 | 14,290.90         |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) |                                                                                                                                                                                      |           |                           | 11,400.00         |

Report Ref No. CS/FC119009685/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.