

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen SKODA

Commercial Vehicles

Quotation

Non binding - Preview

Page

1/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Ms.
LEE
EE MEEN
10 ANGKLONG LANE
#01-02
Singapore 579982

Document no.
Document date 30-05-2019
Customer no. 5211000972
Customer GST-ID 198703792K
Dealer 39999
Job order number 2019000811/ 1
Job order date 30-05-2019
Service Advisor TIOW CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SMG6960Z	3H74PT	28-12-2018	VWVZZZ3HZKE005995	Arteon R-Line 2.0 TSI 206kW 4Motion DSG	2,279

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
3G8807417 GRU	Cover Primed	1	pcs.	1,555.13	#1	1,555.13	1,663.99
	REAR BUMPER						
3G8919397	Sensor Bracket	1	pcs.	10.29	#1	10.29	11.01
3G8919398	Sensor Bracket	1	pcs.	10.29	#1	10.29	11.01
3G8919491	Sensor Bracket	1	pcs.	10.29	#1	10.29	11.01
3G8919491A	Sensor Bracket	1	pcs.	10.29	#1	10.29	11.01
3G8919492A	Sensor Bracket	1	pcs.	10.29	#1	10.29	11.01
3G8919491	Sensor Bracket	1	pcs.	10.29	#1	10.29	11.01
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	74.29	#1	74.29	79.49
D 822150A1	Bonding Agent For Plastic	1	pcs.	56.90	#1	56.90	60.88
5Q0919275B GRU	Sensor Primed	2	pcs.	164.62	#1	329.24	352.29
5Q0919133 9B9	Seal Ring Satin Black	2	pcs.	1.18	#1	2.36	2.53
3G8807521D GRU	Spoiler Primed	1	pcs.	271.47	#1	271.47	290.47
	SPOILER						
3G0807305T	Bumper	1	pcs.	501.32	#1	501.32	536.41
	REINFORCEMENT						
3G8807863	Attachment Strip	1	pcs.	62.20	#1	62.20	66.55
	REAR CTR BRACKET						
3G8807484	Guide	1	pcs.	20.09	#1	20.09	21.50
	TAILLIGHT BRACKET RH						
3G8807376	Guide Piece	1	pcs.	66.81	#1	66.81	71.49
	REAR SIDE BRACKET RH						
WHT005263	Rivet	4	pcs.	1.09	#1	4.36	4.67
3G8853835 2ZZ	Decorative Moulding Brigh	1	pcs.	146.09	#1	146.09	156.32
	RR CTR CHROME						
3G8853841 2ZZ	Decorative Moulding Brigh	1	pcs.	80.71	#1	80.71	86.36
	RR LH CHROME						
3G8853842 2ZZ	Decorative Moulding Brigh	1	pcs.	80.71	#1	80.71	86.36
	RR RH CHROME						
3G0807056	Bracket	1	pcs.	49.06	#1	49.06	52.49
	RH EXHAUST BRACKET						
3G8945208J	Led Tail Light	1	pcs.	563.53	#1	563.53	602.98
	RH OUTER						
3G8945308P	Led Tail Light	1	pcs.	459.09	#1	459.09	491.23
	RH INNER						
1K8943021D	Led Licence Place Light	2	pcs.	91.78	#1	183.56	196.41
3G8945104A	Reflector	1	pcs.	63.86	#1	63.86	68.33
	RH INNER						
3G8945106	Reflector	1	pcs.	63.86	#1	63.86	68.33
	RH OUTER						
	LABOUR	4	pcs.	840.00	#1	3,360.00	3,595.20
	SPRAY PAINT	4	pcs.	800.00	#1	3,200.00	3,424.00
	B&P NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60

3G8807441 GRU (up primed) / Cat
Low cover

24.10

24.10

25.79

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-05 IOB BUILDING
Singapore 049711

Customer Details:
Ms.
LEE
EE MEEN
10 ANGKLONG LANE
#01-02
Singapore 579982

Document no.
Document date 30-05-2019
Customer no. 5211000972
Customer GST-ID 198703792K
Dealer 39999
Job order number 2019000811/ 1
Job order date 30-05-2019
Service Advisor TIOW CHUAN CHEE

License plate SMG6960Z	Model code 3H74PT	First registration 28-12-2018	VIN WVWZZZ3HZKE005995	Model Arteon R-Line 2.0 TSI 206kW 4Motion DSG	Mileage 2,279
---------------------------	----------------------	----------------------------------	--------------------------	--	------------------

Quotation valid till 06-06-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	11,336.38	7%	846.75	12,096.38	12,943.13
Total	760.00	11,336.38		846.75	12,096.38	12,943.13

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

3 Days.
before paint photos.
Gmo Qian - 8288082
04/6/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: