

ASS. REC. BY:

Surveyor: Steve

REF: CS/FCI19009731/Eq312

Special Instruction:

ASSIGNMENT (Office)

From (Person): Eileen Lee

of FCI

Date/Time: 01/6/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLH 5174J

Insured: SHA 5098K

at Workshop m/s: Wearnes

Tel: 9818 7217

of 249 Long Kee

Policy No:

Claim No: 019003543MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 28/5/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>SLH 5174J</u>
	<u>SHA 5098K</u>
<u>12/6/19 @</u>	<u>2pm revised to Eileen Lee by email.</u>
<u>18/7/19 @</u>	<u>234pm confirmed with Richmond final fig \$12166.48, 7 days by email</u>
	<u>(Ref \$ 6682.71, 35%)</u>

ASS. REC. BY:

Steve

REF PCI

ASSIGNMENT

From: _____ Date: 6.6.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 5124J

at Workshop m/s Warrac

of 249 Alexandra Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: 10.000.000 over waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLH 5124J Yr Rego: 8/11/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volvo S90 C.C. 1969

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 35653 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YVIPSA 28CH 1006494

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/40R19

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Confirmed

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 28/5/19 D.O.I. 6/6/19

Survey held at Warrac

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Mr - 150K

RECEIVED 12 JUL 2019

Date/Time, File Pass to?

1) 12/7/19

Date/Time, File Return to?

2)

Report Format: 71

Lump Sum / I.B.I. (\$) 12166.48

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

G + RS, SI

Photos

Others

TOTAL

8x15=120

170+120

50

50

43

433



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003543MFSH
Our Ref: CS/FC119009731/Eqd3

Date: 07 June 2019

The Motor Claims Department
MS First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLH 5124J

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/06/2019 at the premises of M/s WEARNES AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 18,497.10</u>
Revised Estimate Amount	: <u>S\$ 12,372.30</u>
"Check" Items Amount	: <u>S\$ 3,639.50</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

Steve
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	29-05-2019	Our Ref No. D19003543MFSH
Accident Date	28-05-2019	Claim Type. Third Party
Insured Vehicle	SHA5098K	Third Party Vehicle. SLH5124J
Survey Location	BODY AND PAINT DEPT 249 ALEXANDRA ROAD	
Contact Person.	DEREK OH	
Contact No.	64304895/ 98187217	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

Handwritten signature
 (Circled 'out')

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 12 July 2019 2:34 PM
To: richmond.ho@wearnes.com
Cc: SUR
Subject: RE: Final Bill For SLH5124J

Dear Richmond,

WITHOUT PREJUDICE

Confirm final fig \$12,166.48 before GST and 7 repair days.

Kindly send the relevant documents to MS First Capital Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Steve Chen (LKK Auto)
Sent: Thursday, 11 July 2019 4:47 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: FW: Final Bill For SLH5124J
Importance: High

Dear Shiau Chan,

FYI.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Richmond Ho [<mailto:richmond.ho@wearnes.com>]
Sent: Wednesday, July 10, 2019 11:04 AM
To: Steve Chen (LKK Auto)
Cc: Derek Oh Siong Wee
Subject: Final Bill For SLH5124J
Importance: High

Hi Steve,

Please refer to above attachment for the final bill.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 7 June 2019 2:00 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003543MFSH/1
Attachments: CSFCI19009731Eqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SLH 5124J.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 3 June 2019 12:08 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003543MFSH/1

Dear Sir/Madam,

Please be informed that the vehicle currently not in workshop and repairer will arrange.

Best Regards,

Shiau Chan on behalf of G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [<mailto:admin-d@lkkauto.com>]
Sent: Monday, 3 June 2019 10:16 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003543MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Best Regards,

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1622C
Vehicle Details	
Vehicle No.:	SLH5124J
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jun 2019
Vehicle Make:	VOLVO
Vehicle Model:	S90 T6 INSCRIPTION AT SR
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	B4204T271797647
Chassis No.:	YV1PSA2BCH1006494
Maximum Power Output:	235.0 kW (315 bhp)
Open Market Value:	\$41,051.00
Original Registration Date:	08 Nov 2016
First Registration Date:	08 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$49,472.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Nov 2026
PARF Rebate Amount:	\$37,104.00
Intended COE Rebate Details	
COE Expiry Date:	07 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$39,323.00
Total Rebate Amount:	\$76,427.00

The information contained herein is correct as at 06 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/05/2019 11:54
Date Of Accident	28/05/2019 09:15
Exact Location Of Accident	SLIP RD FROM SERANGOON AVE 1 TO BARTLEY RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH5124J
Insured/Policyholder	
Name Of Registered Owner	GAUGING & AUTOMATION PTE LTD
Co Reg No	198901622C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94506050



Vehicle Particulars

Manufacturer	VOLVO
Model	S90-2.0 T6 INSCRIPTION AT SR (A)
Exact Purpose for which vehicle was being used at time of accident	SOCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100489554
Cover Note Number	

Driver

Name of Driver	TONG MINGXIU
NRIC No	S8909214J
Date Of Birth	20/03/1989
Occupation	INDOOR
Date Of Driving Pass	29/05/2012
Driving Experience	6 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-84996891
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	5 JOON HIANG RD
Postcode	548359
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - ENGINEER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA5098K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



photos attached page 4

Describe Circumstance of the Accident

SLH 5124J (Bansing Automation ME Ltd car) was exiting the slip road from Serangoon Ave 1 towards Bartley Road when SLH 5124J got hit at the rear portion of the car. Accident happened at zebra crossing of the slip road causing SLH 5124J to move across the road by about 0.5m. The car that hit SLH 5124J is car SHA50 981K a blue comfort DELGO Taxi driven by Mr NG YONG TECK of IC number 500018717. Road condition was busy morning traffic at 9:15 am. sunny day without rain.

IMPORTANT NOTE

Under **General Condition – Conduct of Claim** of the Motor Policy, you have to decide within 21 days of occurrence or discovery of damage whether or not to claim under the policy. Please check your policy for more information.

Declaration

(We declare the foregoing particulars are true in every respect)


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Steve (LKK)

 WITH APPROVAL 6/6/19, 10-15 am
 P/P 7 days
 Rep before spray

SERVICE ESTIMATE

87018 - C00001 SL: SERVICE SALES - PC

Gauging & Automation Pte Ltd

60 Kaki Bukit Place

#03-10 Eunos Techpark

Singapore 415979

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page: 1

Inv.date: 29/05/2019

WIP No. : 17053

Veh.In/Out: 28/05/2019

*Tel.No. : Mobile: 94506050KRTON

Reg.No. : SLH5124J

Reg.date: 08/11/2016

Mileage : 0

Chassis No: YV1PSA2BCH100649

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Gauging & Automation

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BOOT LID, 100	0	3200.00	0		3,200.00 S	2400 ✓
	REAR EMBLEM, REAR BUMPER,						
	REAR BRACKET, REAR SPOILER,						
	REAR SENSOR, ETC						
800	TO PUTTY SPRAY PAINT ON REAR 700	0	2800.00	0		2,800.00 S	2100 ✓
	BOOT LID, REAR BUMPER, REAR END						
	PANEL, ETC						
802	TO TRANSFER REAR BOOT LID PART	0	250.00	0		250.00 S	//
802	TO REMOVE & INSTALL REAR BOOT	0	1600.00	0		1,600.00 S	1200 ✓
	COMPARTMENT PARTS						
802	TO REPLACE REAR EXHUST	0	800.00	0		800.00 S	? X
R06	TO INSTALL REAR NUMBER PLATE	0	60.00	0		60.00 S	//
	INCLUDE HOLDER						
280	TO CHECK WIRING INCLUDE	0	480.00	0		480.00 S	//
	RESETTING OF ALL ELECTRICAL						
	MODULES						
①	BOOT REAR 390 17- / DD	1.0 EA	2240.80	20.6.72		2,240.80 S	

SERVICE ESTIMATE

87018 - C00001 SL: SERVICE SALES - PC

Gauging & Automation Pte Ltd

60 Kaki Bukit Place

#03-10 Eunos Techpark

Singapore 415979

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date. : 29/05/2019

WIP No. : 17053

Veh.In/Out: 28/05/2019

*Tel.No. : Mobile: 94506050MRTOH

Reg.No. : SLH5124J

Reg.date. : 08/11/2016

Mileage : 0

Chassis No: YV1PSA2BCH1006494

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Gauging & Automation

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	B
2	EMBLEM 'VOLVO' REAR / MC	1.0 EA	85.20	76.68		85.20	S
3	EMBLEM 'S90' S90 17- / MC	1.0 EA	78.10	70.29		78.10	S
4	EMBLEM 'T6' SVXC90 1 / MC	1.0 EA	84.00	75.60		84.00	S
5	BUMPER COVER REAR S9 / BR	1.0 EA	1412.30	1271.07		1412.30	S
6	BUMPER BRACKET LHR S / BR	1.0 EA	46.70	42.63		46.70	S
7	BUMPER BRACKET RHR S X NAI	1.0 EA	46.70			46.70	S
8	BUMPER BRACKET LHR E / BR	1.0 EA	4.50	4.05		4.50	S
9	BUMPER BRACKET RHR E X NAI	1.0 EA	4.50			4.50	S
10	BUMPER RETAINER LHR / BR	1.0 EA	28.60	25.74		28.60	S
11	BUMPER RETAINER RHR X NAI	1.0 EA	28.60			28.60	S
12	BUMPER SPACER LHR SV / BR	1.0 EA	79.20	71.28		79.20	S
13	BUMPER SPACER RHR SV X NAI	1.0 EA	79.20			79.20	S
14	PARK HOLDER LHR CTR / MC	1.0 EA	29.90	26.91		29.90	S
15	PARK HOLDER RHR CTR / MC	1.0 EA	29.90	26.91		29.90	S
16	PARK HOLDER LHR CORN / MC	1.0 EA	47.30	42.57		47.30	S
17	PARK HOLDER RHR CORN / MC	1.0 EA	47.30	42.57		47.30	S
18	PARK HOLDER LHR SIDE / MC	1.0 EA	26.90	24.21		26.90	S

SERVICE ESTIMATE

87018 - C00001 SL: SERVICE SALES - PC

Gauging & Automation Pte Ltd

60 Kaki Bukit Place

#03-10 Eunos Techpark

Singapore 415979

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Gauging & Automation

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 3

Inv.date : 29/05/2019

WIP No. : 17053

Veh.In/Out: 28/05/2019

*Tel.No. : Mobile: 94506050HRTQM

Reg.No. : SLH5124J

Reg.date : 08/11/2016

Mileage : 0

Chassis No: YV1PSA2BCH1006494

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	S
15	PARK HOLDER RHR SIDE <i>n/c</i>	1.0 EA	26.90	24.21		26.90	S
	BUMPER BRACKET REAR <i>X NAI</i>	1.0 EA	79.20			79.20	S
16	PROTECTING PLATE REA <i>CUT</i>	1.0 EA	253.30	227.97		253.30	S
17	BUMPER HOULDING REAR <i>CUT</i>	1.0 EA	188.40	169.56		188.40	S
	END PIPE BRACKET LH <i>X NAI</i>	1.0 EA	38.10			38.10	S
	END PIPE BRACKET RH <i>X NAI</i>	1.0 EA	38.10			38.10	S
18	END PIPE RIM LH T6 S <i>NAI</i>	1.0 EA	268.40	241.56		268.40	S
	END PIPE RIM RH T6 S <i>X NAI</i>	1.0 EA	268.40			268.40	S
	BUMPER RAIL REAR S90 <i>X NAI</i>	1.0 EA	1304.80			1,304.80	S
	BOOT LAMP LH S90 17- <i>X NAI</i>	1.0 EA	119.80			119.80	S
19	TAILLAMP LH S90 17- <i>NAI</i>	1.0 EA	434.00	390.60		434.00	S
	SILENCER <i>X NAI</i>	1.0 EA	705.10			705.10	S
	END PIPE <i>X NAI</i>	1.0 EA	161.60			161.60	S
	END PIPE <i>X NAI</i>	1.0 EA	436.60			436.60	S
	EXHAUST CLAMP 65mm X <i>X NAI</i>	1.0 EA	114.10			114.10	S
20	BLIND RIVET 4.0*21 P <i>n/c</i>	10.0 EA	3.00	27		30.00	S 2700
21	BUMPER CLIP 8x8.5 <i>n/c</i>	10.0 EA	5.40	49.60		54.00	S 4960

SERVICE ESTIMATE

87018 - C00001 SL: SERVICE SALES - PC

Gauging & Automation Pte Ltd

60 Kaki Bukit Place

#03-10 Eunos Techpark

Singapore 415979

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 4

Inv.date : 29/05/2019

WIP No. : 17053

Veh.In/Out: 28/05/2019

*Tel.No. : Mobile: 94506050HRTON

Reg.No. : SLH5124J

Reg.date : 08/11/2016

Mileage : 0

Chassis No: YV1P9A2BCH1006494

Closed by : Derek Oh Siong Mee

Svc Consultant :

Remarks : Gauging & Automation

Op.No	Description	Rech Qty	Price	Disc%	Pkg	Amount	g
-------	-------------	----------	-------	-------	-----	--------	---

22	BUMPER INSTALLING MT ✓ MC	1.0 EA	83.40	75.00		83.40 S	
23	ADHESIVE TUBE CHEMIC ✓ MC	2.0 EA	151.60	67.1		303.29 S	621.09

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Gross Total. 18,497.10

Labour Total 9,190.00
Parts Total 9,307.10
Package Total 0.00

Net..... 18,497.10
GST @ 7.0% 1,294.80
Total..... 19,791.90
Paid..... 0.00
Please Pay.. 19,791.90

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

18549.19



WEARNES

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD

FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01, CITY HOUSE

SINGAPORE

Singapore 068877

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 1

Inv.Date. : 10/07/2019

WIP No. : 17053

Ven.In/Out: 19/06/2019

*Tel.No. :

Reg.No. : SLH51247

Reg.date : 08/11/2016

Mileage : 0

Chassis No: YV1PSA28CH1006494

Closed by : Richmond Ho

Svc Consultant :

Remarks : Gauging & Automation

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BOOT LID, REAR EMBLEM, REAR BUMPER, REAR BRACKET, REAR SPOILER, REAR SENSOR, ETC	0	2400.00	0		2,400.00	S
800	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR END PANEL, ETC	0	2100.00	0		2,100.00	S
802	TO TRANSFER REAR BOOT LID PART	0	250.00	0		250.00	S
802	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS	0	1200.00	0		1,200.00	S
806	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER	0	60.00	0		60.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	480.00	0		480.00	S
①	BOOT REAR S90 17-①	1.0 EA	2240.80	10		2,016.72	S
②	EMBLEM "VOLVO" REAR ②	1.0 EA	85.20	10		76.68	S

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Co reg no. 198501400R / GST reg no. M28920628X



WEARNES

SERVICE ESTIMATE

U - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date : 10/07/2019

WIP No. : 17053

Veh.In/Out: 19/06/2019

*Tel.No. :

Reg.No. : SLH5124J

Reg.date : 08/11/2016

Mileage : 0

Chassis No: YV1PSA2BCH1006494

Closed by : Richmond Ho

Svc Consultant :

Remarks : Gauging & Automation

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
3	EMBLEM 'S90' S90 17-	1.0 EA	78.10	10		70.29	S
4	EMBLEM 'T6' SVXCVO 1	1.0 EA	84.90	10		75.60	S
5	BUMPER COVER REAR SV	1.0 EA	1412.30	10		1,271.07	S
6	BUMPER BRACKET LHR S	1.0 EA	46.70	10		42.03	S
7	BUMPER BRACKET LHR F	1.0 EA	4.50	10		4.05	S
8	BUMPER RETAINER LHR	1.0 EA	28.60	10		25.74	S
9	BUMPER SPACER LHR SV	1.0 EA	79.20	10		71.28	S
10	PARK HOLDER LHR CTR	1.0 EA	27.90	10		26.91	S
11	PARK HOLDER RHR CTR	1.0 EA	29.90	10		28.91	S
12	PARK HOLDER LHR CORN	1.0 EA	47.30	10		42.57	S
13	PARK HOLDER RHR CORN	1.0 EA	47.30	10		42.57	S
14	PARK HOLDER LHR SIDE	1.0 EA	26.90	10		24.21	S
15	PARK HOLDER RHR SIDE	1.0 EA	26.90	10		24.21	S
16	PROTECTING PLATE REAR	1.0 EA	253.30	10		227.97	S
17	BUMPER MOLDING REAR	1.0 EA	188.40	10		169.56	S
18	END PIPE RH LH T6 S	1.0 EA	268.40	10		241.56	S
19	TAILLAMP LH S90 17-	1.0 EA	434.00	10		390.60	S

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T+65 6430 4700 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X



WEARNES

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD
 35 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

Inv.No.: S&P 0 Page 3
 Inv.date.: 10/07/2019
 WIP No.: 17053
 Veh.In/Out: 19/06/2019
 *Tel.No.:
 Reg.No.: SLH51243
 Reg.date.: 08/11/2016
 Mileage: 0
 Chassis No: YV1PSA7BCH1006494

Closed by: Richmond Ho
 Svc Consultant:
 Remarks: Gauging & Automation

Op.No	Description	Mech Qty	Price	Disc1	Pkg	Amount B
-------	-------------	----------	-------	-------	-----	----------

99	BLIND RIVET 4.0*21 P	10.0 EA	3.00	10		27.00 S
01	BUMPER CLIP 8x8.5	10.0 EA	5.40	10		48.60 S
25	BUMPER INSTALLING HT	1.0 EA	85.40	10		75.06 S
03	ADHESIVE TUBE CHEMIC	2.0 EA	345.00	10		621.00 S
	END PIPE BRACKET LH	1.0 EA	38.10	10		34.29 S

(S&P)

(CR4)

Gross Total 12,166.48

Labour Total 5,490.00
 Parts Total 5,676.48
 Package Total 0.00

Net 12,166.48
 GST @ 7.0% 851.65
 Total 13,018.13
 Paid 0.00
 Please Pay 13,018.13

GST: S-StdRated: 0-OutOfScope: 2-ZeroRated

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19009731/Eqd3n2

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 17-07-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 5098K	Veh. Inspected	SLH 5124J
Policy No.		Coverage (\$)	0.00
Claim No.	D19003543MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	01/06/2019

2. Vehicle Particulars & Condition

Make & Model	VOLVO S90	c.c	1969
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	YV1PSA2BCH1006494	Colour	BLACK
Odometer	35653	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/40 R19	CONTINENTAL	7 mm
L/H Front Tyre	255/40 R19	CONTINENTAL	7 mm
R/H Rear Tyre	255/40 R19	CONTINENTAL	7 mm
L/H Rear Tyre	255/40 R19	CONTINENTAL	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/05/2019	Inspection Date	06/06/2019
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 5124J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT-REAR S90 17 (SN)	DENTED	2,240.80	2,016.72
1	EMBLEM "VOLVO" REAR (SN)	NECESSARY	85.20	76.68
1	EMBLEM "S90" S90 17 (SN)	NECESSARY	78.10	70.29
1	EMBLEM "T6" SVXC90 1 (SN)	NECESSARY	84.00	75.60
1	BUMPER COVER REAR S9 (SN)	BROKEN	1,412.30	1,271.07
1	BUMPER BRACKET LHR S (SN)	BROKEN	46.70	42.03
1	BUMPER BRACKET RHR S (SN)	NOT NECESSARY	46.70	-
1	BUMPER BRACKET LHR E (SN)	BROKEN	4.50	4.05
1	BUMPER BRACKET RHR E (SN)	NOT NECESSARY	4.50	-
1	BUMPER RETAINER LHR (SN)	BROKEN	28.60	25.74
1	BUMPER RETAINER RHR (SN)	NOT NECESSARY	28.60	-
1	BUMPER SPACER LHR SV (SN)	BROKEN	79.20	71.28
1	BUMPER SPACER RHR SV (SN)	NOT NECESSARY	79.20	-
1	PARK HOLDER LHR CTR (SN)	NECESSARY	29.90	26.91
1	PARK HOLDER RHR CTR (SN)	NECESSARY	29.90	26.91
1	PARK HOLDER LHR CORN (SN)	NECESSARY	47.30	42.57
1	PARK HOLDER RHR CORN (SN)	NECESSARY	47.30	42.57
1	PARK HOLDER LHR SIDE (SN)	NECESSARY	26.90	24.21
1	PARK HOLDER RHR SIDE (SN)	NECESSARY	26.90	24.21
1	BUMPER BRACKET REAR (SN)	NOT NECESSARY	79.20	-
1	PROTECTING PLATE REA (SN)	CUT	253.30	227.97
1	BUMPER MOULDING REAR (SN)	CUT	188.40	169.56
1	END PIPE BRACKET LH (SN)	NOT NECESSARY	38.10	-
1	END PIPE BRACKET RH (SN)	NOT NECESSARY	38.10	-
1	END PIPE RIM LH T6 S (SN)	BENT	268.40	241.56
1	END PIPE RIM RH T6 S (SN)	NOT NECESSARY	268.40	-
1	BUMPER RAIL REAR S90 (SN)	NOT NECESSARY	1,304.80	-
1	BOOT LAMP LH S90 17 (SN)	NOT NECESSARY	119.80	-
1	TAILLAMP LH S90 17 (SN)	BROKEN	434.00	390.60
1	SILENCER (SN)	NOT NECESSARY	705.10	-
1	END PIPE (SN)	NOT NECESSARY	161.60	-

Report Ref No. CS/FCI19009731/Eqd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	END PIPE (SN)	NOT NECESSARY	436.60	-
1	EXHAUST CLAMP 65MM X (SN)	NOT NECESSARY	114.10	-
10	BLIND RIVET 4.0 *21 P (SN)	NECESSARY	30.00	27.00
10	BUMPER CLIP 8X8,5 (SN)	NECESSARY	54.00	48.60
1	BUMPER INSTALLING MT (SN)	NECESSARY	83.40	75.06
2	ADHESIVE TUBE CHEMIC (SN)	NECESSARY	621.00	621.00
1	END PIPE BRACKET LH (ADDITIONAL)(SN)	CRUSHED	34.29	34.29
			9,659.19	5,676.48
	LABOUR			
	TO REPLACE REAR BOOT LID, REAR EMBLEM, REAR BUMPER, REAR BRACKET, REAR SPOILER, REAR SENSOR, ETC.		3,200.00	2,400.00
	TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR END PANEL, ETC.		2,800.00	2,100.00
	TO TRANSFER REAR BOOT LID PART.		250.00	250.00
	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS.		1,600.00	1,200.00
	TO REPLACE REAR EXHAUST.	NOT NECESSARY	800.00	-
	TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER.		60.00	60.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		480.00	480.00
			9,190.00	6,490.00
	GRAND TOTAL		18,849.19	12,166.48
	RECOMMENDED COST OF REPAIRS			12,166.48

Report Ref No. CS/FC119009731/Eqd3n2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.