

ASS. REC. BY:

REF: CS3/AG19009733/Ad302

Special Instruction:

Surveyor: Mr Lim

ASSIGNMENT (Office)

From (Person): Lee Yung of AG Date/Time: 03/6/19

Estimated Cost: Bill to:

OD / REP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJP 1342D Insured: SKB 7680A

at Workshop m/s Wee Hoe Tel: 6858 0019

of 19 KIM CHUAN TERRACE

Policy No: 0999994368 Claim No: 747849253686

Sum Insured: Excess:

Make of Veh: D.O.A. 30/5/19

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.P. Endorsement:

Date/Time: Person Contacted: Vehicle IN / OUT

| Date/Time | Action/Instruction     | Estimate (X)           |
|-----------|------------------------|------------------------|
|           | SJP 1342D              | NS/INC 19002423/Agd302 |
|           | SKB 7680 A             | 2019: 06/6/19          |
|           | Dismantle: 4/6/2019    |                        |
|           | After repair: 6/6/2019 |                        |

Mk Lim



# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks  
(Incorporated with limited liability)

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALI D/O MUNIANDY  
ANG KIM NOI DIANE  
RAVENDRA KRISHNASAMY  
TAN YINGXIAN, SELWYN  
CHEONG YUNHUI, CLARISSA  
EDISON TAM CHYI EU  
SONIA LIM WEI LEI

Company Registration No. 200721148H

 **Head Office:**  
133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413  
**Branch:**  
490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

**HEAD OFFICE:**

TEL : 65342811 (Hunting)  
FAX : 65356802 (General)

 E-MAIL: [annatan@visionlawllc.com](mailto:annatan@visionlawllc.com)

**BRANCH**

TEL : 63580703  
FAX : 63580448(conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to **HEAD OFFICE** for this matter

OUR REF: AW1-atv-INS-W30-SJP1342D-2019 - [please reply to: annatan@visionlawllc.com](mailto:annatan@visionlawllc.com)  
YOUR REF: SKB7680A

31 May 2019

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
CHARTIS Building  
78 Shenton Way #07-16  
Singapore 079120  
**Attn: Motor Claims Department**

**BY FAX 6835-7416 ONLY**  
[AIGSGP\\_ClaimsSurvey@aig.com](mailto:AIGSGP_ClaimsSurvey@aig.com)

Dear Sirs

**NAME OF CLAIMANT: MCT AUTO**  
**VEHICLE NUMBER: SJP1342D**  
**YOUR INSURED VEHICLE NUMBER: SKB7680A**  
**ACCIDENT ALONG CTE TOWARDS SLE (AFTER MOULMEIN EXIT) ON 30 MAY 2019 AT ABOUT 2020HOURS**

We refer to your email dated 6 June 2019 wherein there is no agreement to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

**WEE HOE AUTO SERVICE**  
19 KIM CHUAN TERRACE  
SINGAPORE 537041  
**TEL: 6858-0019 (KIAT)**

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

Audrey Wong  
(Head Office)

cc. **SJP 1342 D** - By fax 6858-0195 only

**FOR SURVEYOR**

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :  
(Name & Signature) :

Date & Time of Inspection :

**CONFIDENTIALITY**

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                       |
|----------------------------|---------------------------------------|
| Date Of Report             | 31/05/2019 13:14                      |
| Date Of Accident           | 30/05/2019 20:20                      |
| Exact Location Of Accident | CTE TOWARDS SLE (AFTER MOULMEIN EXIT) |
| Country/State of Loss      | SINGAPORE                             |

### DETAILS OF OWN VEHICLE

|                             |                 |
|-----------------------------|-----------------|
| Vehicle Registration Number | SJP1342D        |
| <b>Insured/Policyholder</b> |                 |
| Name Of Registered Owner    | MCT AUTO        |
| Co Reg No                   | 53386796K       |
| Email Address               | NOEMAIL         |
| Mobile Phone No             |                 |
| Alternative Phone No        | OFFICE-97473050 |

### Vehicle Particulars

|  |                 |
|--|-----------------|
| Manufacturer   | HYUNDAI         |
| Model  | HD AVANTE 1.6 A |
| Exact Purpose for which vehicle was being used at time of accident           |                 |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO              |
| If No, Please state action to be taken                                       | THIRD PARTY     |
| Vehicle Category   | PRIVATE HIRE    |

### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | THIRD PARTY                            |
| Fleet Policy              | NO                                     |
| Policy Number             | 5103791247 TP                          |
| Cover Note Number         |  |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | IBRAHIM BIN NORDIN    |
| NRIC No              | S7320890D             |
| Date Of Birth        | 12/06/1973            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 18/11/1999            |
| Driving Experience   | 19 YEARS AND 6 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-97473050  |
| Fax Number           |                       |
| Contact Number       |                       |
| EEmail Address       | NOEMAIL               |

|   |  |
|---|--|
| Address   | BLK 676 CHOA CHU KANG CRESCENT #06-457 |
| Postcode  | 680676                                 |
| Was driver an employee of the Insured's Company     | NO                                     |
| If No, Relationship of the Driver with the Insured  | OTHER - HIRER                          |
| Vehicle Registration Number of Driver's Own Vehicle | -                                      |
|   | -                                      |
|   | -                                      |
| Insurance Company of Driver's Own Vehicle           | -                                      |
|   | -                                      |
|   | -                                      |

#### General Information of the Accident

|                    |                 |
|--------------------|-----------------|
| Type Of Accident   | CHAIN COLLISION |
| Weather Conditions | CLEAR           |
| Road Surface       | DRY             |

#### Other Information

|   |  |
|---|--|
| Was any foreign vehicle involved in this accident?  | NO   |
| Number of vehicles (including own vehicle) involved in the accident                         | 3  |
| Was any body injured in the Accident?   | NO   |
| Was any injured conveyed to hospital by ambulance?  | NO   |
| Was any other material or property damaged?   | YES  |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO   |
| Number of Passengers (Including Driver)   | 3  |
| Passenger 1   | NAME: : GRAB PASSENGER<br>GENDER: : FEMALE |
| Passenger 2   | NAME: : GRAB PASSENGER<br>GENDER: : FEMALE |

#### Details of Police Action

|   |   |
|---|---|
| Was the accident reported to the police?  | YES   |
| If Yes, Please state which Police Station |   |
| Police Station Name                       | TRAFFIC POLICE DIVISION HQ                                    |
| Police Station Address                    | ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE |
| Police Station Contact                    | TEL NO: 65470000 - FAX NO:                                    |
| Was notice of intended Prosecution given? | NO  |
| If Yes, against whom?                     |   |

#### Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |                    |
|-----------------------------|--------------------|
| Vehicle Registration Number | SKB7680A           |
| Vehicle Make/Model/Colour   | TOYOTA VIOS E AUTO |
| Details Of Properties       |                    |
| Vehicle Category            | PRIVATE CAR        |
| Name of Driver              |                    |

NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

|                                     |                              |
|-------------------------------------|------------------------------|
| Vehicle Registration Number         | SLR3923E                     |
| Vehicle Make/Model/Colour           | HONDA VEZEL HYBRID 1.5X AUTO |
| Details Of Properties               |                              |
| Vehicle Category                    | PRIVATE CAR                  |
| Name of Driver                      |                              |
| NRIC/Passport Number                |                              |
| Contact Number                      |                              |
| Address                             |                              |
| Postcode                            |                              |
| Insurance Company Name              |                              |
| Nature Of Damage                    |                              |
| No. Of Passenger (Including Driver) |                              |

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature \_\_\_\_\_  
 Date & Time: \_\_\_\_\_

Driver's Signature \_\_\_\_\_  
 (If driver is not the policyholder)  
 Date & Time: **31 MAY 2019**

**IDAC KAKI BUKIT (VAC)**  
 23 Kaki Bukit Ave 4  
 Singapore 415933  
 Tel: 67416697 Fax: 67492305  
 Email: [crackb@singnet.com.sg](mailto:crackb@singnet.com.sg)  
 Name: \_\_\_\_\_  
 NRIC/FIN No.: \_\_\_\_\_

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to  
 police Report.

DECLARATION

I/We declare that the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

*[Signature]*  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

31 MAY 2019

**IDAC KAKI BUKIT (VAC)**  
 23 Kaki Bukit Ave 4  
 Singapore 415933  
 Tel: 67416697 Fax: 67492305  
 Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



T/20190531/2058

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20190531/2058

CONTINUATION OF REPORT

**Brief Details.**

ON THE ABOVE MENTIONED DATE, TIME AND LOCATION,

I WAS TRAVELLING ON THE LAST LANE OF CTE EXITING, THE TRAFFIC IS HEAVY SO ALL VEHICLES ARE TRAVELLING AT A SLOW SPEED. THE CAR 'A' (SKB760A) BEHIND ME COLLIDED TO THE REAR OF MY VEHICLE. A CAR 'B' (SLR3923E) COLLIDED TO CAR 'A' WHICH THEN CAUSE THE WHOLE INCIDENT. I WAS ALSO CARRYING 2 PASSENGERS AND CAR 'A' HAS 1 PASSENGER.



SINGAPORE  
POLICE FORCE



T/20190531/2058

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000


3 of 3  
Report No. T/20190531/2058

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

|   |   |
|---|---|
| Signature Of Officer Recording The Report:<br>TP /<br>NG RUI TONG  | Signature Of Informant:<br> |
| Signature Of Interpreter:<br>Not applicable   | Date/Time:<br>31/05/2019 12:22  |
| Officer In Charge Of Case:<br>TP / GIA /<br>Staff Sgt WONG SIEU LUI<br>Contact No.: 65476151  | Classification Of Case:   |
| Authentication Stamp<br>NP168   |                             |

**MOTORCAR (Rear)**

Vehicle No: 3JP1342D

**Rear Portion**

| NAC  | INC    | Item                        | CON | AC | Qt |
|------|--------|-----------------------------|-----|----|----|
| 1137 | 993626 | Rear Number Plate           |     |    |    |
| 1138 | 993627 | Rear Number Plate Base      |     |    |    |
| 1139 | 993630 | Rear Number Plate Garnish   |     |    |    |
| 1140 | 993632 | Rear Number Plate Lamp      |     |    |    |
| 1141 | 992958 | Rear Bumper                 | DD  | ✓  |    |
| 1142 | 993085 | Rear Bumper Upper           |     |    |    |
| 1143 | 993017 | Rear Bumper Lower           |     |    |    |
| 1144 | 993054 | Rear Bumper Side            |     |    |    |
| 1145 | 993103 | Rear Bumper Tow Cover       |     |    |    |
| 1146 | 992341 | Rear Bumper Clips           | NEC | ✓  |    |
| 1147 | 992976 | Rear Bumper Bracket         |     |    |    |
| 1148 | 993068 | Rear Bumper Side Retainer   | NEC | ✓  |    |
| 1149 | 993045 | Rear Bumper Reinforcement   | BR  | ✓  |    |
| 1150 | 992970 | Rear Bumper Beam            |     |    |    |
| 1151 | 993077 | Rear Bumper Sponge          |     |    |    |
| 1152 | 992999 | Rear Bumper Damper          |     |    |    |
| 1153 | 993040 | Rear Bumper Protector       |     |    |    |
| 1154 | 993036 | Rear Bumper Pad             |     |    |    |
| 1155 | 993026 | Rear Bumper Moulding        |     |    |    |
| 1156 | 993044 | Rear Bumper Reflector       |     |    |    |
| 1157 | 993023 | Rear Bumper Lower Spoiler   |     |    |    |
| 1158 | 994023 | Reverse Sensor              | BT  | ✓  | 2  |
| 1159 | 993327 | Rear End Panel              | DD  | ✓  |    |
| 1160 | 993339 | Rear End Panel Top Garnish  | DL  | ✓  |    |
| 1161 | 993333 | Rear End Panel Inner Trim   |     |    |    |
| 1162 | 990333 | Boot Compartment Inner Trim |     |    |    |
| 1163 | 993851 | Rear LH Taillamp            |     |    |    |
| 1164 | 993853 | Rear LH Taillamp Garnish    |     |    |    |
| 1165 | 993859 | Rear LH Taillamp Panel      |     |    |    |
| 1166 | 995116 | Rear RH Taillamp            |     |    |    |
| 1167 | 993853 | Rear RH Taillamp Garnish    |     |    |    |
| 1168 | 993859 | Rear RH Taillamp Panel      |     |    |    |
| 1169 | 993554 | Rear Apron Panel            |     |    |    |
| 1170 | 992895 | Bootlid                     | BT  | ✓  |    |
| 1171 | 991328 | Bootlid Emblem              | NEC | ✓  | 3  |
| 1172 | 990356 | Bootlid Handle              |     |    |    |
| 1173 | 995250 | Bootlid Moulding            |     |    |    |
| 1174 | 990376 | Bootlid Reflector           |     |    |    |
| 1175 | 995222 | Bootlid Lamp LH             |     |    |    |
| 1176 | 992899 | Bootlid Lamp RH             |     |    |    |
| 1177 | 995243 | Bootlid Lock                | BT  | ✓  |    |
| 1178 | 990377 | Bootlid Rubber weatherstrip | DL  | ✓  |    |
| 1179 | 990382 | Bootlid Hinge               |     |    |    |
| 1180 | 993877 | Bootlid Spoiler             |     |    |    |
| 1181 | 994543 | Tailgate                    |     |    |    |
| 1182 | 991328 | Tailgate Emblem             |     |    |    |
| 1183 | 994643 | Tailgate Outer Handle       |     |    |    |
| 1184 | 994640 | Tailgate Moulding           |     |    |    |
| 1185 | 994545 | Tailgate Garnish            |     |    |    |
| 1186 | 994648 | Tailgate Reflector          |     |    |    |
| 1187 | 994549 | Tailgate Lamp               |     |    |    |
| 1188 | 994646 | Tailgate Protector          |     |    |    |
| 1189 | 994676 | Tailgate Wiper Arm          |     |    |    |
| 1190 | 994677 | Tailgate Wiper Blade        |     |    |    |
| 1191 | 994679 | Tailgate Wiper Nozzle       |     |    |    |
| 1192 | 994555 | Tailgate Wiper Motor        |     |    |    |
| 1193 | 994602 | Tailgate Glass              |     |    |    |
| 1194 | 994606 | Tailgate Glass Rubber       |     |    |    |
| 1195 | 994604 | Tailgate Glass Moulding     |     |    |    |
| 1196 | 994607 | Tailgate Glass Sealant      |     |    |    |
| 1197 | 994629 | Tailgate Lock               |     |    |    |
| 1198 | 994651 | Tailgate Rubber             |     |    |    |
| 1199 | 994611 | Tailgate Hinge              |     |    |    |
| 1200 | 994594 | Tailgate Damper             |     |    |    |
| 1201 | 994613 | Tailgate Inner Board        |     |    |    |

| NAC  | INC    | Item                           | CON | AC | Qt |
|------|--------|--------------------------------|-----|----|----|
| 1202 | 993784 | Spare Tyre Board               |     |    |    |
| 1203 | 994328 | Spare Tyre Panel               |     |    |    |
| 1204 | 995065 | Spare Tyre                     |     |    |    |
| 1205 | 994326 | Spare Tyre Lock Screw          |     |    |    |
| 1206 | 993787 | Spare Tyre Cover               |     |    |    |
| 1207 | 995323 | Triangle Breakdown Sign        |     |    |    |
| 1208 | 990507 | CD Changer Assy                |     |    |    |
| 1209 | 990164 | Antenna                        |     |    |    |
| 1210 | 990534 | Centre Exhaust Pipe Assy       |     |    |    |
| 1211 | 990532 | Centre Exhaust Mounting        |     |    |    |
| 1212 | 993364 | Rear Exhaust Pipe              |     |    |    |
| 1213 | 993357 | Rear Exhaust Chrome Pipe       |     |    |    |
| 1214 | 993361 | Rear Exhaust Mounting          |     |    |    |
| 1215 | 993358 | Rear Exhaust Heat Shield       |     |    |    |
| 1216 | 995223 | Rear LH Chassis Member         |     |    |    |
| 1217 | 993165 | Rear RH Chassis Member         |     |    |    |
| 1218 | 993436 | Rear LH Fender                 |     |    |    |
| 1219 | 993449 | Rear LH Fender Protector       |     |    |    |
| 1220 | 993420 | Rear LH Fender Inner Panel     |     |    |    |
| 1221 | 993431 | Rear LH Fender Inner Trim      |     |    |    |
| 1222 | 993415 | Rear LH Fender Inner Garnish   |     |    |    |
| 1223 | 993425 | Rear LH Fender Inner Shield    |     |    |    |
| 1224 | 993621 | Rear LH Mudflap                |     |    |    |
| 1225 | 993933 | Rear LH Wheel Rim              |     |    |    |
| 1226 | 994025 | Rear LH Rim Cover              |     |    |    |
| 1227 | 995065 | Rear LH Tyre                   |     |    |    |
| 1228 | 993456 | Rear RH Fender                 |     |    |    |
| 1229 | 993450 | Rear RH Fender Protector       |     |    |    |
| 1230 | 993420 | Rear RH Fender Inner Panel     |     |    |    |
| 1231 | 993431 | Rear RH Fender Inner Trim      |     |    |    |
| 1232 | 993415 | Rear RH Fender Inner Garnish   |     |    |    |
| 1233 | 993425 | Rear RH Fender Inner Shield    |     |    |    |
| 1234 | 993622 | Rear RH Mudflap                |     |    |    |
| 1235 | 993934 | Rear RH Wheel Rim              |     |    |    |
| 1236 | 994025 | Rear RH Rim Cover              |     |    |    |
| 1237 | 995065 | Rear RH Tyre                   |     |    |    |
| 1238 | 995162 | Rear Fender Extension Panel LH |     |    |    |
| 1239 | 993401 | Rear Fender Extension Panel RH |     |    |    |
| 1240 | 993430 | Rear Fender Inner Top Garnish  |     |    |    |
| 1241 | 993673 | Rear Fender 1/4 Glass          |     |    |    |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber   |     |    |    |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant  |     |    |    |
| 1244 | 993949 | Rear Windscreen Glass          |     |    |    |
| 1245 | 993976 | Rear Windscreen Rubber         |     |    |    |
| 1246 | 993961 | Rear Windscreen Moulding       |     |    |    |
| 1247 | 993955 | Rear Windscreen Sealant        |     |    |    |
| 1248 | 994729 | Third Brake Light              |     |    |    |
| 1249 | 993385 | Rear Fender Air Grille         |     |    |    |
| 1250 | 992167 | Fuel Lid                       |     |    |    |
| 1251 | 992168 | Fuel Neck                      |     |    |    |
| 1252 | 992179 | Fuel Tank                      |     |    |    |
| 1253 | 992184 | Fuel Tank Bracket              |     |    |    |
| 1254 | 992191 | Fuel Tank Float                |     |    |    |
| 1195 | 990247 | Sticker                        |     |    |    |

No of Items: 11

Assessor: TTCM

3/6/19

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

| CLAIM SUBFOLDER TRACKING |   |               |  |  |  |             |   |
|--------------------------|---|---------------|--|--|--|-------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                              | Ins Auth'ed | Status  |
| Main                     | 03 Jun 2019<br><a href="#">Edit Reg</a> |               | 03 Jun 2019<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main  | Reference  | Claim Details          | Documents   | Show All       |                |                    |                     |                   |              |
|---|--|------------------------|---|----------------|----------------|--------------------|---------------------|-------------------|--------------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float:right">[Created by adjuster]</span>   |  |                        |   |                |                |                    |                     |                   |              |
| Insured:  | <b>ALLSWELL MOTOR TRADERS</b> , Co. Reg. No.: 53192889   |                        |   |                |                |                    |                     |                   |              |
| Main Claimant:  | <b>MCT AUTO</b> , Co. Reg. No.: 53386796K  |                        |   |                |                |                    |                     |                   |              |
| Vehicle Reg. No.:   | <b>SJP1342D</b>  | Date of Loss:          | 30/05/2019 20:00 - :59<br>[124 Months and 29 Days From LTA Reg Date (Man Yr)] |                |                |                    |                     |                   |              |
| Claim Type:   | <b>TP / 7478492536SG</b>   | Policy/Cover Note No.: | 0999994368 (Comprehensive)  |                |                |                    |                     |                   |              |
| Vehicle Reg. No. (Insured):   | <b>SKB7680A</b>  | Policy No. (Claimant): |   |                |                |                    |                     |                   |              |
|   |  | Excess:                |   |                |                |                    |                     |                   |              |
| Repairer:   | <b>Wee Hoe Auto Service (HQ)</b> 19 Kim Chuan Terrace, Singapore 537041, 537041 Kaki Bukit - Tel: 68580019                             |                        |   |                |                |                    |                     |                   |              |
| Handling Insurer:   | <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Foo, Chit Yan</b> ] Chityan.Foo@aig.com   |                        |   |                |                |                    |                     |                   |              |
| Adjuster:   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... <b>[Final Rpt due 13/06/2019]</b> |                        |   |                |                |                    |                     |                   |              |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float:right"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |  |                        |   |                |                |                    |                     |                   |              |
| <ul style="list-style-type: none"> <li>AIG_SG (04/06/2019): <b>Request To Upload TP GIA Report</b></li> </ul>   |  |                        |   |                |                |                    |                     |                   |              |
| <b>ALL ASSOCIATED TASKS</b> <span style="float:right"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |  |                        |   |                |                |                    |                     |                   |              |
| <b>Due Date</b>   | <b>Priority</b>  | <b>Type</b>            | <b>Task Group</b>   | <b>Subject</b> | <b>Handler</b> | <b>Assigned By</b> | <b>Completed On</b> | <b>Created On</b> | <b>Done?</b> |
| No results.   |  |                        |   |                |                |                    |                     |                   |              |

## Claim Documents

\*SJP1342D (7478492536SG)  
 [SKB7680A]  
 TP  
 MCT AUTO  
 May 30 2019 8:00PM  
 [ALLSWELL MOTOR TRADERS]  
 Wee Hoe Auto Service

| Upload Documents     |                 | Upload Photos                     |  | Compose New Letter |  | Upload Video |  | Upload Audio |          | View                                | View in Browser |                                     |
|----------------------|-----------------|-----------------------------------|--|--------------------|--|--------------|--|--------------|----------|-------------------------------------|-----------------|-------------------------------------|
| <b>Photos/Images</b> |                 |                                   |  |                    |  |              |  |              |          |                                     | 3 per page      | <input checked="" type="checkbox"/> |
| No                   | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |  |                    |  |              |  | Thumbnail    | Print    |                                     |                 |                                     |
| 1                    | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 2                    | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 3                    | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 4                    | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 5                    | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 6                    | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 7                    | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 8                    | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 9                    | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 10                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 11                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 12                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 13                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 14                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 15                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 16                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 17                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 18                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 19                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 20                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 21                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 22                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 23                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 24                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 25                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 26                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 27                   | 09/09/19 09:46  | General View                      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 28                   | 09/09/19 09:47  | Photographs of Damaged Parts      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 29                   | 09/09/19 09:47  | Photographs of Damaged Parts      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 30                   | 09/09/19 09:47  | Photographs of Damaged Parts      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 31                   | 09/09/19 09:47  | Photographs of Damaged Parts      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 32                   | 09/09/19 09:47  | Photographs of Damaged Parts      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 33                   | 09/09/19 09:47  | Photographs of Damaged Parts      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 34                   | 09/09/19 09:47  | Photographs of Damaged Parts      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 35                   | 09/09/19 09:47  | Photographs of Damaged Parts      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 36                   | 09/09/19 09:47  | Photographs of Damaged Parts      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |
| 37                   | 09/09/19 09:47  | Photographs of Damaged Parts      |  |                    |  |              |  |              | Load JPG | <input checked="" type="checkbox"/> |                 |                                     |

| Photos/Images |                 |   | 3 per page | <input checked="" type="checkbox"/>          |
|---------------|-----------------|---|------------|--|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         |            | Thumbnail Print                              |
| 38            | 09/09/19 09:47  | Photographs of Damaged Parts              |            | Load JPG <input checked="" type="checkbox"/> |
| 39            | 09/09/19 09:47  | Photographs of Damaged Parts              |            | Load JPG <input checked="" type="checkbox"/> |
| 40            | 09/09/19 09:47  | Photographs of Damaged Parts              |            | Load JPG <input checked="" type="checkbox"/> |
| 41            | 09/09/19 09:47  | Photographs of Damaged Parts              |            | Load JPG <input checked="" type="checkbox"/> |
| 42            | 09/09/19 09:47  | Photographs of Damaged Parts              |            | Load JPG <input checked="" type="checkbox"/> |
| 43            | 09/09/19 09:47  | Photographs of Damaged Parts              |            | Load JPG <input checked="" type="checkbox"/> |
| 44            | 09/09/19 09:47  | Photographs of Damaged Parts              |            | Load JPG <input checked="" type="checkbox"/> |
| 45            | 09/09/19 09:47  | Photographs of Damaged Parts              |            | Load JPG <input checked="" type="checkbox"/> |
| 46            | 09/09/19 09:49  | Photo After Spray                         |            | Load JPG <input checked="" type="checkbox"/> |
| 47            | 09/09/19 09:49  | Photo After Spray                         |            | Load JPG <input checked="" type="checkbox"/> |
| 48            | 09/09/19 09:49  | Photo After Spray                         |            | Load JPG <input checked="" type="checkbox"/> |
| Documentation |                 |   | 1 per page | <input checked="" type="checkbox"/>          |
| No            | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) |            | Thumbnail Print                              |
| 1             | 04/06/19 10:51  | OI GIA REPORT                             |            | Load PDF <input type="checkbox"/>            |

### Documents Checklist

| DOCUMENTS CHECKLIST  | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured.   |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>   |       |      |       |
| <div style="border: 1px solid black; width: 100%; height: 100%;"></div>  |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG19009733/BCD3E2

**Date:** 09/09/2019

#### REFERENCE

|  |                                      |                        |
|--|--------------------------------------|------------------------|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No: 0999994368                |                        |
| <b>Claimant Vehicle No :</b> SJP1342D                  | <b>Insured Vehicle No :</b> SKB7680A |                        |
| Date of Loss: 30/05/2019                               | Nature of Claim: TP                  | Claim No: 7478492536SG |

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |  |             |                   |
|-----------------------------|--|-------------|-------------------|
| Reg No:                     | <b>SJP1342D</b>                            | Engine No:  | HIDDEN            |
| Make & Model:               | HYUNDAI HD AVANTE 1.6 A (BI-FUEL), 1.6 (A) | Chassis No: | KMHDU41BR9U711811 |
| Reg. Date:                  | 01/01/2009 (Man. Year: 2009)               | Odometer:   | 310366 km         |
| Colour:                     | Silver                                     |             |                   |
| Engine Capacity:            | 1591 cc                                    |             |                   |
| Market Value/New Car Price: | N/A  |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>          |             |                   |

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

#### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/65 R15    | Rear Tyre Size:  | 195/65 R15    |
| Front Left Side:  | Goodyear 7 mm | Rear Left Side:  | Goodyear 7 mm |
| Front Right Side: | Goodyear 7 mm | Rear Right Side: | Goodyear 7 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

#### INSPECTION

|                             |                          |   |
|-----------------------------|--------------------------|---|
| Date of Assignment:         | 03/06/2019               |   |
| Date Inspected:             | 03/06/2019 Inspected At: | Wee Hoe Auto Service (HQ)<br>19 Kim Chuan Terrace, Singapore 537041<br>Singapore 537041 |
| Estimated Period of Repair: | 6.0 days                 |   |

**Adjuster:** Lim Teow Guan

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                  | Condition | Repairer's               | Amount      |             |
|-----|-----|----------|------------------------------|-----------|--------------------------|-------------|-------------|
| 1   | 1   |          | *REAR BUMPER                 | Dented    | 0.00 F                   | *- F        |             |
| 2   | 1   |          | *REAR BUMPER CLIPS           | Necessary | 0.00 F                   | *- F        |             |
| 3   | 1   |          | *REAR BUMPER SIDE RETAINER   | Necessary | 0.00 F                   | *- F        |             |
| 4   | 1   |          | *REAR BUMPER REINFORCEMENT   | Broken    | 0.00 F                   | *- F        |             |
| 5   | 2   |          | *REVERSE SENSOR              | Cut       | 0.00 F                   | *- F        |             |
| 6   | 1   |          | *REAR END PANEL              | Dented    | 0.00 F                   | *- F        |             |
| 7   | 1   |          | *REAR END PANEL TOP GARNISH  | Dislodged | 0.00 F                   | *- F        |             |
| 8   | 1   |          | *BOOTLID                     | Bent      | 0.00 F                   | *- F        |             |
| 9   | 3   |          | *BOOTLID EMBLEM              | Necessary | 0.00 F                   | *- F        |             |
| 10  | 1   |          | *BOOTLID LOCK                | Bent      | 0.00 F                   | *- F        |             |
| 11  | 1   |          | *BOOTLID RUBBER WEATHERSTRIP | Distorted | 0.00 F                   | *- F        |             |
|     |     |          |                              |           | <b>Total Parts (S\$)</b> | <b>0.00</b> | <b>0.00</b> |

F=Franchise part.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >