




**ASSIGNMENT**

Vehicle: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 (GD) / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Repair Vehicle No: \_\_\_\_\_  
 at Workshop no: \_\_\_\_\_  
 id: \_\_\_\_\_  
 Account: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claim No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.  
 Est. or Market Value: \_\_\_\_\_  
 IDAC Accident Report Consistent? : Yes or No  
 CAR / PE / Seen Consistent? : Yes or No  
 Est. Repair: 4 days Res: Yes or No  
 Loss Sum 20 % J Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Job No: **FBM 1846C** Date: **Aug 2017**  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: **Honda CB400 SF** CC: **399**  
 Color: **Red** ACC: Insured / Std / NI / NA  
 Up Roading: **12717** U/C: Insured / Std / NI / NA  
 Eng/No: **NC42E1207938**  
 C/No: **HC421803500**  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Insured / Jammed / Leaked / Burnt or  
 Brake: Good / Jammed / Leaked / Burnt or  
 Mod: Nil / SRim / STD A/Rim or  
 Tyre Size: F: **120/60 R17**  
 R: **160/60 R17**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Dunlop**  
 Front Front  
 R/Bal. 2 mm R/Bal. 2 mm  
 L/Bal. mm L/Bal. mm  
 D.O.A. 29/05/2019 D.O.I. 03/06/2019  
 Survey held at **SG 98 Motor AMK**  
 Des. of Damages: FIT / Rear / OFS / NIS / UIC / Rooftop or  
**Front 1/4 S Body**  
 The UIC / Chassis frame / Body Structure affected due to collision.



Entry / Date	Action / Instruction
	Chnc Taping XB 8687 X
	MV 15K LTA 4.4K NL 10.6K
	RECEIVED 20 NOV 2019
18/11/19	Final 1/5 4500 - with Rose (Red @ 4719.20, 51%) 4 days of rep

Date/Time, File Path to:  : Profi. Report  
 18/11/19 to 19/11/19  : Final Report  
 Date/Time, File Path to: \_\_\_\_\_  
 Days Of Repair: 4  
 Resurvey No. of Trip: 2  
 Add Fee:  Site Insp £  
 Interview £  
 Tech. Ins £  
 Weekend £  
 Survey Fee: **220**  
 Transporter: \_\_\_\_\_  
 G + H: \_\_\_\_\_  
 Hubs: \_\_\_\_\_  
 Hubs: \_\_\_\_\_  
 1011 **220**

Rep. Form: \_\_\_\_\_  
 Temp. Cost: 4500

## Catherine Chong (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Monday, 3 June, 2019 8:44 AM  
**To:** Sg Motor  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D202439 - Please arrange PRI on bike FBM 1846C

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### Chong Boon Sen

Claims Executive  
Department

#### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Sg Motor [mailto:sgmotor2000@yahoo.com.sg]  
**Sent:** Friday, 31 May, 2019 5:16 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** Re: OUR REF: SNM19D202439 - Please arrange PRI on bike FBM 1846C

Hi,

Pls arrange Mr Xing Quo Qiang to survey the bike FBM 1846C.

Thank You  
rose

Regards

### SG 98 Motor Pte Ltd

Blk 4001 #01-21  
Ang Mo Kio Industrial Park 1  
Singapore 569622  
Tel: 64524898 Fax: 64526898

On Friday, 31 May 2019, 9:01:44 am GMT+8, Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

### **Chong Boon Sen**

Claims Executive

Department

### **China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](http://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Lim Shu Min  
**Sent:** Friday, 31 May, 2019 8:51 AM  
**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; [sgmotor2000@yahoo.com.sg](mailto:sgmotor2000@yahoo.com.sg); Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>  
**Subject:** OUR REF: SNM19D202439 - Please arrange PRI on bike FBM 1846C

Dear Boon Sen,

Please conduct PRS – FBM1846C soonest possible.

File with Officer-In-Charge – Chong Boon Sen - 63896171

Thank you

**Lim Shu Min**

Executive

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896156 | F: (65) 62247175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI  
**Sent:** Thursday, 30 May, 2019 4:30 PM

**To:** Lim Shu Min <[shumin.lim@sg.cntaiping.com](mailto:shumin.lim@sg.cntaiping.com)>  
**Subject:** FW: Please arrange PRI on bike FBM 1846C

---

**From:** Sg Motor [<mailto:sgmotor2000@yahoo.com.sg>]  
**Sent:** Thursday, 30 May 2019 4:29 PM  
**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Cc:** Sg Motor <[sg\\_motor\\_enterprise@yahoo.com.sg](mailto:sg_motor_enterprise@yahoo.com.sg)>  
**Subject:** Please arrange PRI on bike FBM 1846C

Dear Sir/Madam

Please arrange PRI on bike FBM 1846C as per attached.

Thank You

Regards

Linda

**SG 98 Motor Pte Ltd**

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/06/2019 13:36
Date Of Accident	29/05/2019 13:30
Exact Location Of Accident	LIM CHU KANG PATH 4 CHINESE CEMETARY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBM1846C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TEO LIANG HONG
NRIC No	S1778967H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91882617
Alternative Phone No	OTHERS-91882617

### Vehicle Particulars

Manufacturer	HONDA
Model	REVO CB 400
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5093490928-01
Cover Note Number	

### Driver

Name of Driver	TEO LIANG HONG
NRIC No	S1778967H
Date Of Birth	31/01/1966
Occupation	INDOOR
Date Of Driving Pass	06/08/1996
Driving Experience	22 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91882617
Fax Number	
Contact Number	OTHERS-91882617
EEmail Address	NOEMAIL

Address	BLK 384 TAMPINES ST 32 #11-37
Postcode	520384
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED - VEHICLE B REVERSED AND HIT MY VEHICLE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XB8687X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	RAJANGAM GANESH
NRIC/Passport Number	G8480851U
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	TEO LIANG HONG
------	----------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

LEFT ANKLE SWOLLEN / BACK PAIN

FBM1846C

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repeal policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


ON 29th May at 1:30pm : I was riding my bike no: FBM 1846c along Kim Chu Kang Path 4. The weather was clear + dry. I stopped on the side of the road to check the direction. Suddenly a heavy truck. XB 8687X reversed without checking the blind-spot and I was about 2-3 car length behind the truck (XB 8687X). I started honking at the driver but it did not stop - I then jump off to my left and it hit the frontal of my bike FBM 1846c causing major damaged (frontal) - I sustained injuries to my left ankle + wrist pain (Back pain). The truck driver - Rajangan Ganesh Fin no: G8400851U then alighted and apologized to me for his negligence. Due to the major damaged to my bike and cost. I'm lodging this report for insurance claim purpose. The same day - I then go to Healthway medical to seek treatment for my injuries + was given 2 days medical leave. I'll be forwarding all my damages to the XB 8687X Insurance Company.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 3 June 2019

To : LKK

By Fax: 6256-4315

Attn: Bryan Ang

Tel: 97237799

VEHICLE NO : FBM 1846C

Honda Revo 400

ACCIDENT DATE: 29 May 2019

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Handle Bar NN	1	180.00 X
2 Head Lamp Bracket <i>kt</i>	1	185.00 ✓
3 Head Lamp <i>Dendra</i>	1	450.00 ✓
4 Fork <i>kt</i>	2	760.00 ✓
5 Fork Under Bracket <i>Down</i>	1	320.00 ✓
6 Front Mudguard <i>crack/broken</i>	1	265.00 ✓
7 Fork Guard L/RH <i>Cut</i>	2	380.00 ✓
8 Front Rim <i>kt</i>	1	1,100.00 ✓ <i>600/-SN</i>
9 Head Lamp Rim <i>kt/Dendra</i>	1	175.00 ✓
10 Brake Lever <i>broken</i>	1	65.00 ✓
11 RH Mirror NN	1	150.00 X
12 LH Signal <i>broken</i>	1	150.00 ✓
13 Balancer <i>Cut</i>	1 set	150.00 ✓
14 Brake Disc NN	1	560.00 X
15 Fork Oil Seal <i>new</i>	1	68.00 ✓
16 Crash Bar <i>Dendra</i>	1 set	450.00 <i>450/-</i>
17 RH Side Engine <i>Cover Cut</i>	1	480.00 ✓
18 Clutch Lever NN	1	95.00 X
19 Front Wheel Shaft <i>distorted</i>	1	180.00 ✓
20 Side Stand <i>kt</i>	1	95.00 ✓
	Sub-Total	6,238.00
	Less 10%	623.80
	Sub-Total	5,614.20

4173.00

10% 3755.70

VEHICLE NO : FBM 1846C

Honda Revo 400

Nett Items

1 Front Tyre <i>cut 20% depletion</i>	210.00	150/-	30/-
2 Rear Tail Box <i>SLV</i>	380.00	X	
3 Rear Carrier Box <i>SLV</i>	280.00	X	
4 Front number plate <i>SLV</i>	15.00	✓	
5 Towing fee <i>NW</i>	50.00	X	
6 Remove & replace necessary parts, align & etc	280.00	200/-	
7 Remove & replace fork assy, top up fork oil, oil seal change	200.00	80/-	
8 Remove & replace front rim, tyre, brake disc & wheel shaft	180.00	20/-	
9 Touch up & respray paint	280.00	80/-	
10 Check & reconnect harness wiring	60.00	30/-	
11 Gasket Set <i>NW</i>	120.00	40/-	

1095.00

Special Nett Items

1 Meter Assy <i>Check</i>	800/-	1,550.00	800/-
---------------------------	-------	----------	-------

Sub-Total 3,605.00  
 Nett Total 9,219.20

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

5650.70  
 L/S 4500/-

Kindly revert upon completion. Thank you

  
 SG 98 MOTOR PTE LTD

03/06/2019 e 1200m  
 NA Auction  
 25m

3 *you* 4 days  
 LKK Auto  


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Nov 2019		18 Nov 2019 10:17 <a href="#">Edit Adj Rpt</a>	<b>S\$4,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	-, Co. Reg. No.: 0		
Main Claimant:	TEO LIANG HONG, ID: S1778967H		
Vehicle Reg. No.:	FBM1846C	Date of Loss:	29/05/2019 13:00 - :59 [21 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202439C02	Policy/Cover Note No.:	DMCVSN17193419022
Vehicle Reg. No. (Insured):	XBB687X	Policy No. (Claimant):	5093490928-01
		Excess:	S\$0.00
Repairer:	Sg 9B Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 27/11/2019]		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

## Claim Documents

\*FBM1846C (SNM19D202439C02)  
[XBB687X]  
TP  
TEO LIANG HONG  
May 29 2019 1:00PM  
[-]  
Sg 98 Motor Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View	View in Browser
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail Print
1	03/06/19 13:48	<b>Accident Statement</b>		Load HTML
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail Print
1	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
2	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
3	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
4	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
5	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
6	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
7	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
8	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
9	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
10	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
11	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
12	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
13	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
14	03/06/19 13:47	<b>Accident Photo</b> <small>[Linked Accident Report Documents]</small>		Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	19/11/19 16:30	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
2	19/11/19 16:30	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
3	19/11/19 16:30	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
4	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
5	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
6	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
7	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
8	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
9	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
10	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
11	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
12	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
13	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
14	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
15	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
16	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
17	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
18	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
19	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
20	19/11/19 16:31	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
21	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
22	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
23	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
24	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
25	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
26	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
27	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
28	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
29	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
30	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
31	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
32	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
33	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
34	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
35	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
36	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
37	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
38	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
39	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
40	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
41	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
42	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
43	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
44	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
45	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
46	19/11/19 16:32	Odometer Reading		<input checked="" type="checkbox"/>
47	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
48	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
49	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
50	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
51	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
52	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
53	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
54	19/11/19 16:32	General View		<input checked="" type="checkbox"/>
55	19/11/19 16:41	Reinspection Photo		<input checked="" type="checkbox"/>
56	19/11/19 16:41	Reinspection Photo		<input checked="" type="checkbox"/>
57	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
58	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
59	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
60	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
61	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
62	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
63	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
64	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
65	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
66	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
67	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
68	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
69	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
70	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
71	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
72	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
73	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
74	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
75	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>
76	19/11/19 16:42	Reinspection Photo		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
77	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	19/11/19 16:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	19/11/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	19/11/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	19/11/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	19/11/19 16:43	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	03/06/19 13:47	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	03/06/19 13:47	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	03/06/19 13:48	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	03/06/19 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	03/06/19 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	03/06/19 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	03/06/19 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	03/06/19 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	03/06/19 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	03/06/19 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	03/06/19 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	03/06/19 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	03/06/19 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	03/06/19 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	03/06/19 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	03/06/19 13:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
14	03/06/19 13:47	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	03/06/19 13:47	Sketch Plan		Load TIF	
2	03/06/19 13:47	Sketch Plan #2		Load TIF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT119009741/DQD3E2

**Date:** 29/11/2019

#### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17193419022
Claimant Vehicle No :	FBM1846C	Insured Vehicle No :	XB8687X
Date of Loss:	29/05/2019	Nature of Claim: TP	Claim No: SNM19D202439C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM1846C	Engine No:	NC42E1207938
Make & Model:	HONDA CB400, 399cc	Chassis No:	NC421803500
Reg. Date:	15/08/2017 (Man. Year: 2017)	Odometer:	12717 km
Colour:	Red		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	120/60 R17	Rear Tyre Size:	160/60 R17
Front Left Side:	Dunlop 2 mm	Rear Left Side:	Dunlop 2 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,169.20	5,240.70	2,928.50	35.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	410.00	640.00	60.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,219.20</b>	<b>5,650.70</b>	<b>3,568.50</b>	<b>38.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,219.20</b>	<b>4,500.00</b>	<b>4,719.20</b>	<b>51.19</b>

#### INSPECTION

Date of Assignment:	18/11/2019	
Date Inspected:	03/06/2019 Inspected At:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 Singapore 569622
Estimated Period of Repair:	4.0 days	

**Adjuster:** BRYAN TANI

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b>	(Last Synchronised: 29 Nov 2019)
<b>Parts:</b>	N/A HONDA CB400 399cc (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBM1846C)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Not Necessary	160.00 FL	*- FL
2	1		*HEAD LAMP BRACKET	Bent	185.00 FL	*185.00 FL
3	1		*HEAD LAMP	Dented	450.00 FL	*450.00 FL
4	2		*FORK	Bent	760.00 FL	*760.00 FL
5	1		*FORK UNDER BRACKET	Damaged	320.00 FL	*320.00 FL
6	1		*FRONT MUDGUARD	Cracked / Broken	265.00 FL	*265.00 FL
7	2		*FORK GUARD L/RH	Cut	380.00 FL	*380.00 FL
8	1		*HEAD LAMP RIM	Bent / Dented	175.00 FL	*175.00 FL
9	1		*BRAKE LEVER	Broken	65.00 FL	*65.00 FL
10	1		*RH MIRROR	Not Necessary	150.00 FL	*- FL
11	1		*LH SIGNAL	Broken	150.00 FL	*150.00 FL
12	1		*SET BALANCER	Cut	150.00 FL	*150.00 FL
13	1		*BRAKE DISC	Not Necessary	560.00 FL	*- FL
14	1		*FORK OIL SEAL	Necessary	68.00 FL	*68.00 FL
15	1		*SET CRASH BAR	Dented	450.00 FL	*450.00 FL
16	1		*RH SIDE ENGINE COVER	Cut	480.00 FL	*480.00 FL
17	1		*CLUTCH LEVER	Not Necessary	95.00 FL	*- FL
18	1		*FRONT WHEEL SHAFT	Distorted	180.00 FL	*180.00 FL
19	1		*SIDE STAND	Bent	95.00 FL	*95.00 FL
20	1		*FRONT RIM	Bent	990.00 FS	*600.00 FS
21	1		*FRONT TYRE	Cut	210.00 FS	*30.00 FS
			(\$150.00) (20%)			
22	1		*REAR TAIL BOX	Serviceable	380.00 FS	*- FS
23	1		*REAR CARRIER BOX	Serviceable	280.00 FS	*- FS
24	1		*FRONT NUMBER PLATE	Bent	15.00 FS	*15.00 FS
25	1		*METER ASSY	Cracked	1,550.00 FS	*800.00 FS
26	1		*SET GASKET	Necessary	120.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>8,683.00</b>	<b>5,658.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	513.80	417.30
<b>Total Parts (S\$)</b>	<b>8,169.20</b>	<b>5,240.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING FEE.	New	50.00	0.00
2	REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC.	New	280.00	200.00
3	REMOVE & REPLACE FORK ASSY, TOP UP FORK OIL, OIL SEAL CHANGE.	New	200.00	80.00
4	REMOVE & REPLACE FRONT RIM, TYRE, BRAKE DISC & WHEEL SHAFT.	New	180.00	20.00
5	TOUCH UP & RESPRAY PAINT.	New	280.00	80.00
6	CHECK & RECONNECT HARNESS WIRING.	New	60.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,050.00</b>	<b>410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >