

Neiman

REF CS3/III 19005026/Ggd3br-1

ASSIGNMENT (Office)

GA
Gabriel wee

III
Billie

03/6/19
~~14/3/19 @ 3:37pm~~

From (Vehicle)
To (Workshop)

OD / (A) WS / TP RES / OD RES / EVA / RV / MY / (S)

To (Inspect Vehicle) On

SLG 7806S
Motor Intel

Issued SHA 15932
Tel 8838338

13 kaki Bukit Rd 4 #01-20
MCOM 0015

Chun Ho

MCT 19030351

of

Policy No

Time Received

Make of Vehicle

(C) Don't Record

DOA 13/3/19

CA / REV / REP / RRV 24 HRS

Date/Time 10:23am @ 20/3/19 Person Controlled

Wilson

ROAD Endorsement

Vehicle IN (OUT)

Date/Time

Actual/Estimate (X) Estimate

SLG 7806S - X

SHA 15932 - (C4/III 19004927/10/13


DOA - 07/03/2019

Dismantle: 7/5/2019 @ 06:00pm

After repair: 10/5/2019 @ 02:47pm

\$2700, 5 Days.

(Cost \$3700, 56%)


27/6/2019

290-130+10=17

Singer

REF:

AII

B 8607J

ASSIGNMENT

(-2022)

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

Motor Intel

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$21K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SG7806S

Yr Regn:

05 Apr 2007

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota wish

c.c

1794

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

298595

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZNE100353 885

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A.

D.O.I.

06-05-19

Survey held at

w/s

4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

COTE: \$15142.

7/5/2019

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

2

Survey Fee:

120

Transportation:

S + RS \$

Photos

Others

)

TOTAL

10

130

Report Format:

PRG

Lump Sum / I.B.I: (\$

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Catherine Chong (LKK Auto)

From: Stanley Lai <stanley.lai@iii.com.sg>
Sent: Monday, 3 June, 2019 4:10 PM
To: 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Mekavathanan Sarangapani; Sundari Nagarajan - III
Subject: III REF: MCT19030351 | REQUEST PAPER SURVEY - TPV SLG7806S

Dear Sir/Mdm,

Rights granted in Merimen for the above LOD. Kindly proceed with the paper survey.

TP Veh No. : SLG7806S

Warmest regards,

Stanley Lai

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

S&P 'A-' rated Company



This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 19 March 2019 3:37 PM
To: Natalie Ng; 'sur@lkkauto.com'; admin-d@lkkauto.com
Cc: Sundari Nagarajan - III
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLG7806S (Accident involving SLG7806S and SHA1593Z on 13.03.2019)
Attachments: sha1593z_20190319114743.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SLG7806S
III INSURED VEHICLE NO. : SHA1593Z
DATE OF LOSS : 13.03.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sundari**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Natalie Ng [mailto:natalie_ng@rssolomon.com]
Sent: 19 March, 2019 12:07 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLG7806S (Accident involving SLG7806S and SHA1593Z on 13.03.2019)

Dear Mr Wee,

We thank you for your email of even date.

We write to inform that our clients will be appointing their own surveyors.

In this regard, please arrange your surveyors to contact Ms Ivy Pang of Motor Intelligence Automo Pte. Ltd. at Tel: 6281 0087 for a pre-repair survey of our client's vehicle located at 13 Kaki Bukit Road 4 #01-20 Bartley Biz Centre Singapore 417807.

Thank you and Best Regards,

Natalie Ng | Office Manager 人事与行政经理

R. S. Solomon LLC | 正氣律師事務所

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e natalie_ng@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information. If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including attachment) from your computer system. Thank you.

On Tue, 19 Mar 2019 at 11:55, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	8607J
Vehicle No.:	SLG78065
Vehicle to be Exported:	No
Intended Deregistration Date:	06 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	1ZZ2836805
Chassis No.:	ZNE100353885
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$16,725.00
Original Registration Date:	05 Apr 2007
First Registration Date:	05 Apr 2007
Transfer Count:	1
Actual ARF Paid:	\$18,398.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	04 Apr 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$26,004.00
COE Rebate Amount:	\$15,142.00
Total Rebate Amount:	\$15,142.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 May 2019

OK



SEARCH

Home > Used Cars > Carz World Pte Ltd > Toyota Wish 1.8A (COE till 03/2022)

▶ Toyota Wish 1.8A (COE till 03/2022)

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price	\$21,988		
Depreciation ⓘ	\$7,580 /yr	Reg Date	24-Apr-2007 (2yrs 10mths 24days COE left)
Mileage	112,000 km (9.3k /yr)	Manufactured ⓘ	2006
Road Tax ⓘ	\$1,166 /yr	Transmission	Auto
Dereg Value ⓘ	\$14,608 as of today (change)	OMV ⓘ	\$18,690
COE ⓘ	\$25,174	ARF ⓘ	\$20,559
Engine Cap	1,794 cc	Power	97.0 kW (130 bhp)
Curb Weight ⓘ	1,320 kg	No. of Owners ⓘ	1
Type of Vehicle	MPV		



[☆ Shortlist](#)
[Report Error](#)

Features

1.8L DOHC 16V VVT-i Engine, Smooth 5 Speed Steptronic Gearbox, Digital Climatic Control Aircon, Dual Airbags, ABS, 7 Seaters.

Accessories

Sports Rims, Leather Seats, Reverse Sensors, Electrical Retractable Side Mirrors.

Description

1 Faithful Owner For 13 Years With Low Mileage, Hardly Used Except To Ferry Grandchildren To School. The Wish Has Always Been The Trusted By Singaporeans On Its Reliability As A MPV. Come And Experience The Durability Of Japanese Engineering At Its Finest. The Wish Comes With Sunroof Which Brings Additional Vibrancy During Your Drive. Come Down For A Viewing And Make Your Wish Come True!

Category

COE Car, Premium Ad Car, Low Mileage Car

Status

Av. [Compare](#)

Seller Information

Company

Address

Location

Office No

Contact
Person(s)

► Toyota Wish Used Vehicle List (19 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Toyota Wish 1.8A (COE till 03/2024) Office No. - 63443344 Wan - 82805406 2.98% Per Annum. \$638 Monthly. \$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warranty For Engine And Gearbox. New 2k Metallic Paint. New Pure Leather. New Rims, 16" Tyres. New Pl...	\$34,800	\$7,100 /yr	01-Apr-2009	1,794 cc	-	GV Credit Pte Ltd	Availal
Toyota Wish 1.8A (COE till 11/2020) A018 Consignment Unit. Flexible Loan Packages Available To Choose From. No Hidden Cost. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us. Viewing By Appointmen... Office No. - 63443344 Francis Chen - 87539539	\$13,888	\$8,850 /yr	24-Dec-2005	1,794 cc	270,500 km	GV Credit Pte Ltd	Availal
Toyota Wish 1.8A Sunroof (COE till 01/2021) 6 Months Warranty. Office No. - 67930080 Richard - 81667779 Soh - 97955598	\$15,800	\$9,420 /yr	09-Jan-2006	1,794 cc	-	StarBright Auto	Availal
Toyota Wish 1.8A (COE till 02/2021) Weekend Promo!Don't Take The Risk!Buy From A Case Trust Col!Beautiful TOYOTA WISH Looking For New Owner!Too Good For De-Registration. Preciously Taken Care And Well Maintained By Previous Owner Mdm Yat... Office No. - 64666220 Frankie Chen - 97281121 Shah - 97308666 Darren Yeo - 86088466 Nanda - 84374929	\$19,800	\$11,050 /yr	20-Feb-2006	1,794 cc	127,452 km	Car House Pte Ltd	Availal
Toyota Wish 1.8A (COE till 03/2021) Engine, Gearbox And Undercarriage Are All In Good Running Condition, No Repair Is Needed. Owner Registering Existing Car Plate Numbers New Car. A New Car Plate Numbers Will Be Allocated. Office No. - - James - 81170055	\$16,800	\$9,080 /yr	13-Mar-2006	1,794 cc	-		Availal
Toyota Wish 1.8A Sunroof (COE till 05/2021) "One Year In-House Warranty", High Loan Available, Price Stated Above Is Actual Selling Price, Bank & In-House Loan Available, Purchase Comes With Official Warranty Certificate For A Peace Of Mind, Fu... Office No. - - Sam Ong - 86660777 Angel Chai - 83831777	\$17,800	\$8,850 /yr	11-May-2006	1,794 cc	151,000 km	Carway	Availal
Toyota Wish 1.8A (COE till 05/2021) "One Year In-House Warranty", High Loan Available, Price Stated Above Is Actual Selling Price, Bank & In-House Loan Available, Purchase Comes With Official Warranty Certificate For A Peace Of Mind, Fu... Office No. - 68440777 Peter Quek - 84840777 Tanisha - 88665777 Addy Ho - 88330777	\$17,800	\$8,790 /yr	16-May-2006	1,794 cc	-	Carway	Availal
Toyota Wish 1.8A (COE till 05/2021) - Office No. - - John Fernandis - 98190331	\$16,800	\$8,230 /yr	22-May-2006	1,794 cc	340,000 km		Availal
Toyota Wish 1.8A (COE till 05/2026)	\$45,800	\$6,480 /yr	06-Jun-2006	1,794 cc	165,133 km	Lake View Credit Pte Ltd	Availal

Safest Buy, Wish 1.8A With Low Depreciation And High Paper Value! Super Low Mileage Clocked Of 13000km Annually. No Further Repairs Needed. 1 Owner. Road Tax Till Jun 19. 100% Accident Free. Call Now!

Office No. - 67459995

Frands - 96778690 | Kelvin - 98789995 | John Gan - 90478223

Toyota Wish 1.8A (COE till 05/2021) **\$16,388** **\$7,920 /yr** **07-Jun-2006** **1,794 cc** **-** **ABS Auto Capital Pte Ltd** **Availal**

We Are The COE Specialist. No Gimmicks, Honest Dealing, 2 Owners With Low Mileage Clocked, Car In Very Good Condition, Full Loan Available! 100% Approval. Trade In Welcome, Bank Loan Available. Please...

Office No. - 64753423

Ken - 91196006 | Kenny - 98259995 | Roy - 83158315 | Alex - 82298229

Toyota Wish 1.8A (COE till 05/2021) **\$17,800** **\$8,610 /yr** **14-Jun-2006** **1,794 cc** **-** **ST Carz Pte Ltd** **Availal**

Selling Cheap For Sincere Buyers! Car In Beautiful Flawless Condition! 100% Accident-Free! STA Evaluation! View To Believe! High And Flexi Loan Available! Call Us Now To Make An Appointment To View...

Office No. - 64654747

Ryan - 90778009 | Chris Liao - 83565566 | Daven - 88225151

Toyota Wish 1.8A (COE till 06/2021) **\$16,500** **\$7,820 /yr** **16-Jun-2006** **1,794 cc** **158,000 km** **SD Motors Pte Ltd** **Availal**

Beautiful MPV Needs A New Owner! Engine And Gearbox Running Smoothly. Previously Taken Care And Well Maintained By Previous Owner Top Original Condition! Very Little Cash To Drive Away! So Hurry D...

Office No. - -

Rey - 86669749 | Damien - 96735465 | Rita - 91132943

Toyota Wish 1.8A (COE till 05/2021) **\$17,800** **\$8,610 /yr** **29-Aug-2006** **1,794 cc** **-** **Availal**

I'm The First Owner And Have Driven This Car Since Brand New, 2 Ownership Due To COE Finance, Regular Maintenance Carry Out By Friend Workshop Over The Years, Never Once Breakdown While Driving, Reliab...

Office No. - -

S H - 90012229 | K H - 84999448

Toyota Wish 1.8A (COE till 10/2021) **\$19,800** **\$8,230 /yr** **02-Oct-2006** **1,794 cc** **-** **Cars 19** **Availal**

Well Kept. Good Condition. High Paper Value. High Trade In. Bank Loan And In House Loan Available.

Office No. - 63385723

Brandon - 90034566 | Wilson - 90067020

Toyota Wish 1.8A (COE till 11/2026) **\$49,800** **\$6,600 /yr** **21-Nov-2006** **1,794 cc** **137,378 km** **Leco Auto Pte Ltd** **Availal**

Depreciation At \$540 Monthly! 100% Safe Buy With Low Risk Involved. The Scrap Value Is Already \$43,000! Beautiful Condition Inside Out. Space, Reliability, Good Fuel Economy, Affordability, You Get Al...

Office No. - 68410020 / 68460020

Eric - 90550932 | Edmund - 81611022 | Douglas - 96680056

Toyota Wish 1.8A (COE till 10/2026) **\$49,900** **\$6,660 /yr** **23-Nov-2006** **1,794 cc** **145,000 km** **Availal**

Selling 5k Above Paper! Price Slightly Nego. Owner Relocating. Minimal Loss! Good For Both Short And Long Term Drive. Engine, Gearbox And Undercarriage Are All In Good Running Condition, No Repair Is ...

Office No. - -

Lawrence - 91999690

Toyota Wish 1.8A (COE till 01/2022) **\$20,838** **\$7,770 /yr** **11-Jan-2007** **1,794 cc** **155,000 km** **Hoe Beng Auto Trading** **Availal**

High Trade In Most Welcome! Flexible Bank/In-House Loan Available! 100% Loan Can Be Arranged! View To Believe! Don't Miss, Call Now To Arrange A Test Drive Today!

Office No. - 67450138 / 65523003

Eric - 83538778 | Agnes - 93680138 | Lee - 98300138

Toyota Wish 1.8A (COE till 03/2027) **\$45,988** **\$5,820 /yr** **20-Apr-2007** **1,794 cc** **130,175 km** **Carz World Pte Ltd** **Availal**

Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Bank And In House Loan Available! Trade In Welcome. Call For Appointment To A Test Drive Now Before The Car Is Gone.

Office No. - 65709482

Carson Chen - 96754500 | Venessa Chua - 96262237 | Ben Lam - 87428218

Toyota Wish 1.8A (COE till 03/2022) **\$21,988** **\$7,580 /yr** **24-Apr-2007** **1,794 cc** **112,000 km** **Carz World Pte Ltd** **Availal**

1 Faithful Owner For 13 Years With Low Mileage, Hardly Used Except To Ferry Grandchildren To School. The Wish Has Always Been The Tru By Singaporeans On Its Reliability As A MPV. Come And Experien...

Office No. - 65709482

Joel Yew - 93874209 | Jason Tan - 81980412 | Edwin Foo - 96437773

Toyota Wish 1.8A X (COE till 08/2022) **\$30,800** **\$9,510 /yr** **02-Aug-2007** **1,794 cc** **118,300 km** **Car House Pte Ltd** **Availal**

Sporty Black Colour Unit. Low Mileage. Well Maintained By Previous Owner. The Most Reliable And Low Maintenance. Smooth Gearbox And Engine. Flexible Loan And Trade In Are Welcome. Please Contact Our Fr...

Office No. - 64631939

Michelle - 86063381 | Teo - 96116191 | Damien - 87848949 | Wing - 82273461

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/03/2019 17:21
Date Of Accident	13/03/2019 15:45
Exact Location Of Accident	ALONG SIMS AVENUE(INFRONT OF 450 SIMS AVENUE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG7806S
Insured/Policyholder	
Name Of Registered Owner	BLEND AUTO
Co Reg No	53348607J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88284828
Alternative Phone No	OFFICE-88284828

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5106866429
Cover Note Number	

Driver

Name of Driver	TAN EE HONG
NRIC No	S9179984G
Date Of Birth	22/10/1991
Occupation	OUTDOOR
Date Of Driving Pass	29/05/2015
Driving Experience	3 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88284828
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	101 SERANGOON NORTH AVENUE 1 #05-811
Postcode	550101
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RENTAL
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA1593Z
Vehicle Make/Model/Colour	HYUNDAI SONATA
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation, withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The error and omissions of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Auto claims reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurer to the GIA Regional Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that issuing of this report will not incur a fee. Services provided are complimentary to all insured parties.
7. By the submission of this report to the Insurer, the insured consents to the following: (i) a report of this claim will be issued to the Insurer, being made available elsewhere;
8. **Consent under the Personal Data Protection Act (PDPA)**
 - i. I understand, acknowledge, agree and consent that:
 - (a) My claims, my sketching and the General Insurance Association of Singapore ("GIA") may/are provided to collect, store, discuss and/or process my personal data/personal information set out in this form and any other personal information provided by me or processed by my Insurer (collectively the "Personal Information") and discuss and transfer such Personal Information to all Insurers who have insured vehicles involved in this accident (Insurer(s)) who have insured vehicle(s) involved in this accident shall be collected, stored in the "Insurers", the Insurers' Administrative Centre, the Monetary Authority of Singapore, and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims involving the settlement of the claim and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions in accordance to any provision by me;
 - (iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me (in being about delivery of the same as well as on my external cover of correspondence/package); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' Insurers/Reinsurers, may/are permitted to collect, store, discuss and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be provided by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/firm(s)), which may be used outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under 2.8 above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing their employees, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulatory, legal or court orders;


 Policyholder's Signature
 Date & Time:


 Insurer's Signature
 (If Insurer is not the policyholder)
 Date & Time:

(DAC, KAKI BUKIT(VAC))
 27 KAKI BUKIT AVE 4
 Reporting Centre (Insurance) Singapore
 Singapore 475933
 Tel: 67416697
 Fax: 67493305
 Email: cackhi@singnet.com.sg

18 MAR 2019



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/03/2019 @ about hrs I was travelling along Sims Ave turning into 450 Sims Ave. When my vehicle is half way into 450 Sims Ave I felt a strong impact from my driver side. I stopped & alighted & found out a taxi that was stationary park in a parking lot move off suddenly without checking hence hit onto the driver side of my vehicle.

DECLARATION

(I/We declare that the above statement is true and correct to the best of my/our knowledge)

[Signature]
 Name of Driver's Signature
 Date & Time



[Signature]
 Driver's Signature
 Date & Time

ST. Andrew's Road 110 (for documents)
 Date & Time

18 MAR 2019

(DAC KAKI BURIT (VAC))

23 KAKI BURIT AVE 4
 Resolving Centre
 Singapore 415957
 Tel: 67416697
 Fax: 67492305
 Email: uak.kb@singnet.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 May 2019 15:49 Edit Reg		19 Mar 2019 00:00 Edit Adj Rpt	\$40.00 Edit Estimates	\$40.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	SLG7806S	Date of Loss:	13/03/2019 00:00 - :59 [143 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHA1593Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Motor Intel Automo Pte Ltd (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari NagaraJan - 6347 6071]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents






































*SLG7806S
[SHA1593Z]



































TP

Mar 13 2019 12:00AM

[-]

Motor Intel Automo Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
2	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
3	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
4	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
5	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
6	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
7	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
8	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
9	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
10	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
11	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
12	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
13	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
14	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
15	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
16	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
17	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
18	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
19	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
20	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
21	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
22	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
23	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
24	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
25	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
27	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
28	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
29	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
30	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
34	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/05/19 12:49	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/05/19 12:51	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
39	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
40	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
41	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
42	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
43	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
44	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
45	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
46	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
47	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
48	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
49	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
50	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
51	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
52	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
53	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
54	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
55	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
56	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
57	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
58	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
59	14/05/19 12:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
60	14/05/19 12:51	Photo After Spray		<input checked="" type="checkbox"/>
61	14/05/19 12:51	Photo After Spray		<input checked="" type="checkbox"/>
62	14/05/19 12:51	Photo After Spray		<input checked="" type="checkbox"/>
63	14/05/19 12:51	Photo After Spray		<input checked="" type="checkbox"/>
64	14/05/19 12:51	Photo After Spray		<input checked="" type="checkbox"/>
65	14/05/19 12:51	Photo After Spray		<input checked="" type="checkbox"/>
66	14/05/19 12:51	Photo After Spray		<input checked="" type="checkbox"/>
67	14/05/19 12:51	Photo After Spray		<input checked="" type="checkbox"/>
68	14/05/19 12:51	Photo After Spray		<input checked="" type="checkbox"/>
69	14/05/19 12:51	Photo After Spray		<input checked="" type="checkbox"/>
70	14/05/19 12:51	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/03/19 08:52	Singapore Accident Statement		<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19005026/GCD3E2

Date: 24/05/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle
No : SLG7806S

Insured Vehicle No : SHA1593Z

Date of Loss: 13/03/2019

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG7806S

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ2836805

Reg. Date: 05/04/2007 (Man. Year: 2007)

Chassis No: ZNE100353885

Colour: Grey

Odometer: 298595 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Giti 5 mm

Rear Left Side:

Giti 5 mm

Front Right Side: Giti 5 mm

Rear Right Side:

Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/03/2019

Date Inspected: 06/05/2019 Inspected At:

Motor Intel Automo Pte Ltd (HQ)

13 Kaki Bukit Road 4, #01-20 Bartley Biz

Centre

Singapore 417807

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 May 2019)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLG7806S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

Met/19030351

RESERVES			
TPPD	PRESERVE	41c	
TPPI	PRESERVE		
UNINSURED LOSS	PRESERVE		
SUBRO	PRESERVE		
LPPN		25 3w	
INVESTIGATION FEE			
SURVEY FEES			
LEGAL FEES			
OTHERS			
FRAUD CHECK			
UPLOAD TO MERIMEN			
GRANT RIGHTS			

 *** TX REPORT ***

TRANSMISSION OK

TX/RX NO 0915
 RECIPIENT ADDRESS 62922665
 DESTINATION ID
 ST. TIME 30/05 13:11
 TIME USE 00'29
 PAGES SENT 2
 RESULT OK

FAXED
 30 MAY 2019
 MOTCLM DEPT.

Our Ref. : RSS/1903-7148 (MI)(PD)

Your Ref. :

W : Natalie Ng

E : natalie_ng@rssolomon.com

27 May 2019

India International Insurance Pte Ltd
 64 Cecil Street
 #04-05 IOB Building
 Singapore 049711
 Attn: Motor Claims Dept

Dear Sirs,



R. S. SOLOMON LLC
 ADVOCATES & SOLICITORS

By PDX: 8172

WITHOUT PREJUDICE

We are in receipt of your letter, which is receiving our attention. We shall revert shortly. Kindly note that we are preserving our rights to conduct a medical re-examination on your claim where necessary.

Our Ref: MC119030351
 Name: Sund
 Date: 30/5/2019
 India International Insurance P.L.

ACCIDENT INVOLVING SLG7806S & SHA1593Z ALONG SIMS AVENUE IN FRONT OF 450 SIMS AVENUE ON 13TH MARCH 2019 AT ABOUT 1545 HRS

We act for Blend Auto ("our client"), owner of vehicle registration no. SLG7806S, and refer to the above-captioned matter.

2. We are instructed that you are the insurers of vehicle registration no. SHA1593Z at the material time. We are further instructed that the aforesaid accident was caused solely by your insured and/or insured driver's negligence in her/his driving, controlling and/or management of the said vehicle. As a result of the accident, our Client's vehicle was damaged and it's has been put to loss and expense, particulars of which are as follows:-

(a) Cost of Repair	\$ 6,848.00
(b) Loss of use for 8 working days at \$120.00 per day (i.e. including two days for Pre-repair survey)	\$ 960.00
(c) Survey report fee	\$ 642.00
(d) GIA report & search fees	\$ 29.00
(e) LTA search fee	\$ 7.49
(f) Costs	\$ 700.00

Our Ref. : RSS/1903-7148 (MI)(PD)
Your Ref. :

W : Natalie Ng
E : natalie_ng@rssolomon.com

27 May 2019

India International Insurance Pte Ltd

64 Cecil Street
#04-05 IOB Building
Singapore 049711
Attn: Motor Claims Dept



R. S. SOLOMON LLC
ADVOCATES & SOLICITORS

By PDX: 8172

WITHOUT PREJUDICE

We are in receipt of your letter, which is receiving our attention. We shall revert shortly. Kindly note that we are preserving our rights to conduct a medical re-examination on your client where necessary.

Our Ref: **MC119030351**
Name: **Sund**
Date: **30/5/2019**
India International Insurance P L

Dear Sirs,

ACCIDENT INVOLVING SLG7806S & SHA1593Z ALONG SIMS AVENUE IN FRONT OF 450 SIMS AVENUE ON 13TH MARCH 2019 AT ABOUT 1545 HRS

We act for Blend Auto ("our client"), owner of vehicle registration no. SLG7806S, and refer to the above-captioned matter.

2. We are instructed that you are the insurers of vehicle registration no. SHA1593Z at the material time. We are further instructed that the aforesaid accident was caused solely by your insured and/or insured driver's negligence in her/his driving, controlling and/or management of the said vehicle. As a result of the accident, our Client's vehicle was damaged and it's has been put to loss and expense, particulars of which are as follows:-

(a) Cost of Repair	\$ 6,848.00
(b) Loss of use for 8 working days at \$120.00 per day (i.e. including two days for Pre-repair survey)	\$ 960.00
(c) Survey report fee	\$ 642.00
(d) GIA report & search fees	\$ 29.00
(e) LTA search fee	\$ 7.49
(f) Costs	\$ 700.00
(g) Transport, Xerox, postages & Other Incidentals	\$ 50.00
Total:	\$ 9,236.49

3. We enclose herewith copies of the following documents in support of our Clients' claim:-

- Final Repair Bill dated 14th May 2019 by Motor Intelligence Auto Pte. Ltd;
- Survey Report with Invoice No. CL/190581 from C L Appraiser Pte Ltd;
- GIA report lodged by our client's driver;
- GIA report lodged by your insured/insured driver with payment advice for search and report fees;
- LTA search result with payment advice; and

...2

Our Ref. : RSS/1903-7148 (MI)(PD)
Your Ref. :

W : Natalie Ng
E : natalie_ng@rssolomon.com

27 May 2019



R. S. SOLOMON LLC
ADVOCATES & SOLICITORS

PAGE 2

(f) 72 coloured photographs depicting damages to our client's vehicle registration No. SLG7806S.

4. **TAKE NOTICE** that unless we receive your acknowledgement of receipt to this letter and enclosures **within fourteen (14) days from the date hereof**, our Client will have no alternative but to commence proceedings against your insured and/or its driver without further notice to you.

Yours faithfully,

R. S. SOLOMON LLC
ADVOCATES & SOLICITORS

Encl.

Cc: **COMFORT TRANSPORTATION PTE LTD**
383 Sin Ming Drive
GAS Building
Singapore 575717

BY CERTIFICATE OF POSTING
WITHOUT PREJUDICE

Note to insured and/or the driver: No enclosures have been provided to you; should you require copies of the afore-mentioned enclosures, please contact our office.

TAKE NOTICE that if you have a counterclaim against our Client arising out of the above-captioned accident, you are required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of you receiving this letter.



Motor Intelligence Automo Pte. Ltd.
Regn & GST No. : 201732961N
Bartley Biz Centre, 13 Kaki Bukit Road 4, #01-20
Singapore 417807
Phone: 6281 0087/Fax: 6281 0187/Mobile: 9150 1587
Email: sales@mia.com.sg

Customer: BLEND AUTO C/O MOTOR INTELLIGENCE AUTOMO PTE LTD	Tax Invoice No: INVOICE	Date: 14/May/2019
	Make and Model: TOYOTA WISH	Due upon receipt
	Mileage: 298595	Chasis/Car Plate No: ZNE100353885 SLG 7806 S

S/No:	Product	Description	Qty	Unit	Priced (SGD)	Amount (SGD)
1	COST OF REPAIR	LUMP SUM REPAIR OF ACCIDENT PORTION	1	JOB	6400.00	6400.00
Sub Total (SGD)						6400.00
GST 7%						448.00
Total (SGD)						6848.00

Amount in words:

DOLLARS SIX THOUSAND EIGHT HUNDRED AND FORTY EIGHT ONLY.

Declaration:

We declare that this Tax Invoice shows the actual price of the goods described and that all particulars are true and correct.

or Motor Intelligence Automo Pte. Ltd

Authorised Signatory

Remarks :

Receiver Chop & Sign

C L APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Blend Auto
C/o: Motor Intelligence Automo Pte Ltd
13 Kaki Bukit Road 4, #01-20
Bartley Biz Centre, Singapore 417807

Invoice No: CL/190581

Ref No: MITA/05/1905/TP

Date: 13 May 2019

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
<ul style="list-style-type: none">SURVEY INSPECTION FOR VEHICLE NO. <u>SLG 7806 S</u>RESURVEY INSPECTIONDIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)TRANSPORTATION	
GRAND TOTAL	SS 642.00

E & O. E

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd

CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Blend Auto
C/o: Motor Intelligence Automo Pte Ltd
13 Kaki Bukit Road 4, #01-20
Bartley Biz Centre, Singapore 417807

Date : 13 May 2019
Our ref : MITA/05/1905/TP

Accident Date : 13 March 2019
Inspection Date : 07 May 2019
Repairer Name : Motor Intelligence Automo Pte Ltd
13 Kaki Bukit Road 4, #01-20
Bartley Biz Centre, Singapore 417807

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : SLG 7806 S
Make / Model : Toyota Wish
Chassis No : ZNE100353885
Engine No : 1ZZ2836805

Year / Capacity : 2007 / 1794 cc
Colour : Grey
Mileage : 298595

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Acenda	195/65 R15	5 mm	Normal
Front Offside	: Acenda	195/65 R15	5 mm	Normal
Rear Nearside	: Acenda	195/65 R15	5 mm	Normal
Rear Offside	: Acenda	195/65 R15	5 mm	Normal

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the o/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 72 copies

REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis
and we have not given authorization and instruction to the repairer to proceed with the repair

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$ 6,400.00** on a contractual basis.

Under normal circumstances, the repair period would be about 6 (Six) working days.

Vehicle Registration No: SLG 7806 S

Our Ref No: MITA/05/1905/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front o/s door	Damage	\$ 1,265.60	\$ 1,265.60 Repair
1	Front o/s door rubber	Necessary	\$ 245.40	\$ 245.40 NN
1	Rear o/s door	Damage	\$ 1,265.50	\$ 1,265.50 - 1/22.2
1	Rear o/s door rubber	Necessary	\$ 243.40	\$ 243.40 NN
1	Rear bumper	Damage	\$ 895.70	\$ 895.70 - 545
1	Rear bumper o/s side retainer	Necessary	\$ 64.40	\$ 64.40 /
1	Rear o/s fender	Repair	\$ 1,013.50	
1	Rear o/s fender air gate	Damage	\$ 125.50	\$ 125.50 /
1	Rear o/s fender inner shield	Damage	\$ 124.10	\$ 124.10 /
1	Rear o/s fender quarter glass moulding	Intact	\$ 185.90	
1	Rear o/s wheel hub with bearing	Damage	\$ 781.50	\$ 781.50 - 390
1	Rear o/s shock absorber	Damage	\$ 426.50	\$ 426.50 NN
1	Rear axle	Repair	\$ 2,017.60	
			\$ 8,654.60	\$ 5,437.60 2371.8
Less 25%			\$ 2,163.65	\$ 1,359.40
Total Cost - List Items			\$ 6,490.95	\$ 4,078.20 1778.85

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	Necessary	\$ 45.00	\$ 45.00 32
1	Rear o/s fender quarter glass sealant	Intact	\$ 80.00	
1	Rear o/s tyre (Depreciation)	Damage	\$ 400.00	\$ 200.00 NN
1	Rear o/s wheel rim	Damage	\$ 300.00	\$ 300.00 NN
1	Rear o/s wheel rim cap cover	Damage	\$ 150.00	\$ 150.00 55
Total Cost - Special Nett items			\$ 975.00	\$ 695.00 85

Total cost of parts

\$ 7,465.95 \$ 4,773.20

Vehicle Registration No: SLG 7806 S

Our Ref No: MITA/05/1905/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 7,465.95	\$ 4,773.20

LABOUR

- | | | | |
|---|--|-------------|----------------------------|
| 1 | To remove, refit, replaced damaged lamps and check up rear electrical wiring | \$ 80.00 | \$ 50.00 NN |
| 2 | To remove and refit inner garnishes, inner trim to assist repair. | \$ 180.00 | \$ 120.00 NN |
| 3 | To remove and refit rear undercarriage. | \$ 350.00 | \$ 300.00 80 |
| 4 | To remove and refit quarter glass to assist repair. | \$ 120.00 | \$ 80.00 NN |
| 5 | To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door. | \$ 300.00 | \$ 240.00 60 |
| 6 | To apply undercoating on repaired and replaced panel. | \$ 180.00 | \$ 120.00 60 |
| 7 | To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident. | \$ 1,600.00 | \$ 1,250.00 300 |
| 8 | To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident. | \$ 1,500.00 | \$ 1,100.00 80 |

1500

GRAND TOTAL

\$ 11,775.95 \$ 8,033.20

2363.25

20% : 2700

SCL APPRAISER PTE LTD

Vehicle Registration No: SLG 7806 S

Our Ref No: MITA/05/1905/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 6,400.00**


By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H.
Automotive Appraiser

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an Admission of policy liability on the part of the insurance companies.
5. Any issue respecting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/inmail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

10AC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 475913
Tel: 67416697
Fax: 67492305
Email: vacbk@singnet.com.sg

18 MAR 2019



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/03/2019 @ about hrs. I was travelling along Sims Ave turning into 450 Sims Ave. When my vehicle is half way into 450 Sims Ave I felt a strong impact from my driver side. I stopped & alighted & found out a taxi that was stationary park in a parking lot move off suddenly without checking hence hit onto the driver side of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time




Driver's Signature
(If driver is not the policyholder)
Date & Time

18 MAR 2019

10AC KAKI BUKIT(VAC)
Reporting Centre
Singapore 418519
Tel: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg

9459131



Identity Card No. S9179984G



Nationality
MALAYSIAN
Date of issue
13-09-2017

Address
APT BLK 101 SERANGOON NORTH AVENUE 1
P05-B11
SINGAPORE 550101

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2b Motorcycles <= 200 cc
Class 3 Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver, and other motor vehicles with unladen weight <= 2500kg
29 May 2015
29 May 2015



License No. S9179984G

NP 425A

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9179984G



Name

TAN EE HONG



陈义鸿

Race

CHINESE

Date of birth

22-10-1991

Country/Place of birth

MALAYSIA

Sex

M

REPUBLIC OF SINGAPORE DRIVING LICENCE

License No. S9179984G



TAN EE HONG

Start Date: 22 Oct 1991

Expiry Date: 17 Nov 2017



0027447010

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5106866429

Cover : Third Party, Fire & Theft

1. Index mark and Registration Number of Vehicle : **SLG78065**
Chassis Number : **ZNE100353885**
2. Name of Policyholder : **BLEND AUTO**
3. Effective Date of Insurance : **09 Jan 2019**
4. Expiry Date of Insurance : **08 Jan 2020**
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
 - (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
 - (c) Use for any purpose in connection with the Motor Trade.
- # Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: S\$1,500
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: N/A
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: INDEX CREDIT PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : ASSURE (SINGAPORE) PTE. LTD. (00000615327)

Date of Issue : 09 Jan 2019 14:51 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/03/2019 13:47
Date Of Accident	13/03/2019 15:50
Exact Location Of Accident	SIMS AVE TWDS EUNOS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA1593Z
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	SONATA
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	CHA SHAY SHIAN
NRIC No	S1614912H
Address	BLK 11 CHAI CHEE ROAD #15-19

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	2

Circumstances of Accident

PLS REFER TO ATTACHED / Type Of Accident: HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLG7806S

Vehicle Make/Model/Colour

Name of Driver

Insurance Company Name

NTUC INCOME INSURANCE CO-OPERATIVE LTD

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO REG NO. 199203351R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIA/MC SketchPlanForm_V3

1-1
1-1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13. March 2019 @ 15:50 hrs.

I, Vett A stop and pick up PAK on the side of the road. I vert A CHC on my left there was no vehicle. I just move suddenly vert B came very fast turn on my lane and hit vett A left front. at the point of accident vett A ferry a male PAK. not injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PERS LTD
 27-277 RD 1922073316

Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

GIWIMC SketchPlanForm_V3

Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-079555

Date of Request: 21/05/2019

Your Ref No: RSS/1903-7148(MI)(PD)

R.S. SOLOMON LLC
300 Beach Road
#12-03/04 The Concourse
Singapore 199555

Dear Sir/Madam,

Date of Accident: 13/03/2019

Vehicle No: SLG7806S

Place of Accident: ALONG SIMS AVENUE(INFRONT OF 450 SIMS AVENUE)

Involving Vehicle No: SHA1593Z

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHA1593Z	ALONG SIMS AVENUE(INFRONT OF 450 SIMS AVENUE)	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-19-079549

Date of Request: 21/05/2019

Your Ref No: RSS/1903-7148(MI)(PD)

R.S. SOLOMON LLC
300 Beach Road
#12-03/04 The Concourse
Singapore 199555

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 13/03/2019
Place of Accident: ALONG SIMS AVENUE
Client Vehicle No: SLG7806S

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
SHA1593Z	SIMS AVE TWDS EUNOS	13/03/2019 15:50

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-079549

Date of Request: 21/05/2019

Your Ref No: RSS/1903-7148(MI)(PD)

R.S. SOLOMON LLC
300 Beach Road
#12-03/04 The Concourse
Singapore 199555

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 13/03/2019

Place of Accident: ALONG SIMS AVENUE

Client Vehicle No: SLG7806S

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Enquire Vehicle & Owner Information (Vehicle No. SHA1593Z As At 13 Mar 2019 / 15:45:00)**Previous Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: RSS/1903-7148(MI)PD

Current Owner Details

Owner ID Type: Company
Owner ID: 199303821R
Owner Name: COMFORT TRANSPORTATION PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 383
Registered Street Name: SIN MING DRIVE
Registered Unit No.: -
Registered Building Name: GAS BUILDING
Registered Postal Code: 575717
Current Vehicle Details:

Vehicle No.: SHA1593Z
Make Description/Model: HYUNDAI / SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Insurance Company Name: INDIA INT'L INS PTE LTD



MOTORING



THINKING YOU

Your login details have been successfully updated.
 Your last login date and time was 18 Mar 2019, 14:52:25.
 To return to ONE MOTOREHNC, please click [here](#).
 For security reasons, please CLEAR YOUR CACHE after each session.

Session Transaction History

S/N	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount (S\$)	Log Date/Time
1	Vehicle	SH435932	*	18.19 Enquire With Owner Info (Others) by Law Firm	7.49	18 Mar 2019 / 18:15:09

Please do not use your browser's Back or Forward buttons as this may result in information loss



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CS3/III19005026/Gqd3e2-1		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 27-06-2019		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1593Z	Veh. Inspected	SLG 7806S	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT19030351	Excess (\$)	0.00	
Assign From	GABRIEL WEE	Assign Date	03/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	ZNE100353885	Colour	GREY	
Odometer	298595	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GITI	5 mm	
L/H Front Tyre	195/65 R15	GITI	5 mm	
R/H Rear Tyre	195/65 R15	GITI	5 mm	
L/H Rear Tyre	195/65 R15	GITI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/03/2019	Inspection Date	06/05/2019	
Survey held at	MOTOR INTEL AUTOMO PTE LTD 13 KAKI BUKIT ROAD 4 @ BARTLEY BIZ CENTRE #01-20 SINGAPORE 147807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 7806S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT O/S DOOR	TO REPAIR SEE LABOUR	1,265.60	-
1	FRONT O/S DOOR RUBBER	NOT NECESSARY	245.40	-
1	REAR O/S DOOR	DAMAGED	1,265.50	1,122.80
1	REAR O/S DOOR RUBBER	NOT NECESSARY	243.40	-
1	REAR BUMPER	DAMAGED	895.70	545.00
1	REAR BUMPER O/S SIDE RETAINER	NECESSARY	64.40	64.40
1	REAR O/S FENDER	TO REPAIR SEE LABOUR	1,013.50	-
1	REAR O/S FENDER AIR GATE	DAMAGED	125.50	125.50
1	REAR O/S FENDER INNER SHIELD	DAMAGED	124.10	124.10
1	REAR O/S FENDER QUARTER GLASS MOULDING	INTACT	185.90	-
1	REAR O/S WHEEL HUB WITH BEARING	DAMAGED	781.50	390.00
1	REAR O/S SHOCK ABSORBER	NOT NECESSARY	426.50	-
1	REAR AXLE	TO REPAIR SEE LABOUR	2,017.60	-
LESS 25% DISCOUNT			-2,163.65	-592.95
			6,490.95	1,778.85
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	30.00
1	REAR O/S FENDER QUARTER GLASS SEALANT (SN)	INTACT	80.00	-
1	REAR O/S TYRE (SN)	NOT NECESSARY	400.00	-
1	REAR O/S WHEEL RIM (SN)	NOT NECESSARY	300.00	-
1	REAR O/S WHEEL RIM CAP COVER (SN)	DAMAGED	150.00	55.00
			975.00	85.00
LABOUR				
TO REMOVE,REFIT,REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.		NOT NECESSARY	80.00	-
TO REMOVE AND REFIT INNER GARNISHES,INNER TRIM TO ASSIST REPAIR.		NOT NECESSARY	180.00	-
TO REMOVE AND REFIT REAR UNDERCARRIAGE.			350.00	80.00

Report Ref No. CS3/III19005026/Gqd3e2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT QUARTER GLASS TO ASSIST REPAIR.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT DOORS COMPLETE FITTINGS AND REPLACE DAMAGED PARTS,TRANSFER ALL FITTINGS TO NEW DOOR.		300.00	60.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		180.00	60.00
	TO PROVIDE LABOUR CHARGES,WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS,REPAIR INCLUDING CUT AND WELD;RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF FRONT O/S DOOR,REAR O/S FENDER AND REAR AXLE.		1,600.00	500.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS,REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		1,500.00	800.00
			4,310.00	1,500.00
GRAND TOTAL			11,775.95	3,363.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS3/III19005026/Gqd3e2-1

XING GUO QIANG**M.MATAI, AMSAE-A****Automotive Assessor****ADRIAN LING WAI PING****B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.