

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



Survey & repair
17.06 @ 10am

* arrange rental car from
AIG/BKW. Owner will reach
PML at 8.30am

GST REG. NO : M2 - 0020081 - X

03 JUN 2019

E S T I M A T E

Estimate No. : b1 51400
Date Estimated : 03/06/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Tan Boon Yew
2 Jubilee Road

Singapore 128523

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJP2S	AG14184	21/09/2018	420i/2	0

DESCRIPTION

To replace front right fender, right door, repair rear right fender and repair right side sill.

2975 4,250.00

Painting front right fender, right door, rear right fender and side sill right.

3133 3,481.00

To check electrical wiring systems.

150 177.00

To carry out body cavity preservation (Per panel).

200 236.00

Sundries.

? 150.00

Insurance Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total Labour 1: 8,294.00

DESCRIPTION

FRT RH DOOR
FRT RH SIDE PANEL
EMBLEM (M)
FRT RH DOOR JOINT SEAL
FRT RH AIR DUCT SIDE PANEL PRIMED

Acknowledged by Repairer

Signature:

Date:

QTY	PRIC	VALUE
1	1,584.35	bt - 1,584.35
1	702.65	bb - 702.65
1	81.90	ny - 81.90
1	42.25	ny - 42.25
1	55.95	wt - 55.95

Total Parts : 2,467.10

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 17/6/19 Excess \$

Surveyor's Name Tan Yew Sign

Surveyor's Tel 97445347 Authorised Yes / No

Authorised Date 17/6/19 Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail tanym@pml.com.sg

Labour 1 : 8,294.00

Parts : 2,467.10

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 753.28

Grand Total : 11,514.38

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **