

ASS. REC. BY:

REF: CS MSG 14009828 / Utd 3/9

Special Instructions:

Surveyor: MARCUSASSIGNMENT (Office)From (Person): Jasmine Lok Hing Kwai

of

MSGDate/Time: 3-6-19 11:38 PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: PBJ 2681UInsured: GBH 6414Jat Workshop m/s Ted Spray PaintingTel: 62835674of Blk 6 Refu Lane 10 Refu Ind Park C #01-553Policy No: 29093156MFCClaim No: 595237

Sum Insured:

Excess:

Make of Veh:

D.O.A. 29-5-2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 4-6-19 10:18 AMPerson Contacted: Shu Qi

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

PBJ 2681U - N/A / MSG 14006692 / e1D.O.A. - 04/04/2014GBH 6414J - X7/6/19 9:51 - Revised preli advise via mmmmm

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inv Auth'd	Status
Main	03 Jun 2019		03 Jun 2019 16:38 Assign				New Assignment Cancel Case

Main Reference Claim Details Documents Show All

CLAIM SUBFOLDER DETAILS			[Created by insurer]	
Insured:	LCS ENTERPRISE PTE LTD, Co. Reg. No.: NA			
Main Claimant:	DEWANAN BIN ISA, ID: 52661448A			
Vehicle Reg. No.:	FBJ2681U	Date of Loss:	29/05/2019 00:00 - :59 [63 Months and 4 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 595237	Policy/Cover Note No.:	29093156MKC (Comprehensive) Coverage: 16/08/2018 - 15/08/2019	
Vehicle Reg. No. (Insured):	GBH6414J	Policy No. (Claimant):		
		Excess:		
Reparer:	Teo Spray Painting (HQ) BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558, 539187 Defu Lane - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/06/2019]			
Adj. Asg. Remarks:	on WP, Liab: dispute (OI NR), TP Agree on SJE- assign Marcus Chua from LKK Auto Consultants. Contact: Shu Qi @ 6283 5474			

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1448A

Vehicle Details

Vehicle No.: FBJ2681U
Vehicle to be Exported: No
Intended Deregistration Date: 04 Jun 2019
Vehicle Make: YAMAHA
Vehicle Model: JUPITER MX (HC)
Primary Colour: Blue
Manufacturing Year: 2013
Engine No.: 50C684563
Chassis No.: MH350C004DK684556
Maximum Power Output: -
Open Market Value: \$1,822.00
Original Registration Date: 25 Feb 2014
First Registration Date: 25 Feb 2014
Transfer Count: 1
Actual ARF Paid: \$274.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 24 Feb 2024
COE Category: D - Motorcycle
COE Period(Years): 10
QP Paid: \$3,501.00
COE Rebate Amount: \$1,653.00
Total Rebate Amount: \$1,653.00

The information contained herein is correct as at 04 Jun 2019

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 07 Jun 2019

Preliminary Advice

Insured Vehicle No	: GBH6414J	Accident Date	: 29/05/2019
TP Vehicle No	: FBJ2681U	Assignment Date	: 03/06/2019
Make	: YAMAHA JUPITER MX	Est. Duration of Repair	: 3.00
Date of Inspection	: 04/06/2019		
Inspection At	: TEO SPRAY PAINTING (HQ) BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558 SINGAPORE 539187		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	911.04
Revised Amount	:S\$	824.34
Check Items (Estimated)	:S\$	0.00
Total	:S\$	824.34

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/05/2019 09:50
Date Of Accident	29/05/2019 13:40
Exact Location Of Accident	BLK 120 BUKIT MERAH LANE 1 OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ2681U
Insured/Policyholder	
Name Of Registered Owner	DEWANAN BIN ISA
NRIC No	S2661448A
Email Address	DEWAK9@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82699982
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	YAMAHA
Model	JUPITER MX-134CC HC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MC/00366290/01
Cover Note Number	

Driver

Name of Driver	DEWANAN BIN ISA
NRIC No	S2661448A
Date Of Birth	17/06/1965
Occupation	INDOOR
Date Of Driving Pass	10/10/1985
Driving Experience	33 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82699982
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	DEWAK9@GMAIL.COM

Address	BLK 363B SEMBAWANG CRESCENT #08-729
Postcode	752363
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	POLICE STATION OF ORIGIN-QUEENSTOWN N.P.C
Police Station Address	ROAD: 3 QUEENSTOWN N.P.C . POSTCODE: 149073 . COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN AND POLICE REPORT (REPORT NO.: T/20190529/2137)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH6414J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

VEHICLE NO: 40H 641HJ
ACCIDENT DATE: 29/05/2019 @ 13:40

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

NOTE: DO NOT THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.

Policyholder's Signature
Date & Time:


29.5.2019
16:30

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29.5.2019 at about 13.15, I have enter carpark
 B1K120 Bukit Merah Lane 1, Alexandra Village Food Centre
 to go to the toilet at the Food Centre, 15 minute later
 when I come back to my motorcycle, one of the guy
 there inform me that my motorcycle have been hit by a lorry
 when the driver make a reverse, and the lorry driver
 just go away without looking at my motorcycle damage.
 And the guy also forward me the photo of the lorry
 and number plate to me, so I want to claim the
 other party for the damage of my motorcycle.

OWN DAMAGE () 3RD PARTY CLAIM ☒ REPORTING ONLY () OWN WORKSHOP ☒

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

CHARN'S CUSTOM CRAFT
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190529/2137

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

1 of 3

Report No. T/20190529/2137

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/05/2019 17:07	Video Report No.:	Station Diary No.: 56
--	-------------------	--------------------------

Informant's Particulars

Name of Informant: DEWANAN BIN ISA			Address: APT BLK 363B SEMBAWANG CRESCENT #08-729 SINGAPORE 752363	
ID Type / ID No.: NRIC NO / S2661448A			Contact No.: Home/Office: Mobile: 82699982	
Nationality: MALAYSIAN			Email:	
Sex: Male	Age: 53	Date of Birth: 17/06/1965	Type of Informant: Rider	
Race: Malay			Language: English	Institution / School Name:
Occupation: DISPATCH RIDER			Driving Licence Information: Class: 2B,2A,2,3,4 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 29/05/2019 13:00	Type of Location: Car Park
Location: ALEXANDRA ROAD Alexandra Village, near food court				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBJ2681U	Motorcycle	YAMAHA	JUPITER MX (HC)	Blue	Seriously Damaged	0
GBH6414J	Lorry	TOYOTA		Silver		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBJ2681U	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MC/00366290/02	28/02/2017	25/02/2020



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999



T/20190529/2137

3 of 3


Report No. T/20190529/2137

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D / Sgt 3 MUHAMMAD FAUZY BIN HUSAIN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 29/05/2019 17:07
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt ESTHER CHONG Contact No.: 65476368	Classification Of Case:
Authentication Stamp NP168	



**SINGAPORE
POLICE FORCE**



T/20190529/2137

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

3 of 3


Report No. T/20190529/2137

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D / Sgt 3 MUHAMMAD FAUZY BIN HUSAIN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 29/05/2019 17:07
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt ESTHER CHONG Contact No.: 65476368	Classification Of Case:
Authentication Stamp NP168	



張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)
Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-E
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

MSIG Insurance
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
Tel: 68277660 / 68277666
Fax: 62256371

Handwritten notes:
7/6/19 Not Affected
a/s = 500
3 Lys.
4/6/19
the job. Attorney.

Dear Sir/Madam

30.05.2019

RE: THIRD PARTY CLAIMS FOR FB2681U AGAINST YOUR
INSURED GBH6414J, ACCIDENT ON 29.05.2019 AT ALEXANDRA
ROAD ALEXANDRA VILLAGE, NEAR FOOD COURT.

PG 1

DESCRIPTION	AMOUNT
1 MAGNET COVER	cas \$ 168.00 ✓
2 GASKET	rec \$ 35.00 ✓
3 FRONT FOOTREST BRACKET	bet \$ 81.20 ✓
4 REAR FOOTREST BRACKET	bet \$ 53.20 ✓
5 CLUTCH LEVER	cas \$ 35.00 ✓
6 BALANCER	scr \$ 53.20 ✓
7 SIDE MIRROR LH	cas \$ 49.00 ✓
8 HORN COVER	cas \$ 63.00 ✓
9 SIDE COVER LH	cas \$ 63.00 X
10 BOX	SUL \$ 210.00 X
11 WINDSCREEN	cas \$ 35.00 ✓
	\$ 845.60
Less 10%	\$ 84.56
Sub Total	\$ 761.04

Nett Item
1 LABOUR CHARGES

Sub Total

\$ 150.00	120
\$ 150.00	

Total

\$ 911.04

THANKS
TSP

Stamp area with text:
I hereby certify that the above is a true and correct copy of the original document.
Signed: _____
Date: _____
Position: _____
Company: _____




































...CLAIM SUBFOLDER...(Pending for Survey Report)



































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jun 2019		03 Jun 2019 16:38 Edit Adj Rpt	S\$500.00 Edit Estimates	S\$500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	LCS ENTERPRISE PTE LTD, Co. Reg. No.: NA								
Main Claimant:	DEWANAN BIN ISA, ID: S2661448A								
Vehicle Reg. No.:	FBJ2681U	Date of Loss:	29/05/2019 00:00 - :59 [63 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 595237	Policy/Cover Note No.:	29093156MKC (Comprehensive) Coverage: 16/08/2018 - 15/08/2019						
Vehicle Reg. No. (Insured):	GBH6414J	Policy No. (Claimant):							
		Excess:							
Repairer:	Teo Spray Painting (HQ) BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558, 539187 Defu Lane - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwel - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 03/07/2019]								
Adj Asg. Remarks:	on WP. Liab: dispute (OI NR). TP Agree on SJE- assign Marcus Chua from LKK Auto Consultants. Contact: Shu Qi @ 6283 5474								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBJ2681U (595237)
 [GBH6414J]
 TP
 DEWANAN BIN ISA
 May 29 2019 12:00AM
 [LCS ENTERPRISE PTE LTD]
 Teo Spray Painting

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	07/06/19 09:51	Adjuster Immediate Advice						Load HTM	
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
2	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
3	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
4	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
5	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
6	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
7	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
8	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
9	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
10	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
11	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
12	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
13	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
14	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
15	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
16	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
17	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
18	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
19	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
20	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
21	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
22	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
23	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
24	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
25	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
26	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
27	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
28	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
29	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
30	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
31	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
32	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
33	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	
34	04/06/19 18:42	General View						<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
36	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
37	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
38	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
44	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
47	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
48	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
49	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
50	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
51	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
52	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
53	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
54	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
55	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
56	04/06/19 18:42	General View	 Load JPG	<input checked="" type="checkbox"/>
57	12/06/19 11:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	12/06/19 11:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	12/06/19 11:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	12/06/19 11:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	12/06/19 11:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	12/06/19 11:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	12/06/19 11:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	12/06/19 11:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	12/06/19 11:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	12/06/19 11:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/06/19 13:36	TP PRI	 Load PDF	
2	03/06/19 14:06	TP agree on SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19009828/UTD3Q2

Date: 26/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29093156MKC

Claimant Vehicle No: FBJ2681U

Insured Vehicle No: GBH6414J

Date of Loss: 29/05/2019

Nature of Claim: TP

Claim No: 595237

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBJ2681U

Make & Model: YAMAHA JUPITER MX, 134cc HC

Reg. Date: 25/02/2014 (Man. Year: 2013)

Colour: Multi-colour

Engine Capacity: 134 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 50C684563

Chassis No: MH350C004DK684556

Odometer: 6677 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90-17

Rear Tyre Size: 80/90-17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	761.04	515.34	245.70	32.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	150.00	120.00	30.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	911.04	635.34	275.70	30.26
Approved Total (Overridden) (S\$)		500.00		
Nett Amount (S\$)	911.04	500.00	411.04	45.12

INSPECTION

Date of Assignment: 03/06/2019

Date Inspected: 04/06/2019 Inspected At:

Teo Spray Painting (HQ)
BLK 6 DEFU LANE 10, DEFU IND PARK
C #01-558
Singapore 539187

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jun 2019)	
Parts:	N/A	YAMAHA JUPITER MX 134cc HC (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBJ2681U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MAGNET COVER	Cracked	168.00 FL	*168.00 FL
2	1		*GASKET	Necessary	35.00 FL	*35.00 FL
3	1		*FRONT FOOTREST BRACKET	Bent	81.20 FL	*81.20 FL
4	1		*REAR FOOTREST BRACKET	Bent	53.20 FL	*53.20 FL
5	1		*CLUTCH LEVER	Cracked	35.00 FL	*35.00 FL
6	1		*BALANCER	Scratched	53.20 FL	*53.20 FL
7	1		*SIDE MIRROR LH	Cracked	49.00 FL	*49.00 FL
8	1		*HORN COVER	Cracked	63.00 FL	*63.00 FL
9	1		*SIDE COVER LH	Repair	63.00 FL	*- FL
10	1		*BOX	Serviceable	210.00 FL	*- FL
11	1		*WINDSCREEN	Cracked	35.00 FL	*35.00 FL
					Sub Total (S\$)	845.60
					- List Item Discount on L Items 10.00/10.00% (S\$)	84.56
					Total Parts (S\$)	515.34

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES	New	150.00	120.00
Gross Labour Cost (S\$)			150.00	120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >