

ASS. REC. BY:

REF: CS3/CT1 19009847/ Gcd322

Special Instruction:

Surveyor: GR**ASSIGNMENT (Office)**From (Person): Tan Kah Leongof CT1Date/Time: 4.6.19 10:29 AM

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKZ 953

Insured:

GBD 604M

at Workshop m/s

AS Auto Service

Tel:

9738 8183of 1 Kaki Bukit Ave 6 #01-106Policy No: DMCVSN3036981800

Claim No:

SNM19D202448

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 29.5.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4.6.19 12:15 PM

Person Contacted:

Ah SoonVehicle IN/OUT

| Date/Time | Action/Instruction | Estimate | Inspection |
|-----------|-------------------------------------|----------------------|-------------------------------|
| | SKZ 953 - X | (X) | AS Auto Service |
| | GBD 604M - CS/CT1.8016269 / R1rd392 | | 1 Kaki Bukit Avenue 6 #01-106 |
| | | | D.O.A. - 01/09/2018 |
| 06/06/19 | @ 14:48 pm | checked with Ah Soon | repaired, |
| | | no estimate provide. | |

(08/11/13)

ASS. REC. BY:

REF

C71

C7397C

ASSIGNMENT

From:

Date:

04/6/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SK2 95J

at Workshop m/s

A S Auto

of

1 KAKI BUKIT AVE 6 #01-106

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

PAS

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SK2 95J

Yr Regn:

12 Mar 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Merce C180

c.c.

1595

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

3454

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2050 40 2R 455 759

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

225/50 R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

D.O.I.

w/s

04-06-19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$ 3000 - \$ 4000

Demand: 6/6/2019

After repair: 10/6/2019

7/6/2019

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

150

Transportation:

3 + RS, SI

Photos

Others

TOTAL

150

Report Format:

PRC

Lump Sum / I.B.I. (\$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|---------|---------------|------------|---|
| Main | 31 May 2019 | | 04 Jun 2019 10:22 Edit Adj Rpt | | | | Pending for Survey Report Cancel Case |

| | | | | |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|--------------------------|

CLAIM SUBFOLDER DETAILS [Created by insurer]

| | |
|-----------------------------|---|
| Insured: | |
| Main Claimant: | ASIA CAR LEASING PTE LTD, Co. Reg. No.: 201437397C |
| Vehicle Reg. No.: | SKZ95J |
| Claim Type: | TP / SNM19D202448 |
| Vehicle Reg. No. (Insured): | GBD604M |
| Date of Loss: | 29/05/2019 19:00 - :59 |
| Policy/Cover Note No.: | DMCVSN3036981800 |
| Policy No. (Claimant): | 999994406 |
| Excess: | S\$1,350.00 |
| Repairer: | As Auto Service (HQ) Blk 1 Kaki Bukit Avenue 6 #01-106 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193] |
| Claimant's Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/06/2019] |

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Nivitha (LKK Auto)

From: Elaine Toh <Elainetoh@visionlawllc.com>
Sent: Tuesday, 4 June 2019 10:24 AM
To: 'Tan Kah Leong'; assignments@lkkauto.com
Cc: 'Chee So Chow'
Subject: RE: SNM19D202448: PRE REPAIR SURVEY --- YOUR REF: GBD 604 M --- ACCIDENT INVOLVING SKZ 95 J (#1) AND GBD 604 M (#2) AND SGL 9040 D (#3) ON 29 MAY 2019 ALONG NEW UPPER CHANGI ROAD AT ABOUT 1930 HOURS

Importance: High

Our Ref: SKZ 95 J (et)
WITHOUT PREJUDICE

We refer to your email of even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Venue: A S AUTO SERVICE
1 Kaki Bukit Avenue 6
#01-106 Autobay@Kaki Bukit
Singapore 417883
Contact: Ah Soon @ 9738 8183 (Please call before going)

(1a)
XGQ

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Regards,
Elaine Toh
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802



FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

cc: SKZ 95 J – By email only

From: Tan Kah Leong [mailto:KahLeong.Tan@sg.cntaiping.com]
Sent: Tuesday, 4 June, 2019 10:15 AM
To: Elaine Toh; assignments@lkkauto.com
Cc: Chee So Chow
Subject: RE: SNM19D202448: PRE REPAIR SURVEY --- YOUR REF: GBD 604 M --- ACCIDENT INVOLVING SKZ 95 J (#1) AND GBD 604 M (#2) AND SGL 9040 D (#3) ON 29 MAY 2019 ALONG NEW UPPER CHANGI ROAD AT ABOUT 1930 HOURS

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Elaine,

We refer to your email of 03.06.2019.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]

Sent: Tuesday, 4 June, 2019 9:45 AM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

Cc: Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: RE: SNM19D202448: PRE REPAIR SURVEY --- YOUR REF: GBD 604 M --- ACCIDENT INVOLVING SKZ 95 J (#1) AND GBD 604 M (#2) AND SGL 9040 D (#3) ON 29 MAY 2019 ALONG NEW UPPER CHANGI ROAD AT ABOUT 1930 HOURS

Importance: High

Our Ref: SKZ 95 J (et)

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to our email of 3 June 2019.

Please let us hear from you urgently.

Thank you.

Regards,

Elaine Toh

Vision Law LLC

Tel: 65342811 (Ext. 122)
Fax: 65356802

From: Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]

Sent: Monday, 3 June, 2019 9:47 AM

To: 'Tan Kah Leong'

Cc: 'Chee So Chow'

Subject: RE: SNM19D202448: PRE REPAIR SURVEY --- YOUR REF: GBD 604 M --- ACCIDENT INVOLVING SKZ 95 J (#1) AND GBD 604 M (#2) AND SGL 9040 D (#3) ON 29 MAY 2019 ALONG NEW UPPER CHANGI ROAD AT ABOUT 1930 HOURS

Importance: High

Our Ref: SKZ 95 J (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to your email of 31 May 2019 informing that you wish to conduct a pre-repair survey and to your List of Surveyors.

TAKE NOTICE that we are instructed to object to all your surveyors stated in your said List for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we propose Constant Appraiser Services as the Single Joint Expert.

Please reply within 2 working days.

Thank you.

Regards,
Elaine Toh
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

cc: SKZ 95 J – By email only

From: Tan Kah Leong [<mailto:KahLeong.Tan@sg.cntaiping.com>]

Sent: Friday, 31 May, 2019 5:56 PM

To: Elainetoh@visionlawllc.com

Cc: Chee So Chow

Subject: RE: SNM19D202448: PRE REPAIR SURVEY --- YOUR REF: GBD 604 M --- ACCIDENT INVOLVING SKZ 95 J (#1) AND GBD 604 M (#2) AND SGL 9040 D (#3) ON 29 MAY 2019 ALONG NEW UPPER CHANGI ROAD AT ABOUT 1930 HOURS

Without Prejudice

Dear Elaine,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

| |
|-------------------------|
| ADRIAN LING |
| LOW SAR HUEI |
| SEE CHEW SENG |
| MOHD FADHILAH BIN OSMAN |
| XING QUO QIANG |
| KENNETH KONG |
| HONG FOOK CHOY |
| CHUA WEIJIE |
| MARCUS CHUA |
| HENRY NG |

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Lim Shu Min
Sent: Friday, 31 May, 2019 5:15 PM
To: Elainetoh@visionlawllc.com; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Cc: Lim Shu Min <shumin.lim@sg.cntaiping.com>
Subject: SNM19D202448: PRE REPAIR SURVEY --- YOUR REF: GBD 604 M --- ACCIDENT INVOLVING SKZ 95 J (#1) AND GBD 604 M (#2) AND SGL 9040 D (#3) ON 29 MAY 2019 ALONG NEW UPPER CHANGI ROAD AT ABOUT 1930 HOURS

Dear Kah Leong,

Please conduct PRS – SKZ95J soonest possible.

File with Officer-In-Charge – Tan Kah Leong – 63896193

Thank you

Lim Shu Min
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896156 | F: (65) 62247175

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Friday, 31 May, 2019 10:55 AM
To: Lim Shu Min <shumin.lim@sg.cntaiping.com>
Subject: FW: PRE REPAIR SURVEY --- YOUR REF: GBD 604 M --- ACCIDENT INVOLVING SKZ 95 J (#1) AND GBD 604 M (#2) AND SGL 9040 D (#3) ON 29 MAY 2019 ALONG NEW UPPER CHANGI ROAD AT ABOUT 1930 HOURS
Importance: High

From: Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]
Sent: Friday, 31 May 2019 10:46 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Irene Tay <irene.tay@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>
Subject: PRE REPAIR SURVEY --- YOUR REF: GBD 604 M --- ACCIDENT INVOLVING SKZ 95 J (#1) AND GBD 604 M (#2) AND SGL 9040 D (#3) ON 29 MAY 2019 ALONG NEW UPPER CHANGI ROAD AT ABOUT 1930 HOURS
Importance: High

Our Ref: SKZ 95 J (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We are instructed by **ASIA CAR LEASING PTE LTD** to notify you of a road traffic accident on 29 May 2019 at about 1930 hours along New Upper Changi Road involving our client's vehicle registration number SKZ 95 J and vehicle registration number GBD 604 M T driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thank you.

Regards,
Elaine Toh
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

cc: SKZ 95 J – By email only

VISION LAW LLC
Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

| | |
|-------------------------------|---------------------------------------|
| Owner ID Type: | Company |
| Owner ID: | 7397C |
| Vehicle No.: | SKZ95J |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 05 Jun 2019 |
| Vehicle Make: | MERCEDES BENZ |
| Vehicle Model: | C180 AVG (R17 LED) |
| Primary Colour: | Silver |
| Manufacturing Year: | 2018 |
| Engine No.: | 27491031606235 |
| Chassis No.: | WDD2050402R455759 |
| Maximum Power Output: | 115.0 kW (154 bhp) |
| Open Market Value: | \$36,172.00 |
| Original Registration Date: | 12 Mar 2019 |
| First Registration Date: | 12 Mar 2019 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$42,641.00 |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 11 Mar 2029 |
| PARF Rebate Amount: | \$31,980.00 |
| COE Expiry Date: | 11 Mar 2029 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$34,509.00 |
| COE Rebate Amount: | \$33,701.00 |
| Total Rebate Amount: | \$65,681.00 |

The information contained herein is correct as at 05 Jun 2019

OK

► Nissan X-Trail Used Vehicle List (17 vehicles)

| Car Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Company | Availability |
|--|------------------|---------------------|--------------------|-----------------|------------------|--------------------------------------|------------------|
| Nissan X-Trail 2.0A Premium 7-Seater Sunroof | \$83,000 | \$10,490 /yr | 21-Mar-2016 | 1,997 cc | 37,724 km | AutoPrestige Gallery Pte Ltd | Available |
| TanChong Motor Unit! Meticulously Maintained By Previous Owner. Lowest Mileage! Pearl White Colour. No Chassis Or Structural Damage. 100% Accident Free Zero Mishap. Priced To Sell. Ex Owner Losses At ... Office No. - 69098044 Andy - 82233641 Ben - 88773030 Alex - 98533834 Chris - 90901068 | | | | | | | |
| Nissan X-Trail 2.0A Premium 7-Seater | \$87,800 | \$11,030 /yr | 27-Apr-2016 | 1,997 cc | 27,662 km | Lake View Credit Pte Ltd | Available |
| Incredibly Under Used, Done 8900km Annually Only! 1 Lady Owner. Selectable 4x4. Totally Brand New! Pearl White With Black Interior. Fully Agent Maintained With Warranty. 100% Accident Free. Call Now! Office No. - 67499895 Chun Kit - 81338870 John - 90478223 Tong Hoe - 96433160 Jason - 97643266 | | | | | | | |
| Nissan X-Trail 2.0A Premium 7-Seater Sunroof | \$85,999 | \$10,760 /yr | 29-Apr-2016 | 1,997 cc | 56,000 km | Premium Automobiles | Available |
| New Arrival Sporty Red SUV On Sale, 1st Owner Mileage Done 56,000km Only. Premium 110 Point Checks Peace Of Mind. Bank Interest Rate 2.28%, Call Now. Thank You. Office No. - 68366223 Ben Lim - 91071271 | | | | | | | |
| Nissan X-Trail 2.0A Premium 7-Seater Sunroof | \$87,500 | \$10,950 /yr | 05-May-2016 | 1,997 cc | 37,000 km | Motorist Pte Ltd | Available |
| Owner 2nd Car, Low Mileage Done, Fully Agent Maintained, Comes With 2 Free Servicing With Agent. High Loans/trade In Welcome, Low Interest Rate From 2.28%. Call/whatsapps Now To Arrange To View This Be... Office No. - 65898800 Benedictine - 81813664 Kanthan - 90225037 | | | | | | | |
| Nissan X-Trail 2.0A Premium 7-Seater Sunroof | \$83,800 | \$10,400 /yr | 09-May-2016 | 1,997 cc | 38,700 km | Global Carz Pte Ltd | Available |
| Immaculate Condition, Fully Tan Chong Agent Maintained, Well Kept By Previous Owner, Trade In And Loan Available, Special Interest Rate Promotion 1.98%, Hurry Make An Appointment To View This Unit Now. Office No. - 63851484 Gary - 92200713 | | | | | | | |
| Nissan X-Trail 2.0A Premium 7-Seater Sunroof | \$91,800 | \$10,850 /yr | 04-Oct-2016 | 1,997 cc | 29,890 km | Republic Auto | Available |
| Classy Pearl White Exterior, Low Mileage Done And Well Kept By Single Owner, Still Under Factory Warranty, Maintain By Agent, Authorized Bank Loan At 2.45% Interest Rate Call/SMS Now For Enquiries And... Office No. - 65672000 Freddie Neo - 81132925 | | | | | | | |
| Nissan X-Trail 2.0A Premium 7-Seater Sunroof | \$122,888 | \$14,450 /yr | 17-Jan-2017 | 1,997 cc | 44,000 km | Euro Performance Asia Pte Ltd | Available |
| Agent (Tan Chong Motor) 3 Plus 2 Years Warranty. Fully Agent Maintained. The Popular 7 Seaters SUV. Powerful And Fuel Efficient Engine With Smooth CVT Gearbox. Well Maintained Interior And Exterior. 1... Office No. - 65330588 / 85009000 Sindy - 90602839 | | | | | | | |
| Nissan X-Trail 2.0A 7-Seater | \$92,888 | \$10,490 /yr | 23-Jan-2017 | 1,997 cc | 54,235 km | ST Auto Pte Ltd | Available |
| 1 Very Careful Owner, Fully Serviced And Maintained By Tan Chong Motors, 100% Accident Free, Excellent Condition, Do Not Miss! Office No. - 64649098/64647110 Melvin Yeo - 90074772 Andy Lee - 96867441 | | | | | | | |
| Nissan X-Trail 2.0A Premium 7-Seater Sunroof | \$96,500 | \$10,580 /yr | 19-Apr-2017 | 1,997 cc | 57,000 km | Venus Auto Pte Ltd | Available |
| 1 Owner. Massive Savings From Brand New. Full Agent Maintained With Mint Condition Interior, Still Under Agent Warranty. Daily Sheltered Parking. New Half Year Road Tax. Accident Free, STA Inspection ... | | | | | | | |

Office No. - 67320807

Ang Eng Keat - 97846085 | Devin - 81231199 | Jesse Wu - 97994194

| | | | | | | |
|-------------------------------------|------------------|---------------------|--------------------|-----------------|------------------|------------------|
| Nissan X-Trail 2.0A 7-Seater | \$101,000 | \$11,170 /yr | 29-Apr-2017 | 1,997 cc | 30,000 km | Available |
|-------------------------------------|------------------|---------------------|--------------------|-----------------|------------------|------------------|

Only Driven For 1 Year. Owner Upgrading To Bigger Car. Problem Free And Flexible 5 Plus 2 Seating Arrangement. 2nd Row Seat Is Very Spacious If Not Using 3rd Row. Boot Is Huge And Can Load 3 Strollers...

Office No. - -

Willy Ang - 97818758

| | | | | | | | |
|---|------------------|---------------------|--------------------|-----------------|------------------|-----------------------|------------------|
| Nissan X-Trail 2.0A Premium 7-Seater | \$101,800 | \$11,000 /yr | 22-Jun-2017 | 1,997 cc | 31,000 km | WM Car Pte Ltd | Available |
|---|------------------|---------------------|--------------------|-----------------|------------------|-----------------------|------------------|

Latest Arrival! Fully Maintained And Serviced In Tan Chong Motors Since Day 1! Superbly Maintained! Cheapest In The Market! View To Believe! Flexible Loan Packages Available To Cater To Different Need...

Office No. - 64634936

Sam - 97829493 | Ivan Choo - 97629200 | Peng Hee - 91761283

| | | | | | | | |
|---|------------------|---------------------|--------------------|-----------------|------------------|-------------------------------|------------------|
| Nissan X-Trail 2.0A Premium 7-Seater | \$102,800 | \$11,100 /yr | 30-Jun-2017 | 1,997 cc | 21,500 km | Hui Hua Credit Pte Ltd | Available |
|---|------------------|---------------------|--------------------|-----------------|------------------|-------------------------------|------------------|

1 Owner! Low Mileage Done! Agent Unit Will Agent Warranty! Popular 7 Seaters SUV! In-House Financing Package Available! Call Now To Enquire!

Office No. - 64696611 / 64646611

Jian Rong - 91830337 | Alex Chng - 86661188 | Weisley Koh - 84888000 | Joey Ng - 88110091

| | | | | | | | |
|---|------------------|---------------------|--------------------|-----------------|------------------|-------------------------|------------------|
| Nissan X-Trail 2.0A Premium 7-Seater | \$108,888 | \$11,190 /yr | 20-Dec-2017 | 1,997 cc | 37,000 km | Motorist Pte Ltd | Available |
|---|------------------|---------------------|--------------------|-----------------|------------------|-------------------------|------------------|

Still Under Agent Warranty. Always Parked Under Sheltered. Best Ideal Family Car. Powerful And Fuel Efficient Engine With Smooth CVT Gearbox. Servicing Package Till 50,000km. High Loans Up To 80% Of C...

Office No. - 65898800

Lionel - 93697866 | Kanthan - 90225037

| | | | | | | | |
|---|------------------|---------------------|--------------------|-----------------|------------------|------------------------|------------------|
| Nissan X-Trail 2.0A Premium 7-Seater | \$107,888 | \$10,900 /yr | 09-Feb-2018 | 1,997 cc | 29,038 km | SG Auto Pte Ltd | Available |
|---|------------------|---------------------|--------------------|-----------------|------------------|------------------------|------------------|

Yet Another Luxurious 7 Seaters SUV! Best Priced In Town! Packed With Free Servicing And Extended Warranty! High Loan And Trade In Available! Loan Promo Rates 1.98%! No Unnecessary Or Misc Charges! H...

Office No. - 68484844

Jamme - 98179689 | Koh - 92475893

| | | | | | | | |
|---|------------------|---------------------|--------------------|-----------------|------------------|------------------------------|------------------|
| Nissan X-Trail 2.0A Premium 7-Seater Sunroof | \$113,000 | \$11,170 /yr | 22-May-2018 | 1,997 cc | 20,000 km | Munich Alpina Pte Ltd | Available |
|---|------------------|---------------------|--------------------|-----------------|------------------|------------------------------|------------------|

Loan Interest At 2.28%. Extremely Well Maintained And Fully Agent Maintained. Comes With First 5 Years Agent Warranty. This Beast Does Not Just Look Beautiful, It's 100% Accident Free. View To Believe...

Office No. - -

Ben - 91849182 | Dave - 94559794

| | | | | | | | |
|---|------------------|---------------------|--------------------|-----------------|-----------------|-----------------------|------------------|
| Nissan X-Trail 2.0A Premium 7-Seater | \$122,800 | \$11,670 /yr | 26-Oct-2018 | 1,997 cc | 8,034 km | Carbiz Pte Ltd | Available |
|---|------------------|---------------------|--------------------|-----------------|-----------------|-----------------------|------------------|

1 Owner With Very Low Mileage Done! Premium Model With Panoramic Sunroof, 360 Surround View Camera And Powered Tailgate. Warranty 3 Plus 2 Years With Tan Chong Motors. Trade-In Welcome. Flexible Finan...

Office No. - 64650258

Abel Eng - 94553667

| | | | | | | | |
|---|------------------|---------------------|--------------------|-----------------|-----------------|------------------------|------------------|
| Nissan X-Trail 2.0A Premium 7-Seater | \$123,800 | \$11,760 /yr | 31-Oct-2018 | 1,997 cc | 9,000 km | Cargent Pte Ltd | Available |
|---|------------------|---------------------|--------------------|-----------------|-----------------|------------------------|------------------|

Low Mileage. Current Face-lift Model. Agent (Tan Chong Motor) 3+2 Year Warranty With 2 Free Servicing. 1 Owner. Fully Agent Serviced/Maintained. Like New. 100% Accident Free. Sheltered Park. Highest T...

Office No. - 66335766

Mag - 81332103 | Peter - 81806338

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

MCD519070641 / ComfortDelGro Engineering Pte Ltd - Braddell
ENTRY DATE & TIME: 30/05/2019 16:22
SUBMITTED BY: Rohaini Binte Mustafa

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 30/05/2019 16:22
Date Of Accident 29/05/2019 19:30
Exact Location Of Accident NEW UPPER CHANGI ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKZ95J
Insured/Policyholder
Name Of Registered Owner ASIA CAR LEASING PTE LTD
Co Reg No 201437397C
Email Address KRISTINE@ASIACARRENTAL.COM.SG
Mobile Phone No
Alternative Phone No Office-91250012

Vehicle Particulars

Manufacturer MERCEDES-BENZ
Model C180 AVG (R17 LED)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 999994406
Cover Note Number

Driver

Name of Driver LUR BOON BENG
NRIC No S1620678D
Date Of Birth 02/06/1963
Occupation INDOOR
Date Of Driving Pass 26/09/1983
Driving Experience 35 YEARS AND 8 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-91250012

Fax Number
Contact Number
Email Address KRISTINE@ASIACARRENTAL.COM.SG
Address 9 LEEDON HEIGHTS #27-27
Postcode 267954
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - RENTAL
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 3
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 Name: : WONG CHUN SOONG
Gender: : Male

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 1 DUKE ROAD , POSTCODE: 268914 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-4629999 - FAX NO: 64628933
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD604M
Vehicle Make/Model/Colour
Details Of Properties RUKUMAN THIRUMALAI
Vehicle Category COMMERCIAL VEHICLE
Name of Driver

NRIC/Passport Number G7907512X
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGL9040D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver PNG YEOW HWEE
NRIC/Passport Number S1641696G
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)


Sketch Plan


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN







DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190529/2171

1 of 4

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

Report No. T/20190529/2171

REPORT OF A TRAFFIC ACCIDENT

| | | | | | |
|--|------------|------------------------------|--|---------------------------|----------------------------|
| Date/Time Report Made: 29/05/2019 20:28 | | Vide Report No.: | | Station Diary No.: 118 | |
| Informant's Particulars | | | | | |
| Name of Informant: LUR BOON BENG | | | Address: 9 LEEDON HEIGHTS #27-27 SINGAPORE 267954 | | |
| ID Type / ID No.: NRIC NO / S1620678D | | | Contact No.: Home/Office: Mobile: 91250012 | | |
| Nationality: SINGAPORE CITIZEN | | | Email: | | |
| Sex: Male | Age: 55 | Date of Birth: 02/06/1963 | Type of Informant: Driver | | |
| Race: Chinese | | | Language: English | | Institution / School Name: |
| Occupation: SALES | | | Driving Licence Information: Class: 2B,2A,3 | | Date of Expiry: |

| | | | | |
|---|------------|------------------------------------|--|------------------------------------|
| General Information of the Accident | | | | |
| Type of Accident: | Non-Injury | Drink Drive: No | Date/Time of Accident: 29/05/2019 19:30 | Type of Location: Straight Road |
| Location: Along Road 1 NEW UPPER CHANGI ROAD New Upper Changi Road towards Changi Road | | | | |
| Weather: Clear | | Road Surface: Dry | Road Speed Limit: | |
| Traffic Flow: Two Way | | Traffic Control: Not Controlled | Traffic Volume: Moderate | |
| Type of Collision: Between Moving Vehicles - Head To Rear | | | Anyone conveyed by ambulance: No | |

| Details of Vehicle Involved | | | | | | |
|------------------------------------|-------|------|-------|-------|------------------|------------------|
| Vehicle No. | Type | Make | Model | Color | Condition | No. of Passenger |
| GBD604M | Lorry | | | | | 0 |
| SGL9040D | Car | | | | | 0 |
| SKZ95J | Car | | | | Slightly Damaged | 1 |

| | |
|-----------------------------------|--------------------------------|
| Details of Person Involved | |
| Any Pedestrian Involved: No | |
| No. of Pedestrians Injured: NIL | Use of Pedestrian Crossing: NA |



**SINGAPORE
POLICE FORCE**

XU DAN
#98577900



T/20190529/2171

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

ACE WATER
(SUPERVISOR)

2 of 4

Report No. T/20190529/2171

CONTINUATION OF REPORT

765626128 ACE WATER

| | | | |
|-----------------------------------|---------------------------------|--|---------------------------------------|
| Driver | | | |
| Name | RUKUMAN THIRUMALAI #83465443 | ID No. | G7907512X |
| Related Vehicle | GBD604M (Lorry) | Contact No. | NIL |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |
| Driver | | | |
| Name | PNG YEOW HWEE | ID No. | S1641696G |
| Related Vehicle | SGL9040D (Car) | Contact No. | NIL |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |
| Driver | | | |
| Name | LUR BOON BENG | ID No. | S1620678D |
| Related Vehicle | SKZ95J (Car) | Contact No. | 91250012 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: 2B,2A,3 Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |

Brief Details.

On 29/05/2019 at 1930hrs, I was travelling in my vehicle SKZ95J with another passenger along New Upper Changi Road towards Changi Road.

I came to a complete stop as the vehicle in front of me came to a stop as well. The vehicle behind me GBD604M also came to stop. About 5 seconds after I came to a complete stop, I felt an impact to the back of my vehicle.

I went down of my vehicle to make a check and saw that the third vehicle SGL9040D did not manage to stop in time and had hit onto the vehicle in front of him GBD604M and in turn GBD604M had collided into my vehicle.



SINGAPORE
POLICE FORCE



T/20190529/2171

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999

3 of 4


Report No. T/20190529/2171

CONTINUATION OF REPORT

No one was injured and we exchanged particulars but I did not manage to get their contact numbers.

NEW UPPER CHANGI ROAD.

SK295 ← LORRY ← CAR
G8D604M SGL9040D



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999



T/20190529/2171

4 of 4

Report No. T/20190529/2171

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Staff Sgt ISAAC YEO QING KAI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

29/05/2019 20:28

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

SINGAPORE
POLICE FORCE

SN 1

Authentication Stamp

NP168

SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 31 May 2019 | | 04 Jun 2019 10:22 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| | | | | |
|-------------|------------------|----------------------|------------------|-----------------|
| Main | Reference | Claim Details | Documents | Show All |
|-------------|------------------|----------------------|------------------|-----------------|

CLAIM SUBFOLDER DETAILS [Created by insurer]

| | | | |
|-----------------------------|---|------------------------|---|
| Insured: | -, Co. Reg. No.: - | | |
| Main Claimant: | ASIA CAR LEASING PTE LTD, Co. Reg. No.: 201437397C | | |
| Vehicle Reg. No.: | SKZ95J | Date of Loss: | 29/05/2019 19:00 - :59 [2 Months and 17 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / SNM19D202448 | Policy/Cover Note No.: | DMCVSN3036981800 |
| Vehicle Reg. No. (Insured): | GBD604M | Policy No. (Claimant): | 999994406 |
| | | Excess: | S\$1,350.00 |
| Repairer: | As Auto Service (HQ) Blk 1 Kaki Bukit Avenue 6 #01-106 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: | | |
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193] | | |
| Claimant's Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/06/2019] | | |

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)



































There are no mail for this case.


































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)













































| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

*SKZ95J (SNM19D202448)
[GBD604M]
TP
ASIA CAR LEASING PTE LTD
May 29 2019 7:00PM
[-]
As Auto Service

| | | | | | | | | | |
|------------------|-----------------|--|--|--------------------|--|--|--|-------------------------------------|--|
| Upload Documents | | Upload Photos | | Compose New Letter | | View | | View in Browser | |
| Video | | | | | | 1 per page | | <input checked="" type="checkbox"/> | |
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Braddell) | | | | Thumbnail | | Print | |
| 1 | 30/05/19 16:43 | Video - Accident [Linked Accident Report Documents] | | | |  Load MP4 | | | |
| | | | | | | 3 per page | | <input checked="" type="checkbox"/> | |
| Photos/Images | | | | | | | | | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | | | Thumbnail | | Print | |
| 1 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 2 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 3 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 4 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 5 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 6 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 7 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 8 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 9 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 10 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 11 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 12 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 13 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 14 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 15 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 16 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 17 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 18 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 19 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 20 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 21 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 22 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 23 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 24 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 25 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 26 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 27 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 28 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 29 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 30 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 31 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 32 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |
| 33 | 13/06/19 19:01 | General View | | | |  Load JPG | | <input checked="" type="checkbox"/> | |

| Video | | | 1 per page | <input checked="" type="checkbox"/> |
|-------|----------------|--|--|-------------------------------------|
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Braddell) | Thumbnail | Print |
| 34 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 38 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 13/06/19 19:01 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 55 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 56 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 57 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 58 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 59 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 60 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 61 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 62 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 63 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 64 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 65 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 66 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 67 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 68 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 69 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 70 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 71 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 72 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 73 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 74 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 75 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 76 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 77 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 78 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 79 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 80 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 81 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 82 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 83 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |

| Video | | | 1 per page | <input checked="" type="checkbox"/> |
|-------|----------------|--|--|-------------------------------------|
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Braddell) | Thumbnail | Print |
| 84 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 85 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 86 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 87 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 88 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 89 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 90 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 91 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 92 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 93 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 94 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 95 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 96 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 97 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 98 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 99 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 100 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 101 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 102 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 103 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 104 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 105 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 106 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 107 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 108 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 109 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 110 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 111 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 112 | 13/06/19 19:02 | Photographs of Damaged Parts |  Load JPG | <input checked="" type="checkbox"/> |
| 113 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 114 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 115 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 116 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 117 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 118 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 119 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 120 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 121 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 122 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 123 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 124 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 125 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 126 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |
| 127 | 13/06/19 19:03 | Photo After Spray |  Load JPG | <input checked="" type="checkbox"/> |

Linked Accident Report Documents

View

| Video | | | | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|----------------|--|--|------------|-------------------------------------|
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Braddell) | | Thumbnail | Print |
| 1 | 30/05/19 16:43 | Video - Accident | | Load MP4 | |
| Assessment Reports | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Braddell) | | Thumbnail | Print |
| 1 | 30/05/19 16:52 | Accident Statement | | Load HTM | |
| Photos/Images | | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Braddell) | | Thumbnail | Print |
| 1 | 30/05/19 16:51 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 30/05/19 16:51 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 30/05/19 16:51 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 30/05/19 16:51 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 30/05/19 16:51 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 30/05/19 16:51 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 30/05/19 16:51 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 30/05/19 16:51 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 30/05/19 16:51 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 30/05/19 16:51 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 30/05/19 16:51 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 30/05/19 16:51 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 30/05/19 16:51 | Accident Photo | | Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Finalized On | ComfortDelGro Engineering Pte Ltd (Braddell) | | Thumbnail | Print |
| 1 | 30/05/19 16:42 | Sketch Plan | | Load TIF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19009847/GCD3E2

Date: 20/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3036981800

Claimant Vehicle No: SKZ95J Insured Vehicle No: GBD604M

Date of Loss: 29/05/2019 Nature of Claim: TP Claim No: SNM19D202448

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ95J**

Make & Model: MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A) Engine No: 27491031606235

Reg. Date: 12/03/2019 (Man.. Year: 2018) Chassis No: WDD2050402R455759

Colour: Silver Odometer: 3454 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17

Front Left Side: Continental 9 mm Rear Left Side: Continental 9 mm

Front Right Side: Continental 9 mm Rear Right Side: Continental 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 04/06/2019

Date Inspected: 04/06/2019 Inspected At: As Auto Service (HQ)
Blk 1 Kaki Bukit Avenue 6 #01-106
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 20 Jun 2019)

Parts: 143 MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKZ95J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >