

ASS. REC. BY:

REF: CS3/A1G19009848/Gcd302 Special Instruction:

Surveyor: YGD

## ASSIGNMENT (Office)

From (Person): Chin Lee Yung of A1G Date/Time: 04/6/19

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 9757G Insured: SML 12095

at Workshop m/s LARSMITH PL Tel: 9091 000 Alex

of 13 KAKI BUKIT RD 4 #01-20 BARTLEY B2 CENTRE

Policy No: 0999994322 Claim No: 729859902386

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 01/6/19

CA / REV / REP. / REV 24 HRS 'PRS' H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate ( )
	SMA 9757G / SML 12095	NA/CT/19009745/64 DOR: 01/6/19
	Dismantle:	6/6/2019
	After repair:	7/6/2019



PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying  
To: assignments, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 6/4/2019 10:48:07 AM  
Attachments:  tmp70FF.TIF

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

(M)

PRS

xGA

CarSmith PL.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Ref: SML 1209 S

Our Ref: AL.INS.2019.SMA9757G

3 June 2019

**AIG ASIA PACIFIC INSURANCE PTE. LTD.**

**BY FAX: 6835 7416 ONLY**

78 Shenton Way  
Tower 2 #07-16  
Singapore 079120

Dear Sirs,

**ACCIDENT INVOLVING SMA 9757 G & SML 1209 S ALONG SIMS AVENUE  
TOWARDS CHANGI INBETWEEN LORONG 9 & 11 ON 1 JUNE 2019 AT ABOUT  
1250 HOURS**

We act for the owner of vehicle no. SMA 9757 G.

We are instructed to claim damages against you in connection with the above accident.

Pursuant to NIMA protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop:-

**CARSMITH PRIVATE LIMITED**

13 Kaki Bukit Road 4  
#01-20 Bartley Biz Centre  
Singapore 417807  
Person In-Charge: Alex  
Mobile Number: 9091 0000

TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Please contact our staff, Jerdine / Jiamin at 6422 2187 or email us at [jiamin.mak@alt.sg](mailto:jiamin.mak@alt.sg) / [jerdine.wang@alt.sg](mailto:jerdine.wang@alt.sg) for future correspondences.

Yours faithfully



**ALLISTER LIM**

**ALLISTER LIM & THRUMURGAN**

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	2733H
Vehicle No.:	SMA9757G
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jun 2019
Vehicle Make:	NISSAN
Vehicle Model:	X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	MR20791980B
Chassis No.:	JN1JANT32Z0001245
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$21,714.00
Original Registration Date:	10 Dec 2015
First Registration Date:	10 Dec 2015
Transfer Count:	1
Actual ARF Paid:	\$22,400.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Dec 2025
PARF Rebate Amount:	\$16,800.00
COE Expiry Date:	09 Dec 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,103.00
COE Rebate Amount:	\$39,782.00
<b>Total Rebate Amount:</b>	<b>\$56,582.00</b>

The information contained herein is correct as at 05 Jun 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/06/2019 14:05
Date Of Accident	01/06/2019 12:50
Exact Location Of Accident	SIMS AVE TWDS CHANGI IN BETWEEN LOR 9 & 11
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA9757G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MR HYRIL ANNUAR BIN BORHAN
NRIC No	S7042733H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81382266
Alternative Phone No	OFFICE-81382266

### Vehicle Particulars

Manufacturer	NISSAN
Model	X-TRAIL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3067391800
Cover Note Number	-

### Driver

Name of Driver	MR HYRIL ANNUAR BIN BORHAN
NRIC No	S7042733H
Date Of Birth	09/12/1970
Occupation	OUTDOOR
Date Of Driving Pass	05/04/1995
Driving Experience	24 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81382266
Fax Number	
Contact Number	OFFICE-81382266
EMail Address	NOEMAIL

Address	BLK 673A YISHUN AVE 4 #12-638
Postcode	761673
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : INDAH WULAN DARI SITUMEANG GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SML1209S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF INJURED PERSON 1**

Name	MR HYRIL ANNUAR BIN BORHAN
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SMA9757G
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

# Accident Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(if driver is not the policyholder)  
Date & Time:




Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELLING ALONG THE STATED TIME AND LOCATION.

I noticed a vehicle on my right signalling to cut into my lane. I SLOWED DOWN AND STOPPED. SUDDENLY I FELT AN IMPACT ON MY REAR. I GOT DOWN AND INSPECT AND KNOW THAT VEHICLE 'B' HAD HIT INTO MY VEHICLE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched  
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary  
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

**MOTORCAR (Rear)**

(1) Replace (✓) (2) Repair (X) (3) Check (✓)  
 (4) Not Consistent (NC)

Vehicle No: **SMA97576**

**Rear Portion**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	Rep	/	
1142	993085	Rear Bumper Upper	Rep	/	
1143	993017	Rear Bumper Lower	Rep	/	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	Rep	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement	Repair		
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding	Cost	/	
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	Repair		
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	Rep	/	
1182	991328	Tailgate Emblem	Rep	/	4
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	Rep	/	
1196	994607	Tailgate Glass Sealant	Rep	/	
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			Rep - 2

*[Handwritten Signature]*  
 7/6/2019

No of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_

*original copy*

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jun 2019 <a href="#">Edit Reg</a>		04 Jun 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		[Created by adjuster]							
Insured:	<b>BIS MOTORING PTE LTD</b> , Co. Reg. No.: 201735055D								
Main Claimant:	<b>NA</b> , Co. Reg. No.: NA								
Vehicle Reg. No.:	<b>SMA9757G</b>	Date of Loss:	01/06/2019 12:00 - :59 [41 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 7298599023SG</b>	Policy/Cover Note No.:	0999994322 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SML1209S</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Carsmith Private Limited (HQ)</b> 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 14/06/2019]								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
<ul style="list-style-type: none"> <li>AIG_SG (06/06/2019): <b>Request To Upload TP GIA Report</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*SMA9757G (7298599023SG)**  
**[SML1209S]**  
**TP**  
**NA**  
**Jun 1 2019 12:00PM**  
**[BIS MOTORING PTE LTD]**  
**Carsmith Private Limited**

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
<b>Photos/Images</b>											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
2	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
3	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
4	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
5	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
6	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
7	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
8	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
9	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
10	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
11	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
12	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
13	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
14	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
15	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
16	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
17	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
18	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
19	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
20	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
21	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
22	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
23	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
24	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
25	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
26	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
27	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
28	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
29	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
30	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
31	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
32	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
33	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
34	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
35	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
36	13/06/19 18:55	General View							Load JPG	<input checked="" type="checkbox"/>		
37	13/06/19 18:56	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	13/06/19 18:56	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	13/06/19 18:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	06/06/19 11:22	OI GIA report	 Load PDF	

## Documents Checklist

**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:**  Handling InsurerNote: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19009848/GCD3E2

Date: 24/06/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994322  
**Claimant Vehicle No :** SMA9757G **Insured Vehicle No :** SML1209S  
 Date of Loss: 01/06/2019 Nature of Claim: TP Claim No: 7298599023SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SMA9757G**  
 Make & Model: NISSAN X-TRAIL, 2.0 CVT (A) Engine No: MR20791980B  
 Reg. Date: 10/12/2015 (Man. Year: 2015) Chassis No: JN1JANT32Z0001245  
 Colour: White Odometer: 98063 km  
 Engine Capacity: 1997 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18  
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 04/06/2019  
 Date Inspected: 04/06/2019 Inspected At: Carsmith Private Limited (HQ)  
 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY  
 BIZ CENTRE  
 Singapore 417807  
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER UPPER	Cracked	0.00 F	*- F
3	1		*REAR BUMPER LOWER	Deformed	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Repair	0.00 F	*- F
6	1		*REAR BUMPER MOULDING	Cut	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*TAILGATE	Cracked	0.00 F	*- F
9	4		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
10	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
11	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
12	2		*STICKER	Necessary	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >