

Number

Surveyor: Tan Fich

**ASSIGNMENT (Office)**

From (Person): ONG Zi Hui

of MSG

Date/Time: 3.6.19 4.00p.m

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No: SLV 1136 C

Insured: FBE F292C

at Workshop m/s Ace Autolution

Tel: 9657 2134

of 13 Kaki Bukit Road 4 #03-29

Policy No: MSD/VMS/19-998534-WTT

Claim No: MSCV/19-000611

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27.5.2019

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 4.6.19 9.40a.m

Person Contacted: Shu Win

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 1136C - X
	FBE F292C - X
4/7/19 @	We informed Wane Tan, we are pending estimate from repairer.

Typist | REF: MSIG

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 12/7/19  
 Estimated Cost: \_\_\_\_\_  
 OD: (TP) / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: SLV 1136C  
 at Workshop n/s: Ace Autolution  
 of 13 kaki Bukit Road 4 # 03-29  
 Insured: \_\_\_\_\_  
 Policy No: MSD/VMS/19-998534-WTT  
 Claims No: MSC/V/19-000611  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS 1up ~~AKS~~  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

N/S	O/S

Veh No: SLV 1136C Yr Regn: 2017 Dec  
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Toyota CHR Hybrid c.c. 1792  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 98928 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: ZYX10206976  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 225/55R18  
 R: 225/55R18  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 12/7/19 C3pm  
 Survey held at Ace Autolution  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
23/09/20 @ 11.12am	revised to Irene Tan via Merimen.
	LS \$4500, 5 days (Red \$12269.25, 73%)

Date/Time, File Pass to?  : Preli. Report  
 1) 23/09 Typist  : Final Report  
 Date/Time, File Return to? \_\_\_\_\_  
 Add Fee:  : Site Insp (\$)  : Interview (\$)  : Tech. Insp (\$)  : Meal end (\$)  
 Days Of Repair: 5  
 Resurvey No. of Trip: 1  
 Report Form: MER-TP  
 Emp. No: 4500  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Plates: \_\_\_\_\_  
 Other: \_\_\_\_\_  
 Page: \_\_\_\_\_

## Nivitha (LKK Auto)

---

**From:** Ong Zi Hui <zihui\_ong@sg.msig-asia.com>  
**Sent:** Monday, 3 June 2019 4:00 PM  
**To:** assignments@lkkauto.com; admin-d@lkkauto.com  
**Cc:** Crystal Lee  
**Subject:** Survey Request - Manual Assigned

**SLV1136C D.O.A 27/5/2019 DOA: 27/05/19 FBE7292C (MSIG) (NR case)**

### Manual Assigned

Dear LKK

Refer to the email below, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you.

Ong Zi Hui  
Admin Officer, Claims Services  
D: +65 6643 1320 | F: +65 6225 7402 | [zihui\\_ong@sg.msig-asia.com](mailto:zihui_ong@sg.msig-asia.com)



**MSIG**

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Nabilah Rasol  
**Sent:** Monday, 3 June, 2019 3:34 PM  
**To:** 'Ace Autolution' <admin@aceauto.com.sg>  
**Cc:** Irene Tan <irene\_tan@sg.msig-asia.com>; Crystal Lee <crystal\_lee@sg.msig-asia.com>; Ong Zi Hui <zihui\_ong@sg.msig-asia.com>  
**Subject:** RE: SLV1136C D.O.A 27/5/2019 DOA: 27/05/19 FBE7292C (MSIG) (NR case)

Hi Jenny , Shu Wen,

Thank you for your selection.

We will proceed to assign Marcus Chua from LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

**Nabilah Rasol (Ms)**

Admin Officer, Claims Services (Motor)

Direct line +65 6643 1335 | Direct fax +65 6225 7402 | [nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

**From:** Ace Autolution [<mailto:admin@aceauto.com.sg>]

**Sent:** Monday, 3 June, 2019 12:09 PM

**To:** Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)>

**Cc:** Irene Tan <[irene\\_tan@sg.msig-asia.com](mailto:irene_tan@sg.msig-asia.com)>

**Subject:** Re: SLV1136C D.O.A 27/5/2019 DOA: 27/05/19 FBE7292C (MSIG) (NR case)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Hi all,

We choose LKK Auto Consultants Pte Ltd - Marcus Chua.  
Thank you.

Regards ,

Jenny / Shu Wen

**ACE AUTOLUTION PTE LTD**

13 KAKI BUKIT ROAD 4 ,

#03-29 BARTLEY BIZ CENTRE

SINGAPORE 417807

Tel : 6844 1184 / 9657 2134

On Mon, Jun 3, 2019 at 11:46 AM Nabilah Rasol <[nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)> wrote:

Hi Jenny , Shu Wen,

We refer to your email dated 01/06/2019.

Please note that our insured has yet to report.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) **MSIG In-House Surveyors**

\*This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor\*

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1) Calvin Ang	6) Frankie Pang
2) Kenneth Kong	7) Ng You Han
3) Marcus Chua	8) Gary Soon
4) Henry Ng	9) Chow Bo Xiong
5) Lau Kwok Kwong	10) Axel Lee

NB:

**(a) \*Fast lane settlement is not applicable for cases that liability is in dispute\***

(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: [motorsurvey@sg.msig-asia.com](mailto:motorsurvey@sg.msig-asia.com)

Have a great week ahead!

**Nabilah Rasol (Ms)**

Admin Officer, Claims Services (Motor)

Direct line +65 6643 1335 | Direct fax +65 6225 7402 | [nabilah\\_rasol@sg.msig-asia.com](mailto:nabilah_rasol@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65

6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



**From:** Ace Autolution [mailto:admin@aceauto.com.sg]  
**Sent:** Saturday, June 01, 2019 4:08 PM  
**To:** Claims <claims@sg.msig-asia.com>  
**Subject:** SLV1136C D.O.A 27/5/2019

**EXTERNAL EMAIL:** Be careful when you click any links or open any attachment(s).

Dear Sir/Mdm,

Please take note of the attached file for your reference.

Thank you.

Regards ,

Jenny / Shu Wen  
ACE AUTOLUTION PTE LTD

13 KAKI BUKIT ROAD 4 ,

#03-29 BARTLEY BIZ CENTRE

SINGAPORE 417807

Tel : 6844 1184 / 9657 2134

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

## Shiau Chan (LKKAuto)

---

**From:** Do-Not-Reply <do-not-reply@merimen.com>  
**Sent:** Tuesday, 16 July 2019 12:00 PM  
**To:** do-not-reply@merimen.com  
**Cc:** SUR  
**Subject:** TP VEHICLE SLV 1136C (YOUR REF: MSC/V/19-000611)

This mail is associated with :  
**\*SLV1136C (MSC/V/19-000611)**  
**[FBE7292C]**  
TP  
IEGOLPY  
May 27 2019 12:00AM  
[ABDUL GAFFORE MOHAMED JAMEEL]  
Ace Autolution Pte Ltd

Dear Irene,

Please be informed that we have inspected the vehicle SLV 1136C on 12/07/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)  
LKK Auto Consultants Pte Ltd  
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

mslg

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/05/2019 17:22
Date Of Accident	27/05/2019 11:45
Exact Location Of Accident	MARINA BOULEVARD TOWARDS STRAITS VIEW
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV1136C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	IEGOLPY
Co Reg No	53373023J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98890509

### Vehicle Particulars

Manufacturer	TOYOTA
Model	C-HR-1.2 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCTHQ18-000075
Cover Note Number	

### Driver

Name of Driver	SAM UTTAMA
NRIC No	S8026093H
Date Of Birth	16/08/1980
Occupation	OUTDOOR
Date Of Driving Pass	13/12/2005
Driving Experience	13 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98890509
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 118 LORONG 1 TOA PAYOH #08-423
Postcode	310118
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE ATTACHED REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBE7292C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	ABDUL GAFFORE MOHAMED JAMEEL
NRIC/Passport Number	S7568231Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27 May 2019 at around 11:43 AM, I was travelling along Marina Boulevard turning into Straits View. Suddenly, I felt an impact from the right side of my vehicle. When I got off my vehicle (SLV 1136 C) (FBE 7202 C) to check on what has happened, I realise that vehicle B have collided to the right-hand side of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

*[Handwritten Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



T/20190528/2179

2 of 3

Report No. T/20190528/2179

Police Station Of Origin:  
Boon Teck NPP  
207 Toa Payoh North #01-1231 SINGAPORE  
310207  
Tel No: 1800-2549999

**CONTINUATION OF REPORT**

Rider			
Name	ABDUL GAFFORE MOHAMED JAMEEL	ID No.	S7568231Z
Related Vehicle	FBE7292C (Motorcycle)	Contact No.	93439039
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	SAM UTTAMA	ID No.	S8026093H
Related Vehicle	SLV1136C (Car)	Contact No.	98890509
Hospital/Clinic	EJ FAMILY CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	28/05/2019	Date Discharge	28/05/2019
No. of Days granted Medical Leave	05	Degree of Injury	NIL

**Brief Details.**

On 27/5/2019 at about 11.40am, I was driving my car(SLV1136C) along Marina Boulevard. I was turning right to Straits View towards MBFC. When I was turning right, I suddenly heard a bang from the right side of my car. I then immediately braked and I alighted from my car. I saw that a motorbike (FBE7292C) on the ground and the rider was already standing. I am not sure where the bike came from and how he hit onto my car. I felt pain on my neck area and I saw a doctor. I got 5 days MC.



**SINGAPORE  
POLICE FORCE**



T/20190528/2179

3 of 3

Report No. T/20190528/2179

Police Station Of Origin:  
Boon Teck NPP  
207 Toa Payoh North #01-1231 SINGAPORE  
310207  
Tel No: 1800-2549999

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 SATHISH KUMAR S/O TAMBIRAJAH

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

28/05/2019 19:31

Officer In Charge Of Case:

TP / AEIT /

SSI 2 JUREMAH BINTE AHMAD

Contact No.: 65472076

SINGAPORE  
POLICE FORCE

Authentication Stamp

NP168

SIGNATURE

1st Accident Estimate.

TP: MS19.



ACE AUTOLUTION PTE LTD  
13 Kaki Bukit Road 4 Bartley Biz Centre #03-29  
Singapore 417807  
Tel:6702 4282 Fax:6702 4202

68441184 / 96572134  
(Anna)

Page No. 1

Vehicle No. SLV1136C TOYOTA CHR

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
<b>PARTS (LIST ITEMS)</b>				
1	FRONT DOOR RH		1109 1320.00	bt ✓
1	FRONT INNER DOOR BOARD RH		590.00	x
1	FRONT DOOR LOWER MOULDING RH		242.00	x
1	FRONT DOOR UPPER MOULDING RH		211.00	x
1	FRONT DOOR GLASS RUN CHANNEL RH		142.00	x
1	FRONT DOOR LOWER TRIM COVER RH		342.00	cut ✓
1	FRONT DOOR BLACK TAPE RH		25.00	new ✓
1	FRONT DOOR LOCK RH		473.90 520.00	bt ✓
1	FRONT DOOR POWER WINDOW REGULATOR RH		585.00	x
1	REAR DOOR RH		1084.90 1420.00	bt ✓
1	REAR INNER DOOR BORD RH		490.00	x
1	REAR DOOR GLASS RUN CHANNEL RH		142.00	x
1	REAR DOOR LOWER MOULDING RH		242.00	x
1	REAR DOOR UPPER MOULDING RH		211.00	x
1	REAR DOOR LOWER TRIM COVER RH		342.00	cut ✓
1	REAR DOOR BLACK TAPE RH		25.00	new ✓
1	REAR DOOR POWER WINDOW REGULATOR RH		585.00	x
1	REAR FENDER RH		980.00	Rx
1	REAR FENDER ARCH RH		210.00	ab ✓
1	REAR FENDER SPLASH SHIELD RH		253.00	x
1	REAR SHOCK ABSORBER RH		592.00	x
1	REAR LOWER ARM RH		298.00	x
1	REAR TIE ROD RH		145.00	x
1	REAR WHEEL BEARING RH		278.00	x
1	REAR KNUCKLE ARM RH		398.00	x
1	REAR BUMPER		1030.00	x
1	REAR BUMPER SIDE RETAINER RH		115.00	x
1	REAR BUMPER LOWER		620.00	x
1	REAR BUMPER LOWER REFLECTOR RH		355.00	x
1	REAR BUMPER LOWER REFLECTOR COVER RH		291.00	x
			12999.00	
less 25%			3249.75	25%
			9749.25	
<b>SPECIAL NETT ITEMS</b>				
1 SET	REAR FENDER INNER SHEILD CLIPS		80.00	x
1 SET	REAR BUMPER CLIPS		120.00	x
1	FRONT BODY BIG STICKER		300.00	200.
1	FRONT FENDER GRILLE RH		310.00	x
1	DOOR VISOR		280.00	180
1	REAR 18' TYRE RH		350.00	x
1	REAR SPORT RIM RH		980.00	500 cut ✓
Total Parts			12169.25	

5611.80.

2708.85.

850.



**ACE AUTOLUTION PTE LTD**  
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29  
 Singapore 417807  
 Tel:6702 4282 Fax:6702 4202

Vehicle No. SLV1136C TOYOTA CHR

S/N	DESCRIPTION	REPAIRER'S ESTIMATE	OUR ASSESSMENT
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1800.00	600.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1600.00	600.
3	To remove, refix wiring system at accident damage areas and check for proper function	150.00	30.
4	To perform anti-rust treatment on affected areas	180.00	40.
5	To clear fault code with diagnostic computer and reset to specification.	250.00	100.
6	To remove and replace / refix front & rear door inner parts fitting etc rhs	150.00	120.
7	To conduct computerised wheel alignment test	120.00	80.
8	To remove and replace front undercarriage parts rhs	350.00	Xun.
	Labour Total :	4600.00	1570
<b>TOTAL (PARTS &amp; LABOUR):</b>		16769.25	

Tanpin 97425749  
 WP  
 12/7/20  
 Lump sum  
 Resurvey after repairs  
 5 days.

2708.85  
 880  
 1570  
 5158.85  
 4/s \$4100 #  
 5 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: