

7203/2012

ASS. REC. BY:

REF: CS/MSG19009881/ F1td3m2 Special Instruction:

Surveyor: QuinnASSIGNMENT (Office)From (Person): Jasmine Lok Kheng Kwai of MSI Date/Time: 4.6.19 10.00am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH 7600EInsured: SJE 6894Cat Workshop m/s Comfort & CoTel: 62148316of 59, loyang DrivePolicy No: 1000985166Claim No: 22 7774

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 2.6.2019

CA / REV / REP. / REV 24 HRS

rup

H.O.D. Endorsement: _____

Date/Time: 4.6.19 10.00amPerson Contacted: LarryVehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	SH 7600E - CS / FCI 18007056 / Uthm2.	R.O.A. - 16/04/2018
	SJE 6894C - ✓	
	7/6/19 @ 9:41am - Revised via menmen preli aduse.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 07 Jun 2019

Preliminary Advice

Insured Vehicle No	: SJE6894C	Accident Date	: 02/06/2019
TP Vehicle No	: SH7600E	Assignment Date	: 04/06/2019
Make	: HONDA CIVIC	Est. Duration of Repair	: 3.00
Date of Inspection	: 04/06/2019		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,375.00
Revised Amount	:S\$	1,535.25
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,535.25

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jun 2019		04 Jun 2019 10:00 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	Jean Wan Yen-Ping, ID: S7722537D, Tel: 97935805, Email: jeanwan@dbs.com								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SH7600E	Date of Loss:	02/06/2019 09:00 - :59 [24 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 227774	Policy/Cover Note No.:	1000985166 (Comprehensive) Coverage: 05/05/2019 - 04/05/2020						
Vehicle Reg. No. (Insured):	SJE6894C	Policy No. (Claimant):							
		Excess:							
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/06/2019]								
Driver/Custodian (Insured):	WAN CHENG YAN (74 / Male), NRIC: S0352877D Email:								
Adj Asg. Remarks:	on WP. Please contact us ASAP if you cannot attend this assignment. Car in 04/06/2019 - rooftop carpark. Liab: dispute. Contact: Larry 6214 8316. Manually assigned to LKK via email on 04/06/2019								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Tuesday, 4 June 2019 9:52 AM
To: assignments@lkkauto.com; admin-d@lkkauto.com
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: SH7600E Repair Estimate.pdf

SH 7600E VS SJE6894C (MSIG) DOA: 02.06.2019 Car in 04/06/19 (Loyang Drive) roof top carpark

Manual Assigned

Dear LKK

Refer to the email below and attachment, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Motor Survey

Sent: Monday, 3 June, 2019 5:31 PM

To: Eileen Ang <eileen_ang@sg.msig-asia.com>; Jasmine Lok Kheng Kwei <jasmine_lok@sg.msig-asia.com>

Cc: Ong Zi Hui <zihui_ong@sg.msig-asia.com>; Crystal Lee <crystal_lee@sg.msig-asia.com>

Subject: FW: SH 7600E VS SJE6894C (MSIG) DOA: 02.06.2019 Car in 04/06/19 (Loyang Drive) roof top carpark

Please see attached Repair Estimate and SAS. Kindly arrange to survey the taxi at 59 Loyang Drive.

The taxi is at the rooftop carpark

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Ng Nyuk Phin [<mailto:ngnp@cdge.com.sg>]
Sent: Monday, 3 June 2019 3:25 PM
To: Motor Survey <motorsurvey@sg.msig-asia.com>
Subject: Fw: SH 7600E VS SJE6894C (MSIG) DOA: 02.06.2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Motor Claims,

Please ignore earlier Repair Estimate as the DOA and Ins Co were wrongly typed.

Kindly use this attached.

Apologies for the error.

Regards,
Larry Ng
ComfortDelgro Engineering Pte Ltd
Loyang Taxi Crash Repairs
6214 8316

From: Ng Nyuk Phin
Sent: Monday, 3 June 2019 3:19 PM
To: motorsurvey@sg.msig-asia.com
Subject: SH 7600E VS SJE6894C (MSIG) DOA: 02.06.2019

Dear Motor Claims,

Please see attached Repair Estimate and SAS. Kindly arrange to survey the taxi at 59 Loyang Drive.

The taxi is at the rooftop carpark.

Regards,
Larry Ng
ComfortDelgro Engineering Pte Ltd
Loyang Taxi Crash Repairs
6214 8316

From: ApeosPort-IV C5570 <sbs-singnalling@sbstransit.com.sg>
Sent: Monday, 3 June 2019 3:15 PM
To: Ng Nyuk Phin
Subject: Scan Data from CDG_LO_AW_A5570

Number of Images: 7
Attachment File Type: PDF

Device Name: ApeosPort-IV C5570
Device Location:

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

SBS Transit Ltd [Registration No. 199206653M]

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/06/2019 11:15
Date Of Accident	02/06/2019 09:50
Exact Location Of Accident	BLK 114 BISHAN ST 12 OPEN SPACE CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH7600E
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 4G
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	HO CHOONG LEONG
NRIC No	S1378865J
Date Of Birth	06/10/1959
Occupation	OUTDOOR
Date Of Driving Pass	10/07/1982
Driving Experience	36 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98523470
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 417 ANG MO KIO AVENUE 10 #07-1025
Postcode	560417
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED * TYPE OF ACCIDENT :- 3P REVERSED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJE6894C
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

REAR RH

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303921R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Loke Yian Heng

316119

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/6/19 at about 09:50 hrs, I was waiting oncall passenger at above said location. I drive out and stop. let the female passenger boarding taxi. A few second later, Veh B reversing towards me and it rear right portion collided onto the right front door of my taxi. I took some scene photo after shifted our vehicle. Another driver witnessing the accident happen, Mr Sim h/p: 90676933 willing to be witness. No injury reported in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Loi Wei Yeng

3/6/19



COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7600E

DATE: 3. Jun. 2019

MAKE : TOYOTA

MODEL : PRIUS

DOA: 2. Jun. 2019

MSIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Door – RH <i>X mpr</i>			\$1,227.00
1	Side Mirror – RH <i>X mpr</i>			\$1,374.00
SUB TOTAL				\$2,601.00
LESS 25%				\$280.56
DISCOUNTED TOTAL				\$2,320.44
1	Front Door ComfortDelgro Sticker <i>— m</i>			\$75.00
				Nett
				\$75.00
Labour Charge				
1	Panel Beating			²⁰⁰ \$350.00
1	Spray Painting Charge			²⁰⁰ \$350.00
1	Wiring Charge			²⁰ \$80.00
1	Tuff Kote			²⁰ \$80.00
1	Transfer of Door			⁵⁰ \$120.00
TOTAL LABOUR				\$980.00
ESTIMATE TOTAL				\$3,375.44
				3005.75

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Acknowledged by:
Signature:
Date:

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO. 305300447

CUSTOMER

COMFORT TRANSPORTATION PTE LTD

VARS

R/MS 7010045

CUSTOMER NO. 383 SIN MING DRIVE

ADDRESS Singapore SINGAPORE 575717

65508755

L (R)

(O)

(P)

SCOUT CARD NO.

REGN NO. SH 7600E

MILEAGE

MAKE: TOYOTA

FUEL

E.....1/2.....F

MODEL PRIUS HYBRID(G4) 03.06.2019 09:40

DATE/TIME IN

YR OF MANUF 25.05.2017

TARGET DATE

CHASSIS CODE JTDKB3FU003556841

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 02.06.2019


NATURE: 3P 02.06.2019

S/NO

LABOR CODE

DESCRIPTION

MSIG - Right Front door, Side mirror



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

id:

No.:

Plate No.:

SH 7600E

LARRY

Vehicle No.:

SH 7600E

Larry Ng

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 10.06.2019

Time: 10:28:11

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305300447
REGN NO : SH 7600E
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 25.05.2017
DATE/TIME IN : 03.06.2019 09:40
ACCIDENT DATE : 02.06.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-0592-G	PRIG4 PANEL SUB-ASSY FRON	1	1,227.00	25.00	920.25
0002 28-01-0103-0003-A	(140)FRT DOOR LOGO SONATA	1	75.00		75.00

SUB-TOTAL : 995.25

JOB NATURE

0000 PB	PANEL BEATING	200.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00
0002 17-01	WIRING CHARGE	20.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	20.00
0004 L	TRANSFER OFF DOOR	50.00

SUB-TOTAL : 490.00

TOTAL : 1,485.25

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305300447

Date : 10. Jun. 2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Calvin

Vehicle Reg No. : SH 7600E

Date of Accident: 2. Jun. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: MSIG SJE6894C

2. The finalized amount shall be:

(a) Spare Parts after List discount \$995.25

(b) Labour Charges \$490.00

Total for Part-By-Part Repair Cost \$1,485.25

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: _____

Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kaha

Date : 11/6/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19009881/K1TD3N2

Date: 17/06/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1000985166
Claimant:	SH7600E	Insured Vehicle No :	SJE6894C
Vehicle No :		Nature of Claim:	TP
Date of Loss:	02/06/2019	Claim No:	227774

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7600E	Engine No:	2ZRS042834
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU003556841
Reg. Date:	25/05/2017 (Man. Year: 2017)	Odometer:	180869 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Davanti 7 mm	Rear Left Side:	Davanti 7 mm
Front Right Side:	Davanti 7 mm	Rear Right Side:	Davanti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,025.75	995.25	1,030.50	50.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	490.00	490.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,005.75	1,485.25	1,520.50	50.59
+ GST 7.00/7.00% (S\$)	210.40	103.97	106.43	50.58
Nett Amount (S\$)	3,216.15	1,589.22	1,626.93	50.59

INSPECTION

Date of Assignment:	04/06/2019	
Date Inspected:	04/06/2019 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Jun 2019)
Parts: 144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SH7600E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-RH	Buckled	1,227.00 FL	*1,227.00 FL
2	1		*SIDE NIRROR-RH	Repair	1,374.00 FL	*- FL
3	1		*FRONT DOOR COMFORTDELGRO STICKER	Necessary	75.00 FS	*75.00 FS
				Sub Total (\$\$)	2,676.00	1,302.00
				- List Item Discount on L Items 25.00/25.00% (\$\$)	650.25	306.75
				Total Parts (\$\$)	2,025.75	995.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	200.00
2	SPRAY PAINTING CHARGE	New	350.00	200.00
3	WIRING CHARGE	New	80.00	20.00
4	TUFF KOTE	New	80.00	20.00
5	TRANSFER OF DOOR	New	120.00	50.00
Gross Labour Cost (\$\$)			980.00	490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >