

ASS. REC. BY:

REF:

C93/A1619009884/064302

Special Instruction:

Surveyor:

Cano Cano

ASSIGNMENT (Office)

From (Person):

Hor Yinarul

of

A15

Date/Time:

04/6/19

Estimated Cost:

Bill to:

OD-TP-WS-TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SGT 6089A

Insured:

SKB 1508E

at Workshop m/s

Tel:

98528621

of

2A Starlight Rd S217755

Policy No:

2100301745

Claim No:

76160986175G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/2/19

CA / REV / REP. / REV 24 HRS

4RS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction	Fohmote (X)
	SGT 6089A	X
	SKB 1508E	C03/A1619009884/Avd3 008: 25/2/19

AIG

PRS

6.6. 2019

SGT 089A

Mar, 07

of 2A Starlight Rd S 217755

loop in our waiting

Ragu contact: 985 28621

Remark: The vehicle had commenced its repair at the time of inspection.

	N/S	O/S

Honda Accord 2.0 C.C. 1998

white

193312

CL73204273

F:

Re:

6

R/Bal.

7

L/Bal.

D.O.I.

2A starlight RD 1 pm

n/s Near

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]☐

11

TOTAL

Report Format : DAR

Lump Sum / I.B.I: (\$)

180

1

194

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Jun 2019 Edit Reg		04 Jun 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main		Reference		Claim Details		Documents		Show All	
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	JUNE TEY SU MIN, ID: S7318689G, Tel: +6590468240								
Main Claimant:	JEEVA NAIDU S/O SOMASUNDARAM, ID: S1451726Z								
Vehicle Reg. No.:	SGT1089A			Date of Loss:	25/02/2019 12:00 - :59				
Claim Type:	TP / 7616098617SG			Policy/Cover Note No.:	2100301745 (Comprehensive)				
Vehicle Reg. No. (Insured):	SKB1508E			Policy No. (Claimant):					
				Excess:					
Repairer:	- Not Applicable - (-)								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/06/2019]								
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail	
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>								View All Search Tasks Create New Task Complete	
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION REQUEST – SGT1089A vs SKB1508E (OI) on D.O.A.: 25/02/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tor
Sent: 6/4/2019 11:17:38 AM
Attachments:  tmp4638.tif  tmp4638.tif

Hi,

Please refer to the enclosed request from **Clifford Law**.

Claim no : 76160986175G003
Case Owner : Wan Nur Saliha Binti Syed Yusoff

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor, Yinrul (Viviane)

AK

Claims Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinrul.Hor@aig.com | www.aig.sg

From: Jennie Chan [mailto:JennieChan@cliffordlaw.sg]
Sent: Tuesday, June 04, 2019 10:56 AM
To: Hor, Yinrul; Jia Ying Chow
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin
Subject: [EXTERNAL] PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKB1508E AND SGT1089A ON 25/02/2019 (Ref: VS.JY.JG.6853.19.jc)

This message is from an external sender; be cautious with links and attachments.

Dear Yinrul,

We refer to your email attached.

We have our client's instruction to arrange any surveyor from Priority Services, Automobile Inspection Services, Formteam Adjusters and LKK Auto Consultants to conduct the joint pre-repair survey. Please liaise with Mr Ragu directly at his email ragan84@yahoo.com to arrange.

Thank you.

Regards

Jennie Chan

Legal Secretary to Ms Vivienne Sandhu

I
Advocates & Solicitors | Commissioners for Oaths | Notaries Public | Mediators
1 Coleman Street | #08-04 The Adelphi | Singapore 179803
Tel: (65) 6223 4456 | Fax: (65) 6223 1151 | Email : JennieChan@cliffordlaw.sg | Website: www.cliffordlaw.sg

Disclaimer: This message is privileged and confidential and is intended solely for the named recipient. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is strictly prohibited. If this e-mail has reached you in error, please delete the e-mail immediately and inform us of the error by sending an e-mail to JennieChan@cliffordlaw.sg. Thank you.

From: Hor, Yinrul [mailto:Yinrul.Hor@aig.com]
Sent: Tuesday, 4 June, 2019 8:48 AM
To: Sylvia Chia; Joe Suppiah; Jennie Chan
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKB1508E AND SGT1089A ON 25/02/2019

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้
เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부
파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-06-11 08:48 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual named. Please notify the sender if you have received this email in error or simply delete it.

Secure Mail using Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul.Hor@aig.com
To: SylviaChia@cliffordlaw.sg, JoeSuppiah@cliffordlaw.sg, JennieChan@cliffordlaw.sg
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baljit.Kaur@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Divyashni.Subramaniam@aig.com, Wahxin.Tong@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKB1508E AND SGT1089A ON 25/02/2019
Date: Tue, 4 Jun 2019 00:47:39 +0000
Without Prejudice

Your Reference : VS.JY.JG.6853.19.jc
Our Reference : 7616098617SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Mareus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Muhammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yinrul Hor (Viviane)

AIG

Claims Adjuster II, Singapore FNOL, Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.sg

CLIFFORD Law

DATE 3 June 2019
OUR REF VS.JY.JG.6853.19.jc
YOUR REF -

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
(Insurers Concerned)
78 Shenton Way #07-16
Singapore 079120


URGENT
BY FAX 6835 7416 ONLY

Dear Sirs

YOUR INSURED: SKB 1508E
ROAD TRAFFIC ACCIDENT ON 25 FEBRUARY 2019 INVOLVING SGT 1089A AND SKB 1508E - CLAIM FOR COMPENSATION

1. We act for Ragu S/O Jeeva Naidu in his claim for personal injuries, property damage and consequential loss and expense as a result of the abovementioned road traffic accident against your insured driver of SKB 1508E.
2. We write to inform you that our client's motor car SGT 1089A is available for survey and inspection within the next 48 hours at:
 - (a) 2A Starlight Road, Singapore 217755
(in between 10am to 6pm on weekdays)
 - (b) Blk 425 Serangoon Avenue 1, Singapore 550425
(after 7pm on weekdays and all day on weekends)
3. Please note that under the new protocol, if you fail to do so, you automatically waive your right to contest the claim.
4. Please also let us have the lump sum cost of repair.
5. In the circumstances, please liaise with our Ms Jennie at 6223 4456 or our client, Mr Ragu at raegan84@yahoo.com, failing which we will proceed accordingly.

Yours faithfully


Vivienne Sandhu / Chow Jia Ying
Partner / Associate
Clifford Law LLP

cc client
Mr Ragu
By email: raegan84@yahoo.com

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1726Z
Vehicle Details	
Vehicle No.:	SGT1089A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	ACCORD 2.0 A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	K20A6044896
Chassis No.:	CL73204273
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$21,929.00
Original Registration Date:	30 Mar 2007
First Registration Date:	30 Mar 2007
Transfer Count:	4
Actual ARF Paid:	\$24,122.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Mar 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$25,174.00
COE Rebate Amount:	\$14,008.00
Total Rebate Amount:	\$14,008.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/02/2019 19:46
Date Of Accident	25/02/2019 12:55
Exact Location Of Accident	TRAFFIC LIGHT JUNCTION ALONG MACPHERSON RD JUST OP
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGT1089A
Insured/Policyholder	
Name Of Registered Owner	JEEVA NAIDU S/O SOMASUNDARAM
NRIC No	S1451726Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98528621
Alternative Phone No	OTHERS-98528621
Vehicle Particulars	
Manufacturer	HONDA
Model	ACCORD-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00011898
Cover Note Number	N.A
Driver	
Name of Driver	RAGU S/O JEEVA NAIDU
NRIC No	S8403358H
Date Of Birth	25/01/1984
Occupation	INDOOR
Date Of Driving Pass	29/08/2016
Driving Experience	2 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98528621
Fax Number	
Contact Number	
EMail Address	RAEGAN84@YAHOO.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was travelling along Machperson Road just opposite Esso station. The traffic was moderate. I was on the right lane changing onto second lane. After I managed to change lane, this vehicle SKB1508E wanted to overtake my vehicle but he saw roadworks on the first lane and he could not stop on time and hit my rear left side of my vehicle. Damages to my car were on the left rear portion. No injuries were involved but I felt pain on my back and stomach. I will consult a doctor later.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB1508E
Vehicle Make/Model/Colour	AUDI / A1 SB 1.4 TFSI S TRONIC (122BHP) PSR / WHITE
Details Of Properties	N.A
Vehicle Category	PRIVATE CAR
Name of Driver	VINCENT CHIA KHENG BOON
NRIC/Passport Number	S7340323E
Contact Number	90468240
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF INJURED PERSON 1

Name	RAGU S/O JEEVA NAIDU
Approximate Age	
Injuries Sustain	PAIN ON BACK AND STOMACH
Injured person in which vehicle?	SGT1089A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(X) (3)Check (✓)
(4)Not Consistent (NC)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	re ✓		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NC ✓		
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	re ✓		
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler	OK ✓		
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	OK ✓		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: 56T1089A

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	Buc ✓		
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield	re ✓		
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding	NC ✓		
1247	993955	Rear Windscreen Sealant	NC ✓		
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: _____

Assessor: _____

original copy

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Jun 2019 Edit Reg		04 Jun 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: JUNE TEY SU MIN , ID: S7318689G, Tel: +6590468240									
Main Claimant: JEEVA NAIDU S/O SOMASUNDARAM , ID: S1451726Z									
Vehicle Reg. No.: SGT1089A		Date of Loss: 25/02/2019 12:00 - :59 [142 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7616098617SG		Policy/Cover Note No.: 2100301745 (Comprehensive)							
Vehicle Reg. No. (Insured): SKB1508E		Policy No. (Claimant):							
		Excess:							
Repairer: - Not Applicable - (-)									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/06/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents


























***SGT1089A (7616098617SG)**
[SKB1508E]

TP

JEEVA NAIDU S/O SOMASUNDARAM

Feb 25 2019 12:00PM

[JUNE TEY SU MIN]

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	17/06/19 10:13	General View														Load JPG	<input checked="" type="checkbox"/>	
2	17/06/19 10:13	General View														Load JPG	<input checked="" type="checkbox"/>	
3	17/06/19 10:13	General View														Load JPG	<input checked="" type="checkbox"/>	
4	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
5	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
6	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
7	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
8	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
9	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
10	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
11	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
12	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
13	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
14	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
15	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
16	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
17	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
18	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
19	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
20	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
21	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
22	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
23	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
24	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	
25	17/06/19 10:14	General View														Load JPG	<input checked="" type="checkbox"/>	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19009884/GCD3E2

Date: 24/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100301745

Claimant Vehicle
No : SGT1089A

Insured Vehicle No : SKB1508E

Date of Loss: 25/02/2019

Nature of Claim: TP

Claim No: 7616098617SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGT1089A

Make & Model: HONDA ACCORD, 2.0 (A)

Engine No: K20A6044896

Reg. Date: 30/03/2007 (Man. Year: 2006)

Chassis No: CL73204273

Colour: White

Odometer: 193312 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17

Rear Tyre Size: 215/50 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/06/2019

Date Inspected: 06/06/2019

Inspected At:

2A STARLIGHT ROAD
SINGAPORE 217755

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Cut	0.00 F	*- F
4	1		*REAR BUMPER LOWER SPOILER	Cracked	0.00 F	*- F
5	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
6	1		*REAR LH FENDER	Buckled	0.00 F	*- F
7	1		*REAR LH FENDER INNER SHIELD	Deformed	0.00 F	*- F
8	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
9	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >