

ASS. REC. BY:

REF: CS31/SMD19009896 / GC d30 Special Instruction:

SURVEYOR: GIB

ASSIGNMENT (Office)

From (Person): Thelma Choo

of SMD

Date/Time: 4.6.19 15.49 P.M

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKV 8282 D

Insured: GBC 8180X

at Workshop m/s KUO Li Auto

Tel: 96943328

of Blk 5035 Amc Ind Park 2 #01-363

Policy No: D19MTHCVE000181

Claim No: CMTD 1902675

Sum Insured:

Excess:

Make of Veh:

D.O.A. 02/06/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4.6.18 4:00 P.M

Person Contacted: Alvin

Vehicle- IN / OUT

Date/Time

Action/Instruction (X) Estimate

SKV 8282D - CS31/ALG 17020919 / Tina SQZ

ROA - 31/10/2017

GBC 8180X - X

Dismantle: 11/6/2019.

After repair: 14/6/2019

ASSIGNMENT

From: _____ Date: 10-6-2019
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKV 8282D
 at Workshop m/s Kuo Li Auto
 of Blk 50315 Amk Ind Park 2, #01-363
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS mp'
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKV 8282D Yr Regn: 28 sep 2015
 Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or 1.2
 Make: Nissan Dashgari c.c. 1197
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 58453 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: SJNFEAJ11U1447764
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Insider / Jammed / Leaked / Burnt or
 Brake: Insider / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / R/Rim or
 Tyre Size: F: 245/55 R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 10-06-19
 Survey held at W/S
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$3000 - \$4000</u>
	<u>12/3/2019</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 4
 Resurvey No. of Trip: 2

1) _____
 Date/Time, File Return to?
 2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	<u>100</u>
Transportation:	<u>60</u>
S + RS, SI	<u>60</u>
Photos	
Others	<u>11</u>
TOTAL	<u>231</u>

Report Format : PRE
 Lump Sum / I.B.I: (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jun 2019		04 Jun 2019 15:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H								
Main Claimant:	KHOO IVAN, ID: S8233245F								
Vehicle Reg. No.:	SKV8282D	Date of Loss:	02/06/2019 18:00 - :59						
Claim Type:	TP / CMTD1902675	Policy/Cover Note No.:	D19MTHCVE000181 (Third Party Only)						
Vehicle Reg. No. (Insured):	GBC8180X	Policy No. (Claimant):							
		Excess:							
Repairer:	Kuo Li Auto Workshop (HQ) Blk 5035 Ang Mo Kio Ind Park 2, #01-363, 569538 Ang Mo Kio - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/06/2019]								
Driver/Custodian (Insured):	LIU YOUCHAO (), NRIC: G8772699T, Tel: +6587424324 Email:								
Adj Asg. Remarks:	WS: 9694 3328 - Alvin								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3245F
Vehicle Details	
Vehicle No.:	SKV8282D
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	HRA2168731A
Chassis No.:	SJNFEAJ11U1447764
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$19,084.00
Original Registration Date:	28 Sep 2015
First Registration Date:	28 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$14,084.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2025
PARF Rebate Amount:	\$10,563.00
Intended COE Rebate Details	
COE Expiry Date:	27 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,498.00
COE Rebate Amount:	\$36,207.00
Total Rebate Amount:	\$46,770.00

The information contained herein is correct as at 10 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	03/06/2019 15:28
Date Of Accident	02/06/2019 18:45
Exact Location Of Accident	UBI ROAD 1
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKV8282D
Insured/Policyholder	
Name Of Registered Owner	KHOO IVAN
NRIC No	S8233245F
Email Address	IVANKHOO82@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-88220000
Alternative Phone No	OTHERS-88220000
Vehicle Particulars	
Manufacturer	NISSAN
Model	QASHQAI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100430977
Cover Note Number	
Driver	
Name of Driver	KHOO IVAN
NRIC No	S8233245F
Date Of Birth	01/10/1982
Occupation	OUTDOOR
Date Of Driving Pass	28/01/2004
Driving Experience	15 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88220000
Fax Number	
Contact Number	OTHERS-88220000
EMail Address	IVANKHOO82@YAHOO.COM.SG

Address	101 JALAN MULIA
Postcode	368688
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : KELLY LAM KHAN FHONG GENDER: : FEMALE
Passenger 2	NAME: : JAYDEN KHOO KAI JIE GENDER: : MALE
Passenger 3	NAME: : KAYVEN KHOO KAI CONG GENDER: : MALE
Passenger 4	NAME: : JANELLE KHOO ZI YAO GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	KAMPONG UBI NPP
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN / POLICE REPORT NO: T/20190603/2087

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC8180X
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIU YOU CHAO
NRIC/Passport Number	G8772699T
Contact Number	91747987
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 3/6/19
1524

Driver's Signature


(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: Jenny Lim
NRIC/FIN No.: S6927273H

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date of Report - 03 Jun 2019
Date of Incident = 02 JUN 2019 Time of Incident = 6:45pm (1845hrs)
Location of Incident = Paya Ubi Industrial Park 51 ubi Ave1(S) 408933
On the above mentioned date, place and time while I was waiting for my turn to enter the gantry into Paya Ubi Industrial Park, there was a white van (Vehicle Registration number: GBC8180X) in front of my vehicle about half car length apart about to enter into the parking gantry as well. My car is stationary ^{while} in view waiting for the vehicle in front to enter.
Out of a sudden, the white van (GBC8180X) started to reverse. I sounded my horn to warn the driver that my vehicle is behind him. However, the driver did not stop reversing and hit onto the front bumper of my vehicle.
We the alighted and exchange our particulars, however the other party is a male Chinese national provided me with a China Driving License (Name = Liu You chao), fin no. = G8772699T. I have ^{was} provided with his supervisor's contact no. 87424324 (Name: Mohamed Yunus).
The accident caused my vehicle's bumper to be dented and the other party's rear bumper to be slightly dislodged. The Driver is working under MGM Foods Pte Ltd
* I want to state that my car in-camera was not working at the incident. However the building's security informed that there is a working CCTV, facing the gantry. We are requesting for the retrieval of the footage.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 3/6/19
 1524

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: Jenny Lim
 NRIC/FIN No.: S6927273H



**SINGAPORE
POLICE FORCE**



T/20190603/2087

1 of 4

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20190603/2087

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/06/2019 13:39	Vide Report No.:	Station Diary No.: 17
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: KHOO IVAN		Address: 101 JALAN MULIA SINGAPORE 368688	
ID Type / ID No.: NRIC NO / S8233245F		Contact No.: Home/Office: Mobile: 88220000	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 36	Date of Birth: 01/10/1982	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: TECHNICIAN		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 02/06/2019 18:45	Type of Location: Straight Road
Location: UBI ROAD 1 51 Ubi Avenue 1				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
GBC8180X	Van				Slightly Damaged	0
SKV8282D	Car	NISSAN	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR	White	Slightly Damaged	4

Details of Vehicle Insurance				
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date



**SINGAPORE
POLICE FORCE**



T/20190603/2087

2 of 4

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20190603/2087

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SKV8282D	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100430977-03	28/09/2018	27/09/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Name	Liu You Chao	ID No.	G8772699T	
Related Vehicle	GBC8180X (Van)	Contact No.	91747987	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Driver				
Name	KHOO IVAN	ID No.	S8233245F	
Related Vehicle	SKV8282D (Car)	Contact No.	88220000	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight	

Brief Details.

On the above mentioned date, place and time while I was waiting for my turn to enter the gantry to Paya Ubi Industrial Park, there was a White Van (Vehicle Registration Number: GBC8180X) in front of my vehicle about half car length apart about to enter the parking gantry.

Out of a sudden the white van started to reverse. I tried sounding my horn to warn the driver that my vehicle is behind him however, the driver did not stop reversing and hit onto the front bumper of my vehicle.

We then alighted our vehicles and tried to exchange our particulars, however the other party whom is a male Chinese national provided me with a China Driving License (Name: Liu You Chao, FIN Number: G8772699T Contact Number: 91747987). I was also provided with the driver supervisor's name and contact number (Name: Mohamed Yunus, Contact: Number: 87424324). The accident caused my vehicle's bumper to be dented and the other party's rear bumper to be slightly dislodged.



**SINGAPORE
POLICE FORCE**



T/20190603/2087

3 of 4

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20190603/2087

CONTINUATION OF REPORT

I called up the supervisor whom informed that the van driver is working under MGM Foods Pte Ltd.

I want to state that my in car camera was not working at the time of the incident, however the building's security informed that there is a working CCTV which is facing the parking gantry.



**SINGAPORE
POLICE FORCE**



T/20190603/2087

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

4 of 4

Report No. T/20190603/2087

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Sgt 1 CHUN KHANG YEE 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 03/06/2019 13:39
Officer In Charge Of Case: TP / GIA / 	Classification Of Case:


Staff Sgt WONG SIEU LUI
 SINGAPORE
 CONTACT NO: 65476151
 Authentication Stamp
 NP168

 SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jun 2019		04 Jun 2019 15:49 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ETHOZ GROUP LTD , Co. Reg. No.: 198104531H								
Main Claimant:	KHOO IVAN , ID: S8233245F								
Vehicle Reg. No.:	SKV8282D	Date of Loss:	02/06/2019 18:00 - :59 [44 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1902675	Policy/Cover Note No.:	D19MTHCVE000181 (Third Party Only)						
Vehicle Reg. No. (Insured):	GBC8180X	Policy No. (Claimant):							
		Excess:							
Repairer:	Kuo Li Auto Workshop (HQ) Blk 5035 Ang Mo Kio Ind Park 2, #01-363, 569538 Ang Mo Kio - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/06/2019]								
Driver/Custodian (Insured):	LIU YOUCHAO (), NRIC: G8772699T, Tel: +6587424324 Email:								
Adj Asg. Remarks:	WS: 9694 3328 - Alvin								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKV8282D (CMTD1902675)
 [GBC8180X]
 TP
 KHOO IVAN
 Jun 2 2019 6:00PM
 [ETHOZ GROUP LTD]
 Kuo Li Auto Workshop

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="checkbox"/>	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	04/06/19 15:44	Accident Statement From: SC - Reg. No: GBC8180X, Claimant: ETHOZ GROUP LTD	1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	17/06/19 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	17/06/19 14:12	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
26	17/06/19 14:12	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
27	17/06/19 14:12	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
28	17/06/19 14:12	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
29	17/06/19 14:12	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
30	17/06/19 14:12	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
31	17/06/19 14:12	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
32	17/06/19 14:12	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
33	17/06/19 14:12	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
34	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
35	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
36	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	17/06/19 14:12	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	17/06/19 14:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
52	17/06/19 14:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
53	17/06/19 14:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
54	17/06/19 14:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
55	17/06/19 14:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
56	17/06/19 14:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
57	17/06/19 14:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
58	17/06/19 14:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
59	17/06/19 14:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
60	17/06/19 14:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
61	17/06/19 14:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
62	17/06/19 14:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
63	17/06/19 14:14	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	04/06/19 13:18	Third Party E-filed GIA report(M)	Load PDF	
2	04/06/19 15:43	Pre-Repair Survey - ASSIGN LKK	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/SMO19009896/GCD3E2**Date:** 21/06/2019REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTHCVE000181		
Claimant Vehicle No :	SKV8282D	Insured Vehicle No :	GBC8180X		
Date of Loss:	02/06/2019	Nature of Claim:	TP	Claim No:	CMTD1902675

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV8282D		Engine No:	HRA2168731A
Make & Model:	NISSAN QASHQAI, 1.2 (A)		Chassis No:	SJNFEAJ11U1447764
Reg. Date:	28/09/2015 (Man. Year: 2015)		Odometer:	58453 km
Colour:	White		Engine Capacity:	1197 cc
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	04/06/2019	
Date Inspected:	10/06/2019 Inspected At:	Kuo Li Auto Workshop (HQ) Blk 5035 Ang Mo Kio Ind Park 2, #01-363 Singapore 569538
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2019)
Parts: M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV8282D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >