



SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	S9M01P90
Reference	CS/ASM19009901/Ktd3e2 
Loss Date	30 May 2019
Report Date	31 May 2019 9:44:40 AM
Request Date	4 June 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated survey and authorize

Actions

Next Step

Wait for: Approve invoice

[Add Invoice](#)

Vehicle Information

Incident Vehicle SLX5250T
Registration #

Make HONDA

Model VEZEL 1.5

Service Address

160 Sin Ming Drive, #, , , 575722

Primary Contact/Insured

ZHOU CHONG
476 SIGLAP ROAD, #04-56, 454946, Singapore

EVECHONG_23@HOTMAIL.COM

Claim Handler

WANG Peter

Additional Instructions

Wkshop: K Kim Hin OD Excess: \$500 Pls proceed to authorize if dmg is consistent

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Add

REFERENCE #	DESCRIPTION	TOTAL AMOUNT	SUBMITTED	STATUS	PAID DATE	WITHDRAW
AC2004120	Final Invoice	\$160.50	27/5/20 5:53 PM	Waiting for Approval		<div></div>

Totals

Outstanding Invoices	\$160.50		Rejected and Withdrawn	\$0.00
Payments Made	\$0.00			
Total	\$160.50			