

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details		Workshop Details	
Involving	1 2016 HONDA VEZEL 1.5 (SLX5250T)	Total Rebate Amount	42190
Date of Loss	30 May 2019	Nett Loss Amount	\$39,810.00
Time of Loss	11.10	Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Loss Description	SLX5250T (INSD) C/W REAR OF SJJ4088A (TP)	Days of work completion	20
Comment			

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#	SLX5250T	Purchase Date	<div>dd/mm/yyyy</div> <div>📅</div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>29/03/2018</div> <div>📅</div>
Mileage	<div>19447</div>	Age of Vehicle	1

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2016	<div>2016</div>
Make	HONDA	<div>HONDA</div>
Model	VEZEL 1.5	<div>VEZEL 1.5X CVT ABS D/AIR</div>
		<div></div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name		<div></div>
Date of Birth		<div>dd/mm/yyyy</div> <div>📅</div>
Age		

Type	POLICY	ASSESSMENT INFORMATION
CATEGORY	INFORMATION	
Type of Paint		
Chassis No	RU11206539	RU11206539
Engine No	L15B4406539	L15B4406539
Engine Capacity		1496
Sum Insured	0	0
Market Value	0	82000

CATEGORY	FNOL
Information	INFORMATION
Education Qualification	
Driving Experience	
Driver License #	
License Type	
License Issue Date	dd/mm/yyyy
License Expiration Date	dd/mm/yyyy
Address	
Address type	

Gender CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
<hr/>		
<hr/>		
Marital status		
<hr/>		
Identification #		
<hr/>		



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

10/06/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

500

Young/Inexperienced/Un  
named Driver Excess

0

Other Excess

### Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



### Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

215/60R16

Front left side

DUNLOP7mm

Front right side

DUNLOP7mm

Rear Tyre Size

215/60R16

Rear left side

DUNLOP7mm

Rear right side

DUNLOP7mm

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add





















Approve

















Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		FRONT LOWER BUMPER	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		FRONT BUMPER (WCP) (10%)	Bent	0	374	No					374	Reviewing	
<input type="checkbox"/>		0	1		FRT TOWING EYE COVER (WCP) (10%)	Dented	0	16.5	No					16.5	Reviewing	
<input type="checkbox"/>		0	1		L/F UPP BUMPER BRKT	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		R/F UPP BUMPER BRKT (WCP) (10%)	Damaged	0	13.2	No					13.2	Reviewing	



	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		FRT BUMPER SUPPORT (WCP) (10%)	Cracked	0	209	No					209	Reviewing	
<input type="checkbox"/>		0	1		R/BUMPER CORNER BRKT (WCP) (10%)	Damaged	0	33	No					33	Reviewing	
<input type="checkbox"/>		0	1		R/F MOULDING	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		FRT BUMPER CLAMP KIT (WCP) (10%)	Necessary	0	16.5	No					16.5	Reviewing	
<input type="checkbox"/>		0	1		LOWER FRONT GRILLE	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		GRILLE (WCP) (10%)	Cracked	0	220	No					220	Reviewing	
<input type="checkbox"/>		0	1		UP/CVR RADIAT GRILLE	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		RAD GRILLE BRACKET	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		L/RAD-GRILLE BRACKET	Repair	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		R/RAD-GRILLE BRACKET	Repair	0	0	No					0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		0	1		RAD GRILLE COVER (WCP) (10%)	Dented	0	176	No					176	Reviewing	
<input type="checkbox"/>		0	1		L/GRILLE TRIM	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		R/GRILLE TRIM	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		R/F HEADLAMP CPL (WCP) (10%)	Cracked	0	891	No					891	Reviewing	
<input type="checkbox"/>		0	1		R/F FOG LAMP	Serviceable	0	0	No					0	Deny	
<input type="checkbox"/>		0	1		R/FOG LAMP COVER (WCP) (10%)	Dented	0	22	No					22	Reviewing	
<input type="checkbox"/>		0	1		FRT BUMPER AIR GUIDE (WCP) (10%)	Cracked	0	33	No					33	Reviewing	
<input type="checkbox"/>		0	1		FRT GRILLE CLIPS (WCP) (10%)	Necessary	0	16.5	No					16.5	Reviewing	



Labour



Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>		0		121.0 WU X 45.00 SGD/H	0	198	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>		0		LABOUR COST 129.0 WU X 45.00 SGD/H	0	580.5	0	0	Reviewing		
<input type="checkbox"/>		0		MATERIAL COST	0	244.53	0	0	Reviewing		

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous







Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 3 DAYS	Reviewing		0		
<input type="checkbox"/>		0	AIR CON GAS	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	FRT NUMBER PLATE	Deny		0	SERVICEABLE	

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$2,543.73

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$2,020.70
Labour	\$0.00	\$1,023.03
Excess		-\$500.00

Submit for Review