

**K.Kim Hin Auto Pte Ltd**  
**160 Sin Ming Drive, #02-20, Sin**  
**Ming AutoCity**  
**575722**

**Claim Reference:**

**Assessment number: 190289**

**Version: 1810**

**Date calculated: 03/06/2019 7:55 PM**

**Full Report**

**Registration: SLX5250T**

**Printed: 03/06/2019 7:55 PM**

40D AXA  
\* Not in  
\* SER.

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	SANDRA KHONG	Currency:	SGD
Claim Reference:		Date of Incident:	30/05/19
Estimated Repair Time:	5	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

**Vehicle**

Manufacturer:	HONDA
Model:	VEZEL/HR-V RU1/5
Sub Model:	BASE MODEL
Model Sheet Number:	35 VE 01
Registration:	SLX5250T
VIN number:	
Odometer:	

**Model Specs**

FOG LAMPS	SIDE FLASHER	LED HEADLAMP	AUTO HEADLAMP LEVEL
ULTRASONIC PARK SYS	1496CCM 97KW	PREPARE OFF VEHICLE	PAINTED MOULDINGS
TWO COAT PEARL/MICA			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not done  
Return Blupaint  
Ex 8500k  
3 days