

NATIONAL Assessment Centre Services

(Form 1, January 2018)

NA1904193

Date In: 08/06/2019 16:42	Job description	Date & Time Completed	Done by
Ref No: N89/INC/19009905/V	SAS e-filing		
Veh No: SP2216 D	E-mail (within 2hrs, MFC 2hrs)		
DOA: 08/06/2019 21:30	i-Motor Claim Form	mi/1047623 - 001	08/06/2019 17:05
☒ TP / Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
	Assessment/Survey Report		
TP Insurer:	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel: (	Fax: (
TP Particulars:	Veh No: /	INC () / Non-INC ()
Owner / Driver: (	Tel: (	
Policy No: (	Period: (	Cover Type: (
Confirmed by: (	Date: (	Time: (
Insured/Driver Liability: (%)	[Note-Est. Status (WO): N: 0-20%; P: 21-79%; F: 80-100%]	
Year of Registration: (	Warranty: YES () / NO ()	
Excess: (\$	Loading: \$1,000 () / \$2,000 ()	

General Remarks:
() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.
() Total Loss Case: to e-mail Insurer URGENTLY.
Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

Remarks: (INC hotline: 6788 6616)	Date & Time Completed:	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: ()

Date/Time	Actions

NA1904193	Invoice Preparation Checklist	Am't (\$) In Bill	Am't (\$) Add Bill
Claimant's Particulars:	1) AR: Accident Reporting (\$30)		
Driver/Owner:	2) DA: Damage Assessment (\$100) INC (\$40)		
Contact No:	3) TP: Towing Fee \$40/\$45		
Damaged Portion:	4) FT: Follow-Through Survey \$120		
QC Checked by (Engr-In-Charge):	5) FT: Follow-Through Survey (Resurvey) \$30		
Auditors' Comments:	For claims against INC Only (wef 10 Jan 2019)		
Cal 1:	6) TR: Re-inspection \$75		
Cal 2/3:	7) N1: Idm DA + SMRT Survey \$160		
P. 1/1	8) NTUC Additional Services:		
	9) N12: Idm Mobile \$0		
	*N3: Courtesy Car / Tpt Allowance \$5		
	*N6: Repair Co-ordination \$10		
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
	TP (N11): TP (N1a INC) against INC \$20		
	Pen Charged		
	Fine Charged		

07-MAY-2019 16:39

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2019 16:42
Date Of Accident	03/06/2019 21:30 ✓
Exact Location Of Accident	AT 24 JALAN ARNAP SINGAPORE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU2276D ✓
Insured/Policyholder	
Name Of Registered Owner	TAN KHOON LENG ✓
NRIC No	S0202549C
Email Address	ETAN16@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98591612
Alternative Phone No	OTHERS-98591612

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5042572775-05 ✓
Cover Note Number	

Driver

Name of Driver	TAN ENG CHUAN ✓
NRIC No	S2706924Z ✓
Date Of Birth	05/01/1947
Occupation	INDOOR
Date Of Driving Pass	19/10/1984
Driving Experience	34 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98591612
Fax Number	
Contact Number	OTHERS-98591612
EEmail Address	ETAN16@GMAIL.COM

Address	25 JALAN ARNAP
Postcode	249331
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WIFE
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When reversing into parking lot hit table which was not visible from rear view mirror.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Claim Handling

Accident MT/1047623

Policy No.	SD4237275-08	Vehicle No.	SDU2276D	GST Registration No.	
Certificate No.					
Policyholder Name	TAN KHOON LENG			Policyholder NRIC	91201549C
Product Code	PRIVATE CAR INSURANCE	Cover Type	Drive CLASSIC	Loading	0
Contact No.(Mobile)	90391612	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KPI	Yes	TCA	No	eCode Reason	
NCD Protection	Yes	NCD Entitlement(%)	50	Private Hire	No
Accident Details					
Report Date	04/06/2019 17:02	Accident Report Within 24 hrs	Yes	Accident Type	Collision into Property
Date of Accident	03/06/2019	Time of Accident (hh:mm)	21:30	Country of Accident	Singapore
Reporting Centre		Orange Force		ICH No.	
Accident Location	AT 24 SALAN ARABAI SINGAPORE				
Excess					
Own damage Excess	0.00	Additional Excess	0	Windscreen Excess	100.00
Uninsured Driver Excess	0.00	Outside Singapore OD Excess	0.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		
Benefits					
Coverage		Sum Insured	9999999.99		
Excess Waiver			9999999.99		
Transport Allowance			9999999.99		
GST Registered Information					
GST Registered	No	GST Registration Date		GST Status Verified	Yes
GST Registration No.					
Modification History					
Policyholder Mailing Address					
Address 1	25 JALAN ARABAI	Address 2	KIM LIN PARK	Address 3	SINGAPORE 249331
Address 4		Address Type	Singapore address	Post Code	146331
Unit No.		Related Policy Number	SD4237275-08		
OT Driver Info					
Driver Name	TAN ENG CHUAN	Driver Type	Named Driver	Driver DOB	05/06/1947
Uninsured driver Name		Driver NRIC	S27069142	Driving Experience	12
Register Date of Driver License	01/01/2007	Driver Age	72	Contact No.(Home)	
Contact No.(Mobile)	90391612	Contact No.(Office)		Contact No.(Home)	
Address 1		Address 2		Address 3	
Address 4		Address Type	Foreign address	Post Code	
Unit No.					
Does he own a Singapore Registered car?	Yes - No	Driver Vehicle No.	SDU2276D	Driver Insurer Company	NTUC
Declaration					
Breathalyzer or Blood Test Reading?	0 mg	Any injury?	Yes - No		
Modification History					

Claim 001

New

Claim Type *	OO-MD	Insured Name	TAN KHOON LENG	Insured NRIC	91201549C
Contact No.(Mobile)	97717851	Contact No.	87321138	Contact No.(Office)	
Email Address	maykhen@yahoo.com.sg	OT Vehicle Number	SDU2276D	TP	
Claim Description	SDU2276D - On 3 Jun 2019			Name of Preferred Workshop	
Preferred Workshop		Insured Liability	Fully at Fault	GIA Report	Received
Select no. Finalization	Yes	Breakdown Repair Option	Income to assign workshop		
Date Registered	04/06/2019 17:04	Claim Close Date		Date Received	04/06/2019 00:00
Report Taken By	ECOLI WANAS				
Print & E-mail					
Save Submit					

Attachment

Accident No.	MT/1047623	Claim No.	001
Last Doc. Received	Yes No	Upload Date	04/06/2019 17:05
Form *			
Choose File	No file chosen	Clear	Please Select *
Choose File	No file chosen	Clear	Please Select *
Choose File	No file chosen	Clear	Please Select *
Choose File	No file chosen	Clear	Please Select *
Choose File	No file chosen	Clear	Please Select *
Choose File	No file chosen	Clear	Please Select *
Choose File	No file chosen	Clear	Please Select *
Message Board		Send Message	
Attachment List			
Attachment	Uploaded By/Date	Category	Urgency
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05		NRIC/ Driving License	Normal
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05		SAS	Normal
Description		Msg Sent? (CO)	
NRIC/ Driving License 2019-6-4			
SAS 2019-6-4			



NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4
NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 04 Jun 2019 17:05	Photos	Normal	Photos 2019-6-4

Video List

Uploaded By/Date	Folder Date	File Name	Source	Action
------------------	-------------	-----------	--------	--------

[Displays in New Window](#)
[Scan and uploading](#)

ASSIGNMENT (IDAC)By CSO- Nature of Accident:

1) Vehicle hit Vehicle:

a) Motorcar ()

b) M/cycle ()

c) Bicycle ()

2) Vehicle hit ??

a) Pedestrian ()

b) Animal ()

3) Vehicle hit Road Side Objects:

a) Govt. Property ()
(Eg. signboard, barrier, tree etc)

b) Road Work Object ()

c) Private Property ()

4) Vehicle drop into drain ()

5) Damage due to Act of God:

a) Fallen Object ()

b) Flood ()

c) Other, _____

6) Parked & Found Damaged:

a) Vandalism ()

b) Hit by Moving Object ()

7) Theft Case

a) Stolen ()

b) Damage found ()
when recovered.

8) Fire

a) Whilst driving ()

b) Parked ()

9) Accident date more than 24hrs ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

1) Potential Total Loss ()

2) SRS Light on ()

3) ABS Light on ()

By Assessor- 1) Vehicle InformationVeh No: 834276DYr Regn: NOV 2009Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / MPV
/ Truck / Trailer orMake & Model: Toyota Camry 2.4 1820 2262Colour: Grey Transmission Type: Auto / ManualEng/No: 2A2E156445 Sp. Reading: 227202C/No: MPR0538K 4007037615Gen. Cond: Good / Fair / Poor / Burnt orSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60 R15R: 215/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WIPACFrontR/Bal. 6 mmL/Bal. 6 mmRearR/Bal. 6 mmL/Bal. 6 mmParallel Import: Yes / NoTowed-In: Yes No

Repair Type: LS / I.B.I

Towing Required: Yes No

No of Repair Days:

Vehicle in Idac: Yes NoD.O.I. 04/06/2019Time: 16:00By Assessor- 2) Comments

1) Damages not due to recent accident.

2) Damages do not seem hit onto:

a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()

e. Animal () f. Govt. Object () g. Road Work Object ()

h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()

3) Vehicle does not seem damaged as a result of:

a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()

e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started:

Time completed:

1) CSO

2) ASS

3) Entire Operation Completed Time:

Original Copy

75 Simon **MOTORCAR (Rear)**

101Broken 102Defunct 103Unroadworthy 104Unusable 105Unusable 106Unusable 107Unusable 108Unusable 109Unusable 110Broken 111Unusable 112Unusable 113Unusable 114Unusable 115Unusable 116Unusable 117Unusable 118Unusable 119Unusable 120Unusable 121Unusable 122Unusable 123Unusable 124Unusable 125Unusable 126Unusable 127Unusable 128Unusable 129Unusable 130Unusable 131Unusable 132Unusable 133Unusable 134Unusable 135Unusable 136Unusable 137Unusable 138Unusable 139Unusable 140Unusable 141Unusable 142Unusable 143Unusable 144Unusable 145Unusable 146Unusable 147Unusable 148Unusable 149Unusable 150Unusable 151Unusable 152Unusable 153Unusable 154Unusable 155Unusable 156Unusable 157Unusable 158Unusable 159Unusable 160Unusable 161Unusable 162Unusable 163Unusable 164Unusable 165Unusable 166Unusable 167Unusable 168Unusable 169Unusable 170Unusable 171Unusable 172Unusable 173Unusable 174Unusable 175Unusable 176Unusable 177Unusable 178Unusable 179Unusable 180Unusable 181Unusable 182Unusable 183Unusable 184Unusable 185Unusable 186Unusable 187Unusable 188Unusable 189Unusable 190Unusable 191Unusable 192Unusable 193Unusable 194Unusable 195Unusable 196Unusable 197Unusable 198Unusable 199Unusable 200Unusable 201Unusable 202Unusable 203Unusable 204Unusable 205Unusable 206Unusable 207Unusable 208Unusable 209Unusable 210Unusable 211Unusable 212Unusable 213Unusable 214Unusable 215Unusable 216Unusable 217Unusable 218Unusable 219Unusable 220Unusable 221Unusable 222Unusable 223Unusable 224Unusable 225Unusable 226Unusable 227Unusable 228Unusable 229Unusable 230Unusable 231Unusable 232Unusable 233Unusable 234Unusable 235Unusable 236Unusable 237Unusable 238Unusable 239Unusable 240Unusable 241Unusable 242Unusable 243Unusable 244Unusable 245Unusable 246Unusable 247Unusable 248Unusable 249Unusable 250Unusable 251Unusable 252Unusable 253Unusable 254Unusable 255Unusable 256Unusable 257Unusable 258Unusable 259Unusable 260Unusable 261Unusable 262Unusable 263Unusable 264Unusable 265Unusable 266Unusable 267Unusable 268Unusable 269Unusable 270Unusable 271Unusable 272Unusable 273Unusable 274Unusable 275Unusable 276Unusable 277Unusable 278Unusable 279Unusable 280Unusable 281Unusable 282Unusable 283Unusable 284Unusable 285Unusable 286Unusable 287Unusable 288Unusable 289Unusable 290Unusable 291Unusable 292Unusable 293Unusable 294Unusable 295Unusable 296Unusable 297Unusable 298Unusable 299Unusable 300Unusable 301Unusable 302Unusable 303Unusable 304Unusable 305Unusable 306Unusable 307Unusable 308Unusable 309Unusable 310Unusable 311Unusable 312Unusable 313Unusable 314Unusable 315Unusable 316Unusable 317Unusable 318Unusable 319Unusable 320Unusable 321Unusable 322Unusable 323Unusable 324Unusable 325Unusable 326Unusable 327Unusable 328Unusable 329Unusable 330Unusable 331Unusable 332Unusable 333Unusable 334Unusable 335Unusable 336Unusable 337Unusable 338Unusable 339Unusable 340Unusable 341Unusable 342Unusable 343Unusable 344Unusable 345Unusable 346Unusable 347Unusable 348Unusable 349Unusable 350Unusable 351Unusable 352Unusable 353Unusable 354Unusable 355Unusable 356Unusable 357Unusable 358Unusable 359Unusable 360Unusable 361Unusable 362Unusable 363Unusable 364Unusable 365Unusable 366Unusable 367Unusable 368Unusable 369Unusable 370Unusable 371Unusable 372Unusable 373Unusable 374Unusable 375Unusable 376Unusable 377Unusable 378Unusable 379Unusable 380Unusable 381Unusable 382Unusable 383Unusable 384Unusable 385Unusable 386Unusable 387Unusable 388Unusable 389Unusable 390Unusable 391Unusable 392Unusable 393Unusable 394Unusable 395Unusable 396Unusable 397Unusable 398Unusable 399Unusable 400Unusable 401Unusable 402Unusable 403Unusable 404Unusable 405Unusable 406Unusable 407Unusable 408Unusable 409Unusable 410Unusable 411Unusable 412Unusable 413Unusable 414Unusable 415Unusable 416Unusable 417Unusable 418Unusable 419Unusable 420Unusable 421Unusable 422Unusable 423Unusable 424Unusable 425Unusable 426Unusable 427Unusable 428Unusable 429Unusable 430Unusable 431Unusable 432Unusable 433Unusable 434Unusable 435Unusable 436Unusable 437Unusable 438Unusable 439Unusable 440Unusable 441Unusable 442Unusable 443Unusable 444Unusable 445Unusable 446Unusable 447Unusable 448Unusable 449Unusable 450Unusable 451Unusable 452Unusable 453Unusable 454Unusable 455Unusable 456Unusable 457Unusable 458Unusable 459Unusable 460Unusable 461Unusable 462Unusable 463Unusable 464Unusable 465Unusable 466Unusable 467Unusable 468Unusable 469Unusable 470Unusable 471Unusable 472Unusable 473Unusable 474Unusable 475Unusable 476Unusable 477Unusable 478Unusable 479Unusable 480Unusable 481Unusable 482Unusable 483Unusable 484Unusable 485Unusable 486Unusable 487Unusable 488Unusable 489Unusable 490Unusable 491Unusable 492Unusable 493Unusable 494Unusable 495Unusable 496Unusable 497Unusable 498Unusable 499Unusable 500Unusable 501Unusable 502Unusable 503Unusable 504Unusable 505Unusable 506Unusable 507Unusable 508Unusable 509Unusable 510Unusable 511Unusable 512Unusable 513Unusable 514Unusable 515Unusable 516Unusable 517Unusable 518Unusable 519Unusable 520Unusable 521Unusable 522Unusable 523Unusable 524Unusable 525Unusable 526Unusable 527Unusable 528Unusable 529Unusable 530Unusable 531Unusable 532Unusable 533Unusable 534Unusable 535Unusable 536Unusable 537Unusable 538Unusable 539Unusable 540Unusable 541Unusable 542Unusable 543Unusable 544Unusable 545Unusable 546Unusable 547Unusable 548Unusable 549Unusable 550Unusable 551Unusable 552Unusable 553Unusable 554Unusable 555Unusable 556Unusable 557Unusable 558Unusable 559Unusable 560Unusable 561Unusable 562Unusable 563Unusable 564Unusable 565Unusable 566Unusable 567Unusable 568Unusable 569Unusable 570Unusable 571Unusable 572Unusable 573Unusable 574Unusable 575Unusable 576Unusable 577Unusable 578Unusable 579Unusable 580Unusable 581Unusable 582Unusable 583Unusable 584Unusable 585Unusable 586Unusable 587Unusable 588Unusable 589Unusable 590Unusable 591Unusable 592Unusable 593Unusable 594Unusable 595Unusable 596Unusable 597Unusable 598Unusable 599Unusable 600Unusable 601Unusable 602Unusable 603Unusable 604Unusable 605Unusable 606Unusable 607Unusable 608Unusable 609Unusable 610Unusable 611Unusable 612Unusable 613Unusable 614Unusable 615Unusable 616Unusable 617Unusable 618Unusable 619Unusable 620Unusable 621Unusable 622Unusable 623Unusable 624Unusable 625Unusable 626Unusable 627Unusable 628Unusable 629Unusable 630Unusable 631Unusable 632Unusable 633Unusable 634Unusable 635Unusable 636Unusable 637Unusable 638Unusable 639Unusable 640Unusable 641Unusable 642Unusable 643Unusable 644Unusable 645Unusable 646Unusable 647Unusable 648Unusable 649Unusable 650Unusable 651Unusable 652Unusable 653Unusable 654Unusable 655Unusable 656Unusable 657Unusable 658Unusable 659Unusable 660Unusable 661Unusable 662Unusable 663Unusable 664Unusable 665Unusable 666Unusable 667Unusable 668Unusable 669Unusable 670Unusable 671Unusable 672Unusable 673Unusable 674Unusable 675Unusable 676Unusable 677Unusable 678Unusable 679Unusable 680Unusable 681Unusable 682Unusable 683Unusable 684Unusable 685Unusable 686Unusable 687Unusable 688Unusable 689Unusable 690Unusable 691Unusable 692Unusable 693Unusable 694Unusable 695Unusable 696Unusable 697Unusable 698Unusable 699Unusable 700Unusable 701Unusable 702Unusable 703Unusable 704Unusable 705Unusable 706Unusable 707Unusable 708Unusable 709Unusable 710Unusable 711Unusable 712Unusable 713Unusable 714Unusable 715Unusable 716Unusable 717Unusable 718Unusable 719Unusable 720Unusable 721Unusable 722Unusable 723Unusable 724Unusable 725Unusable 726Unusable 727Unusable 728Unusable 729Unusable 730Unusable 731Unusable 732Unusable 733Unusable 734Unusable 735Unusable 736Unusable 737Unusable 738Unusable 739Unusable 740Unusable 741Unusable 742Unusable 743Unusable 744Unusable 745Unusable 746Unusable 747Unusable 748Unusable 749Unusable 750Unusable 751Unusable 752Unusable 753Unusable 754Unusable 755Unusable 756Unusable 757Unusable 758Unusable 759Unusable 760Unusable 761Unusable 762Unusable 763Unusable 764Unusable 765Unusable 766Unusable 767Unusable 768Unusable 769Unusable 770Unusable 771Unusable 772Unusable 773Unusable 774Unusable 775Unusable 776Unusable 777Unusable 778Unusable 779Unusable 780Unusable 781Unusable 782Unusable 783Unusable 784Unusable 785Unusable 786Unusable 787Unusable 788Unusable 789Unusable 790Unusable 791Unusable 792Unusable 793Unusable 794Unusable 795Unusable 796Unusable 797Unusable 798Unusable 799Unusable 800Unusable 801Unusable 802Unusable 803Unusable 804Unusable 805Unusable 806Unusable 807Unusable 808Unusable 809Unusable 810Unusable 811Unusable 812Unusable 813Unusable 814Unusable 815Unusable 816Unusable 817Unusable 818Unusable 819Unusable 820Unusable 821Unusable 822Unusable 823Unusable 824Unusable 825Unusable 826Unusable 827Unusable 828Unusable 829Unusable 830Unusable 831Unusable 832Unusable 833Unusable 834Unusable 835Unusable 836Unusable 837Unusable 838Unusable 839Unusable 840Unusable 841Unusable 842Unusable 843Unusable 844Unusable 845Unusable 846Unusable 847Unusable 848Unusable 849Unusable 850Unusable 851Unusable 852Unusable 853Unusable 854Unusable 855Unusable 856Unusable 857Unusable 858Unusable 859Unusable 860Unusable 861Unusable 862Unusable 863Unusable 864Unusable 865Unusable 866Unusable 867Unusable 868Unusable 869Unusable 870Unusable 871Unusable 872Unusable 873Unusable 874Unusable 875Unusable 876Unusable 877Unusable 878Unusable 879Unusable 880Unusable 881Unusable 882Unusable 883Unusable 884Unusable 885Unusable 886Unusable 887Unusable 888Unusable 889Unusable 890Unusable 891Unusable 892Unusable 893Unusable 894Unusable 895Unusable 896Unusable 897Unusable 898Unusable 899Unusable 900Unusable 901Unusable 902Unusable 903Unusable 904Unusable 905Unusable 906Unusable 907Unusable 908Unusable 909Unusable 910Unusable 911Unusable 912Unusable 913Unusable 914Unusable 915Unusable 916Unusable 917Unusable 918Unusable 919Unusable 920Unusable 921Unusable 922Unusable 923Unusable 924Unusable 925Unusable 926Unusable 927Unusable 928Unusable 929Unusable 930Unusable 931Unusable 932Unusable 933Unusable 934Unusable 935Unusable 936Unusable 937Unusable 938Unusable 939Unusable 940Unusable 941Unusable 942Unusable 943Unusable 944Unusable 945Unusable 946Unusable 947Unusable 948Unusable 949Unusable 950Unusable 951Unusable 952Unusable 953Unusable 954Unusable 955Unusable 956Unusable 957Unusable 958Unusable 959Unusable 960Unusable 961Unusable 962Unusable 963Unusable 964Unusable 965Unusable 966Unusable 967Unusable 968Unusable 969Unusable 970Unusable 971Unusable 972Unusable 973Unusable 974Unusable 975Unusable 976Unusable 977Unusable 978Unusable 979Unusable 980Unusable 981Unusable 982Unusable 983Unusable 984Unusable 985Unusable 986Unusable 987Unusable 988Unusable 989Unusable 990Unusable 991Unusable 992Unusable 993Unusable 994Unusable 995Unusable 996Unusable 997Unusable 998Unusable 999Unusable 1000Unusable

Vehicle No:

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid INNER TRIM			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items:

Assessor:

Claim Handling

Task Transfer Exit

Accident MT/1047623

LOGS TAB SUB

Policy No.	5042572775-08	Vehicle No.	SJU2276D	GST Registration No.	
Certificate No.					
Policyholder Name	TAN KHOON LENG			Policyholder NRIC	S0202549C
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	98591612	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KPI	Yes No Yes	TCA	Yes No Yes	eCode Reason	
NCD Protection	Yes	NCD Entitlement(%)	50	Private Hire	No

Accident Details

Report Date	04/06/2019 17:02	Accident Report Within 24 hrs	Yes	Accident Type	Collided into Property
Date of Accident	03/06/2019	Time of Accident hh:mm	21:30	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	AT 24 JALAN AIRNAP SINGAPORE				

Excess

Own damage Excess	0.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	0.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

Coverage	Sum Insured
Excess Waiver	99999999.99
Transport Allowance	99999999.99

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	25 JALAN AIRNAP	Address 2	KIM LIN PARK	Address 3	SINGAPORE 249331
Address 4		Address Type	Singapore address	Post Code	249331
Unit No.		Related Policy Number	5042572775-08		

OT Driver Info

Driver Name	TAN ENG CHUAN	Driver Type	Named Driver		
Unnamed driver Name		Driver NRIC	S2706924Z	Driver DOB	05/01/1947
Register Date of Driver License	01/01/2007	Driver Age	72	Driving Experience	12
Contact No.(Mobile)	98591612	Contact No.(Office)		Contact No.(Home)	
Address 1		Address 2		Address 3	
Address 4		Address Type	Foreign address	Post Code	
Unit No.					
Does he own a Singapore Registered car?	Yes No	Driver Vehicle No.	SJU2276D	Driver Insurer Company	NTUC

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	Yes No
-------------------------------------	------	-------------	--------

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Ng Hak Joe

LOGS TAB SUB

Claim Type	OD-MD	Insured Name	TAN KHOON LENG	Insured NRIC	S0202549C
Contact No.(Mobile)	97717851	Contact No. (Home)	67321138	Contact No. (Office)	
Email Address	maykitan@yahoo.com.sg	OT Vehicle Number	SJU2276D	TP Vehicle Number	
Claim Description	SJU2276D / - ON 3 Jun 2019			Name of Preferred Workshop	
Preferred Workshop	Yes	Preferred Repair Option		Income to assign workshop	
Insured Fully at Replied					
Date Registered	04/06/2019 17:14	Claim Close Date		Date Received	04/06/2019 00:00
Report Taken By	R0SLI WAKAB	Workshop Repairer		Total Loss but Repaired	
				OD Excess Collected By Workshop	

Print AK letter

Modification History

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment

Attachment

Vehicle Info

Vehicle Make	TOYOTA	Vehicle Model	CAMRY	Engine Capacity	
Date of		Class No.			

Registration	24/11/2009	MR053BK4007037615
Towing Required *	☐ Yes * ☒ No	Vehicle in IDAC *
Type of Tender *	Own Damage	Assessor Name *
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTRE	IDAC/Workshop Location
Windscreen		Total Loss *
Parts & Labour Cost		Scrape Value(\$)
Market Value(\$)		Economical Repair Value(\$)
1)REAR END PANEL -REPLACE, 2)REAR END PANEL TOP GARNISH -REPLACE.		
Remark		

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
root						
Not Applicable	1	16000102	BUMPER (REAR)	1	Replace	X
ABS	2	16001303	BUMPER BRACKET (REAR LEFT)	1	Replace	X
ABSORBER	3	16001304	BUMPER BRACKET (REAR RIGHT)	1	Replace	X
ACCELERATOR	4	16002402	BUMPER CLIPS (REAR)	1	Replace	X
ACTUATOR	5	16005002	BUMPER REINFORCEMENT (REAR)	1	Replace	X
ADVERTISEMENT STICKER	6	16005103	BUMPER RETAINER (REAR LEFT)	1	Replace	X
AIR BAG	7	16005104	BUMPER RETAINER (REAR RIGHT)	1	Replace	X
AIR BLOWER	8	16004903	BUMPER REFLECTOR (REAR LEFT)	1	Unconfirm	X
AIR BOX	9	16004904	BUMPER REFLECTOR (REAR RIGHT)	1	Unconfirm	X
AIR CHAMBER BOX	10	160053	BUMPER REVERSE SENSOR	1	Replace	X
AIR CLEANER	11	42000101	TAIL LAMP (LEFT)	1	Replace	X
AIR COMPRESSOR	12	42000102	TAIL LAMP (RIGHT)	1	Unconfirm	X
AIR CON	13	420002	TAIL LAMP GARNISH	2	Unconfirm	X
AIR CON (VAN)	14	420007	TAIL LAMP PANEL	2	Unconfirm	X
AIR COOLER	15	150014	BOOT EMBLEM	1	Replace	X
AIR DISTRIBUTOR	16	150030	BOOT LAMP	2	Replace	X
AIR FILTER	17	150033	BOOT LID	1	Replace	X
AIR FLOW	18	15004802	BOOT LOCK (TDP)	1	Replace	X
AIR GRILLE	19	150043	BOOT LID RUBBER	1	Replace	X
AIR HORN	20	150026	BOOT INNER TRIM	1	Unconfirm	X
AIR INTAKE	21	390002	SPARE TYRE BOARD	1	Unconfirm	X
AIR RESONATOR BOX	22	390032	SPARE TYRE PANEL INSULATOR	1	Unconfirm	X
AIR THROTTLE BODY AND SENSOR	23	25400106	FENDER (REAR RIGHT)	1	Repair	X
ALARM						
ALTERNATOR						
ALUMINIUM PANEL - SIDE						
AMPLIFIER						
ANTENNA						
ANTI ROLL						
APRON						
ARCH						

Save Submit

ACCIDENT STATEMENT

ACCIDENT DATE: (03/06/2019) (DD/MM/YYYY), TIME: (21:30) (HH:MM)

LOCATION: 29 JALAN ARNAP, S'PORE

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SJU 2276D
 b) INSURANCE COMPANY: NTUC INCOME
 c) POLICY NUMBER: 5042572775-08
 d) POLICY TYPE: (COMPREHENSIVE) / THIRD PARTY / THIRD PARTY FIRE & THEFT
 e) MAKE & MODEL: TOYOTA CAMRY
 f) TYPE: (SALOON) / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS
 g) VEHICLE CATEGORY: (PRIVATE) / COMMERCIAL / MOTORCYCLE
 h) PURPOSE OF USING AT ACCIDENT TIME: PRIVATE
 i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
 IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: TAN KHOON ENG (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: S0202549C CONTACT: 98591612
 c) ADDRESS: 25 JALAN ARNAP
 SINGAPORE 249331

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: TAN ENG CHUAN (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: S24069242 CONTACT: 98591612
 c) ADDRESS: 25 JALAN ARNAP
 SINGAPORE 249331

* d) DATE OF BIRTH: (05/01/1984) (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) DATE OF DRIVING PASS: 19 OCT 1984

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
 IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: HUSBAND

5. a) WEATHER CONDITION: (CLEAR / RAINING) / OTHERS
 b) ROAD SURFACE: (DRY / WET) / OTHERS

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION:

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: MODEL:
 b) DRIVER'S NAME:
 c) NRIC/FIN/PASSPORT: CONTACT:

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: MODEL:
 e) DRIVER'S NAME:
 f) NRIC/FIN/PASSPORT: CONTACT:

email = etan16@gmail.com
 VIDEO

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2706924Z



Name

TAN ENG CHUAN

Race

CHINESE

Date of birth

05-01-1947

Sex

M

Country of birth

MALAYSIA

For LKK/NAC Use Only

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S2706924Z

Name

TAN ENG CHUAN

Birth Date 05 Jan 1947

Issue Date 06 Mar 2018



For LKK/NAC Use Only



8127028

NRIC No. S2706924Z



Nationality

MALAYSIAN

Date of issue

06-05-2011

Address

25 JALAN ARNAP
SINGAPORE 249331

For LKK/NAC Use Only

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B	Motorcycles <= 200 cc	19 Oct 1984
Class 3	Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg	19 Oct 1984

NP 428A



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5042572775-08

Cover : drive CLASSIC

1. Index mark and Registration Number of Vehicle : **SJU2276D**
Chassis Number : **MR053BK4007037615**
2. Name of Policyholder : **TAN KHOON LENG**
3. Effective Date of Insurance : **24 May 2018**
4. Expiry Date of Insurance : **23 Nov 2019**
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: YES (FREE)
TRANSPORT ALLOWANCE	: YES
EXCESS WAIVER	: YES
PRIMARY DRIVER	: TAN KHOON LENG
NAMED DRIVER (1)	: TAN SUE YEN
NAMED DRIVER (2)	: TAN ENG CHUAN
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : DIRECT SALES (00000607908)

Date of Issue : 22 May 2018 11:27 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive