

ASS. REC. BY:

REF: CS3/smok90099061 Ac d302

Special Instruction:

Surveyor: (no change)

ASSIGNMENT (Office)

From (Person): Huang shiang yi

of SMO

Date/Time: 4.6.19 16.16p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKB 2793 R

Insured: SLG 5338 P

at Workshop m/s Ak workshop

Tel: 93397880

of 10 Amk Industrial Park 2n #04-10

Policy No: DIBMTProto16302

Claim No: CMTD 707688

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 03.06.2019

6.6.2019 14p.m

CA / REV / REP. / REV 24 HRS

Date/Time: 4.6.19 4.20p.m

Person Contacted: Matthew

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (X)
	SKB 2793 R - X	
	SLG 5338 P - X	
	Dismantle: 7/6/2019	
	After repair: 14/6/2019.	

(08/11/13)

ASS. REC. BY:

REF SMO

0210A

ASSIGNMENT

From: _____ Date: 6.6.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKB 2793R

at Workshop m/s AK Workshop

of 10 Amst Industrial Park m #04-10

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: after 1.00 p.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$20k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKB2793R Yr Regn: 13 May 2011

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Cerato Forte c.c 1591

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading 1985365 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAFW41MB5379096

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD AirRim or

Tyre Size: F: 215/45R17

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

EAGLE

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$5000 - \$6000

7/6/2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 2

Report Format: PRE

Lump Sum / I.B.I.: (\$ _____)

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, \$ _____

Photos

Others

TOTAL

100

60

60

11

231

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2019		04 Jun 2019 16:16 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ZHANG SU XIA, ID: S2630729E		
Main Claimant:	LEONG HONG MUN, ID: S7420210A		
Vehicle Reg. No.:	SKB2793R	Date of Loss:	03/06/2019 00:00 - :59
Claim Type:	TP / CMTD1902688	Policy/Cover Note No.:	D18MTPV01016302 (Comprehensive)
Vehicle Reg. No. (Insured):	SLG5338P	Policy No. (Claimant):	
		Excess:	
Repairer:	AK WORKSHOP (HQ) 10 Ang Mo Kio Industrial Park 2A, #04-10 AMK Autopoint, 568047 Ang Mo Kio - Tel: 8383 5050 / 9339 7880 / 9321 0855		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/06/2019]		
Adj Asg. Remarks:	AK WORKSHOP 9339 7780		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0210A
Vehicle Details	
Vehicle No.:	SKB2793R
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE 1.6 SX 6AT ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	G4FCAH304821
Chassis No.:	KNAFW411MB5379096
Maximum Power Output:	91.1 kW (122 bhp)
Open Market Value:	\$13,156.00
Original Registration Date:	13 May 2011
First Registration Date:	13 May 2011
Transfer Count:	1
Actual ARF Paid:	\$13,156.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 May 2021
PARF Rebate Amount:	\$7,235.00
Intended COE Rebate Details	
COE Expiry Date:	12 May 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$44,790.00
COE Rebate Amount:	\$8,644.00
Total Rebate Amount:	\$15,879.00

The information contained herein is correct as at 07 Jun 2019

OK

► Kia Cerato Used Vehicle List (6 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Kia Cerato Forte 1.6A SX	\$21,188	\$8,630 /yr	26-Jan-2011	1,591 cc	147,933 km	Sincere Motoring	Availabl

(100% Quality Buy!) 1st Owner Unit. Pearl White In Colour. Vehicle Comes With 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assistance For Better Assurances. STA/VICOM/AA Evaluation Fr...

Office No. - 67476066

David - 98529920 | Edwin - 92331607

Kia Cerato Forte 1.6A SX	\$22,333	\$8,710 /yr	17-Mar-2011	1,591 cc	115,000 km	Juzt Carz Auto	Availabl
--------------------------	----------	-------------	-------------	----------	------------	----------------	----------

New Arrival! Beautiful Sporty White Among Its Class. Very Well Taken Care By Owner And Service Regularly Without Fail. Accident Free, No Repairs Needed. Stylish, Sporty, Comfort And Spacious To Fit Yo...

Office No. - 63383813

James Li - 88588866 | Joey Lim - 96229169 | Shawn Zheng - 97520620 | Phillip Koh - 82338484

Kia Cerato Forte 1.6M SX	\$20,800	\$7,730 /yr	23-May-2011	1,591 cc	125,000 km	Hou Auto	Availabl
--------------------------	----------	-------------	-------------	----------	------------	----------	----------

1 Owner! Real Man Drive Manual! SX Model. Low Depreciation. Easy Maintenance. Smooth Drive. High Trade In. Easy Loan. Enjoy The Fun C Driving! View Now!

Office No. - 94574576

Black - 94574576 | Andrew - 91054418

Kia Cerato Forte 1.6A SX	\$24,800	\$9,390 /yr	25-May-2011	1,591 cc	128,000 km	Speedo Motoring	Availabl
--------------------------	----------	-------------	-------------	----------	------------	-----------------	----------

In House Finance Available! New Arrived Kia Cerato Forte SX Model! Low Mileage Done 16,000km Yearly! Very Well Maintained And Regular Serviced By Previous Owner, High Paper Value And Low Depreciation ...

Office No. - 67637757

Alan Tan - 97540238 | Tan Kai Hong - 96456965 | Javier Eu - 91811291 | Luke Ang - 92974366

Kia Cerato Forte 1.6A SX	\$25,800	\$9,440 /yr	29-Jun-2011	1,591 cc	-	AA Trust Automotive	Availabl
--------------------------	----------	-------------	-------------	----------	---	---------------------	----------

01 Owner! AA Trust Certified Quality Pre-Owned Vehicle! Super Low Mileage Kia Cerato SX In The Market! Nice Bidded No. Plate. Low Maintenance And Fuel Efficient. This Is The Everyday Car Ideally For C...

Office No. - 63450381

Andra - 92221331 | Clement - 93365036 | Willey - 91692071 | Dave - 98500051

Kia Cerato Forte 1.6A SX	\$26,000	\$8,700 /yr	15-Sep-2011	1,591 cc	93,000 km	Juzt Carz Auto	Availabl
--------------------------	----------	-------------	-------------	----------	-----------	----------------	----------

New Arrival! Beautiful Sporty Silver Among Its Class. Very Well Taken Care By Owner And Service Regularly Without Fail. Accident Free, No Repairs Needed. Stylish, Sporty, Comfort And Spacious To Fit Y...

Office No. - 63383813

James Li - 88588866 | Joey Lim - 97898277 | Shawn Zheng - 97520620 | Phillip Koh - 82338484

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	04/06/2019 11:36
Date Of Accident	03/06/2019 15:55
Exact Location Of Accident	NANYANG DRIVE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKB2793R
Insured/Policyholder	
Name Of Registered Owner	LEONG HONG MUN
NRIC No	S7420210A
Email Address	ANTHONY.LEONG@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96881974
Alternative Phone No	OFFICE-67787738
Vehicle Particulars	
Manufacturer	KIA
Model	CERATO FORTE 1.6 SX 6AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	WORK (GOING BACK OFFICE)
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103750479
Cover Note Number	
Driver	
Name of Driver	LEONG HONG MUN
NRIC No	S7420210A
Date Of Birth	14/06/1974
Occupation	OUTDOOR
Date Of Driving Pass	03/03/2006
Driving Experience	13 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96881974
Fax Number	
Contact Number	OFFICE-67787738
EEmail Address	ANTHONY.LEONG@YAHOO.COM

Address	BLK 656C JURONG WEST STREET 61 #15-321
Postcode	643656
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ACCIDENT STATEMENT AS ATTACHED.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG5338P
Vehicle Make/Model/Colour	TOYOTA / ALTIS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ZHANG SU XIA
NRIC/Passport Number	S2630729E
Contact Number	98360113
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 3rd of June 2019 @ approximately 3:55pm, I was driving along Nanyang Drive (heading towards PIE). As I drive past Singapore Institute of Manufacturing Technology, a car (SGR 5338P) was driving out to the main road. It did not slow down or stop and collided to the side of my car. The collision is on the driver's door as well as the rear door. The driver Ms Zhang Su Xie (NRIC S263729E) admitted that she was at fault and accepted that I will make an insurance claim against her for the repair works.


DECLARATION

I/We declare the foregoing particulars are true in every respect.

 11/6/2019

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Jelle Tan
NRIC/ID No.: AMK AUTOPPOINT PTE LTD
06.06.2019

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 4/6/2019

Driver's Signature
(If driver is, not the policyholder)
Date & Time:


Representative Person's signature
Name: Belle Tan
NRIC/FIN No: AME AUTOPOINT PRE LTD
14.6.2019






































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jun 2019		04 Jun 2019 16:16 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ZHANG SU XIA , ID: S2630729E								
Main Claimant:	LEONG HONG MUN , ID: S7420210A								
Vehicle Reg. No.:	SKB2793R	Date of Loss:	03/06/2019 00:00 - :59 [96 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1902688	Policy/Cover Note No.:	D18MTPV01016302 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLG5338P	Policy No. (Claimant):							
		Excess:							
Repairer:	AK WORKSHOP (HQ) 10 Ang Mo Kio Industrial Park 2A, #04-10 AMK Autopoint, 568047 Ang Mo Kio - Tel: 8383 5050 / 9339 7880 / 9321 0855								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/06/2019]								
Adj Asg. Remarks:	AK WORKSHOP 9339 7780								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKB2793R (CMTD1902688)
[SLG5338P]
TP
LEONG HONG MUN
Jun 3 2019 12:00AM
[ZHANG SU XIA]
AK WORKSHOP

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
5	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
6	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
22	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
24	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
25	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
26	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
27	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
28	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
31	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
34	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
38	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/06/19 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
45	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	21/06/19 15:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	21/06/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	21/06/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	21/06/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	21/06/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	21/06/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	21/06/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	21/06/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	21/06/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	21/06/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	21/06/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
88	21/06/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	21/06/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	21/06/19 15:24	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail Print
1	04/06/19 13:51	Pre-Repair Survey - BONNIE KWOK LLC	 Load PDF	
2	04/06/19 16:09	Third Party E-filed GIA report(M)	 Load PDF	
3	04/06/19 16:12	Singapore Accident Statement - OI	 Load PDF	
4	04/06/19 16:16	Pre-Repair Survey - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19009906/GCD3E2

Date: 21/06/2019

REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01016302

Claimant Vehicle No : SKB2793R **Insured Vehicle No :** SLG5338P

Date of Loss: 03/06/2019 Nature of Claim: TP Claim No: CMTD1902688

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKB2793R**

Make & Model: KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A) Engine No: G4FCAH304821

Reg. Date: 13/05/2011 (Man. Year: 2010) Chassis No: KNAFW411MB5379096

Colour: Silver Odometer: 195365 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17

Front Left Side: Eagle 5 mm Rear Left Side: Eagle 5 mm

Front Right Side: Eagle 5 mm Rear Right Side: Eagle 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/06/2019

Date Inspected: 06/06/2019 Inspected At:

 AK WORKSHOP (HQ)
 10 Ang Mo Kio Industrial Park 2A, #04-10
 AMK Autopoint
 Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2019)
Parts:	143	KIA CERATO FORTE 1.6 A/T ABS AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB2793R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >