

12/03/2019

ASS. REC. BY:

REF: CS3/MSG19009911/NC d367 Special Instruction:

Surveyor: Naz

ASSIGNMENT (Office)

From (Person): Monica Chung Di Chun of MSIG Date/Time: 4.6.2019 16.24 P.M

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SNE 5783K Insured: SLG 4278K

at Workshop m/s Toh Painting & Service Tel: 67607541

of B1C-3 Woodland Road, Unit 391 C & G, New Tec

Policy No: 29014701MCX Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 30/06/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 4.6.19 5.00 P.M Person Contacted: Xiu Hui Vehicle IN / OUT

Date/Time	Action/Instruction Estimate (X)
	SNE 5783K - X
	SLG 4278K - X

ASS. REC. BY: NAZ

REF MSIG

ASSIGNMENT

From: Date: 6-6-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNE5783K

at Workshop m/s Toh Painting & Service
of B1K 3 woodland road unit 391C & G Low Tee Industrial

Insured: estate.

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: morning

Contact xid Hui: 67631055

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "ny"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SNE 5783K Yr Regn: 5 OCT, 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES E250 c.c. 1,991

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: DOOR JAM T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2130452A31.8571

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40 R19

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 30/5/19 D.O.I. 6/6/19

Survey held at TOH PAINTING

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Range \$8K-\$9K

Signature

18/6/2019

Date/Time, File Pass to?

: Prel. Report

1)

: Final Report

Date/Time, File Return to?

2)

Report Format: PRE

Lump Sum / I.B.I. (\$))

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

120

11

131

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jun 2019 13:53		04 Jun 2019 16:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	33 AUCTION ASIA PTE. LTD., Co. Reg. No.: 201321468H								
Main Claimant:	CAESARIAN TAN KAI CHAH, ID: S2656513H								
Vehicle Reg. No.:	SME5783K	Date of Loss:	30/05/2019 00:00 - :59 [7 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	29014701MCX (Comprehensive) Coverage: 29/09/2018 - 28/09/2019						
Vehicle Reg. No. (Insured):	SLG4278K	Policy No. (Claimant):							
		Excess:							
Repairer:	Toh Painting & Services Pte Ltd (HQ) BLK 3 WOODLANDS ROAD, UNIT 391C&G YEW TEE INDUSTRIAL ESTATE, 677966 Woodlands - Tel: 67607541								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/06/2019]								
Driver/Custodian (Insured):	LINDA HARDI LIM (), NRIC: X335027 Email:								
Adj Asg. Remarks:	on WP, Liab: 100%. TP lawyer disagree on SJE - assign LKK Auto Consultants. Contact: Jennifer/ Xiuhui @ 6763 1055.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6513H
Vehicle Details	
Vehicle No.:	SME5783K
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jun 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E250 AMG LINE AUTO
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	27492031180557
Chassis No.:	WDD2130452A318571
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$53,424.00
Original Registration Date:	05 Oct 2018
First Registration Date:	05 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$68,164.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Oct 2028
PARF Rebate Amount:	\$51,123.00
Intended COE Rebate Details	
COE Expiry Date:	04 Oct 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,001.00
COE Rebate Amount:	\$29,750.00
Total Rebate Amount:	\$80,873.00

The information contained herein is correct as at 17 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	02/06/2019 14:25
Date Of Accident	30/05/2019 19:10
Exact Location Of Accident	JCT OF CHANCERY LANE AND JLN PASIRAN
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SME5783K
Insured/Policyholder	
Name Of Registered Owner	CAESARIAN TAN KAI CHAH
NRIC No	S2656513H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91870188
Alternative Phone No	OTHERS-91870188
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	E250 AMG LINE AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA403776/1
Cover Note Number	
Driver	
Name of Driver	CAESARIAN TAN KAI CHAH
NRIC No	S2656513H
Date Of Birth	05/10/1953
Occupation	INDOOR
Date Of Driving Pass	16/12/1994
Driving Experience	24 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91870188
Fax Number	
Contact Number	OTHERS-91870188
EEmail Address	NOEMAIL

Address	1 NEWTON ROAD #28-01 SPORE 307943
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG4278K
Vehicle Make/Model/Colour	TOYOTA HARRIER ELEGANCE 2.0 A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to your insurance company.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIC Property Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report in the register, you hereby consent to the archiving of this report at the centre and to copies of the report being made available thereafter.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) We (we, my, yours, them, the General Insurance Association of Singapore ("GIA")) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, intenders, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail envelopes) and/or;
 - (v) complying with applicable law in administering or issuing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) who may be, and/or outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and non-accident claimant and all future claims;
- (e) the information we collect, use and/or process may be used to:
 - (i) to inform and/or in any other claim process that about investigating, investigating, controlling or managing fraud, regulation, law enforcement and government agencies as lawfully required for the purposes stated; or
 - (ii) for complying with requirements under any regulation, law or court orders;


Policyholder's Signature
Print Name

31/5/19
Driver's Signature
Insurer's Representative's Signature
Print Name

Reporting Centre Personnel's Signature
Name: Alan
Print Name: B. Subramanian

Sketch Plan #2

SKETCH PLAN



A - SME 5783K
B - SLG 4278K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 30/5/19 @ ABOUT 1910HR, MY VEHICLE SME 5783K
WAS STATIONARY @ JUNCTION OF DALAN PARISAN &
CHANCERY LANE, PENDING TRAFFIC CLEARANCE.
SUDDENLY VEHICLE SLG 4278K CUT INTO MY LANE
WHILE TURNING IN FROM CHANCERY LANE &
COLLIDED ONTO MY VEHICLE'S FRONT RH PORTION
RESPITE HORING HER OUT OF PANIC NO INJURIES
NO PASSENGERS

DECLARATION

I/We declare that the above particulars are true and correct.

Signature of Driver
Name: [Signature]

31/5/19

Witness Name: [Signature]
Signature of Driver
Name: [Signature]

Signature of Driver
Name: [Signature]

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jun 2019 13:53		04 Jun 2019 16:24 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: 33 AUCTION ASIA PTE. LTD., Co. Reg. No.: 201321468H									
Main Claimant: CAESARIAN TAN KAI CHAH, ID: S2656513H									
Vehicle Reg. No.: SME5783K		Date of Loss: 30/05/2019 19:00 - :59 [7 Months and 25 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 595467		Policy/Cover Note No.: A29014701MCX (Comprehensive) Coverage: 29/09/2018 - 28/09/2019							
Vehicle Reg. No. (Insured): SLG4278K		Policy No. (Claimant):							
		Excess: S\$3,600.00							
Repairer: Toh Painting & Services Pte Ltd (HQ) BLK 3 WOODLANDS ROAD, UNIT 391C&G YEW TEE INDUSTRIAL ESTATE, 677966 Woodlands - Tel: 67607541									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Imm.Advice due 05/06/2019]									
Driver/Custodian (Insured): LINDA HARDI LIM (), NRIC: X335027 Email:									
Adj Asg. Remarks: on WP. Liab: 100%. TP lawyer disagree on SJE - assign LKK Auto Consultants. Contact: Jennifer/ Xiuhui @ 6763 1055.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SME5783K (595467)**
[SLG4278K]
TP
CAESARIAN TAN KAI CHAH
May 30 2019 7:00PM
[33 AUCTION ASIA PTE. LTD.]
Toh Painting & Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
2	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
3	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
4	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
5	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
6	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
7	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
8	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
9	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
10	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
11	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
12	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
13	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
14	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
15	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
16	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
17	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
18	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
19	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
20	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
21	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
22	07/06/19 11:38	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/06/19 13:54	OI GIA	Load PDF	
2	03/06/19 13:54	TP GIA	Load PDF	
3	04/06/19 10:17	Workshop details	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19009911/NCD3E2

Date: 20/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29014701MCX

Claimant Vehicle No : SME5783K

Insured Vehicle No : SLG4278K

Date of Loss: 30/05/2019

Nature of Claim: TP

Claim No: 595467

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME5783K

Make & Model: MERCEDES-BENZ E250, 2.0 AMG LINE (R19 LED) (A)

Engine No: 27492031180557

Reg. Date: 05/10/2018 (Man. Year: 2017)

Chassis No: WDD2130452A318571

Colour: Blue

Odometer: 0 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19

Rear Tyre Size: 245/40 R19

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/06/2019

Date Inspected: 06/06/2019 Inspected At:

Toh Painting & Services Pte Ltd (HQ)
BLK 3 WOODLANDS ROAD, UNIT
391C&G YEW TEE INDUSTRIAL ESTATE
Singapore 677966

Estimated Period of Repair: 5.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 -\$9,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2019)
Parts:	143	MERCEDES-BENZ E250 2.0 AMG LINE (R19 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME5783K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >