

ASS. REC. BY:

REF:

C53/CT119009912/NCd362

Special Instruction:

25/6/19

Surveyor: MACRUSASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CT1

Date/Time:

04/6/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGT 35605

Insured:

GBO 45167

at Workshop m/s

BLUNEL

Tel:

6745-2088

of

BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55

Policy No:

DMCVSN30191719033

Claim No:

SNM19D2024P2C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

'PRS'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SGT 35605 to</u>
	<u>GBO 45167 to</u>
	<u>Dismantle: 6/6/2019</u>
	<u>After repair: 10/6/2019</u>

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

C71

**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA50190

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGT 3560 S Yr Regn: 7, 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra C.C 159/

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

84082

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMMD 841 CMHU 200 45

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45-RH

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

3/6/19

D.O.I.

6/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

no effnd. 3-4 k.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

150

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + RS. \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

PRE

Lump Sum / I.B.I. (\$

TOTAL

150

**Nivitha (LKK Auto)**

---

**From:** Serene Tan <serene.tan@mneduco.com.sg>  
**Sent:** Tuesday, 4 June 2019 5:04 PM  
**To:** Chong Boon Sen  
**Cc:** Igene Lim; assignments; 'Bluwel2088'  
**Subject:** RE: our ref: snm19d202482 / gbb4516t and your ref: sgt3560s - pri

Our Ref: MN.IG.B1.1913091.st (SGT 3560S)

WITHOUT PREJUDICE  
SAVE AS TO COSTS

**NOTICE TO INSURERS OBJECTING TO THE LIST OF MOTOR SURVEYORS  
PROVIDED WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2.6 OF THE  
STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**

Dear Boon Sen,

We refer to your reply on even date.

In compliance with paragraph 2.9 of the State Courts Practice Direction Amendment No. 1 of 2016,  
you may proceed to instruct your appointed surveyor M/s LKK Auto Consultants Pte Ltd to conduct  
and/or complete the pre-repair survey within 2 working days from the date hereof.

*Note : workshop's details are stated in our letter dated 4<sup>th</sup> June 2019.*

Thanks & Best Regards,  
(For and on behalf of Mr Nedumaran Muthukrishnan)  
Serene Tan (Ms)  
M NEDUMARAN & CO  
Advocates & Solicitors  
Commissioner for Oaths

(1/1)

pr

Branch Office:  
11 Sin Ming Road  
#B2-09 (Unit 2), Thomson V Two  
Singapore 575629  
Tel: 6509-8480 / 6509-8481  
Fax: 6509-8482  
Email : [serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)

**IMPORTANT NOTE:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error.  
Thank you.

---

**From:** Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]  
**Sent:** Tuesday, 4 June 2019 5:00 PM  
**To:** Serene Tan <serene.tan@mneduco.com.sg>  
**Cc:** Igene Lim <igene.lim@mneduco.com.sg>; assignments <assignments@lkkauto.com>  
**Subject:** RE: our ref: snm19d202482 / gbb4516t and your ref: sgt3560s - pri

WITHOUT PREJUDICE  
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Serene Tan [mailto:serene.tan@mneduco.com.sg]  
**Sent:** Tuesday, 4 June, 2019 4:57 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Cc:** Igene Lim <igene.lim@mneduco.com.sg>  
**Subject:** RE: our ref: snm19d202482 / gbb4516t and your ref: sgt3560s - pri

Our Ref : MN.IG.B1.1913091.st

WITHOUT PREJUDICE  
SAVE AS TO COSTS

**NOTICE TO INSURERS OBJECTING TO THE LIST OF MOTOR SURVEYORS  
PROVIDED WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2.6 OF THE  
STATE COURTS PRACTICE DIRECTIONS (AMENDMENT NO. 1 OF 2016)**

Hi Boon Sen,

1. We refer to your email below.

2. We are instructed by **POON CHOON SUN**, the claimant and/or **BLUWEL AUTOMOTIVE SERVICE PTE LTD**, the motor workshop for **SGT 3560S** that they are not agreeable to the appointment of the motor surveyors as stated in your said email.
3. In compliance with The State Courts Practice Directions (Amendment No. 1 of 2016), we propose to use one of the below mentioned motor surveyor to conduct the joint pre-repair survey ("hereinafter referred to as PRS") as a Single Joint Expert ("hereinafter referred to as a SJE").

1. NICKY SEAH (Absolute Appraisal Services)	6. ANDREW HOW (Prominent Appraiser Services)
2. MICHAEL YAP TECK CHYE (MC-COY Appraiser Pte Ltd)	7. LOI BOON JUAN (PAR Automotive)
3. DIXON YEO (Treasure Appraisal Services)	8. ANANDA KUMAR BISWAS S/O B N BISWAS (United Appraisal & Management Pte Ltd)
4. LAWRENCE NG (PRIORITY Services)	9. DENNIS YAP TECK WEE (PAL's Appraiser Pte Ltd)
5. AMAS ONG (AEON Auto Consultants LLP)	10. ANDY YAP TECK LEE (LCW Appraiser Pte Ltd)

4. Please let us know within two (2) working days whether you agree to the appointment of any of the above motor surveyors as proposed by the claimant and/or the motor workshop as a Single Joint Expert ("hereinafter referred to as "SJE").

Thanks & Best Regards,  
 (For and on behalf of Mr Nedumaran Muthukrishnan)  
**Serene Tan (Ms)**  
**M NEDUMARAN & CO**  
**Advocates & Solicitors**  
**Commissioner for Oaths**

Branch Office:  
 11 Sin Ming Road  
 #B2-09 (Unit 2), Thomson V Two  
 Singapore 575629  
 Tel: 6509-8480 / 6509-8481  
 Fax: 6509-8482  
Email : [serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)

**IMPORTANT NOTE:** This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509 8480, if you have received this message in error. Thank you.

---

**From:** Chong Boon Sen [[muli@boonsen.chong@sg.cntaiping.com](mailto:muli@boonsen.chong@sg.cntaiping.com)]  
**Sent:** Tuesday, 4 June 2019 4:44 PM  
**To:** Serene Tan <[serene.tan@mneduco.com.sg](mailto:serene.tan@mneduco.com.sg)>  
**Subject:** our ref: snm19d202482 / gbb4516t and your ref: sgt3560s - pri

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

For more information please visit <http://www.symanteccloud.com>

---

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	0182A

### Vehicle Details

Vehicle No.:	SGT3560S
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	G4FGGU194340
Chassis No.:	KMHD841CMHU200415
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$17,432.00
Original Registration Date:	13 Jul 2016
First Registration Date:	13 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$17,432.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jul 2026
PARF Rebate Amount:	\$13,074.00

### Intended COE Rebate Details

COE Expiry Date:	12 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$37,116.00
<b>Total Rebate Amount:</b>	<b>\$50,190.00</b>

The information contained herein is correct as at 07 Jun 2019

OK



05/06 2019 THU 10:44 FAX

001/005

MSME1007310R / SMC Motor Pte Ltd - Kold Build  
 ENTRY DATE & TIME: 04/06/2019 17:31  
 SUBMITTED BY: Chia Pei Ying

## SINGAPORE ACCIDENT STATEMENT

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available if/when so required.

**ACCIDENT STATEMENT**

Date Of Report 04/06/2019 17:31  
 Date Of Accident 03/06/2019 17:10  
 Exact Location Of Accident WOODLANDS AVE 12  
 Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number SGT3560S  
**Insured/Policyholder**  
 Name Of Registered Owner POON CHOON SUN  
 NRIC No S8010182A  
 Email Address NOEMAIL  
 Mobile Phone No (LOCAL) +65-96808791  
 Alternative Phone No OFFICE-96808791

**Vehicle Particulars**

Manufacturer HYUNDAI  
 Model ELANTRA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

**Insurance Company**

Name of Insurance Company QBE INSURANCE (SINGAPORE) PTE LTD  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number 8-V0015521-MVA-R001

**Cover Note Number****Driver**

Name of Driver POON CHOON SUN  
 NRIC No S8010182A  
 Date Of Birth 10/04/1980  
 Occupation INDOOR  
 Date Of Driving Pass 29/03/2000  
 Driving Experience 19 YEARS AND 2 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-96808791  
 Fax Number  
 Contact Number OFFICE-96808791  
 EMail Address NOEMAIL

06/06 2019 THU 10:44 FAX

002/005

Address BLK 312B ANCHORVALE LANE #16-68  
 Postcode 542312  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions RAINING  
 Road Surface WET

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 3  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

ON 03/06/2019 AT ABOUT 5.08PM, I WAS DRIVING ALONG WOODLANDS AVE 12 ON THE SECOND LANE. TRAFFIC LIGHTS TURNED RED. I STOPPED MY CAR. I HEARD A BANG BEHIND MY CAR THEN FOLLOWED BY A PUSH ON THE REAR OF MY CAR. I ALIGHTED FROM MY CAR AND FOUND OUT THAT I WAS INVOLVED IN A 3 CARS CHAIN COLLISION. WE EXCHANGED OUR DETAILS.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GBB4516T  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver ZAMIR  
 NRIC/Passport Number  
 Contact Number 93796349  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (including Driver)

06/06 2019 THU 10:44 FAX

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBE5009J
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	AZMI BIN RAMLI
NRIC/Passport Number	S7328505F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

06/06 2019 THU 10:44 FAX

0004/005

## Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time: 4/6/19, 2:40pm

Driver's Signature  
(if driver is not the policyholder)  
Date & Time: 4/6/19, 2:40pm

Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.:


GIA/ACC Sketch PD21/Form\_V2

06/06 2019 THU 10:45 FAX

005/005

## Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 03/06/19 at about 5.08pm, I was driving along Woodlands Ave 12 on the 2nd lane. Traffic lights turned red, I stopped my car. I heard a bang behind my car then followed by a push on the rear of my car. I alighted from my car and found out that I was involved in a 3 cars chain collision. We exchanged our details.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 4/6/19, 240pm

GLA/NC SketchPlanForm\_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time: 4/6/19, 240pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jun 2019		25 Jun 2019 16:43 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	POON CHOON SUN, ID: S8010182A								
Vehicle Reg. No.:	SGT3560S	Date of Loss:	03/06/2019 17:00 - :59 [34 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202482C02	Policy/Cover Note No.:	DMCVSN30191719033						
Vehicle Reg. No. (Insured):	GBB4516T	Policy No. (Claimant):	8-V0015521-MVA-R001						
		Excess:	S\$0.00						
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	QBE Insurance (Singapore) Pte Ltd (HQ) - Tel: 62246633								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 04/07/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGT3560S (SNM19D202482C02)

[GBB4516T]
































TP

POON CHOON SUN



















































Jun 3 2019 5:00PM

[-]







Bluwel Automotive Service Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	04/06/19 17:37	Accident Statement	 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	04/06/19 17:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	04/06/19 17:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	04/06/19 17:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	04/06/19 17:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	04/06/19 17:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	04/06/19 17:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	04/06/19 17:37	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
2	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
3	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
4	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
5	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
6	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
7	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
8	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
9	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
10	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
11	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
12	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
13	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
14	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
15	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
16	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
17	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
18	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
19	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
20	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
21	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
22	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
23	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>















Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
24	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
25	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
26	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
27	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
28	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
29	27/06/19 10:43	General View	 Load JPG	<input checked="" type="checkbox"/>
30	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	27/06/19 10:46	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	27/06/19 10:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	27/06/19 10:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	27/06/19 10:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	27/06/19 10:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	27/06/19 10:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	27/06/19 10:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	27/06/19 10:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	27/06/19 10:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	27/06/19 10:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	27/06/19 10:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
74	27/06/19 10:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	27/06/19 10:48	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	04/06/19 17:36	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	04/06/19 17:36	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	04/06/19 17:36	Sketch Plan #3 [Linked Accident Report Documents]	 Load TIF	
4	04/06/19 17:36	Sketch Plan #4 [Linked Accident Report Documents]	 Load TIF	

## Linked Accident Report Documents

Assessment Reports			View	View in Browser	1 per page	<input checked="" type="checkbox"/>
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print		
1	04/06/19 17:37	Accident Statement	 Load HTM			
Photos/Images			3 per page	<input checked="" type="checkbox"/>		
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print		
1	04/06/19 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
2	04/06/19 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
3	04/06/19 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
4	04/06/19 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
5	04/06/19 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
6	04/06/19 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
7	04/06/19 17:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>		
Documentation			1 per page	<input checked="" type="checkbox"/>		
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print		
1	04/06/19 17:36	Sketch Plan	 Load TIF			
2	04/06/19 17:36	Sketch Plan #2	 Load TIF			
3	04/06/19 17:36	Sketch Plan #3	 Load TIF			
4	04/06/19 17:36	Sketch Plan #4	 Load TIF			

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b> <span>Reset</span> <span>Save</span> <span>Print</span>
There are no document checklists configured.
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19009912/UCD3E2

Date: 01/07/2019

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN30191719033

Claimant Vehicle  
No : SGT3560SInsured Vehicle  
No : GBB4516T

Date of Loss: 03/06/2019

Nature of Claim: TP

Claim  
No: SNM19D202482C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGT3560S**

Make &amp; Model: HYUNDAI ELANTRA, 1.6 (A)

Reg. Date: 13/07/2016 (Man. Year: 2016)

Colour: Red

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: G4FGGU194340

Chassis No: KMHD841CMHU200415

Odometer: 84082 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Front Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Tyre Size: 215/45 R17

Rear Left Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 25/06/2019

Date Inspected: 06/06/2019 Inspected At:

Bluwel Automotive Service Pte Ltd (HQ)  
1 Kaki Bukit Avenue 6, #01-28/37/53/55/56  
Autobay@Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2019)
<b>Parts:</b>	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGT3560S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >