

7/2/2019

ASS. REC. BY:

REF: CS1C72 1900 9913 / NVd352

Surveyor: NAZ

Special Instructions:

Meriman

ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of CTI

Date/Time: 4.6.19 17.03 PM

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKX 8139A

Insured:

at Workshop m/s Sin Yew Hup

Tel: 67600819

of B1K D4 Woodland Road 393m, Yew Tee Industrial

Policy No: DM PCSN 3018601900

Claim No: SYM19D20472

Sum Insured:

Excess: \$500.00

Make of Veh:

(Client's Record)

D.O.A. 29.5.2019

CA / REV / REP. / REV 24 HRS

6.6.2019 morning

Date/Time: 4.6.19 5.29 PM

Person Contacted: Josephine

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate (✓)
	SKX 8139A - CCH / ASM 19002015 / U393
	D.O.A - 23/11/2019
10/6/19	Revert vehicle T/L via meriman
11/6/19	Submit Ext T/L

ASS. REC. BY:

NAZ

REF

CTI

ASSIGNMENT

From: _____ Date: 6.6.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX 839A

at Workshop m/s Sin Yew Hup

of Blk D4 Woodland Road 393m, New Tree Industrial

Insured: Estate

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$500.00

(Client's Record)

Make of Veh: Contact: 67600819 Josephine
Morning

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 46K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKX 839A

Yr Regn: 29 DEC 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: CHEVROLET SONIC

C.C. 1,398

Colour: RED

A/C: Insured / Std / NI / NA

Sp. Reading: dashboard damage

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KL 1TA69F348510735

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/55 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 29/5/19

D.O.I. 6/6/19

Survey held at

SIN YEW HUP

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COE Rebate \$45,893

Repair cost \$107. Unconcerned to repair. Recommend total loss.

RECEIVED 12 JUN 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

11/6 - typist

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

10/6/2019

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jun 2019 Sendback Est	03 Jun 2019 17:01 S\$0.00	04 Jun 2019 17:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	THANGASWAMY SOLOMON, ID: S7661544F, Tel: +6585692569, Email: solz1801@gmail.com								
Vehicle Reg. No.:	SKX8139A	Date of Loss:	29/05/2019 21:00 - :59 [41 Months From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D202472-TANKL	Policy/Cover Note No.:	DMPCSN3018601900 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate, 677981 Woodlands - Tel: 67600819								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/06/2019]								
Driver/Custodian:	THANGASWAMY SOLOMON (43 / Male), NRIC: S7661544F, Tel: +6585692569 Email: solz1801@gmail.com								
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
View All Compose Case Mail									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date:	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SKX8139A (SNM19D202472-TANKL)

OD

May 29 2019 9:00PM

[THANGASWAMY SOLOMON]

Sin Yew Hup Auto Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 11/06/2019 15:26 PM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SKX8139A - Claim Handler: Tan Kah Leong

Maintained:Please submit survey report.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 10 Jun 2019

Preliminary Advice

Vehicle No	: SKX8139A	Accident Date	: 29/05/2019
Make	: CHEVROLET SONIC	Policy No.	: DMPCSN3018601900
Assignment Date	: 04/06/2019	Excess	: S\$500.00
Date of Inspection	: 06/06/2019	Est. Duration of Repair	: 0.00
Inspection At	: SIN YEW HUP AUTO PTE LTD (HQ) BLK D4 WOODLANDS ROAD 393M, YEW TEE INDUSTRIAL ESTATE SINGAPORE 677981		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s and n/s body. The body structure affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	46,000.00
COE / PARF Rebate	:S\$	45,893.00
Salvage Value	:S\$	
Margin for Repair	:S\$	107.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/05/2019 16:33
Date Of Accident	29/05/2019 21:20
Exact Location Of Accident	ALONG ROAD 1 PAN ISLAND EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX8139A
Insured/Policyholder	
Name Of Registered Owner	THANGASWAMY SOLOMON
NRIC No	S7661544F
Email Address	SOLZ1801@GMAIL.COM
Mobile Phone No	(LOCAL) +65-85692569
Alternative Phone No	OFFICE-85692569

Vehicle Particulars

Manufacturer	CHEVROLET
Model	SONIC-1.4 HB 2WD (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3018601900
Cover Note Number	

Driver

Name of Driver	THANGASWAMY SOLOMON
NRIC No	S7661544F
Date Of Birth	18/01/1976
Occupation	INDOOR
Date Of Driving Pass	12/12/2008
Driving Experience	10 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85692569
Fax Number	
Contact Number	OFFICE-85692569
Email Address	SOLZ1801@GMAIL.COM

Address

Postcode

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190529/2198

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

1 of 3

Report No. T/20190529/2198

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/05/2019 23:33	Vide Report No.:	Station Diary No.: 207
--	------------------	---------------------------

Informant's Particulars

Name of Informant: THANGASWAMY SOLOMON			Address: APT BLK 687D CHOA CHU KANG DRIVE #14-372 SINGAPORE 684687	
ID Type / ID No.: NRIC NO / S7661544F			Contact No.: Home/Office: Mobile: 85692569	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 43	Date of Birth: 18/01/1976	Type of Informant: Driver	
Race: Indian			Language: English	Institution / School Name:
Occupation: MANAGER			Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 29/05/2019 21:20	Type of Location: Bend
Location: Along Road 1 PAN ISLAND EXPRESSWAY				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Moving Vehicle Against - Lamp Post			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKX8139A	Car	CHEVROLET	SONIC NB 1.4 A/T 2WD	Red	Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKX8139A	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN30186019 00	12/03/2019	11/03/2020



**SINGAPORE
POLICE FORCE**



T/20190529/2198

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

3 of 3

Report No. T/20190529/2198

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 3 NUR RAQIB BIN RASMAN

Signature Of Interpreter: CHOA CHU KANG NPC

Not applicable 20 CHOA CHU KANG ST 52 #01
SINGAPORE 689286
TEL : 1800-7659999
FAX : 67673651

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt MOHAMMED FEROZ BIN HUSSEIN
Contact No.: 65476206

Signature Of Informant:

Date/Time:

29/05/2019 23:33

Classification Of Case:

Authentication Stamp

NP166

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1544F
Vehicle Details	
Vehicle No.:	SKX8139A
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	CHEVROLET
Vehicle Model:	SONIC NB 1.4 A/T 2WD
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	A14XER152580368
Chassis No.:	KL1TA69FJGB510735
Maximum Power Output:	74.0 kW (99 bhp)
Open Market Value:	\$13,781.00
Original Registration Date:	29 Dec 2015
First Registration Date:	29 Dec 2015
Transfer Count:	1
Actual ARF Paid:	\$13,781.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2025
PARF Rebate Amount:	\$10,335.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,301.00
COE Rebate Amount:	\$35,558.00
Total Rebate Amount:	\$45,893.00

The information contained herein is correct as at 10 Jun 2019

OK

1 vehicles

Search Chevrolet Sonic

Advanced Search

Search

View All

Make

Model

Price

Depreciation

Reg

Eng

Mileage

Veh

Statu

Search
Selection

Chevrolet Sonic

Any

Any

2015

Any

Any

Any

Available

☐ Chevrolet Sonic 1.4A
LTZ (OPC)

\$42,388

\$6,430 /yr

28-May-
2015

1,398 cc

57,000 km

Sedan

Available

High Trade In, Low Loan Interest. Fuel Efficiency, Fully Agent Serviced. Comfortable And Easy Drive

Car Empire Automobiles Pte Ltd



Posted: 04-Jun-2015

Title: 2015 Chevrolet Sonic, 2015 chevrolet sonic, Chevrolet Sonic, chevrolet
sonic, Chevrolet Sonic, sonic, used Chevrolet

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





新友合汽车私人有限公司

SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981

Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg

Co./OST Regn. No. 200921075G

Specialise in Insurance Claims and General Motor Repair Work

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSN3018601900	Date of Loss:	29/05/2019
Vehicle Reg. No.:	SKX8139A	Driveable?	
Driver Age/Info:	43 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	THANGASWAMY SOLOMON	Contact No:	+6585692569
Driver:	THANGASWAMY SOLOMON		
Make/Model:	CHEVROLET SONIC, 1.4 HB 2WD (A)	Vehicle Reg. Date:	29/12/2015
Vehicle Colour:	RED		
Engine No:	A14XER152580368	Chassis No:	KL1TA69FJGB510735
Odometer:	0 KM		
Paint Type:			
Total Loss?	YES		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	STATEMENT, PLEASE REFER TO POLICE REPORT NO: T/20190529/2198.		
Present Location:	SIN YEW HUP AUTO PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Nett Amount (S\$)	0.00

This claim is handled by: TEO HONG ENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jun 2019)
Parts: 144 CHEVROLET SONIC 1.4 HB 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Sin Yew Hup Auto Pte Ltd/SKX8139A/03/06/2019 17:31
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

There are no new parts selected.

Sin Yew Hup Auto Pte Ltd/SKX8139A/03/06/2019 17:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Sin Yew Hup Auto Pte Ltd/SKX8139A/03/06/2019 17:31. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jun 2019 Sendback Est	03 Jun 2019 17:31 S\$0.00	04 Jun 2019 17:08 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	THANGASWAMY SOLOMON, ID: S7661544F, Tel: +6585692569, Email: solz1801@gmail.com		
Vehicle Reg. No.:	SKX8139A	Date of Loss:	29/05/2019 21:00 - :59 [41 Months From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM19D202472-TANKL	Policy/Cover Note No.:	DMPCSN3018601900 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate, 677981 Woodlands - Tel: 67600819		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 14/06/2019]		
Driver/Custodian:	THANGASWAMY SOLOMON (43 / Male) , NRIC: S7661544F, Tel: +6585692569 Email: solz1801@gmail.com		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPING (11/06/2019): Alert - Adj Mandate Maintained - SKX8139A - Claim Handler: Tan Kah Leong

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

SKX8139A (SNM19D202472-TANKL)
OD
May 29 2019 9:00PM
[THANGASWAMY SOLOMON]
Sin Yew Hup Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	03/06/19 17:31	Repairer Estimates	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/06/19 15:41	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/06/19 11:35	General View	 Load JPG ☒	☒
2	07/06/19 11:35	General View	 Load JPG ☒	☒
3	07/06/19 11:35	General View	 Load JPG ☒	☒
4	07/06/19 11:35	General View	 Load JPG ☒	☒
5	07/06/19 11:35	General View	 Load JPG ☒	☒
6	07/06/19 11:35	General View	 Load JPG ☒	☒
7	07/06/19 11:35	General View	 Load JPG ☒	☒
8	07/06/19 11:35	General View	 Load JPG ☒	☒
9	07/06/19 11:35	General View	 Load JPG ☒	☒
10	07/06/19 11:35	General View	 Load JPG ☒	☒
11	07/06/19 11:35	General View	 Load JPG ☒	☒
12	07/06/19 11:35	General View	 Load JPG ☒	☒
13	07/06/19 11:35	General View	 Load JPG ☒	☒
14	07/06/19 11:35	General View	 Load JPG ☒	☒
15	07/06/19 11:35	General View	 Load JPG ☒	☒
16	07/06/19 11:35	General View	 Load JPG ☒	☒
17	07/06/19 11:35	General View	 Load JPG ☒	☒
18	07/06/19 11:35	General View	 Load JPG ☒	☒
19	07/06/19 11:35	General View	 Load JPG ☒	☒
20	07/06/19 11:35	General View	 Load JPG ☒	☒
21	07/06/19 11:35	General View	 Load JPG ☒	☒
22	07/06/19 11:35	General View	 Load JPG ☒	☒
23	07/06/19 11:35	General View	 Load JPG ☒	☒
24	07/06/19 11:35	General View	 Load JPG ☒	☒
25	07/06/19 11:35	General View	 Load JPG ☒	☒
26	07/06/19 11:35	General View	 Load JPG ☒	☒
27	07/06/19 11:35	General View	 Load JPG ☒	☒
28	07/06/19 11:36	General View	 Load JPG ☒	☒
29	07/06/19 11:36	General View	 Load JPG ☒	☒
30	07/06/19 11:36	General View	 Load JPG ☒	☒
31	07/06/19 11:36	General View	 Load JPG ☒	☒
32	07/06/19 11:36	General View	 Load JPG ☒	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
33	07/06/19 11:36	General View	 Load JPG	☒
34	07/06/19 11:36	General View	 Load JPG	☒
35	07/06/19 11:36	General View	 Load JPG	☒
36	07/06/19 11:36	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/06/19 15:09	Log card (if available)	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser	☒
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print	
1	30/05/19 17:33	Accident Statement	 Load HTM		
Photos/Images			3 per page	☒	
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print	
1	30/05/19 17:32	Accident Photo	 Load JPG	☒	
2	30/05/19 17:32	Accident Photo	 Load JPG	☒	
3	30/05/19 17:32	Accident Photo	 Load JPG	☒	
4	30/05/19 17:32	Accident Photo	 Load JPG	☒	
5	30/05/19 17:32	Accident Photo	 Load JPG	☒	
6	30/05/19 17:32	Accident Photo	 Load JPG	☒	
7	30/05/19 17:32	Accident Photo	 Load JPG	☒	
8	30/05/19 17:32	Accident Photo	 Load JPG	☒	
9	30/05/19 17:32	Accident Photo	 Load JPG	☒	
10	30/05/19 17:32	Accident Photo	 Load JPG	☒	
Documentation			1 per page	☒	
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print	
1	30/05/19 17:29	Accident Sketch Plan	 Load TIF		
2	30/05/19 17:29	Accident Sketch Plan	 Load TIF		
3	30/05/19 17:29	Accident Sketch Plan	 Load TIF		
4	30/05/19 17:29	Accident Sketch Plan	 Load TIF		
5	30/05/19 17:29	Accident Sketch Plan	 Load TIF		
6	30/05/19 17:29	Accident Sketch Plan	 Load TIF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19009913/NVD3S2

Date: 12/06/2019

REFERENCE

Insured/Claimant: THANGASWAMY SOLOMON

Policy No: DMPCSN3018601900

Date of Loss: 29/05/2019

Nature of Claim: OD

Claim No: SNM19D202472-TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX8139A

Make & Model: CHEVROLET SONIC, 1.4 HB 2WD (A)

Reg. Date: 29/12/2015 (Man. Year: 2015)

Colour: Red

Engine Capacity: 1398 cc

Market Value/New Car Price: S\$46,000.00

Sum Insured (S\$): Market Value/New Car Price

Engine No: A14XER152580368

Chassis No: KL1TA69FJGB510735

Odometer: 0 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Poor Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Front Left Side: Nexen 5 mm

Front Right Side: Nexen 5 mm

Rear Tyre Size:

205/55R16

Rear Left Side:

Nexen 5 mm

Rear Right Side:

Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	0.00	-500.00	500.00	
+ GST 0.00/7.00% (S\$)	0.00	-35.00	35.00	
Nett Amount (S\$)	0.00	-535.00	535.00	

INSPECTION

Date of Assignment: 04/06/2019 Present Location:

Sin Yew Hup Auto Pte Ltd (HQ)

Sin Yew Hup Auto Pte Ltd (HQ)

Date Inspected: 06/06/2019 Inspected At:

Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate

Singapore 677981

Estimated Period of Repair: 0.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$46,000.00
OMV :	\$13,781.00
PARF Rebate (1) :	\$10,335.00
Quota Premium Paid :	\$54,301.00
COE Rebate (2) :	\$35,558.00
Total Rebate (1) + (2) = :	\$45,893.00

The total amount incurred will be Market Value \$46,000.00 minus Total Rebate \$45,893.00 = \$107.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jun 2019)

Parts: 144 CHEVROLET SONIC 1.4 HB 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX8139A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >