

Ref. No : <u>CS/TP 190090165/Und³ 12</u>	Res. Date: <u>7/6/19</u>	Date Received:
Veh. No : <u>56788043</u>	SP:	WKSP: <u>Bent</u>
C/No :		
Action/Instruction:		
1. File	2. Submit Photo?	YES / NO
3. Indicate Res. Date On Photo Page?	YES / NO	Message:
If No, due to a) No authorisation b) Days of repair		
others:		
Final Re-inspection or Progress Photos		Inspected By: <u>[Signature]</u>

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 20

DAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: 9 Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

2049I
Vehicle: IN / OUT

Date: Person Contacted: next 6088

Modi: Nil (S/Rim) / STD A/Rim or

Tyre Size: F: 195/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / (MIC) / OHTSU / PIR / SUMI / TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. mm R/Bal. mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 1/6/19 D.O.I. 6/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

[Signature]

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
11/6/19	FIA in car 31-3-2022
	L/S & 4900 (Red 7010.42, 6390)
	4300

RECEIVED 11 JUN 2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Date/Time, File Return to?

1) 11/6 - typist

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

170 + 15
50
50 + 50
8
80

S + RS, SI

Photos

Others

TOTAL

Report Format : TP

Lump Sum / I.B.I. (\$) 4300

500