

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ 70 19009965/Uvd3

ASSIGNMENT

From: Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lump Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21.5.2019. 474139/2
 11/6/19 F1A in c 31-3-2022
 4/5 4900 (Red 7012.42, 63%)
 4300

RECEIVED 11 JUN 2019

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

11/6 - typst

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Report Format :

TP

Lump Sum / I.B.I. (\$

4300)

170 + 15

50

50 + 50

85

80

80

80

80

500

Ref. No : <u>CS/TP 19009965/Uvd³</u>	Res. Date: <u>7/6/18</u>	Date Received:
Veh. No : <u>SG7F8043</u>	SP:	WKSP: <u>[Signature]</u>
C/No :		
Action/Instruction:		
1. File	2. Submit Photo? YES / NO	
3. Indicate Res. Date On Photo Page?	YES / NO	Message:
If No, due to	a) No authorisation b) Days of repair	
others:		
Final Re-inspection	or Progress Photos	Inspected By: <u>[Signature]</u>

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

MANAGEMENT CAR DEALS. 7 – 9 JUNE 2019.

Find out more

Performance Premium Selection Limited. 280 Kampong Arang Road, S438180.

toyota corolla altis

Price Range

Depreciation

> 10 year(s)

Vehicle Type



Home » Used Cars » Starise Automobile » Toyota Corolla Altis 1.6A (COE till 02/2022)

Toyota Corolla Altis 1.6A (COE till 02/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



STARISE AUTOMOBILE

Member of



Accredited by



Price \$24,800

Depreciation ⓘ \$9,130 /yr

Reg Date 23-Feb-2007
(2yrs 8mths 15days COE left)

Mileage N.A.

Manufactured 2006

Road Tax ⓘ \$890 /yr

Transmission Auto

Dereg Value ⓘ \$13,682 as of today (change)

OMV ⓘ \$15,355

COE ⓘ \$25,197

ARF ⓘ \$16,891

Engine Cap 1,598 cc

Power 81.0 kW (108 bhp)

Curb Weight ⓘ 1,115 kg

No. of Owners 1

Type of Vehicle Mid-Sized Sedan

Features

Fuel Efficient And Powerful 1.6L 16 Valve DOHC VVTI Engine, Smooth Auto Transmission With ECT, Dual SRS Airbags, ABS, Digital Climate Control Aircon. View specs of the Toyota Corolla Altis (2000-2007)

Category

COE Car

Status

Available

Resources



Car Valuation - Free

Get value of your existing car for free. Get started

Compare



Location Map

Shortlist

Com

Report Error

M

Seller Information

Company

Star



» des

» 51



Address

210 1

Search

Location

Car M

Office No

6469

Contact Person(s)

Louis

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8049I
Vehicle Details	
Vehicle No.:	SGT5804B
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	3ZZ4631735
Chassis No.:	MR053ZEC107141674
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,355.00
Original Registration Date:	18 Apr 2007
First Registration Date:	18 Apr 2007
Transfer Count:	2
Actual ARF Paid:	\$13,443.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$24,715.00
COE Rebate Amount:	\$13,912.00
Total Rebate Amount:	\$13,912.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Jun 2019

OK

04/06 2019 TUE 10:12 FAX

0001/004

MSME100/2362 / SMI Motor Pte Ltd - Kallit Bukit
 ENTRY DATE & TIME: 03/06/2019 17:14
 SUBMITTED BY: Chee Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/06/2019 17:14
 Date Of Accident 01/06/2019 08:30
 Exact Location Of Accident CT HUB MULTI-STOREY CARPARK
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGT5804B
Insured/Policyholder
 Name Of Registered Owner TOH HUI LEONG
 NRIC No S9048049I
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-83823143
 Alternative Phone No OFFICE-83823143

Vehicle Particulars

Manufacturer TOYOTA
 Model ALTIS
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
Insurance Company
 Name of Insurance Company ECICS LIMITED
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number MPG19P00003200
 Cover Note Number

Driver

Name of Driver TOH HUI LEONG
 NRIC No S9048049I
 Date Of Birth 15/12/1990
 Occupation INDOOR
 Date Of Driving Pass 12/01/2011
 Driving Experience 8 YEARS AND 4 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-83823143
 Fax Number
 Contact Number OFFICE-83823143
 Email Address NOEMAIL

04/06 2019 TUE 10:12 FAX

0002/004

Address BLK 526 HOUGANG AVE 6 #10-149
 Postcode 530526
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 01/06/2019 AT ABOUT 8.30AM, I WAS WAITING TO EXIT THE CARPARK. CAR B WHICH WAS IN FRONT OF ME MADE A REVERSE AND HIT THE FRONT PORTION OF MY CAR A.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJV5215E
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver GEORGE SENG JIAN HONG
 NRIC/Passport Number
 Contact Number 98195791
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 3/6/19, 4:15pm

Driver's Signature
(If driver is not the policyholder)
Date & Time: 3/6/19, 4:15pm


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

04/06 2019 TUE 10:13 FAX

004/004

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 01/06/19 at about 8:30am, I was waiting to exit the carpark. Car B which was in front of me made a reversed and hit the front portion of my car (A).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature

Date & Time: 3/6/19, 4:15pm

GUARMC SketchPlanForm_V3

[Signature]
Driver's Signature

(If driver is not the policyholder)

Date & Time: 3/6/19, 4:15pm

[Signature]
Reporting Centre Personnel's Signature

Name:

NRIC/PRN No.:



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
(Unit C) #01-28-53/55 Singapore 417883
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
Co. Reg. No.: 200704951N
GST Reg. No.: 200704951N

Not Alud
N/A
1/2 = 4900
5 day

SGT 5804B

	Bonnet	n	942.10	X
2pc	Bonnet hinges @ 105.00	nn	210.00	X
	front bumper	de	485.10	
	front bumper reinforcement	but	385.10	XR
2pc	front bumper side retainers @ 66.50	nu	133.00	
1set	front bumper clips	nu	50.00	
	front brace panel	twi	121.00	
	front support panel	wp/buy	1866.10	
2pc	headlamps @ 185.10	cne	1170.20	
	Air-con condenser	but/par	1315.30	
	Radiator	nn	1804.10	X
	front grille	cne	385.32	
	front grille logo	nu	65.10	
	front licence plate chrome type	cne	150.00	805.2
			9082.42	
	To check wiring		50.00	-20
	To refill air con gas		120.00	-100
	To spray rust proofing		80.00	-30
	labour for panel beating & replacing parts		980.00	-600
	To putty & spray painting		1200.00	-800
			797.42	11512.42

LKK Auto Consultants hence notify
the Repairer of the following:

- To ensure adequate spray painting
- To ensure damaged part(s) during resurvey
- Repairs are subject to confirmation
- This party survey is on a "Without Prejudice" basis
- Final approval from Insurance Company is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP19009965/Uvd3n2

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 12-06-2019



ON BEHALF OF TOH HUI LEONG

Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SGT 5804B
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	06/06/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	MR053ZEC107141674	Colour	GREY
Odometer	177347	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	MICHELIN	6 mm
L/H Front Tyre	195/60 R15	MICHELIN	6 mm
R/H Rear Tyre	195/60 R15	MICHELIN	6 mm
L/H Rear Tyre	195/60 R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/06/2019	Inspection Date	06/06/2019
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref : CS/TP19009965/Uvd3n2		
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883		Date : 12-06-2019		
ON BEHALF OF TOH HUI LEONG		Code : TP149		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SGT 5804B	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		06/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053ZEC107141674	Colour	GREY	
Odometer	177347	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	MICHELIN	6 mm	
L/H Front Tyre	195/60 R15	MICHELIN	6 mm	
R/H Rear Tyre	195/60 R15	MICHELIN	6 mm	
L/H Rear Tyre	195/60 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/06/2019	Inspection Date	06/06/2019	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 5804B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	TO REPAIR SEE LABOUR	942.10	-
2	BONNET HINGES @\$105.00	NOT NECESSARY	210.00	-
1	FRONT BUMPER	DEFORMED	485.10	485.10
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	385.10	-
2	FRONT BUMPER SIDE RETAINERS @\$66.50	NECESSARY	133.00	133.00
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BRACE PANEL	TWISTED	121.00	121.00
1	FRONT SUPPORT PANEL	DENTED / BENT	1,866.10	1,866.10
2	HEADLAMPS @\$585.10	N/S CRACKED	1,170.20	585.10
1	AIRCON CONDENSER	BENT / PUNCTURE	1,315.30	1,315.30
1	RADIATOR	NOT NECESSARY	1,804.10	-
1	FRONT GRILLE	CRACKED	385.32	385.32
1	FRONT GRILLE LOGO	NECESSARY	65.10	65.10
	LESS 25% DISCOUNT		-	-1,251.51
			8,932.42	3,754.51
<u>SPECIAL NETT ITEMS</u>				
1	FRONT LICENCE PLATE CHROME TYPE (SN)	CRACKED	150.00	80.00
			150.00	80.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO REFILL AIR CON GAS.		120.00	100.00
	TO SPRAY RUST PROOFING.		80.00	30.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF BONNET AND FRONT BUMPER REINFORCEMENT.		980.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	800.00
	-		-	-
	-		-	-
	-		-	-
			2,430.00	1,550.00
GRAND TOTAL			11,512.42	5,384.51



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,300.00
---	--	--	----------

Report Ref No. CS/TP19009965/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.