

INSURANCE CASE OWNER: CC 6/1111900 9076, 11073 9 LKK IDAC

Surveyor: marcus DOI: 6/6/19 Date / Time: 6/6/19
Registered in Merimen: 6/6/19

Pre-assign / CCU / FTE



Insured Vehicle No: PC 92226
Name of Insured: TG TOMPS PLC
Insured Tel No: _____ HP: _____
Excess Sec II : \$S _____ D.O.A: 24/6/19
Is driver the owner? (YES / NO) Nature of Accident: _____

Claim No: _____
Policy No: _____
Make / Model: SUNSONG
Place of Accident: ULLYER QUAY

If NO, Driver Name / Age: FU YANXIN OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Driver Tel No: _____ (VA: YES / NO) Insured Liability: % Final ? Yes / No

SKF 80126



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call OI	
	After call Itr to OI	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	
	After call Itr to OI	
	Authorisation To Act	
	Release Voucher	
	Final Repair Bill	
	Car Rental Invoice	
	Towing Invoice	
	LTA / GIA	
	Medical Bill	
	PIR	
	Mandate/Reject Instruction	
	LOD	
	Payment Breakdown Form	
	Post-Repair Photos	
	Others	

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: marcus
Repair Cost: US \$5 4000.00 (4 days) Reduction: 4070.11 % 69 Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email ☐ Call ☐
Final Liability: % (Agreed / Assessed) BOLA 5/N No. : _____ If NO or B 28, Ass. Lia : _____
Repair Cost: \$S _____
Loss of Rental (LOR): \$S _____ (days) _____
Loss of Use (LOU): \$S _____ (S x days) _____
Loss of Income (LOI): \$S _____ (S x days) _____
LOI only ☐ LOU only ☐ LOR + LOI ☐ LOR + LOI ☐ (Tick only one)
GLA/LTA Search \$S _____
Medical \$S _____
Disbursement \$S _____ (to # Tow/ Independent)
Legal Cost \$S _____
Total: \$S _____ Global Sum \$S: _____
1) Claim status: Normal/Reject/Private Settle
2) Report Format: WP
3) Survey fee: \$350/-

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email ☐ Call ☐
Payee 1: \$S _____ Name 1: _____
Payee 2: (Strike if N.A.) \$S _____ Name 2: _____
Payee 3: (Strike if N.A.) \$S _____ Name 3: _____

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

Cecilia

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ = RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

29/7/19 LTA 4/107 home c. 4 mth 68%
 L/S \$4000 confirmed with 'Adu. (Ref: 44070.71/611.)

CHOO MOTOR SPRAY PAINTER
BLK1 KAKI BUKIT AVE 6
#01-39 AUTOBAY
SINGAPORE 417883

Not Allowed
6/6/19 H/S 4000
Hdy.

VEHICLE NO: SKE 8012G

QTY	PARTICULAR
1 PCS	REAR FENDER O/S
1 PCS	REAR FENDER CHROME MOULDING O/S
1 PCS	REAR FENDER GLASS O/S
1 PCS	REAR BUMPER 1341.32
2 PCS	REAR BUMPER SIDE CHROME MOULDINGS @\$178.00
1 PCS	REAR BUMPER CHROME MOULDING CENTRE
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER SIDE HOLDER O/S
1 PCS	TAILLAMP O/S 645.00
1 PCS	REAR KNUCKLE ARM O/S
1 PCS	REAR WHEEL HUB BEARING O/S
1 PCS	REAR SPORT RIM 18 INCH O/S
1 PCS	REAR TYRE O/S

2	\$2,665.10 X
22	\$188.50
11	\$688.00 X
Cur/ton	\$1,866.11
22	\$356.00
22	\$266.00
22	\$60.00
11	\$155.00 X
scat/cr	\$735.00
11	\$1,066.00 X
11	\$355.00 X
10/Ref	\$1,800.00 1000 SA
82	\$380.00 X
	\$10,580.71

LABOUR CHARGES

TO CHECK WIRING
TO DISMANTLE & REFIX PDC SENSOR
TO CONDUCT WHEEL ALIGNMENT
TO DISMANTLE & REFIX REAR UNDERCARRIAGE
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

TOTAL \$13,070.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-285682
102
2871.13
5001.13

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 0619B

Vehicle Details

Vehicle No.: SKE8012G
Vehicle to be Exported: No
Intended Deregistration Date: 06 Jun 2019
Vehicle Make: MERCEDES BENZ
Vehicle Model: C 180
Primary Colour: Black
Manufacturing Year: 2011
Engine No.: 27182030304277
Chassis No.: WDD2043492F735499
Maximum Power Output: 115.0 kW (154 bhp)
Open Market Value: \$42,032.00
Original Registration Date: 10 Nov 2011
First Registration Date: 10 Nov 2011
Transfer Count: 1
Actual ARF Paid: \$42,032.00 21016

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 09 Nov 2021
PARF Rebate Amount: \$25,219.00

Intended COE Rebate Details

COE Expiry Date: 09 Nov 2021
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$67,000.00
COE Rebate Amount: \$15,888.00
Total Rebate Amount: \$41,107.00

The information contained herein is correct as at 06 Jun 2019

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

500+ dealers competed to buy my car!

> Sell ur Car for More Cash

> Highest Price or Get \$100 Free

> Get Paid Now, Handover Later

SELL YOUR CAR

QUOTZ

Quality Used Cars

c180

Price Range

Depreciation

2011

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Autotruster Traders Pte Ltd > Mercedes-Benz C-Class C180K Avantgarde

Mercedes-Benz C-Class C180K Avantgarde

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Autotruster Traders Pte Ltd

where cars are not currency

PREMIUM DEALER

2012

ASIA PACIFIC REGION AWARD

Price

\$49,800

Depreciation

\$13,880 /yr

View models with similar depre

Mileage

114,000 km (15.1k /yr)

Road Tax

\$742 /yr

Dereg Value

\$32,478 as of today (change)

COE

\$56,112

Engine Cap

1,597 cc

Curb Weight

1,500 kg

Type of Vehicle

Luxury Sedan

Reg Date

25-Nov-2011

(2yrs 5mths 18days COE left)

Manufactured

2011

Transmission

Auto

OMV

\$31,019

ARF

\$31,019

Power

115.0 kW (154 bhp)

No. of Owners

3

Features

1.6L Super Charged Engine, 154 BHP, 5 Speed Automatic With Steptronic, ABS, Airbags, Traction Control, Cruise Control, Auto Headlights/Rain Sensors. View specs of the Mercedes-Benz C-Class Saloon (2002-2006)

Accessories

Sports Rims, Leather Seats, Built In Audio System With Bluetooth/Steering Controls, Reverse Camera/Sensors, Dual Climatic/Rear Aircon, Fog Lights.

Description

90% Loan Of The Car Price Available, Special Interest Rate 2.28%, Flexible Bank/In House Loan Available, Well Maintained Interior And Exterior, Low Mileage Done, Fuel Efficiency! 100% Accident Free! Welcome Trade In, Please Call Our Friendly Sales Now For A Non Obligation Viewing.

Category

PARF Car, Premium Ad Car

Status

Available

Resources

Car Valuation - Free

Find out the market value of your existing car for free. Get started

Compare

Autotruster Traders

Mercedes-Benz C-Class C180K Avantgarde

Map

Price Chart

Summary

Price(\$SGD)

Reg Date

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Autotruster Traders Pte Ltd

https://www.sgcarmart.com/used_cars/info.php?ID=826928&DL=2291

06-Jun-19

MANAGEMENT CAR DEALS. 7 – 9 JUNE 2019.

Find out more

Performance Premium Selection Limited. 280 Kampong Arang Road, S438180.



Price Range

Depreciation

2011

Vehicle Type

Submit

Advanced Search

Home > Used Cars > CSH Motors (S) Pte Ltd > Mercedes-Benz C-Class C180K

Mercedes-Benz C-Class C180K

OverviewFinancialInsuranceAccessoriesSimilarResearchPhotosMap

Price	\$51,800		
Depreciation	\$15,010 /yr <small>View models with similar depre</small>	Reg Date	25-Oct-2011 (2yrs 4mths 18days COE left)
Mileage	104,000 km (13.6k /yr)	Manufactured	2011
Road Tax	\$742 /yr	Transmission	Auto
Dereg Value	\$31,188 as of today (change)	OMV	\$31,979
COE	\$50,289	ARF	\$31,979
Engine Cap	1,597 cc	Power	115.0 kW (154 bhp)
Curb Weight	1,500 kg	No. of Owners	1
Type of Vehicle	Luxury Sedan		

Features

Powerful And Responsive 1.6L 4 Cylinder Supercharged Engine. Auto Headlights, ABS, Cruise Control. View specs of the Mercedes-Benz C-Class Saloon (2002-2006)

Accessories

Leather Seats, Sport Rims, Integrated Bluetooth Telephony, LCD Monitor, Reverse Camera And Sensors, CD Changer, Fog Lamps, Navi.

Description

1 Owner Only. Loan Packages Available. Please Call Or Visit Us Now For Further Details.

Category

PARF Car

Status

Available

Resources



Car Valuation - Free
Find out the market value of your existing car for free. Get started




Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company	CSH Motors (S) Pte Ltd • dealer's pricelist • 31 vehs sold 22 vehs available
Address	210 Turf Club Road Lot A43 Search cars nearby this location

Posted on: 03-Jun-2019 | Last Updated on: 03-Jun-2019

Upfront Payment

> more Financial info

Transfer Fee

\$25

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Friday, 12 July 2019 12:13 PM
To: jason (jason@fastechauto.com.sg)
Cc: Nancy Lam
Subject: YOUR REF: SKE 8012G (OUR REF: CC6/III19009976/Ugb3) *** ACCIDENT INVOLVING PC 9222L & SKE 8012G ON 24/05/2019 ***
Attachments: OI GIA REPORT.pdf

Your Ref: **SKE 8012G** Without Prejudice
Our Ref: CC6/III19009976/Ugb3

Dear Sirs/Madam,

ACCIDENT INVOLVING PC 9222L & SKE 8012G ON 24/05/2019

We refer to the above matter.

Attached is a copy of our insured accident statement for your easy reference. As there is no concrete evidence and we have reviewed the matter and we are of the view that our driver is not liable for the accident. Our Insured reported that your client has encroached into his lane and thus leads to the collision.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 22736900M

Date : 01.08.2019

India International Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Attn: Motor Claim Department

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES : SKE 8012G / PC 9222L ON 24.05.2019

We are the authorized repair workshop for the owner of motor vehicle no: **SKE 8012G**, which was involved in the captioned accident with your insured vehicle no: **PC 9222L**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair	\$	4,000.00
2) Loss of Use (4 Days + 1 Sunday x S\$100)	\$	500.00
3) GIA Search Fee	\$	2.00
	<u>\$</u>	<u>4,502.00</u>

We enclosed herewith the following documents to support the claims:

- | | |
|------------------------------------|--------------------------|
| a) Final Repair Invoice | b) GIA Search Result |
| c) Letter of Authorisation, etc... | d) GIA Report |
| e) I/C & Driving Licence | f) Insurance Certificate |
| g) Vehicle Registration Log Card | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,



Jason Tang (jason@fastechauto.com.sg)
For Choo Motor Spray Painter

TAX INVOICE

CHOO MOTOR SPRAY PAINTER

1 Kaki Bukit Ave 6 #01-39 Autobay

Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 22736900M

India International Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Attn : Motor Claim Department

Tax Invoice : 21138

Date : 01.08.2019
Vehicle No : SKE 8012G
Make/Model : MERCEDES C180
Chassis/Eng# :
Accident Date : 24.05.2019
Claim No :
Reference : 0619 -21138
Policy No :

	Amount
To proceed on lump sum repair	S\$ 4000.00

E. & O. E.

Total : S\$ 4000.00


for CHOO MOTOR SPRAY PAINTER

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-082513

Date of Request: 25/05/2019

Your Ref No:

Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 25/05/2019
Enquiry By Tang Kok Wee, Allan
Vehicle No. PC9222L
Accident Date 24/05/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
PC9222L	India International Insurance Pte Ltd	30/06/2018-29/06/2019	63476100

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-082513

Date of Request: 25/05/2019

Your Ref No:

Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 25/05/2019

Enquiry By Tang Kok Wee, Allan

Vehicle No. PC9222L

Accident Date 24/05/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref:
Claimant Ref:

*** This Discharge Voucher applies only to the claimant's claim for his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later date. Further, the settlement terms herein should not be used as an evidence to prejudice to the claimant's personal injuries claim and/or other uninsured losses claim arising of the subject matter in this action.

We/I, Choo Motor Spray Painter ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$_____ (repair cost), S\$_____ (loss of use/rental), S\$_____ (search fee), vehicle no. SKE 80126 that was damaged pursuant to the accident which occurred on 24.05.2019 (date) at Fullerton Road (location) involving vehicle no. R 92221 (insured vehicle). This is pursuant to the inspection conducted on _____ (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Chua Bing Lin ("the third party claimant") of vehicle no. SKE 80126 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKE 80126 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$_____ to Choo Motor Spray Painter

Dated this _____ day of _____ 20 _____

CLAIMANT:

Signature: _____

Signed by "the workshop" (with chop)

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____

WITNESS:

Signature: _____

Signed by appointed Surveyor

Name: _____

LKK AUTO CONSULTANTS PTE LTD

NRIC: _____

199607198R

Address: _____

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933

Nationality: _____

Occupation: _____

DATE : 06.06.2019

TO : India International Insurance Pte Ltd

RE : ACCIDENT INVOLVING VEHICLE NO. SKE 8012G / PC 9222L

ALONG Fullerton Road

ON 24.05.2019

I/We, Chua Bing Lin

of (NRIC No./ROC No.) S 8840619B

of Blk 234 Perangoon Avenue 3 # 08-82 Singapore 550234

owner of vehicle no. SKE 8012G in consideration of M/s **CHOO MOTOR SPRAY PAINTER** repairing my/our vehicle SKE 8012G at my/our instruction and hereby authorise M/s **CHOO MOTOR SPRAY PAINTER** to demand claim settle receive whatever amount settled/payable by the Insurance Company and/or third party or to commence legal proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use, etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the abovementioned claim cost which may arisen therewith.

Signature of Owner :



Name of Owner :



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2019-00006880 (Comprehensive - Prestige Plan)

Car plate number: SKE8012G

Your name (As the policyholder): Chua Bing Lin

Coverage start date: 09/05/2019

Coverage end date: 08/05/2020

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: Maybank Singapore

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 14/04/2019

Abhishek Bhatia

Chief Executive Officer

FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	0619B

Vehicle Details

Vehicle No.:	SKE8012G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 May 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	27182030304277
Chassis No.:	WDD2043492F735499
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$42,032.00
Original Registration Date:	10 Nov 2011
First Registration Date:	10 Nov 2011
Transfer Count:	1
Actual ARF Paid:	\$42,032.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Nov 2021
PARF Rebate Amount:	\$25,219.00

Intended COE Rebate Details

COE Expiry Date:	09 Nov 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$67,000.00
COE Rebate Amount:	\$16,103.00
Total Rebate Amount:	\$41,322.00

The information contained herein is correct as at 25 May 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jul 2019 Edit Reg		06 Jun 2019 00:00 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TG TOURS PTE LTD, Co. Reg. No.: -								
Main Claimant:	CHUA BING LIN, ID: S8840619B								
Vehicle Reg. No.:	SKE8012G	Date of Loss:	24/05/2019 00:00 - :59 [90 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCV2019D0000545	Policy/Cover Note No.:	D18MCV000112						
Vehicle Reg. No. (Insured):	PC9222L	Policy No. (Claimant):	PNPV2019-00006880						
		Excess:							
Repairer:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67453897								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073]								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (20/11/2019): Alert - Adj Mandate Approved (S\$0.00) - SKE8012G - Claim Handler: C. Meenachi III_SG (15/07/2019): Alert - Adj Mandate Approved (S\$0.00) - SKE8012G - Claim Handler: C. Meenachi III_SG (15/07/2019): Alert - Adj Mandate Approved (S\$0.00) - SKE8012G - Claim Handler: C. Meenachi III_SG (20/06/2019): Alert - Adj Mandate Approved (S\$0.00) - SKE8012G - Claim Handler: C. Meenachi III_SG (18/06/2019): Alert - Adj Mandate Maintained - SKE8012G - Claim Handler: C. Meenachi 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									










































Claim Documents

***SKE8012G (MCV2019D0000545)**
[PC9222L]

TP
CHUA BING LIN
May 24 2019 12:00AM
[TG TOURS PTE LTD]
Choo Motor Spray Painter

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/09/19 18:49	Video - Accident	 Load MP4	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/11/19 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
2	19/11/19 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
3	19/11/19 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
4	19/11/19 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
5	19/11/19 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
6	19/11/19 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
7	19/11/19 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
8	19/11/19 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
9	19/11/19 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
10	19/11/19 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
11	19/11/19 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
12	19/11/19 16:19	General View	 Load JPG	<input checked="" type="checkbox"/>
13	19/11/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
14	19/11/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
15	19/11/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
16	19/11/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
17	19/11/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
18	19/11/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
19	19/11/19 16:20	General View	 Load JPG	<input checked="" type="checkbox"/>
20	19/11/19 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
21	19/11/19 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
22	19/11/19 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
23	19/11/19 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
24	19/11/19 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
25	19/11/19 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
26	19/11/19 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
27	19/11/19 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
28	19/11/19 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
29	19/11/19 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
30	19/11/19 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
31	19/11/19 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
32	19/11/19 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
33	19/11/19 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
34	19/11/19 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
35	19/11/19 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
36	19/11/19 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
37	19/11/19 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
38	19/11/19 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
39	19/11/19 16:23	General View	 Load JPG	<input checked="" type="checkbox"/>
40	19/11/19 16:23	General View	 Load JPG	

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
					<input checked="" type="checkbox"/>
41	19/11/19 16:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	19/11/19 16:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	19/11/19 16:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	19/11/19 16:24	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	19/11/19 16:26	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	19/11/19 16:26	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	19/11/19 16:26	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	19/11/19 16:26	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	19/11/19 16:26	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/06/19 11:40	TP GIA REPORT	1	Load PDF	
2	19/11/19 16:00	EMAIL TO TP	1	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	07/06/19 08:49	Singapore Accident Statement	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> ^ v </div> </div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19009976/UGB3Q2

Date: 12/12/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MCV000112
Claimant Vehicle No :	SKE8012G	Insured Vehicle No :	PC9222L
Date of Loss:	24/05/2019	Nature of Claim:	TP
		Claim No:	MCV2019D0000545

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE8012G	Engine No:	27182030304277
Make & Model:	MERCEDES-BENZ C180, 1.6 (A)	Chassis No:	WDD2043492F735499
Reg. Date:	10/11/2011 (Man. Year: 2011)	Odometer:	105600 km
Colour:	Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/35Z R18	Rear Tyre Size:	225/35Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,580.71	3,571.14	7,009.57	66.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,430.00	1,060.00	42.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,070.71	5,001.14	8,069.57	61.74
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	13,070.71	4,000.00	9,070.71	69.40

INSPECTION

Date of Assignment:	06/06/2019	
Date Inspected:	06/06/2019 Inspected At:	Choo Motor Spray Painter (HQ) 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Dec 2019)
Parts:	143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE8012G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER O/S	Repair	2,665.10 F	*- FL
2	1		*REAR FENDER CHROME MOULDING O/S	Necessary	188.50 F	*188.50 FL
3	1		*REAR FENDER GLASS O/S	Not Necessary	688.00 F	*- FL
4	1		*REAR BUMPER	Cut / Torn	1,866.11 F	*1,341.32 FL
5	2		*REAR BUMPER SIDE CHROME MOULDINGS	Necessary	356.00 F	*356.00 FL
6	1		*REAR BUMPER CHROME MOULDING CENTRE	Necessary	266.00 F	*266.00 FL
7	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
8	1		*REAR BUMPER SIDE HOLDER O/S	Not Necessary	155.00 F	*- FL
9	1		*TAILLAMP O/S	Scratched / Cracked	735.00 F	*645.00 FL
10	1		*REAR KNUCKLE ARM O/S	Not Necessary	1,066.00 F	*- FL
11	1		*REAR WHEEL HUB BEARING O/S	Not Necessary	355.00 F	*- FL
12	1		*REAR SPORT RIM 18 INCH O/S	Dented / Bent	1,800.00 FS	*1,000.00 FS
13	1		*REAR TYRE O/S	Serviceable	380.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,580.71	3,856.82
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	285.68
Total Parts (\$\$)	10,580.71	3,571.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX PDC SENSOR	New	80.00	50.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
4	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	New	150.00	0.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
6	TO SPRAY RUST PROOFING	New	80.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	880.00	600.00
8	TO PUTTY & SPRAY PAINTING	New	980.00	600.00
Gross Labour Cost (S\$)			2,490.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >