

22/05/2008

ASS. REC. BY:

REF: CS / 11/19009905 / Ktd302 Special Instruction:

Surveyor: Kenneth

Mummen

ASSIGNMENT (Office)

From (Person):

tpr Yinml

of

AIG

Date/Time:

4/6/19 @ 10.35am.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH 7827A

Insured:

SMG 9241 X

at Workshop n/s

Yee Auto

Tel:

6457 5768 / 9687 4031

of

Blk 15 #01-107 Sin Ming Industrial Estate

Policy No:

Claim No:

579057109759

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29/5/2009

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4/6/19

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	✓
	SH 7827A-X		
	SMG 9241 X-X		
13/6	C1 Imp @ 2200 email, to email Ured: 4493.40 !67%!		

ASS. REC. BY:

REF:

A/G

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to

Veh No:

SJH 7827A

Yr Regn:

od, od

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c

1595

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

268608

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMF048208S202262

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

29/5/19

Rear

R/Bal.

5

mm

L/Bal.

5

mm

D.O.I.

11/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S R

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 18 JUL 2019

Date/Time, File Pass to?

1) 18/7 Typist

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trlp:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Fines

Others

TOTAL

250

11



261

Report Format :

Lump Sum / I.B.I. (\$

TP
2200/-

PRE-REPAIR INSPECTION REQUEST – SJH7827A vs SMG9241X (OI) on D.O.A.: 29/05/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tor
Sent: 6/4/2019 10:35:23 AM
Attachments:  PRI-SJH 7827A-AIG.pdf  PRI-SJH 7827A-AIG.PDF

Hi,

Please refer to the enclosed request from **K. Krishna & Partners**.

Claim no : 5790571097SG003
Case Owner : Chit Yan Foo

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.sg

From: kkrishna [mailto:kkrishna@singnet.com.sg]
Sent: Tuesday, June 04, 2019 8:43 AM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Chin, Lee-Ying; yeeautopteltd@gmail.com; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMG9241X AND SJH7827A ON 29/05/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sirs

Our client proposes LKK Auto Consultants Pte Ltd.

Kindly contact the workshop directly.

Regards

Daphne on behalf of K. Krishna & Partners



On 03-Jun-19 2:36 PM, Hor, Yinnul wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมัน
ให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-06-10 14:36 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinnul.Hor@aig.com
To: kkrishna@singnet.com.sg
Cc: Andy-SY.Fong@aig.com ,Lee-Ying.Chin@aig.com ,Baljit.Kaur@aig.com ,NoorMariesa.AbuKassim@aig.com ,Syazairdina.Azlan@aig.com ,yokeshi.chan@aig.com ,ShengYang.Lim@aig.com

,Aashweejjeelkaur,Mithoosingh@aig.com ,Divyashni.Subramaniam@aig.com ,Wahxin.Tong@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMG9241X AND SJH7827A ON 29/05/2019
Date: Fri, 31 May 2019 08:37:09 +0000
Without Prejudice

Your Reference : SM.YAS.SJH 7827A
Our Reference : 5790571097SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Ruí (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Yinnul.Hor@aig.com | www.aig.sg

From: kkrishna@singnet.com.sg [mailto:kkrishna@singnet.com.sg]

Sent: Friday, May 31, 2019 11:50 AM

To: AIG SGP, Claims-Survey

Cc: yeeautopteltd@gmail.com

Subject: [EXTERNAL] PRE-REPAIR INSPECTION OF VEHICLE SJH 7827A ACCIDENT ON 29.05.2019 INVOLVING SJH 7827A AND SMG 9241X ALONG PASIR RIS DRIVE TOWARDS TAMPINES AVENUE 9

This message is from an external sender; be cautious with links and attachments.

Dear Sirs

Please see attached letter herein and revert urgently for the PRI to be arranged as soon as possible.

Regards

Farida on behalf of K. Krishna & Partners

K. KRISHNA & PARTNERS

Advocates & Solicitors
Commissioner for Oaths/Notary Public
(UEN No. 53131210X)

GST Registration No. M90371530C
101 Cecil Street #24-03/04 Tong Eng Building, Singapore 069533
Tel : 6323 3038 Fax : 6323 2120 (not for service of Court documents)
E-mail : kkrishna@singnet.com.sg

K. Krishnamoorthi
LLB (Hons) (London)
Barrister-at-Law (Gray's Inn)
B.Sc (Hons) (Est. Man) (S'pore)

S. Manohar
LLB (Hons) (S'pore)

Vengadesh s/o Kumaravelu
LLB (Hons)

Our Ref : SM.YAS.SJH 7827A

31 May 2019

IMMEDIATE ATTENTION

EMAIL: AIGSGP_ClaimsSurvey@aig.com

PRE-REPAIR INSPECTION

AIG ASIA PACIFIC INSURANCE PTE LTD
Singapore

Attention: Motor Claims Department

Dear Sirs

PRE-REPAIR INSPECTION OF VEHICLE SJH 7827A

ACCIDENT ON 29.05.2019 INVOLVING SJH 7827A AND SMG 9241X ALONG
PASIR RIS DRIVE TOWARDS TAMPINES AVENUE 9

We act for Mr Ho Soon Yew, the owner of motor vehicle no. SJH 7827A which was involved in the above captioned accident

We are instructed that the accident was caused by the negligence of the driver of motor vehicle no. SMG 9241X. Our search shows that you are the insurers of motor vehicle no. SMG 9241X.

We are requested to inform you that our client's vehicle is available for pre-repair inspection at the following address :-

M/S YEE AUTO SERVICES
Block 15 #01-107
Sin Ming Industrial Estate
Singapore 575673
Tel; 64575768 Fax : 64574277

K. KRISHNA & PARTNERS

Advocates & Solicitors

31 May 2019

AIG ASIA PACIFIC INSURANCE PTE LTD

Please request your assessor to contact Mr Chan Kai Yee of M/s Yee Auto Services at his mobile no. **96874031** within forty-eight (48) hours from receipt of this fax to arrange for the inspection.

Yours faithfully



cc. workshop - (by email)



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16

Singapore 079120

Estimate No: ES1900019

Date: 11 Jun 2019

Policy No:

Veh Reg No: SJH7827A

Make/Model: HONDA CIVIC 1.6L VTI
AUTO

Chassis No: JHMFD46208S202262

Engine No: R16A13006641

Reg. Date: 23/08/2008

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 29/05/2019

TP Veh Reg No: SMG9241X

Estimate Repair Cost to Vehicle No :SJH7827A

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 FRONT TYRE - LH	300.00	1 PC	300.00	X
2 FRONT WHEEL RIM - LH	550.00	1 PC	550.00	X
			850.00	850.00
Spare Parts				
3 FRONT BUMPER	885.50	1 PC	885.50	—
4 FRONT BUMPER BRACKET - LH	56.60	1 PC	56.60	X
5 FRONT BUMPER CLIPS	40.00	1 SET	40.00	—
6 FRONT BUMPER REINFORCEMENT	350.00	1 PC	350.00	X
7 FRONT BUMPER SIDE RETAINER - LH	65.00	1 PC	65.00	—
8 FRONT BUMPER SIDE RETAINER - RH	65.00	1 PC	65.00	X
9 FRONT FENDER - LH	516.60	1 PC	516.60	—
10 FRONT FENDER SPLASH SHIELD - LH	154.20	1 PC	154.20	X
11 FRONT FENDER SPLASH SHIELD CLIP	60.00	1 SET	60.00	X
12 FRONT FOG LAMP - LH	285.50	1 PC	285.50	—
13 FRONT FOG LAMP COVER - LH	80.00	1 PC	80.00	X
14 FRONT HEAD LAMP - LH	985.00	1 PC	985.00	—
			3,543.40	3,543.40
Labour				
15 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,000.00	1 JOB	1,000.00	4501
16 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,000.00	1 JOB	1,000.00	4801
17 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	120.00	1 JOB	120.00	301
18 WHEEL ALIGNMENT	120.00	1 T	120.00	X
19 TO CHECK WIRING FUNCTIONS.	60.00	1 JOB	60.00	201
			2,300.00	2,300.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are not for confirmation
- Third party survey on a "without Prejudice" basis
- No liability for claims if not surveyed and
- Survey report must be signed by the Insurance Company



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 29/05/2019
TP Veh Reg No: SMG9241X

Estimate No: ES1900019
Date: 11 Jun 2019
Policy No:
Veh Reg No: SJH7827A
Make/Model: HONDA CIVIC 1.6L VTI
AUTO
Chassis No: JHMFD46208S202262
Engine No: R16A13006641
Reg. Date: 23/08/2008

Estimate Repair Cost to Vehicle No :SJH7827A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 6,693.40
			Add GST @ 7%	468.54
			Total Amount Payable	S\$ 7,161.94

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND ONE HUNDRED SIXTY ONE AND CENTS NINETY FOUR ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/05/2019 11:56
Date Of Accident	29/05/2019 09:45
Exact Location Of Accident	ALONG PASIR RIS DRIVE TOWARDS TAMPINES AVE 9
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJH7827A
Insured/Policyholder	
Name Of Registered Owner	HO SOON YEW
NRIC No	S7519590G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84200049
Alternative Phone No	OTHERS-84200049

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102387025
Cover Note Number	

Driver

Name of Driver	HO SOON YEW
NRIC No	S7519590G
Date Of Birth	01/07/1975
Occupation	OUTDOOR
Date Of Driving Pass	17/02/2011
Driving Experience	8 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84200049
Fax Number	
Contact Number	OTHERS-84200049
EEmail Address	NOEMAIL

Address	BLK 63 KALLANG BAHRU #06-399
Postcode	330063
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NPP 25 SIN MING ROAD
Police Station Address	ROAD: 25 SIN MING ROAD #01-180 , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMG9241X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NA
NRIC/Passport Number	

Contact Number NA
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name HO SOON YEW
Approximate Age
Injuries Sustain REFER REPORT
Injured person in which vehicle? SJH7827A
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer to Police Report


Police Report No: T/20190529/2073


(The rest of the section is crossed out with a diagonal line.)

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)


 Reporting Centre Personnel's Signature
 Name:



**SINGAPORE
POLICE FORCE**



T/20190529/2073

Police Station Of Origin:
Thomson NPP.
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

1 of 3

Report No. T/20190529/2073

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/05/2019 13:26	Vide Report No.:	Station Diary No.: 38
--	------------------	--------------------------

Informant's Particulars

Name of Informant: HO SOON YEW	Address: APT BLK 63 KALLANG BAHRU #06-399 SINGAPORE 330063		
ID Type / ID No.: NRIC NO / S7519590G	Contact No.: Home/Office: Mobile: 84200049		
Nationality: SINGAPORE CITIZEN	Email:		
Sex: Male	Age: 43	Date of Birth: 01/07/1975	Type of Informant: Driver
Race: Chinese	Language:		Institution / School Name:
Occupation: Driver	Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 29/05/2019 09:40	Type of Location: X-Junction
Location: Along Road 1 PASIR RIS DRIVE 1 Along Pasir Ris Drive 1 towards Tampines Town				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Pedestrian Crossing	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJH7827A	Car	HONDA	CIVIC 1.6L VTI AUTO	Grey	Slightly Damaged	0
SMG9241X	Car	KIA	CERATO 1.6(A) EX	Silver		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJH7827A	NTUC Income Insurance Co-Operative Limited	5102387025	19/07/2018	22/08/2019



**SINGAPORE
POLICE FORCE**



T/20190529/2073

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

2 of 3

Report No. T/20190529/2073

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	HO SOON YEW	ID No.	S7519590G
Related Vehicle	SJH7827A (Car)	Contact No.	84200049
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	29/05/2019	Date Discharge	29/05/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 29/05/2019 at around 0940hrs, I was driving vehicle: SJH7827A along Pasir Ris Drive 1 towards Tampines Town and stopped at the traffic junction intending to turn right. When the traffic light turned green, I then started to turn right. Subsequently while turning, a vehicle: SMG9241X on my left cut into my lane before knocking into the front portion of my vehicle. I then came down to make a check.

I saw that my vehicle's front left bumper was dented. I then took photographs of the incident before taking my leave. I wish to state that I do not have the other party's particulars. After the incident, I felt some pain as such I went to see a doctor and was given 5 days MC. I wish to state that I have an in car camera in my vehicle.

I am lodging this report for my insurance claims.



**SINGAPORE
POLICE FORCE**



T/20190529/2073

Police Station Of Origin:
Thomson NPP
25 Sin.Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

3 of 3

Report No. T/20190529/2073

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
E/
Sgt 2 KHAIRUL SYAZWAN BIN SAHAK

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
29/05/2019 13:26

Officer In Charge Of Case:
TP / AEIT /
Staff Sgt WONG SIEU LUI
Contact No.: 65476151

Classification Of Case:



SN 070

Authentication Stamp
ND158

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 May 2019 Edit Reg		04 Jun 2019 00:00 Edit Adj Rpt	S\$2,200.00 Edit Estimates	S\$2,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: NGIAM HAI FONG , ID: S7213658F									
Main Claimant: -									
Vehicle Reg. No.: SJH7827A		Date of Loss: 29/05/2019 00:00 - :59 [129 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 5790571097SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SMG9241X		Policy No. (Claimant):							
		Excess:							
Repairer: Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 6457 2625									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/06/2019]									
Claimant's Solicitor: K. Krishna & Partners - Tel: 63233038									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (07/06/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJH7827A (5790571097SG)**
[SMG9241X]
TP

May 29 2019 12:00AM
[NGIAM HAI FONG]
Yee Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	18/07/19 11:36	General View													Load JPG	<input checked="" type="checkbox"/>		
2	18/07/19 11:36	General View													Load JPG	<input checked="" type="checkbox"/>		
3	18/07/19 11:36	General View													Load JPG	<input checked="" type="checkbox"/>		
4	18/07/19 11:36	General View													Load JPG	<input checked="" type="checkbox"/>		
5	18/07/19 11:36	General View													Load JPG	<input checked="" type="checkbox"/>		
6	18/07/19 11:36	General View													Load JPG	<input checked="" type="checkbox"/>		
7	18/07/19 11:36	General View													Load JPG	<input checked="" type="checkbox"/>		
8	18/07/19 11:36	General View													Load JPG	<input checked="" type="checkbox"/>		
9	18/07/19 11:36	General View													Load JPG	<input checked="" type="checkbox"/>		
10	18/07/19 11:36	General View													Load JPG	<input checked="" type="checkbox"/>		
11	18/07/19 11:36	General View													Load JPG	<input checked="" type="checkbox"/>		
12	18/07/19 11:36	General View													Load JPG	<input checked="" type="checkbox"/>		
13	18/07/19 11:36	General View													Load JPG	<input checked="" type="checkbox"/>		
14	18/07/19 11:42	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
15	18/07/19 11:42	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
16	18/07/19 11:42	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
17	18/07/19 11:42	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
18	18/07/19 11:42	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19009985/KTD3E2

Date: 22/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJH7827A

Insured Vehicle No : SMG9241X

Date of Loss: 29/05/2019

Nature of Claim: TP

Claim No: 5790571097SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH7827A**

Make & Model: HONDA CIVIC, 1.6 L VTI (A)

Engine No: R16A13006641

Reg. Date: 23/08/2008 (Man. Year: 2008)

Chassis No: JHMF46208S202262

Colour: Metallic Grey

Odometer: 268608 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,393.40	1,840.32	2,553.08	58.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	940.00	1,360.00	59.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,693.40	2,780.32	3,913.08	58.46
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	6,693.40	2,200.00	4,493.40	67.13
+ GST 7.00/7.00% (S\$)	468.54	154.00	314.54	67.13
Nett Amount (S\$)	7,161.94	2,354.00	4,807.94	67.13

INSPECTION

Date of Assignment: 04/06/2019

Date Inspected: 11/06/2019 Inspected At:

 Yee Auto Pte Ltd (HQ)
 BLK 15, #01-107 SIN MING INDUSTRIAL
 ESTATE .
 SINGAPORE 575673

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	885.50 F	*638.00 FL
2	1		*FRONT BUMPER BRACKET - LH	Repair	56.60 F	*- FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	350.00 F	*- FL
5	1		*FRONT BUMPER SIDE RETAINER - LH	Distorted	65.00 F	*65.00 FL
6	1		*FRONT BUMPER SIDE RETAINER - RH	Serviceable	65.00 F	*- FL
7	1		*FRONT FENDER - LH	Buckled	516.60 F	*516.60 FL
8	1		*FRONT FENDER SPLASH SHIELD - LH	Serviceable	154.20 F	*- FL
9	1		*SET FRONT FENDER SPLASH SHIELD CLIP	Not Necessary	60.00 F	*- FL
10	1		*FRONT FOG LAMP - LH	Mtg Cracked	285.50 F	*250.40 FL
11	1		*FRONT FOG LAMP COVER - LH	Serviceable	80.00 F	*- FL
12	1		*FRONT HEAD LAMP - LH	Mtg Cracked	985.00 F	*790.40 FL
13	1		*FRONT TYRE - LH	Serviceable	300.00 FS	*- FS
14	1		*FRONT WHEEL RIM - LH	Serviceable	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,393.40	2,300.40
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	460.08
Total Parts (\$\$)	4,393.40	1,840.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	New	1,000.00	450.00
2	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	New	1,000.00	440.00
3	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.	New	120.00	30.00
4	WHEEL ALIGNMENT.	New	120.00	0.00
5	TO CHECK WIRING FUNCTIONS.	New	60.00	20.00
Gross Labour Cost (S\$)			2,300.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >