

ASS. REC. BY:

REF:

CS3/CTI1900005/Ncd302

Special Instruction:

Surveyor:

Naz

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

6/6/1901-49pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJL 2498C

Insured:

GBH 2775T

at Workshop n/s

Wei car spray

Tel:

9638 3306

of

Blk 1017 Yishun Ind. Park A # 01-242

Policy No:

DMCVSN30267819011

Claim No:

SNM19D202487002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:37pm 6/6/19

Person Contacted:

Ahwei

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction Estimate (X)
	SJL 2498C - X
	GBH 2775T - X
	Dismantle: 7/6/2019
	After repair: 12/6/2019

REF: CT

REF: CT

Surveyor: NAZ

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

ODI ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NIS	O/S

Est. or Market Value: _____

IWAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Turn Sum: _____ % J Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STL 2498C Yr Regn: Nov 108Type: ☒ M.Car / ☐ M.Cycle / ☐ BUS / Van / Lorry / Taxi / Prime Mover /

Truck / Tractor or

Make: HONDA CIVIC C.O. 1799Colour: GREY A/C: ☒ Insured / ☐ Std / NI / NASp. Reading: 148,007 T/Radio: ☒ Insured / ☐ Std / NI / NA

Eng/No: _____

C/No: JHMF0163095200864Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModl: Nil / SIRlm / ☒ STD / Rlm orTyre Size: F: 205/55R16R: 11

BS / DUN / EXHOVA / GY / FS / LIZA / MIC / OITSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front: _____ Rear: _____

R/Bal. 5 mm R/Bal. 6 mmL/Bal. 5 mm L/Bal. 6 mmD.O.A. _____ U.O.I. 6/6/19Survey held at WEI CARDis. of Damages: Frl / ☒ Rear / ☐ O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Repair Range \$8K - \$6K

2/8/2019

Date/Time, File Pass to?

☐ : Prelim Report☐ : Final Report1) _____
Date/Time, File Return to?

2) _____

Report Format: PRE

Lump Sum / I.B.I. (\$) _____

Days Of Repair: 6Resurvey No. of Trip: 2Survey Fee: 190

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) S + HS _____☐ : Interview (\$ _____) Photos _____☐ : Tech. Invs (\$ _____) Other _____☐ : Weekend (\$ _____)

TOTAL

190

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Aug 2019		01 Aug 2019 18:47 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	E-CAR SOLUTIONS ENTERPRISE, Co. Reg. No.: 53343838A		
Vehicle Reg. No.:	SJL2498C	Date of Loss:	03/06/2019 18:00 - :59
Claim Type:	TP / SNM19D202487C02	Policy/Cover Note No.:	DMCVSN30267819011
Vehicle Reg. No. (Insured):	GBH2775T	Policy No. (Claimant):	5104164100
		Excess:	S\$0.00
Repairer:	Wei Car Spray Painting (HQ) 1017 YISHUN INDUSTRIAL PARK A #01-242, 768759 Yishun - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 14/08/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 6 June 2019 1:49 PM
To: Florence KOH
Cc: assignments
Subject: snm19d202487 / your ref: wcs/sjl2498c

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

Nivitha (LKK Auto)

From: Bee Ling Koh <kohbeeling@yahoo.com.sg>
Sent: Thursday, 6 June 2019 2:39 PM
To: boonsen.chong@sg.cntaiping.com; assignments@lkkauto.com
Cc: florencekohef@yahoo.com.sg
Subject: Fw: snm19d202487 / your ref: wcs/sjl2498c

Our Ref: WCS/ SJL 2498C
Your Ref: GBH 2775T
(Please quote our reference number when replying)

6 June 2019

CHINA TAIPING
Singapore

Dear Sirs

NOTICE OF ACCIDENT

Claimant: E-CAR SOLUTIONS ENTERPRISE

Pre-action Protocol for Non-injury Motor Accident Cases involving motor accident occurring on or after 1st April 2016 ["Protocol"]

We refer to your email dated 6 June 2019.

Firstly, we object to the appointment of any of the motor surveyors proposed by in your List as a single joint expert. We have already stated this at para 4 of our Notice of Accident dated 6 June 2019.

Secondly, we have also given you our proposed list of proposed motor surveyors at para 4 of our Notice of Accident dated 6 June 2019.

Thirdly, if you object to our proposed list of proposed motor surveyors, this matter shall proceed on the basis of para 2.9 of the Protocol. Accordingly, our client shall appoint a surveyor of his choice to conduct the pre-repair survey. And our client shall have his motor vehicle repaired after the pre-repair survey had been done by your appointed surveyor.

Fourthly, for the sake of clarity, we do not agree to your appointed surveyor conducting the Pre-Repair Survey as the single joint expert.

If you wish to conduct a post-repair inspection, please instruct your appointed surveyor to inform our client's repairer of the same during the pre-repair survey.

Finally, the location and contact person of the workshop are as follows:

Name of Workshop : Wei Car Spray Painting Pte Ltd
Address : Blk 1017 Yishun Industrial Park A
#01-242 Singapore 768759

Contact person : Ah Wei
Telephone No : 9638-3306

REGARDS
CINDY
KK CHENG AND CO
DID :6227-1272

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	838A
Vehicle Details	
Vehicle No.:	SJL2498C
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	HONDA CIVIC 1.8L 5AT
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	R18A14005061
Chassis No.:	JHMFD16309S200864
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$23,035.00
Original Registration Date:	20 Nov 2008
First Registration Date:	20 Nov 2008
Transfer Count:	4
Actual ARF Paid:	\$23,035.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Nov 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$32,121.00
COE Rebate Amount:	\$29,863.00
Total Rebate Amount:	\$29,863.00

The information contained herein is correct as at 02 Aug 2019

OK

MSI119072791 / STA INSPECTION PTE LTD - Sin Ming
 ENTRY DATE & TIME: 04/06/2019 12:51
 SUBMITTED BY: Wong Lip Yong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2019 12:51
Date Of Accident	03/06/2019 18:00
Exact Location Of Accident	PIONEER ROAD (ROUNABOUT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL2498C
Insured/Policyholder	
Name Of Registered Owner	E-CAR SOLUTIONS ENTERPRISE
Co Reg No	53343838A
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-93828476
Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC 1.8
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104164100
Cover Note Number	
Driver	
Name of Driver	SYED AHAMED GHAN S/O SYED IBRAHIM
NRIC No	S1404614C
Date Of Birth	09/04/1960
Occupation	INDOOR
Date Of Driving Pass	02/03/1979
Driving Experience	40 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93828476

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

BLK 164 STIRLING ROAD
#12-1218

Postcode

140164

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own
Vehicle-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved
in the accident

1

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by
ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)
soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBH2775T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

SAMSUDIN MOHAMED RIYAS

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

E-CAR SOLUTIONS
ENTERPRISE

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

QIA4346: SKETCH PLAN Form _21

Sketch Plan #2

SKETCH PLAN

Pioneer Road

Pioneer Road

to AVE

my car

lorry.

A = SJL 249

B = GBH 27

A = SJL 24980
B = GBH 2775T

I was driving along pioneer Road from shipyard Road. I was giving way to passing vehicle at the roundabout at Pioneer road. Suddenly this lorry hit me from behind. He is a foreign Worker. He told me, his leg slipped when braking.

I/We declare the foregoing particulars are true in every respect.

Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)






























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Aug 2019		01 Aug 2019 18:47 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	E-CAR SOLUTIONS ENTERPRISE , Co. Reg. No.: 53343838A								
Vehicle Reg. No.:	SJL2498C	Date of Loss:	03/06/2019 18:00 - :59 [126 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202487C02	Policy/Cover Note No.:	DMCVSN30267819011						
Vehicle Reg. No. (Insured):	GBH2775T	Policy No. (Claimant):	5104164100						
		Excess:	S\$0.00						
Repairer:	Wei Car Spray Painting (HQ) 1017 YISHUN INDUSTRIAL PARK A #01-242, 768759 Yishun - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 14/08/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJL2498C (SNM19D202487C02)**
[GBH2775T]
TP
E-CAR SOLUTIONS ENTERPRISE
Jun 3 2019 6:00PM
[-]
Wei Car Spray Painting

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	04/06/19 13:19	Accident Statement		Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	04/06/19 13:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	04/06/19 13:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	04/06/19 13:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	04/06/19 13:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	04/06/19 13:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	04/06/19 13:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	04/06/19 13:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	04/06/19 13:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	04/06/19 13:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	04/06/19 13:06	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
2	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
3	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
4	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
5	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
6	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
7	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
8	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
9	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
10	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
11	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
12	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
13	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
14	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
15	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
16	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
17	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
18	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>
19	02/08/19 17:20	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
20	02/08/19 17:20	General View	 Load JPG	<input checked="" type="checkbox"/>
21	02/08/19 17:20	General View	 Load JPG	<input checked="" type="checkbox"/>
22	02/08/19 17:20	General View	 Load JPG	<input checked="" type="checkbox"/>
23	02/08/19 17:20	General View	 Load JPG	<input checked="" type="checkbox"/>
24	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	02/08/19 17:21	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	02/08/19 17:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	02/08/19 17:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	02/08/19 17:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	02/08/19 17:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	02/08/19 17:22	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	04/06/19 13:19	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	04/06/19 13:19	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	04/06/19 13:19	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	04/06/19 13:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	04/06/19 13:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	04/06/19 13:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	04/06/19 13:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	04/06/19 13:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	04/06/19 13:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	04/06/19 13:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	04/06/19 13:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail Print
9	04/06/19 13:06	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	04/06/19 13:06	Accident Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail Print
1	04/06/19 13:19	Sketch Plan		Load TIF
2	04/06/19 13:19	Sketch Plan #2		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119010005/NCD3E2

Date: 06/08/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30267819011

Claimant Vehicle
No : SJL2498CInsured Vehicle
No : GBH2775T

Date of Loss: 03/06/2019

Nature of Claim: TP

Claim
No: SNM19D202487C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJL2498C**

Make & Model: HONDA CIVIC, 1.8 (A)

Engine No: R18A14005061

Reg. Date: 20/11/2008 (Man. Year: 2008)

Chassis No: JHMF16309S200864

Colour: Grey

Odometer: 148007 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/08/2019

Date Inspected: 06/06/2019 Inspected At:

Wei Car Spray Painting (HQ)
1017 YISHUN INDUSTRIAL PARK A #01-
242
Singapore 768759

Estimated Period of Repair: 6.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Aug 2019)
Parts:	143	HONDA CIVIC 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL2498C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >