

22/03/2003

ASS. REC. BY:

REF:

CS/INC19016031/E/d321

Special Instruction:

Surveyor: Wally JASSIGNMENT (Office)

From (Person):

Guthrie Ang

of

INC

Date/Time:

4/6/19 @ 9.51am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 6405

Insured:

SKR 3762P

at Workshop m/s

Auto Insure

Tel:

of

6 Marsiling Lane

Policy No:

Claim No:

M1/1047352-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

2/6/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

SumVehicle IN / OUT

Date/Time

Action/Instruction

Estimate ✓SLL 6405 - C03 / LCR 18011715 / IC / pu 392DVA: 22/06/2018SKR 3762P - NA / INC19003889 / H+DVA: 28/2/2019lump Sum \$23501 cred: 6572.08 (73%)

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLL 64005 Yr Regn: 3 mar 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Mazda 3 c.c. 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 118977 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM6BN22A8H0142124Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/R / STD A/Rim orTyre Size: F: 205/60 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Newton

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 2/6/19D.O.I. 4/6/19

Survey held at

Auto Insure 0221PMDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 DEC 2019

Date/Time, File Pass to?

1) 16/12 Typist

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Prel. Report☒ : Final ReportDays Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS, SI

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 2350 )290290

**Nivitha (LKK Auto)**

**From:** Cynthia Ang <Cynthia.Ang@income.com.sg>  
**Sent:** Tuesday, 4 June 2019 9:51 AM  
**To:** 'assignments@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** Teng Ken Leong; Thio Tse Kiat; Cynthia Ang  
**Subject:** TP CASES FARMED OUT TO LKK ON 04/06/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Quek Swee Keng	MT/1047395-001	SHD2157C	PRIME AUTO CLAIMS SERVICE PTE LTD	6 BENOI PLACE	Chrissy / 6861 0908		SKJ3337B	31/05/2019	
2	Cyndie Yong	MT/1044568-002	SHD2989T	PRIME AUTO CLAIMS SERVICE PTE LTD	6 BENOI PLACE	Chrissy / 6861 0908		FBC3857K	13/05/2019	
3	Wo Jessie	MT/1047390-001	SHD2480T	PRIME AUTO CLAIMS SERVICE PTE LTD	6 BENOI PLACE	Chrissy / 6861 0908		SGG2155D	03/06/2019	
4	Charlotte Chew	MT/1037523-001	YP8640U	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD	3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457	Janice Chang / 62686183		XD9743A	20/03/2019	After 10am
5	Azhari	MT/1047469-001	SKD2239P	AUTO INSURE PTE LTD	6 MARSILING LANE	SAM / 31572628		SLQ1888S	30/05/2019	
6	Eric Tang	MT/1047352-002	SLL6400J	AUTO INSURE PTE LTD	6 MARSILING LANE	Sam Goh / 9743 6363		SKR3762P	02/06/2019	
7	Serene Lim	MT/1047289-001	SJT452E	AUTO WHEELS MOTOR WORKS	No.1 BUKIT BATOK CRESCENT #02-40	Louis Ong / 91928963		GZ9173E	28/05/2019	
8	Muhammad Airwan	MT/1011852-002	PC8628G	ONE LINE MOTORWORKS TRADING	11 OLD TUCK ROAD	Ms Penny / 93533081		GBB9494P	17/09/2018	
9	Serene Lim	MT/1046034-002	SGS4984B	PRO-JEX V2D MOTOR PTE LTD	25 KAKI BUKIT ROAD 4 #03-93 SYNERGY @ KB	Edmund / 8668-7666		SGK2531E	24/05/2019	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang

Admin Assistant

Motor Insurance

T +65 6430 7900

[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

## Denise Tay (LKKAuto)

---

**From:** Steve Chen (LKK Auto)  
**Sent:** Friday, 13 December 2019 5:01 PM  
**To:** Denise Tay (LKKAuto)  
**Subject:** SLL6400J - Finalize

Dear Denise,

FYI.

Thanks

Best Regards,  
**Steve Chen** | Assistant Automotive Assessor  
LKK Auto Consultants

Phone: 6256 3561 | Email: [SteveChen@lkkauto.com](mailto:SteveChen@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** AutoInsure (Claims) [<mailto:claims01@autoinsure.com.sg>]  
**Sent:** Friday, December 13, 2019 2:58 PM  
**To:** Steve Chen (LKK Auto)  
**Cc:** Denise Tay (LKKAuto)  
**Subject:** Re: SLL6400J - Finalize

### **WITHOUT PREJUDICE**

Dear Steve,

We refer to the above matter and email below.

We confirm finalization amount at \$2350.00

Thank You.

Regards

Sam Goh  
did: (65) 3157 2624 / 3157 2628  
mobile: (65) 9743 6363  
e: [claims01@autoinsure.com.sg](mailto:claims01@autoinsure.com.sg)

Auto Insure Pte. Ltd.  
201437380M  
6 Marsiling Lane S739145

t: (65) 3157 2626  
f: (65) 6368 0081  
w: [www.autoinsure.com.sg](http://www.autoinsure.com.sg)  
g.e: [claims@autoinsure.com.sg](mailto:claims@autoinsure.com.sg)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/06/2019 11:48
Date Of Accident	02/06/2019 12:05
Exact Location Of Accident	JUNCTION OF SIMS AVE & TANJONG KATONG RD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL6400J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31572626

### Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 L 4-DOOR SEDAN SP.6EAT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	19-MK000194-R00
Cover Note Number	

### Driver

Name of Driver	MOHD YUSOFF BIN ABDUL GHANI
NRIC No	S1648522E
Date Of Birth	09/01/1964
Occupation	OUTDOOR
Date Of Driving Pass	15/05/2002
Driving Experience	17 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90584881
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 224 YISHUN ST 21 #04-485
Postcode	760224
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 2/6/2019 AT ABOUT 1205HRS . I WAS TRAVELLING ALONG SIMS AVE. I WAS CHANGING LANE FROM LANE 2 TO LANE 2 . I FELT THE IMPACT OF BANG HIT ON MY LEFT SIDE OF MY VEHICLE .

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR3762P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	THAM KOK KEONG
NRIC/Passport Number	S0135386A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2

### SKETCH PLAN

Junction of Sims Ave & Tanjong Katong Rd

A: 9LL6400J

B: 9KA3762P



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/6/2019 at about 12:00hrs. I was travelling along Sims Ave. I was changing lane, from lane 2 to lane 3. I felt the impact of being hit on my left side of my vehicle.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

3/6/2019

1052 hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

3/6/2019

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	4597K
<b>Vehicle Details</b>	
Vehicle No.:	SLL6400J
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520429743
Chassis No.:	JM6BN22A8H0142124
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,951.00
Original Registration Date:	03 Mar 2017
First Registration Date:	03 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$9,951.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Mar 2027
PARF Rebate Amount:	\$7,463.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	02 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,751.00
COE Rebate Amount:	\$38,480.00
Total Rebate Amount:	\$45,943.00

The information contained herein is correct as at 07 Jun 2019

OK



Auto Insure Pte. Ltd.  
6 Marsiling Lane  
Singapore (739145)  
E: claims01@autoinsure.com.sg  
W: www.autoinsure.com.sg  
T: 3157 2626 F: 6368 0081  
**GST No.: 201437380M**

**Page No.1**

**AUTOMOBILE ASSESSMENT REPORT**

Our Ref: **SLL6400J (SAM)**

Your Ref: **SKR3762P**

Date: **25-Mar-19**

BY EMAIL ONLY  
(claims01@autoinsure.com.sg)

**ATTENTION: MOTOR CLAIMS DEPT**

email: **MTCL@income.com.sg**

1 Maritime Square  
Harbourfront Centre  
#10-01 Singapore 099253

Assessed Vehicle No : **SLL6400J**  
Car Make and Model : **MAZDA 3-1.5 L 4-DOOR SEDAN SP.6EAT (A)**  
Date of Accident : **2-Jun-19**  
Date of Assessment : **3-Jun-19**

We have carried out a physical assessment of SLL6400J at our workshop Auto Insure Pte Ltd sustained damages to the LH portion of the vehicle.


**4. DESCRIPTION OF DAMAGE**

At the time of the inspection observed that this vehicle had sustained damages to the LH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : P/P  
Adjusted Amount : \$ **9,500.00**  
Est. Repair Days : 8



**\*In considering that our client's vehicle is fairly new**

**We will not agree to any repair of parts and only replacement will be done\***

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.  
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

**Disclaimer**

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatever shall be held by

**AUTO INSURE PTE. LTD.** For any reliance on this report by any third party.

Our Ref: SLL6400J

Your Ref: SKR3762P

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<b>PARTS REPLACEMENT - LIST ITEMS</b>				
1	1	FRONT FENDER LH <i>BUL ✓</i>		\$ 685.50 <i>383 ✓</i>
2	1	FRONT FENDER INNER SHEILD LH <i>DEF ✓</i>		\$ 275.90 <i>130 ✓</i>
3	1	FRONT DOOR LH <i>DD ✓</i>		\$ 1,385.00 <i>✓</i>
4	1	FRONT DOOR UPPER HINGE LH <i>nn x</i>		\$ 72.00 <i>X</i>
5	1	FRONT DOOR LOWER HINGE LH <i>nn x</i>		\$ 72.00 <i>X</i>
6	1	ROCKER PANEL LH <i>Repair X</i>		\$ 1,255.00 <i>X</i>
7	1	FRONT WHEEL <i>Cap</i> LH <i>scr ✓</i>		\$ <del>1,101.70</del> <i>80 ✓</i>
8	1	FRONT ABSORBER LH <i>? X nn</i>		\$ 487.00 <i>X</i>
9	1	FRONT LOWER ARM LH <i>? X nn</i>		\$ 632.00 <i>X</i>
10	1	FRONT KNUCKLE LH <i>? X nn</i>		\$ 583.00 <i>X</i>
11	1	FRONT KNUCKLE BEARING LH <i>? X nn</i>		\$ 741.00 <i>X</i>
SUB TOTAL			\$	7,290.10
LESS 20%			\$	1,458.02
TOTAL AMOUNT			\$	5,832.08

Our Ref: SLL6400J

Your Ref: SKR3762P

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED	EST. BY WORKSHOP
1	1	FRONT BUMPER CLIPS <i>rec ✓</i>		\$ 600.00 <i>30 600</i>
2	1	FRONT WHEEL TYRE RH <i>nn x</i>		\$ 300.00
SUB TOTAL			\$	360.00
TOTAL PARTS COST			\$	6,192.08 <i>70</i>

Our Ref: SLL6400J

Your Ref: SKR3762P

S/NO	DESCRIPTION	EST. BY WORKSHOP
<b>LABOUR &amp; PAINTWORK</b>		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 800.00 <i>600</i>
2	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 120.00 <i>30</i>
3	TO REMOVE & REFIT FRONT SUSPENSION LH	\$ 250.00 <i>100 X</i>
4	TO REMOVE & REFIT FRONT DOOR MECHANISM LH	\$ 200.00 <i>50</i>
5	TO CONDUCT WHEEL ALIGNMENT & BALANCING	\$ 150.00 <i>60</i>
6	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 800.00 <i>500</i>
7	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ 80.00 <i>30</i>
8	TO RESPRAY UNDERCOATING ON PARTS REPLACED	\$ 80.00 <i>30</i>
9	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ 60.00 <i>20</i>
10	TO VACUUM, WAXING & CLEAN	\$ 100.00 <i>X</i>
11	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ 100.00 <i>X</i>
TOTAL BEFORE GST		\$ 8,932.08
GST 7%		\$ 625.25
TOTAL (PARTS & LABOUR):		\$ 9,557.33

#### Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$ 9,500.00 for part by part with the third party insurance.

Yours Faithfully,

Jason Heng  
Claims Director

LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee Jie - LKK

4/6/19

5 days

L/S

P-1582-49  
N-30  
L-1320  
2932-49  
L/S-2345-92  
= 2350

1320

10/6/19



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19010031/Etd3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 23-12-2019



ATTN: ERIC TANG

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKR 3762P	Veh. Inspected	SLL 6400J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1047352-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	04/06/2019

#### 2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0142124	Colour	BLUE
Odometer	118977 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	NEUTON	6 mm
L/H Front Tyre	205/60 R16	NEUTON	6 mm
R/H Rear Tyre	205/60 R16	NEUTON	6 mm
L/H Rear Tyre	205/60 R16	NEUTON	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

#### 5. General Information

Accident Date	02/06/2019	Inspect Date / Time	04/06/2019 ( 02:21 PM )
Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 6400J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT FENDER LH	BUCKLED	685.50	383.00
1	FRONT FENDER INNER SHIELD LH	DEFORMED	275.90	130.00
1	FRONT DOOR LH	DENTED	1,385.00	1,385.00
1	FRONT DOOR UPPER HINGE LH	NOT NECESSARY	72.00	-
1	FRONT DOOR LOWER HINGE LH	NOT NECESSARY	72.00	-
1	ROCKER PANEL LH	TO REPAIR SEE LABOUR	1,255.00	-
1	FRONT WHEEL CAP LH	SCRATCHED	1,101.70	80.00
1	FRONT ABSORBER LH	NOT NECESSARY	487.00	-
1	FRONT LOWER ARM LH	NOT NECESSARY	632.00	-
1	FRONT KNUCKLE LH	NOT NECESSARY	583.00	-
1	FRONT KNUCKLE BEARING LH	NOT NECESSARY	741.00	-
	LESS 20% DISCOUNT		-1,458.02	-395.60
			5,832.08	1,582.40
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	FRONT WHEEL TYRE RH (SN)	NOT NECESSARY	300.00	-
			360.00	30.00
<b><u>LABOUR</u></b>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF ROCKER PANEL LH.		800.00	600.00
	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS.		120.00	30.00
	TO REMOVE & REFIT FRONT SUSPENSION LH.	NOT NECESSARY	250.00	-
	TO REMOVE & REFIT FRONT DOOR MECHANISM LH.		200.00	50.00
	TO CONDUCT WHEEL ALIGNMENT & BALANCING.		150.00	60.00
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED.		800.00	500.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		80.00	30.00

Report Ref No. CS/INC19010031/Etd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY UNDERCOATING ON PARTS REPLACED.		80.00	30.00
	SUNDRIES. (SAND PAPER, WELDING WIRE ETC)		60.00	20.00
	TO VACUUM, WAXING & CLEAN.	NOT NECESSARY	100.00	-
	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS.	NOT NECESSARY	100.00	-
			2,740.00	1,320.00
GRAND TOTAL			8,932.08	2,932.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,350.00

Report Ref No. CS/INC19010031/Etd3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.