

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Steve (LKK) wr April 11/6/19, 11.am
83228813 4 days
P/P
Ry bet spray

Quotation Non binding - Preview

Ms.
LIM
YUNG WEI
110 MCNAIR ROAD
#06-255
Singapore 320110

Page 1/1
Document no.
Document date 04-06-2019
Customer no. 5211027136
Customer GST-ID
Dealer 39999
Job order number 2019000834/ 1
Job order date 03-06-2019
Service Advisor EDMUND, HUI HUANG GOH

License plate	Model code	First registration	VIN	Model	Mileage
SMK7740P	7N24MYH0	24-04-2019	WVWZZZ7NZKV011173	Sharan Highline 2.0 I TSI 162kW DSG	678

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
7N0821021B	Fender (LHF) <i>DD</i>	1	pcs.	729.31	#1	729.31	780.36
7N0805911B	Wheelhouse Liner <i>X</i>	1	pcs.	117.11	#1	117.11	125.31
	LABOUR	<i>21</i>	pcs.	840.00	#1 <i>840</i>	2,520.00	2,696.40
	Spray Painting	<i>22</i>	pcs.	800.00	#1 <i>1600</i>	2,400.00	2,568.00

Quotation valid till 10-06-2019

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	5,766.42	7%	456.85	6,526.42	6,983.27
Total	760.00	5,766.42		456.85	6,526.42	6,983.27

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: